
Contract Number N62470-02-D-3260 DCN: SHAW_3260_FZN0_0010 Contract Task ler FZN0

FOLDER 1 OF 6



December 28, 2007
Installation Restoration Site 4, Plume 4-2
DNAPL Removal Action
Alameda Point, Alameda, California



Remoral Action Completion Report

REMOVAL ACTION COMPLETION REPORT Installation Restoration Site 4, Plume 4-2 DNAPL Removal Action Alameda Point Alameda, California

Environmental Remedial Action Contract Number N62470-02-D-3260 Contract Task Order FZN0

Document Control Number SHAW_3260_FZN0_0010 December 28, 2007

Prepared for:



U.S. Department of the Navy Base Realignment and Closure Program Management Office West 1455 Frazee Road, Suite 900 San Diego, California 92108-4310

Prepared by:



Shaw Environmental, Inc. 4005 Port Chicago Highway Concord, California 94520-1120

REMOVAL ACTION COMPLETION REPORT Installation Restoration Site 4, Plume 4-2 DNAPL Removal Action Alameda Point Alameda, California

Environmental Remedial Action Contract Number N62470-02-D-3260 Contract Task Order FZN0

Document Control Number SHAW_3260_FZN0_0010_0 December 28, 2007

Prepared by: Marlet S.

Charles K. So, PE Sr. Project Engineer

Date: December 28, 2007

Date: December 28, 2007

Approved by

David Cacciatore, Ph.D., PE

Project Manager

Table of Contents_

List of	Figure	es		
		98		
		ndices		
Acron	yms ar	nd Abbreviations	iv	
	,			
Evocu	tivo Cr	umman.	5 0.4	
1.0	tive Summary			
1.0	1.1	duction		
	1.1	Site Description		
		Geology and Hydrogeology		
2.0	1.3	Project Background		
2.0		oval Action Description	2-1	
	2.1	Extent of Removal Action Area		
	2.2	Removal Action Objective		
	2.3	Treatment Approach and System Layout		
3.0		ementation of Removal Activities		
	3.1	Site Preparation		
	3.2	Treatment System Installation		
		3.2.1 Electrodes		
		3.2.2 Vapor Piezometers and Temperature Monitoring Points		
		3.2.3 Groundwater Monitoring Wells		
		3.2.4 Hot Vapor Conveyance Piping		
		3.2.5 Vapor Extraction and Treatment Train		
		3.2.6 Liquid Handling and Treatment Train		
		3.2.7 Power Supply and Connection		
		3.2.8 Pre-Operational System Inspections and Testing		
	3.3	Construction and Investigation-Derived Waste Handling		
	3.4	Additional System Design Investigation		
	3.5	Baseline and Progress Performance Sampling		
	3.6	Discharge and Emissions Monitoring	3-8	
	3.7	System Optimization		
	3.8	Termination of Treatment	3-9	
	3.9	Post-Treatment Sampling	3-10	
4.0	Remo	oval Action Effectiveness Assessment	4-1	
	4.1	Effects on Screening Analyte Concentrations and Mass Removal	4-1	
		4.1.1 Changes in Screening Analyte Concentrations		
		4.1.2 Effect on Metals During Treatment		
		4.1.2.1 Effects on Chromium		
		4.1.2.2 Effects on Arsenic and Barium		
		4.1.3 Mass Removal Estimate		
		4.1.3.1 Volatilization		
		4.1.3.2 Groundwater Recovery		
		4.1.3.3 VOC Mass Removal via Other Pathways		
	4.2	Treatment Cost		

Table of Contents (continued)				
5.0 6.0		Post-Removal Action Conditions		
List	of Figu	ıres		
Figure	2 3 4 5 6 7 8 9 10	Site Location Map Plume 4-2 (Building 360) Site Layout Plume 4-2 (Building 360) Removal Action Area Plume 4-2 Treatment System Grid and Equipment Layout Hexavalent Chromium in Soil, 5 feet bgs Total Chromium in Soil, 5 feet bgs Chromium Isoconcentrations in Groundwater Plume 4-2 Baseline and Progress Treatment Sampling Results Well SA Concentration Changes from Baseline through Treatment Plume 4-2 Chromium Concentration Changes in Groundwater During and After In-Situ Treatment Cumulative VOC Mass Recovery and Temperature Plots Versus Hours of Operation During In-Situ Groundwater Treatment Plume 4-2 Post-Removal Action SA Concentrations in Groundwater		
List	of Tab	les		
Table : Table : Table :	2 3	Summary of Additional System Design Investigation Soil Sample Results Summary of Additional System Design Investigation Groundwater Sample Results Summary of Groundwater SA Concentrations from Baseline through Post-Treatment Groundwater VOC Concentration Comparison between Baseline and Last Progress Sampling		
Table :	6	Groundwater Chlorinated VOC Concentration Comparison between May/July and September 2007 DO and ORP Data Comparison between Baseline and Post-Treatment Summary of Additional System Design Investigation Groundwater Sample Results		

List of Appendices_____

Appendix A	TRS Process Equipment Schematic, Construction Drawings and Summary Details for Electrodes, Temperature Monitoring Points, Vapor Piezometers
Appendix B	Building Floor Survey for Utility Clearance
Appendix C	Monitoring Well Construction As-Builts
Appendix D	System Installation Test Report
Appendix E	Waste Manifests (on CD)
Appendix F	Laboratory Analytical Data Packages for Treatment Impact Assessment Soil and
	Groundwater Samples (on CD)
Appendix G	Laboratory analytical data packages for Groundwater Baseline, Progress, and Rebound
	Samples (on CD)
Appendix H	Laboratory analytical data packages for System Compliance Monitoring Samples (on CD)
Appendix I	Statistical Analyses of September Rebound Groundwater Sampling Data (on CD)

Acronyms and Abbreviations

% percent

μg/L micrograms per liter

BAAQMD Bay Area Air Quality Management District

bgs below ground surface
Cr⁶⁺ hexavalent chromium

DCE dichloroethene

DDI design data investigation

DNAPL dense non-aqueous phase liquid

DO dissolved oxygen

EBMUD East Bay Municipal Utility District
EE/CA Engineering Evaluation/Cost Analysis

FWBZ first water-bearing zone
GAC granular activated carbon
IR Installation Restoration

kW kilowatt

mg/L milligrams per liter

mL milliliter

Navy U.S. Department of the Navy

°C degrees Celsius

ORP oxidation-reduction potential

PCE perchlorethene
PCU power control unit
PID photoionization detector

POTW publicly-owned treatment works

SA screening analyte
sf square feet (foot)
SVE soil vapor extraction

TMP temperature monitoring points
TRS Thermal Remediation Services
TSD treatment, storage, and disposal

TtEMI Tetra Tech EM, Inc.

VOC volatile organic compound

VP vapor piezometer

Executive Summary

A removal action was conducted between May 2006 and July 2007 to address the dense non-aqueous phase liquid (DNAPL) in the soil and groundwater at Installation Restoration Site 4, Plume 4-2, within Alameda Point, Alameda, California. The removal action was implemented by Shaw Environmental, Inc. (herein referred to as Shaw), under the Environmental Remedial Action Contract with the U.S. Department of Navy (Navy), Base Realignment and Closure, and followed the conclusions of the Engineering Evaluation/Cost Analysis (EE/CA) completed in 2001. The main objective of the removal action was to reduce the total concentrations of the chlorinated volatile organic compounds (VOC) in the groundwater to below 10,000 micrograms per liter (μ g/L), to the extent technically and economically practicable.

Results of historical investigations at Plume 4-2 suggested the potential presence of DNAPL in the soil and groundwater due to the detection of chlorinated VOCs at levels above 10,000 µg/L. chlorinated **VOCs** of concern were 1.1-dichloroethane. 1,1-dichloroethene, 1,2-dichloroethane, cis-1,2-dichloroethene, trans-1,2-dichloroethene, tetrachloroethene, 1,1,1-trichloroethane, 1,1,2-trichloroethane, trichloroethene, and vinyl chloride. For the purpose of this removal action, these VOCs were also referred to as the screening analytes (SA). The supplemental design data investigation conducted between 2001 and 2002 at the site indicated that part of the groundwater plume was beneath the painting room and the plating shop of Building 360, a former aircraft maintenance facility where solvents and miscellaneous chemicals had been used, stored, and generated as waste. The estimated areal extent of the treatment plume was 34,400 square feet, and the maximum treatment depth was approximately 40 feet below ground surface (bgs).

The EE/CA specified a removal action involving use of in-situ electric resistance heating to remove the VOC mass in the subsurface. Thermal Remediation Services (TRS), a technology vendor subcontracted by Shaw, designed, installed, and operated the in-situ treatment system at Plume 4-2. The treatment system consisted of above-ground and below-grade process components, including 91 electrodes with integral vapor recovery wells, 14 temperature monitoring points co-located with vapor piezometers, a 2000-kilowatt power supply and control unit, and a fleet of vapor and liquid handling and treatment equipment. System installation, begun in late May 2006, was completed in October 2006, followed by system startup testing and routine operation. Treatment operation proceeded until early July 2007 when the system was shut down at the request of Navy.

During system installation, liquid containing elevated levels of chromium and other metals was encountered in two floor structures (also referred to as vats or trenches) inside the former plating

shop of Building 360. The liquid, present at several electrode installation locations, was pumped out for offsite disposal. Due to the unexpected presence of the chromium-laden liquid within the DNAPL treatment area, additional system design investigation to assess the effect from in-situ electrical resistance heating treatment on the chromium, in particular hexavalent chromium, was initiated.

The investigation involved installing two additional groundwater monitoring wells and collecting soil and groundwater samples in and around the plating shop for metals and other analyses before treatment began. Results of soil and groundwater sampling indicated that the source of chromium and hexavalent chromium was mostly confined within the plating shop. As such, additional groundwater samples were taken during and after treatment to monitor for changes in the metal concentrations that could be attributed to the result of the in-situ treatment by electrical resistance heating.

In addition to baseline sampling, treatment progress sampling was conducted periodically at the groundwater monitoring wells, with select well sampling performed the week following the shutdown of the system. In September 2007, one round of groundwater well sampling was conducted to determine the post-treatment concentrations of the chlorinated VOCs.

A total of 5,391,216 kilowatt-hours of energy was input to the ground within the treatment area upon shutdown of the system in July. Based on the results of the post-treatment sampling in September, all except one of the 19 monitoring wells showed SA concentrations below $10,000~\mu g/L$. Excluding the one well above $10,000~\mu g/L$, the reduction of SA concentrations between baseline and post-treatment ranged from about 39% to almost 100%, with a median value of 99.5%. The low percent reduction occurred in the west end of the treatment plume at a monitoring well screened between 32 and 37 feet bgs outside Building 360. The yield of a SA concentration of nearly 7,600 $\mu g/L$ at that well was the cause of the relatively small reduction in that location. The source of the elevated SA concentration is not readily known. Based on the difference in the SA concentrations between baseline and post-treatment, the amount of chlorinated VOCs removed from the plume was estimated at more than 2,000 pounds. Approximately 200 pounds of the VOCs were recovered in the vapor recovery system installed and operated by TRS.

The one well with a post-treatment concentration of 12,000 μ g/L measured in September 2007 is located inside Building 360, near the southeastern corner of the treatment plume and screened between 26 and 31 feet bgs. Sampling results collected from the baseline through the progress monitoring events during treatment did not show a concentration above 2,500 μ g/L. Groundwater temperature at that depth had maintained consistently above 100°C for the latter five months of the treatment period. All of the other well sampling locations that achieved and sustained this elevated temperature yielded total SA concentrations far below 10,000 μ g/L. The

well was sampled again for SA in October 2007, along with several other wells selected for sampling for metals analysis following in-situ heat treatment of the groundwater. The SA concentration was reported at 4,700 μ g/L, still above the baseline concentration of 2,500 μ g/L but well below the removal action goal of 10,000 μ g/L.

Reduction of total and hexavalent chromium concentrations in the groundwater during treatment was noted in several monitoring wells within and outside the plating shop. Although the chromium concentrations showed decreases, arsenic and barium concentrations in some wells showed increases within the first few months of the treatment period. Concentrations of these two metal species remain elevated during the post-treatment sampling conducted in October 2007. However, such increases are expected to be temporal due to the presence of a reducing condition of the groundwater as a result of the in-situ thermal treatment. When the groundwater returns to the anoxic condition, the concentrations of the two metal species should gradually decrease to pre-treatment levels.

In conclusion, the removal action objective at Plume 4-2 was achieved. After eight months of continuous heating, the total SA concentration in the groundwater in the first water bearing zone was reduced to below 10,000 μ g/L, with a mean concentration of approximately 1,600 μ g/L. The bulk of the VOC mass was removed to the extent technically and economically practicable. There appears to be no mobilization of chromium and hexavalent chromium during and following treatment of the soil and groundwater.

1.0 Introduction

This Removal Action Completion Report, prepared by Shaw Environmental, Inc. (herein referred to as Shaw), summarizes the removal action conducted at Plume 4-2 (Building 360) of the Installation Restoration (IR) Site 4. IR Site 4 is located within the former Alameda Naval Air Station (currently known as Alameda Point) in California. Removal activities were executed for the U.S. Department of the Navy (Navy), Base Realignment and Closure, under the Environmental Remedial Action Contract N62474-98-D-2076, Contract Task Order 0133 and Modification Number 1. This report addresses the following main topics:

- Site description and project background
- Removal action objectives and approach
- Field implementation of the removal activities
- Removal action effectiveness assessment
- Post-removal action site conditions and recommendations

Supporting field records and analytical reports are included in the accompanying appendices.

1.1 Site Description

Plume 4-2 resides in the western portion of IR Site 4 and encompasses an area of approximately 34,400 square feet (sf) on the west to southwest end of Building 360. Figure 1, "Site Location Map," shows the locations of both IR Site 4 and Plume 4-2. The building, currently unoccupied, housed specialized production shops for repair and testing of jet-turbine and piston engines. These included a paint shop, a parts-cleaning shop, a plating shop, and machine shops. Industrial wastewater generated in Building 360 was treated at the wastewater treatment facility formerly located north of Building 163, which is approximately 50 feet west of Building 360, as shown in Figure 2, "Plume 4-2 (Building 360) Site Layout." Aircraft engine repair operations began at the site in 1954 (*RI/FS Work Plan, NAS Alameda, Alameda, California* [Canonie Environmental Services, 1990]). Plating operations discontinued and the plating shop was dismantled and removed in 1991. The machine shops, stripping and painting shops, and parts-assembly areas within Building 360 were active until 1996.

The former plating shop operations included paint stripping by blasting; chrome, silver, and nickel stripping; etching; and chrome, silver, nickel, and copper plating. The cleaning and blasting processes used baths of phenol-based cleaners, alkaline-type cleaners, rust removers, descaling compounds, and caustics. Chemical mixtures used in the cleaning process historically included a mixture containing 55 percent (%) tetrachloroethylene also known as perchloroethene (PCE). Several other mixtures containing dichlorobenzene, methylene chloride, toluene, and 30 to 70% solutions of sodium hydroxide were also used. Leaks of these chemicals were

believed to have contributed to the subsurface contamination found across the IR Site 4 area based on historical investigation findings (IT Corporation, 2002a).

Plume 4-2 was identified from a focused groundwater investigation previously conducted at IR Site 4 (Tetra Tech EM, Inc. [TtEMI] and Einarson, Fowler, and Watson, 1998). The groundwater plume was located beneath the former painting and plating shops on the west side of Building 360 (see Figure 2). Based on the detected groundwater concentration of 1,1-dichloroethene (DCE), the investigation results suggested a potential presence of dense non-aqueous phase liquid (DNAPL) contamination at the site.

1.2 Geology and Hydrogeology

Stratigraphy beneath IR Site 4 consists of four geologic units: the Lower San Antonio Formation, Upper San Antonio Unit. the Merritt Sand Formation, and artificial fill (Draft CLEAN II-Operable Unit-2 Remedial Investigation Report [TtEMI, 1999]). The Lower San Antonio Formation, also called the Yerba Buena Mud, extends from 90 feet to between 150 and 175 feet below ground surface (bgs) and is composed of predominantly clay. Above the Lower San Antonio Unit is the Upper San Antonio Formation, which is composed of dark green-gray sand with sandy clay and silty clay. This formation extends from 70 to 90 feet bgs. Overlying the San Antonio Formation is the Merritt Sand Formation and it extends from roughly 10 to 70 feet bgs. It is composed of an orange-brown, fine-grained, silty sand and a fine-grained clayey sand. The top of the Merritt Sand is a dense, well-consolidated clayey sand between 1 and 5 feet thick and has a low hydraulic conductivity. Additionally, a zone divides the Merritt Sand into an upper eolian (i.e., dune sand) and a lower alluvial section. The eolian section of the Merritt Sand represents sediment deposition by airborne processes, and the alluvial section of the Merritt Sand represents sediment deposition by fluvial or water processes. The contact zone between the eolian sand and alluvial sand sections ranges from 5 to 15 feet thick, consisting of a dense to well-consolidated clayey sand. This clayey sand has a low hydraulic conductivity.

Overlying the Merritt Sand Formation is the artificial fill that extends from the surface down to roughly 10 feet bgs. The artificial fill consists of a light to dark brown, fine-grained, silty sand with trace amounts of gravel and brick fragments. The fill is composed of dredge spoils from the San Francisco Bay and the Oakland Inner Harbor.

Groundwater at IR Site 4 is encountered between 2 and 8 feet bgs within the artificial fill, with the average depth around 5 to 7 feet bgs at Plume 4-2. Unlike areas to the west, there is no intervening layer of Bay Sediment between the artificial fill and Merritt Sand beneath the site; therefore, the first water-bearing zone (FWBZ) present elsewhere in Alameda Point behaves as a single hydrogeologic unit at the site. The water-bearing zone is composed of artificial fill, Merritt Sand, and Upper San Antonio Unit. Beneath this interval, the Lower San Antonio


Formation (Yerba Buena Mud) forms a regionally continuous aquitard that inhibits water migration from the water-bearing zone to underlying formations.

The groundwater flow directions are affected by local recharge from precipitation, seasonal variation in groundwater elevations, and tidal influences. For Alameda Point, the groundwater has been found to generally flow from the east and northeast inland areas to the west and southwest. Within IR Site 4 and Plume 4-2, groundwater is affected locally by industrial building storm drains and underground utility trenches. Water levels in the surrounding area of industrial buildings suggest localized groundwater mounds and sinks. Based on a tidal study conducted in nearby wells, there is no tidal fluctuation expected at the site (*Tidal Influence Study Letter Report* [PRC Environmental Management, Inc., 1997]). Total dissolved solids concentration in the shallow groundwater has been measured at approximately 5,000 milligram per liter (mg/L) (*Determination of the Beneficial Uses of Groundwater at Alameda Point, Alameda, California* [TtEMI, 2000]).

1.3 Project Background

Because of the previous investigation findings, a removal action to address the potential DNAPL was initiated for Plume 4-2 (TtEMI, 2001). Between 2001 and 2002, a design data investigation (DDI) was conducted to further determine the contaminant distribution in groundwater and the DNAPL plume extent for the full-scale design of the treatment system (IT Corporation, 2002b). Results of the investigation were discussed further in Section 2.0.

In 2004, Shaw subcontracted the field implementation of the removal action at Plume 4-2 to Thermal Remediation Services (TRS), a small business firm with the experience and expertise to perform the technology utilized for the removal action. The selection of TRS was also due to a request by the Navy to allow simultaneous implementation of similar removal actions at this site and at Building 5 (Plumes 5-1 and 5-3). Building 5 is another IR site with potential DNAPL in the subsurface. To ensure consistency in the execution and administration of Plume 4-2 under the Navy Remedial Action Contract, Shaw provided oversight of TRS performance, including compliance monitoring, and project communication and coordination with the Navy.



2.0 Removal Action Description

This section describes the nature and extent of the inferred DNAPL removal action area and the removal action objectives. In addition, this section provides an overview of the treatment approach taken to address the DNAPL contamination in the groundwater.

2.1 Extent of Removal Action Area

As previously stated, DNAPL at Plume 4-2 was suspected based on the 1,1-DCE concentration in the groundwater. The location identified in the Engineering Evaluation/Cost Analysis (EE/CA) for DNAPL removal covered an area of approximately 120 feet in diameter (or 11,000 sf) and a maximum depth of 30 feet (TtEMI, 2001). The removal action boundary was established based on a concentration contour of 10,000 micrograms per liter (µg/L).

The results from the system DDI completed in 2002 revealed a much larger area required for the full-scale removal action than has been estimated in the EE/CA. Based on the later findings, the treatment area was nearly 35,000 sf and the maximum depth increased to 40 feet (IT Corporation, 2002b). The treatment boundary extended further east and west of the removal action plume originally established in the EE/CA. Figure 3, "Plume 4-2 (Building 360) Removal Action Area," shows the removal action plume described in the EE/CA, compared to the removal action plume area defined in the DDI.

2.2 Removal Action Objective

Historical investigation results identified 10 chlorinated volatile organic compounds (VOCs) in groundwater as the screening analytes (SAs) for monitoring of the removal action at Plume 4-2. These SAs were 1,1,1-trichloroethane, 1,1,2-trichloroethane, 1,1-dichloroethane, 1,1-DCE, 1,2-dichloroethane, cis-1,2-DCE, trans-1,2-DCE, PCE, trichloroethene, and vinyl chloride, with 1,1-DCE being the predominant species historically detected. According to the EE/CA, the primary objective of the removal action was to reduce the total SA concentrations in the groundwater to below 10,000 μ g/L, to the extent technically and economically practicable. The EE/CA also identified electric heating of the soil and groundwater in the plume area as the recommended removal action alternative for Plume 4-2 (TtEMI, 2001).

2.3 Treatment Approach and System Layout

Based on the treatment area and depth, established after the DDI in 2002, TRS divided the plume into five regions, varied by areas and depths. The maximum treatment depth ranged from approximately 18 to 44 feet across the plume.



The treatment system involved the use of energized electrodes to generate heat resistively to accelerate removal of the VOCs from the subsurface. Electricity to the electrodes was supplied from a power supply and control unit and several field step-down transformers. The electrodes were placed in a 20-foot triangular grid across the plume. The grid layout and the five treatment regions are shown on Figure 4, "Plume 4-2 Treatment System Grid and Equipment Layout."

The treatment system also included a vapor recovery and treatment train and a liquid treatment train. Vapor captured from the subsurface was treated with vapor-phase granular activated carbon (GAC) prior to its discharge to the atmosphere. Condensed vapor and vapor-entrained liquid were treated with liquid-phase GAC prior to the discharge to the publicly-owned treatment works (POTW). A process schematic of the treatment system is presented in TRS' system documentation included in Appendix A.

3.0 Implementation of Removal Activities

Implementation of the removal action began with site preparation followed by system installation. Construction of the treatment system began in June 2006 and ended in October 2006. Upon completion of system installation, startup testing and routine operation proceeded. Details of the field implementation of the removal activities are presented in the following subsections.


3.1 Site Preparation

Prior to drilling for installing electrodes and other subsurface components, available facility record drawings were reviewed to identify locations of underground utilities, including inactive fire protection and steam lines. Utility clearance using a geophysical instrument was also conducted over drilling locations to aid in verifying the absence or presence of subsurface obstructions in the area.

Because a large portion of the treatment plume was beneath Building 360, which was constructed with a raised concrete floor including subfloor utility corridors, a survey of the existing utilities and other structures below the building floor was also performed. Approximate locations of the utilities and miscellaneous structures that were potential obstructions were marked on a facility layout map for use by TRS prior to borehole drilling. A copy of the building obstructions survey map is included in Appendix B.

In addition to the utility survey, asbestos pipe removal was performed at several locations to provide unrestricted access to electrode installation. Removed asbestos waste was contained and disposed of to offsite landfills (see Section 3.3 for further details). Concrete coring was also performed to allow access to the native soil below. Borehole clearance to the first 5 feet bgs was then performed by hand augering and/or air knifing before drilling proceeded. Borehole locations that encountered with subsurface obstructions within the top 5 feet bgs were marked and then shifted to new locations. Locations of the electrodes and monitoring points/wells affected by the subsurface obstructions inside the building as a result of the utility survey or borehole clearance were shifted a foot to a few feet away.

One electrode location outside Building 360 encountered ground refusal in and around the area during borehole clearance. This location was near the western boundary of the plume. It appeared to be a concrete slab (or similar structure) of several feet thick extending from the ground surface down and over a rather large surface area. Because electrode distance relative to one another had to be kept at some minimum distance (designed spacing was about 20 to 21 feet), there was no alternate location for that electrode. As such, the electrode, which was at grid point C5, was not installed (see Figure 4).



3.2 Treatment System Installation

System installation included constructing electrodes, vapor piezometers (VPs), temperature monitoring points (TMPs), groundwater monitoring wells, a vapor handling and treatment unit, and a liquid handling and treatment unit. All process equipment and piping were installed aboveground, within a fenced compound built outside of the groundwater plume treatment area (also referred to as the "hot zone"). Access to the "hot zone" was restricted by an alarm system that would sound a siren should the access security be breached. The general arrangement of the process equipment is shown in Figure 4. Installation of these components is described in detail below.


3.2.1 Electrodes

TRS installed 91 electrodes at depths of up to 45 feet bgs within the removal action plume. Each electrode, constructed of 3-inch diameter steel pipe with a slotted screen section in the upper portion, was installed within a 12-inch diameter borehole using a hollow-stem auger drill rig. The annular space around the steel casing at each electrode borehole was backfilled with steel shot pellets and graphite. The steel shot, consisting of zero-valent iron, was mixed with graphite and tremied into the annulus space. Approximately 94,725 pounds of steel shot and 5,550 pounds of graphite were used for the 91 electrodes. The average usage of the steel shot/graphite mix at each electrode was approximately 75 pounds per foot. A low-profile drill rig was used for the electrodes installed inside the building.

The slotted portion of the electrode was used for capture of vapor released from the groundwater during heating. Appendix A contains diagrams showing construction details of the electrodes installed at Plume 4-2. The installation depths of the electrodes, as well as the number within each of the five treatment regions are also summarized in Appendix A. As previously stated, one electrode at C5 location was not installed due to ground refusal.

3.2.2 Vapor Piezometers and Temperature Monitoring Points

Fourteen VPs and TMPs were installed across the treatment area using the hollow-stem auger drill rig and/or a Geoprobe[®] direct-push rig. Each pair of VP and TMP was co-located in the same borehole. The VPs, constructed of ¼-inch Teflon[®] tubing, were installed to about 3 feet bgs, while the TMPs, constructed of ¾-inch chlorinated polychlorinated vinyl chloride piping, were installed at depths corresponding to the electrodes within the same treatment regions. In each TMP, type T thermocouples were placed every 5 feet from the ground surface to the bottom of the monitoring point. Construction details of the VPs and TMPs are presented in Appendix A.



3.2.3 Groundwater Monitoring Wells

Seventeen groundwater monitoring wells were initially installed for monitoring of the treatment performance at the site. These wells, identified as MW4-2-1 through MW4-2-17, were installed to depths varying from 10 to 40 feet bgs, and were placed across the plume based on the 2002 DDI results. The wells were constructed of 2-inch diameter, stainless steel casing with 5 feet of 0.02-inch slotted screen, and were screened at intervals that corresponded to the depths where elevated VOC concentrations were found in the DDI. The wells were installed using a hollow-stem auger and/or a Geoprobe[®] direct-push rig. About 48 hours after installation, each monitoring well was developed in accordance with Shaw standard operating procedures for well development.

In August 2006, two more monitoring wells were installed in and around the plume. These wells were screened from 5 to 10 feet bgs and were used to help monitor and evaluate potential impacts on metals mobility from the treatment operation. Further details about these wells are discussed later in Section 5.0. A summary of well construction details and diagrams are presented in Appendix C.


3.2.4 Hot Vapor Conveyance Piping

Schedule 80 chlorinated polychlorinated vinyl chloride piping of size up to 10-inch diameter was used to convey hot vapor from the electrodes to the vapor extraction and treatment train. Piping from the electrodes was manifolded into one main line connecting to the vapor-condensing unit. Flow, temperature, and vacuum measuring ports, as well as the influent vapor sampling port were installed on the main conveyance pipeline. Data collected from these ports helped monitor the performance of the treatment system operation.

3.2.5 Vapor Extraction and Treatment Train

The vapor extraction and treatment train was made up of a vapor condenser, liquid-vapor separator vessels, six vapor phase GAC vessels, and a positive-displacement blower. Hot vapor captured from the treatment area passed through the vapor condenser for cooling before entering the separator, in which non-condensing vapor was separated from condensing liquid. The cooled vapor then continued through the vapor phase GAC vessels for treatment. The condensed liquid was pumped to the liquid handling and treatment train.

The vapor phase GAC vessels, each containing 1,000 pounds of carbon, removed the VOCs in the vapor stream to comply with the air emissions control requirements (primarily Regulation 8, Rule 47, Sections 301 and 302) established by the Bay Area Air Quality Management District (BAAQMD). These requirements were typical to soil vapor extraction (SVE) operations. Following treatment, the vapor stream was sent through the blower and discharged into the



atmosphere via a 20-foot tall stack. Except for the vapor phase GAC vessels and the blower, the other process equipment was installed within a secondary containment area.

3.2.6 Liquid Handling and Treatment Train

The liquid handling and treatment train consisted of a water-holding tank, liquid transfer pumps, cartridge filters, and liquid phase GAC vessels. Initially, 55-gallon carbon drums were used to treat the liquid consisting of mostly condensate. However, during system startup, it was determined that the carbon drums did not meet the pressure requirements. As such, TRS replaced the carbon drums with the pressure vessels that could withstand higher pressure (approximately 30 pounds per square inches) encountered with the liquid treatment system.

Condensate, formed after the vapor condenser, was pumped through the cartridge filters and the GAC vessels before being discharged to the POTW. The filtering system went through several modifications while in operation due to excessive sediment buildup within the system. TRS attributed the buildup to (1) significant groundwater and sediment entrainment from some areas within the plume, such as in the northwestern corner of the plume outside Building 360, and (2) biological growth inside the filtration units.

Treated liquid was discharged into the sanitary sewer via a manhole under the base-wide permit with the East Bay Municipal Utilities District (EBMUD). The discharge location is shown in Figure 4. Initially, the discharge was conveyed via a one-inch diameter line. Because of the groundwater and sediment issues with the treatment unit, one more discharge line was added to facilitate flow through the liquid treatment train. Flow measurements were recorded on both discharge lines to provide the total flow readings for EBMUD permit compliance.

To comply with discharge permit requirements, a holding tank with double containment was used to temporarily contain the treated condensate and groundwater during the system startup and testing period. As the treatment operation progressed, the tank was incorporated as part of the system components. Rainwater collected into the secondary containment and filter rinsate were pumped into the holding tank. From the holding tank, the water was then pumped through the liquid-phase GAC for treatment along with the condensate and groundwater before discharge to the sanitary sewer. A high-level sensor was installed inside the tank to shut off any running feed pump in the event of a high water level in the tank.

3.2.7 Power Supply and Connection

Power to the treatment system was fed from an existing transformer on the north end of Building 360. Three power poles were installed to bring the power cable from the transformer to the 2,000-kilowatt (kW) power control unit (PCU) furnished by TRS. Figure 4 shows the power drop location by the PCU within the treatment compound. From the PCU, electrical cables were run to four separate, field step-down transformers that supplied lower voltage power to the

electrodes. The PCU also supplied power to the electrical process equipment, such as the blower and the pumps.

Pre-Operational System Inspections and Testing 3.2.8

Pre-operational activities included leak testing of conveyance piping, functionality and safety testing of system components and control devices, and baseline groundwater sampling. System testing began on September 25, 2006 and continued with completion on October 19, 2006. Testing included visual inspections of installed components and a dry run of equipment to verify its functionality and readiness. Types of inspections and tests completed included the following:

- Visual inspection and leak test of the vapor and liquid conveyance piping
- Individual system component leak and function tests
- Equipment control interlocking test
- Vacuum influence test
- Voltage safety test
- Startup tests for energy application evaluation

Based on the startup test results, TRS determined that the system would be operating at approximately 150 to 300 volts. TRS also assessed that the vapor recovery system would exert sufficient vacuum influence within the vadose zone over the plume area based on their vacuum influence test results. The pre-operational test and inspection results were transmitted to the Navy for information on October 23, 2006 and are included herein in Appendix D.

3.3 Construction and Investigation-Derived Waste Handling

Waste generated from system installation and associated construction activities consisted of primarily asbestos-containing waste, drill cuttings, well development water, and the chromiumladen liquid encountered within two-below grade trenches inside Building 360. Copies of the waste manifests are provided in Appendix E.

Asbestos-containing waste was generated from the removal of utilities inside Building 360 prior Approximately 3 cubic yards of non-friable to drilling for electrode installation. asbestos-containing waste material were disposed of at Altamont Landfill in Livermore, California. Four cubic yards of friable asbestos-containing waste material were disposed of at Norcal Waste Systems Hay Road Landfill in Vacaville, California.

Drill cuttings were placed in soil bins. Following profiling, the cuttings were disposed of as nonhazardous waste to Altamont Landfill facility, except for two bins of soil containing elevated levels of chromium generated from the field treatment impact assessment activities. The impact assessment effort, described in detail later, was executed after the finding of chromium-laden liquid in the plating shop. The soil from the two bins was disposed of at Chemical Waste Management, a Class I treatment, storage, and disposal (TSD) facility in Kettleman City, California. The liquid containing elevated levels of chromium was disposed of at the Chemical Waste Management TSD facility in Kettleman City.

The well development water was discharged into the sanitary sewer after profiling analytical results showed that the water quality met the EBMUD permit requirements. The request for discharge was approved by EBMUD on November 2, 2006 (EBMUD, 2006). The discharge was implemented immediately thereafter.

3.4 Additional System Design Investigation

On June 7, 2007, colored liquid was found in two below-grade trenches (also referred to as vats) inside the former plating shop of Building 360 while preparation of drilling for electrode installation was being conducted by TRS. Further visual inspections suggested the liquid contain chromium because of its greenish to yellowish color. Samples were immediately collected from two electrode locations and submitted for metals analysis. Analytical results confirmed the presence of chromium, including hexavalent chromium (Cr⁶⁺), and other metals. Approximately 1,000 gallons of the colored liquid were later pumped from the two trenches into a double-contained Baker tank for subsequent disposal.

Because of the finding of chromium-containing liquid in the trenches, there became a concern about mobilizing chromium, especially Cr⁶⁺, in the underlying groundwater during the electrical heating. As a result, following the Navy's technical direction, Shaw proceeded with additional system design investigation to assess impact on chromium and hexavalent chromium, with a focus in the area of the plating shop.

The additional investigation conducted in the month of August 2006 involved collecting soil and groundwater samples from a number of the electrode installation boreholes and installing two additional groundwater monitoring wells. Soil samples were taken directly from the open boreholes from surface to 5 feet bgs using a Geoprobe® direct-push rig. Groundwater samples were collected from the boreholes using a Hydropunch® direct-push sampler. Samples were submitted for metals, cyanide, and VOC analyses; results for soil and groundwater are summarized in Tables 1, "Summary of Additional System Design Investigation Soil Sample Results," and 2, "Summary of Additional System Design Investigation Groundwater Sample Results," respectively. Complete analytical data packages are provided in Appendix F. Figure 5, "Hexavalent Chromium in Soil, 5 feet bgs," and Figure 6, "Total Chromium in Soil, 5 feet bgs," show the distribution of hexavalent and total chromium concentrations in soil, respectively.

The two groundwater monitoring wells were installed on the north and south perimeters of the plume inside the building. The wells were labeled as MW4-2-18 and MW4-2-19, respectively (see Figure 4). The monitoring wells had the same construction details as the other 17 wells,


except that the two wells were screened from 5 to 10 feet bgs. Following development, the wells were sampled, along with MW360-2 located outside of the plume, south of Building 360. Samples were submitted for metals analyses only. Figure 7, "Chromium Isoconcentrations in Groundwater," shows the chromium and hexavalent chromium concentrations in groundwater prior to DNAPL removal.

3.5 Baseline and Progress Performance Sampling

The baseline groundwater sampling was performed after completion of the initial phase of the treatment impact assessment in August. All 17 groundwater monitoring wells were sampled for VOC analysis. In addition to the baseline sampling event, groundwater sampling was performed periodically during the treatment period to monitor the treatment performance at the site. Samples were collected initially from the 17 monitoring wells installed for the removal action. Near the end of the treatment period in May 2007, the two wells installed as part of the additional investigation effort were also sampled. The primary intent of adding these two wells to the monitoring network was to supplement the monitoring results for the shallower depths (i.e., 5 to 15 feet bgs) around the plating shop and, by doing so, to allow more complete evaluation of DNAPL removal progress at the site.

In each sampling event, groundwater was pumped through a dedicated cooling coil at each well using a low flow peristaltic pump before collected for field water quality measurements. The cooling coil was used to allow for safe boiling water sampling while minimizing volatilization of the VOCs in the samples. This procedure was also followed during the baseline sampling for consistency, per the *Final Sampling and Analysis Plan* (Shaw, 2006). After the water quality parameters, (i.e., pH, temperature, oxidation-reduction potential [ORP], dissolved oxygen [DO], turbidity, and specific conductance) were stabilized, samples were collected into 40-milliliter (mL) vials and submitted for VOC analysis.

Since TRS required the use of groundwater sample results to assist with system adjustment and optimization, sampling was conducted generally monthly between December 2006 and May 2007. One round of sampling was conducted in July 2007 after the shutdown of the system to verify the anticipated drop in the VOC concentrations at some of the "hot" wells. Table 3, "Summary of Groundwater SA Concentrations from Baseline through Post-Treatment," summarizes the groundwater SA concentrations beginning from the baseline sampling event. Complete laboratory analytical data packages are provided in Appendix G. Groundwater concentration distributions from baseline through the progress sampling are presented in Figure 8, "Plume 4-2 Baseline and Progress Treatment Sampling Results."



3.6 Discharge and Emissions Monitoring

A part of the routine treatment system operation involved monitoring of the air emissions and treated effluent from the system for compliance purposes. Although no air permit was required for the vapor extraction system as the removal action was conducted in accordance with the Comprehensive Environmental Response, Compensation, and Liability Act requirements, the system was operated in conformance with the BAAQMD requirements for typical SVE operations. Air emissions from the treatment system were monitored using a field instrument, supplemented with results from influent vapor sampling. The vapor samples were collected in general on a monthly basis and submitted for U.S. Environmental Protection Agency TO-15 analysis.

Additional vapor samples were also obtained from the effluent of the vapor phase GAC treatment train during the startup of the system to verify no immediate carbon breakthrough by vinyl chloride. The additional sampling was requested by BAAQMD prior to commencement of the treatment operation (*Notification of Proposed Six Phase Heating/Vapor Extraction at Alameda Point – Bldg. 360, IR Site 4, Plume 4-2* [BAAQMD, 2006]). All vapor samples were collected using SUMMA canisters. Sample results not only did not show detection of vinyl chloride in the effluent but also indicated low mass emissions of the five regulated VOCs in the recovered vapor stream. According to BAAQMD Regulation 8, Rule 47, the five regulated organic pollutants are benzene, methylene chloride, PCE, trichloroethene, and vinyl chloride. Laboratory data packages are provided in Appendix H.

Field measurements of the vapor concentration were collected at the inlet, midpoint, and outlet of the vapor phase GAC treatment train using a photoionization detector (PID) with a 11.7 electro-volt lamp. Monitoring was generally conducted once daily during the manned operation of the treatment system. Since the predominant VOC species in the vapor stream was 1,1-DCE, the PID measurements of total VOCs generally corresponded relatively well to the laboratory results.

Discharge to the POTW was also monitored through sampling of the treated effluent from the condensate treatment train. Monitoring was performed in accordance with the basewide discharge permit (Number 5024981 2) issued by EBMUD in September 2006. After results of a startup sample verified that the effluent met the discharge criteria, sampling of the effluent was performed on a monthly basis from November 2006 through July 2007. Sample results and flow data were also submitted to EBMUD with approval from the Navy via quarterly discharge reports. Copies of the quarterly reports were distributed to the Navy in each submittal to EBMUD. No exceedances or violations of the discharge to the POTW occurred in the course of the treatment system operation at the site.

3.7 System Optimization

During treatment operation, adjustments were made to optimize the system performance to focus mostly on subsurface energy distribution and VOC concentration reduction within the plume. Groundwater temperatures were one of the key operation parameters used in combination with well sampling results to help with decisions on system adjustment and optimization. It has been from past experiences that a substantial reduction in the VOC concentration is achievable when the groundwater temperature reaches the boiling point.

The general optimization approach was as follows: once the well sampling results indicated that the VOC concentrations were below the removal action goal of 10,000 µg/L and the temperatures at those wells were maintained for a week or so, power supply was then redistributed to increase energy supply to some other areas that had shown cooler subsurface temperatures and limited VOC concentration reduction. In few occasions, some electrodes around the wells that had met the removal action goal were also temporarily turned off to facilitate power redistribution to the cooler areas. For instance, on March 22, 2007, TRS shut down 22 electrodes around MW4-2-1, MW4-2-4, MW4-2-6, and MW4-2-15 after the March sampling results indicated that the VOC concentrations at these wells dropped below 10,000 µg/L and the temperatures ranged from 94°C to 116°C. This allowed for increased energy input in other needed areas, especially inside Building 360 where some monitoring wells had shown relatively small reduction in the VOC concentrations. These electrodes were later brought back to service after receipt of a request from the Navy to continue treatment of the entire plume in late March to further reduce the VOC concentrations in the groundwater.

When power redistribution under the existing power supply configuration was not enough to enhance the treatment performance in certain areas of the plume, additional power cables were installed to facilitate power delivery to those areas. In early June 2007, TRS installed additional electrical cables to channel power from the PCU directly to several electrodes in the area around MW4-2-19, successfully bringing the VOC concentration in the area from 34,000 μ g/L recorded in May 2007 to below the initial removal action goal. The July 2007 sample results showed that the total VOC concentration at MW4-2-19 dropped to about 1,400 μ g/L, well below the treatment goal of 10,000 μ g/L.

3.8 Termination of Treatment

Groundwater treatment continued at Plume 4-2 until a treatment asymptote was reached. The treatment asymptote was determined based on the following operation and performance parameters:

• Well VOC concentrations were below 10,000 μg/L and showed a general trend of reaching asymptotic levels

- Vapor VOC mass captured in the vapor recovery system approached an asymptote
- The average groundwater temperature across the plume was maintained near or above the water boiling points

As of May 2007, the average groundwater temperature reached to 95°C, with a one-degree gradual rise over a two- to three-week period. Sampling results from late May showed that almost all well concentrations had reached below $10,000~\mu g/L$ and simultaneously approached asymptotic levels. The vapor VOC mass recovery rate had also not shown substantially changed throughout the period. Further discussions of the treatment performance are provided in Section 4.0. Based on these observations, by early July 2007, the system was shut down and treatment operations ceased.

3.9 Post-Treatment Sampling

Another round of sampling post-system shutdown was performed in September 2007 to determine the post-treatment levels of the chlorinated VOCs in the treatment plume. Sample results are also included in Table 3. In October 2007, groundwater samples were collected from select wells for metal analyses to determine effects, if any, on mobility of metals (primarily hexavalent chromium) post-treatment of the groundwater. The sample from MW4-2-17 was also analyzed for VOCs. The decision to sample the monitoring well again for VOCs was a result of the finding from the September sampling event.

4.0 Removal Action Effectiveness Assessment

This section discusses the effectiveness of the treatment system based on its effects on SA concentrations and mass removal and cost. The treatment effectiveness, including effects on chromium mobility during treatment, is also discussed.

4.1 Effects on Screening Analyte Concentrations and Mass Removal


This section presents the effects of the treatment system on the groundwater SA concentrations as well as any impacts on the mobility of chromium, with specifics on achievement of the treatment goal of $10,000~\mu g/L$ for the SAs. The changes in the SA concentrations in the groundwater were also used to estimate mass removal attributed to the in-situ treatment.

4.1.1 Changes in Screening Analyte Concentrations

Based on the groundwater sampling results, the SA concentrations in the groundwater dropped below 10,000 μg/L by July. The average reduction of SA concentrations across the treatment area varied from 55% to nearly 100%. Table 4, "Groundwater VOC Concentration Comparison between Baseline and Last Progress Sampling," shows a comparison of the SA concentrations between baseline and the May/July sampling events. The lowest percentage of reduction was recorded at MW4-2-17, while all others were near 90% and above. The cause of the low reduction at MW4-2-17 was not readily known since the groundwater temperature near the monitored interval of the well was over 100 degrees Celsius (°C) (based on the adjacent TMP Q13), a temperature at which significant reductions in the groundwater concentrations occurred in all other monitoring wells within the plume.

Figure 9, "Well SA Concentration Changes from Baseline through Treatment," shows the changes in the SA concentrations versus temperature at the 17 monitoring wells from baseline through treatment. As shown in the figures, the SA concentrations at most of the wells generally decreased to below the treatment goal as temperature rose above 100°C. Some wells also displayed initial rise in the SA concentrations, followed by a gradual reduction as treatment continued. The initial rise could likely be due to an increase in the solubility of the SA sorbed onto the soil into the groundwater caused by heating. As the temperature continued to rise, the SA began to dissipate via various pathways, including volatilization, resulting in decreases in their concentrations in the groundwater. Discussions of the SA mass removal pathways are presented later in the document.

Concentration reduction in the shallower depths between 5 and 15 feet bgs beneath the building had shown some limitation. As shown in Figure 8, MW4-2-14 in particular showed no apparent reduction in the total SA concentration between December 2006 and March 2007. The relatively



low decrease in the SA concentrations in the shallower depths prompted the decision to include the two monitoring wells, MW4-2-18 and MW4-2-19, into the SA monitoring network. The primary goal was to help assess the effectiveness of the heat treatment of the shallow groundwater and provide more complete evaluation of DNAPL removal progress and performance beneath the building. As the May sampling results showed, the total SA concentration at MW4-2-19 was found above the removal action goal, prompting another decision to facilitate energy delivery to that area, as previously discussed in Section 3.7.

The September 2007 post-treatment VOC sampling results showed additional changes of SA concentrations in the groundwater. This sampling event was conducted two months after termination of the treatment operation. A comparison of the sampling results between May/July 2007 and September 2007 is shown in Table 5, "Groundwater Chlorinated VOC Concentration Comparison between May/July and September 2007." All except one well showed a total SA concentration of below 10,000 μ g/L. The well with a total SA concentration of 12,000 μ g/L was MW4-2-17, with 1,1-DCE the predominant SA species. On October 23, 2007, six wells were sampled to determine post-treatment metal levels in the plume. MW4-2-17 was resampled for only VOC on that day. The new total SA concentration at MW4-2-17 was measured at approximately 4,700 μ g/L, well below the 10,000 μ g/L treatment goal.

Results of a statistical analysis of all September groundwater concentrations also indicate that the removal action goal of below 10,000 $\mu g/L$ for the groundwater within the treatment plume was achieved. Following the U.S. Environmental Protection Agency guidance for the statistical analysis, the mean SA concentration was estimated at 1,600 $\mu g/L$, with a 95% upper confidence limit of approximately 3,000 $\mu g/L$. The statistical evaluation approach and results are provided in Appendix I.

The groundwater within the treatment plume was mostly in a reducing condition. The DO level ranged from 0.2 to 2.0 mg/L, with only one well with a DO level at 2.0 mg/L, compared to 11 wells with a DO level at 2.0 mg/L and greater during the baseline sampling. The ORP values ranged from -280 to 68 millivolts, with most of the values in the negative, versus the positive values found in most of the baseline samples. Based on these field readings, the groundwater remained in a mostly anoxic, reducing condition. Table 6, "DO and ORP Data Comparison between Baseline and Post-Treatment," shows the DO and ORP values measured in the baseline and the two post-treatment sampling rounds.

4.1.2 Effect on Metals During Treatment

This section discusses about the effects of the in-situ groundwater treatment by electric resistance heating on metals. The metals of concern were originally chromium and hexavalent

chromium only. However, it was later noted that increases in arsenic and barium concentrations occurred during and after the treatment. As such, the effects on arsenic and barium are also discussed in this section.

4.1.2.1 Effects on Chromium

Results of the impact assessment effort indicated that chromium detected in soil and groundwater was mostly confined to the area directly beneath the trenches within the plating shop (see Figures 5 through 7). As such, four groundwater monitoring wells located outside and two inside the plating shop were selected to monitor for changes in the chromium concentration, particularly for Cr^{6+} , during the treatment of the groundwater. Any increase in the concentrations of total chromium and Cr^{6+} would be indicative of (1) potential migration of the metal species and/or (2) formation of Cr^{6+} in the course of the treatment. Sample results are presented in Table 7, "Summary of Additional System Design Investigation Groundwater Sample Results."

Based on the sampling results, there was no apparent indication of migration of chromium in the groundwater during the treatment process. Figure 10, "Plume 4-2 Chromium Concentration Changes in Groundwater During and After In-Situ Treatment," displays the concentrations of total chromium and Cr⁶⁺ within the first few months of the treatment operation and post-treatment. This finding is expected due to the presence of a reducing condition in the groundwater during and right after the treatment.

4.1.2.2 Effects on Arsenic and Barium

Although no apparent mobility issue was noted with chromium, increases in concentrations of arsenic and barium were observed in several groundwater monitoring wells, including MW4-2-11 and MW4-2-19. As previously mentioned, these two chemical species were not part of the metals of concern identified during the additional system design investigation, and were therefore not specifically monitored for. The highest arsenic concentration was found at MW4-2-11, where the concentration increased from 3.7 μ g/L from baseline to 117 μ g/L in February 2007 (nearly 4 months after heating had begun). The arsenic concentration continued to rise to 160 μ g/L based on the October 2007 sampling results. The highest barium concentration was found at MW4-2-19, where the concentration increased from 158 μ g/L from baseline to 1,170 μ g/L in February 2007. The arsenic concentration at MW4-2-19 also increased from 2.2 μ g/L to 22.8 μ g/L between the same timeframe. During the October 2007 sampling event, arsenic and barium at MW4-2-19 were found at 46.2 μ g/L and 1,020 μ g/L, respectively. The concentrations of arsenic and barium remained above the respective base-wide background levels.

The concentration rise of these two metal species was probably because of the reducing condition and rising temperature of the groundwater during the treatment. In the reducing condition, arsenic becomes more soluble. As shown in Tables 6 and 7, its relatively high concentrations were generally accompanied with low DO and ORP at those wells. In higher groundwater temperature, barium salt would become more soluble, resulting in increases in the groundwater concentrations. Barium sulfate, a barium salt, can also be affected by changes in reduction-oxidation potential. The reduction of sulfate to sulfide in a reducing condition would result in an increase in the barium concentration in the groundwater within the plume. However, these conditions are reversible. The increases in the groundwater concentrations of these two metal species are, therefore, expected to be temporal and spatially contained when the groundwater plume returns to the oxic condition with an increase in the ORP.

4.1.3 Mass Removal Estimate

The amount of chlorinated VOC mass removed as a result of the treatment is roughly determined based on the difference in the residual mass estimated within the plume before and after treatment. The residual mass within the treatment plume is approximated based on (1) the approximate lateral and vertical extent of the plume, (2) an assumed 30 percent of water-filled porosity, (3) an assumed 0.1% of organic carbon content (for sandy soil) and an average bulk soil density of approximately 50 kilograms per cubic foot, and (4) estimated concentrations of the VOC sorbed onto the soil particles (assumed in equilibrium with the groundwater concentrations).

The first basis was used to calculate the physical volume of the treatment zone. The second basis was to determine the groundwater treatment volume which was further divided for the five regions as previously described. Using the average groundwater concentrations for each screened interval within each region, the groundwater VOC mass in each screened layer region was estimated, and the total dissolved phase mass in each region as well as across all five regions was determined.

The third and fourth bases were used to provide an estimate of the VOC mass in the soil in the saturated zone. Using the average groundwater concentrations, the equilibrium soil concentration for each of the VOCs (or SA) was calculated based on the following soil adsorption equation:

$$C_s = K_d * C_w$$

Where,

 C_s = soil concentration of the VOC species

 K_d = distribution coefficient for the VOC species, also equals to $K_{oc} * f_{oc}$

 K_{oc} = soil adsorption coefficient for the VOC species normalized for soil organic carbon content

 f_{oc} = fractional organic carbon content in soil

 C_w = groundwater concentration of the VOC species in equilibrium with its soil concentration, C_s


With the average soil concentration determined for each screened interval within each region, the soil VOC mass for the screened layer in each region was estimated from the soil volume and density, and the total soil mass across the region and the overall treatment area was determined. Together with the estimated groundwater dissolved phase mass, the overall VOC mass in the treatment zone was determined. Based on the groundwater sample results obtained between baseline (August 2006) and post-treatment (September 2007), the total chlorinated VOC mass removed from within the treatment plume was estimated at 2,800 pounds. A majority of the mass reduction was from 1,1-DCE.

It is postulated that the VOC mass removal from the subsurface during the in-situ treatment was through several mechanisms – volatilization, groundwater recovery, hydrolysis, biodegradation, oxidation-reduction reactions, and other thermally-enhanced chemical reactions. These mass removal mechanisms are discussed further below.

4.1.3.1 Volatilization

Since all SAs are volatile compounds and their volatilities are directly proportional to temperature, the increase in the groundwater temperature during the electric resistance heating would therefore accelerate the mass transfer of the SAs from the groundwater into the vapor phase – a physical process referred to as volatilization. Most of the SAs volatilized into the vapor phase would be captured, as soon as they entered the vadose zone, by a vapor recovery well mounted locally at the top of each electrode. However, there could be some that might not have been fully captured if they had strayed outside the vacuum influence of the vapor recovery wells.

According to the vacuum measurements taken by TRS at the vapor piezometers in the midst of the treatment, some levels of vapor capture were maintained. However, some of the vacuum readings were recorded at or slightly below zero. Although the measured values might be indicative of the steam pressure buildup as heating continued, they might also suggest small to no vacuum influence at those locations. During the treatment operations, periodic adjustment of the operating vacuum at some vapor recovery wells was made to reduce entrainment of groundwater and sediment into those wells. Further discussions of the groundwater entrainment are presented in Section 4.1.3.2. The reduction of the applied vacuum at the recovery wells could result in a lack of sufficient vacuum to capture all offgas in the vadose zone within the treatment area, resulting in an unaccounted loss of some of the VOC mass removed.



Based on the offgas influent vapor sample results and the vapor extraction flow rates recorded, the total VOC mass recovered in the vapor stream was estimated at 200 lbs. Figure 11, "Cumulative VOC Mass Recovery and Temperature Plots versus Hours of Operation During In-Situ Groundwater Treatment," presents plots of the cumulative VOC mass captured in the offgas influent and average groundwater temperature over hours of treatment operation from October 2006 to July 2007.

4.1.3.2 Groundwater Recovery

Another mechanism that assisted in the removal of the chlorinated VOCs from the subsurface was recovery of groundwater via vacuum-enhanced entrainment in vapor wells. Groundwater entrainment into the vapor recovery wells occurred frequently from portions, if not all, of the treatment plume area. Besides physical observation, the substantial increases in the VOC concentrations in the untreated liquid influent stream that had been periodically monitored further verified the occurrence of groundwater entrainment into the extraction system.

Although entrainment of the groundwater into the vapor recovery system could assist in the removal of the chlorinated VOCs from the groundwater, this process was not a part of the intended removal mechanism. The condensate treatment train was designed to handle primarily a small amount of water condensed from the steam vapor captured by the vapor recovery wells; the relatively large quantity of groundwater collected via entrainment thus adversely affected the operation and performance of the condensate management system. As a result, periodic adjustment of the operating vacuum at the wellheads had to be made as part of the system optimization effort to minimize groundwater entrainment into the system. Over an eight-month system operation period, a total of one million gallons of treated condensate/groundwater mix were processed through the condensate treatment system.

The substantially low VOC concentrations found in the condensate/groundwater stream also resulted in significantly smaller contaminant mass in the aqueous phase than in vapor phase. Based on the untreated condensate sampling results, the amount of VOCs captured in the liquid phase was estimated at 1.4 pounds, as compared to 200 pounds from the recovered vapor.

4.1.3.3 VOC Mass Removal via Other Pathways

As previously stated, the mass of VOCs in the subsurface could have been depleted via biological and/or chemical reactions and other physical transport means that occurred more readily in elevated temperatures. Some of the biological and chemical reactions include hydrolysis, reductive de-halogenation (abiotic), and biodegradation. Hydrolysis of 1,1,1-trichloroethane into acetic acid and dehydrohalogenation into 1,1-DCE has been documented (*Using the Abiotic Transformation Rate of 1,1,1-Trichloroethane to Estimate the Date of Discharge* [Britton et al, 2006]). Dehalo-elimination is likely the mechanism in which 1,1-DCE might have been partly removed in an abiotic reduction process. One characteristic

product of such a reaction is acetylene (Transformation of Halogenated Aliphatic Compounds [Vogel et al, 1987]).

Abiotic reductive dehalogenation of chlorinated VOCs is also expected to occur in groundwater at sites with presence of ferrous iron and strong reducing conditions. There has been testing at some sites that resulted in approximately 40 percent of 1,1-DCE loss in sandy soil containing reduced iron (*Abiotic and Biotic Pathways in Chlorinated Solvent Natural Attenuation* [Brown et al, 2006]). As previously mentioned, the steel shot used in the conductive backfill at each electrode contained zero-valent iron. With the groundwater becoming more reducing as the treatment progressed, reductive dechlorination of the chlorinated VOCs, such as 1,1-DCE, into non-chlorinated alkanes and alkenes could likely have occurred.

Although these processes were not specifically monitored for during the treatment, some of the end or byproducts noted, such as biofouling in the condensate handling and treatment components, suggested the possible occurrence of such processes in various stages of the groundwater treatment by electric resistance heating. However, as these processes were not monitored, VOC mass lost via these processes could not be determined or accounted for.

Besides mass depletion due to reactions, VOC migration outside of the treatment area in dissolved and/or vapor forms could account for additional loss of the chlorinated VOC mass from the plume. As previously discussed, some of the chlorinated VOC volatilized from the groundwater might not have been captured by the vapor recovery wells due to limited vacuum influence from those wells. This could also occur to the chlorinated VOC species migrated into the stagnant zone surrounded by the vapor recovery wells on top of the electrodes. In this case, the VOC would or could be left in the vadose zone soil with the mass not accounted for.

4.2 Treatment Cost

Treatment costs associated with this removal action included primarily those incurred for (1) design, construction, and operation of the treatment system by TRS, (2) site preparation, (3) electricity for supplying system power, (4) additional system design investigation, (5) system sampling and analysis and performance monitoring, and (6) system operational support by Shaw field personnel. Excluding management and general administrative costs, the total cost incurred was approximately \$3.5 million. This cost includes the power consumption to provide a total energy input of 5,391,216 KW hours over an eight-month treatment period. A rough cost breakdown is presented as follows:

- System design, construction and operation (included electricity) \$3.0 million
- Site preparation (included system dismantling) \$100,000
- Additional System Design Investigation \$80,000
- System sampling and analysis and performance monitoring \$ 100,000

• O&M support - \$200,000

Based on the estimated reduction of VOC mass within the treatment plume, the cost for the removal action at Plume 4-2 was calculated to be around \$1,200 per pound of chlorinated VOC mass removed. The equivalent energy cost was estimated at \$0.65 per kilowatt-hour input to the subsurface.

5.0 Post-Removal Action Conditions

The bulk mass of the chlorinated VOCs has been removed to below the removal action goal. A residual amount of the organic contaminant is still present in dissolved phase. Based on the post-treatment sampling results, the main constituent present is 1,1-DCE. Figure 12, "Plume 4-2 Post-Removal Action SA Concentrations in Groundwater," shows the post-removal action groundwater VOC concentrations within the treatment area.

The presence of zero-valent iron in the electrode backfill may continue to provide further removal of the dissolved phase chlorinated VOCs in the groundwater via reductive dechlorination. However, the extent of this treatment with the electrode backfill has not been established. It is not known if the chlorinated VOCs could be further reduced passively to respective final cleanup goals (such as their respective maximum contaminant levels).

6.0 References

Bay Area Air Quality Management District, 2006, Notification of Proposed Six Phase Heating/Vapor Extraction at Alameda Point - Bldg. 360, IR Site 4, Plume 4-2, Electronic Mail from Robert Cave to Neil Hey, Shaw Environmental, Inc, September 14.

Britton et al, 2006, Using the Abiotic Transformation Rate of 1,1,1-Trichloroethane to Estimate the Date of Discharge, Annual International Conference on Soils, Sediments, and Water, University of Massachusetts, Amherst, Masschusetts, October.

Brown, Richard, R. Hines, C. L. M. C. Leahy, J. Cho, 2006, *Abiotic and Biotic Pathways in Chlorinated Solvent Natural Attenuation*, Proceedings of Battelle's Fifth International Conference on Remediation of Chlorinated and Recalcitrant Compounds, Monterey, California, May 21-26.

Canonie Environmental Services, 1990, *RI/FS Work Plan, NAS Alameda, Alameda, California,* Prepared for the U.S. Department of the Navy, Southwest Division, February.

East Bay Municipal Utilities District, 2006, US Navy Alameda Pt 10-18-2006 Results for 06J179, Electronic Mail from Molly Ong to Charlie So, Shaw Environmental, Inc., November 2.

IT Corporation, 2002a, Final Removal Action Project Plans, Installation Restoration Sites 4 and 5 DNAPL and Dissolved Source Removal Action, Alameda Point, Alameda, California, February 8.

IT Corporation, 2002b, Data Transmittal of Design Investigation (Phase III) for Plume 4-2, IR Site 4, Alameda Point, Alameda, California, August 22.


PRC Environmental Management Inc., 1997, *Tidal Influence Study Letter Report*, NAS Alameda, California, June.

Shaw Environmental, Inc., 2006, Final Sampling and Analysis Plan, Addendum No. 2, DNAPL Removal Action, Installation Restoration Sites 4 and 5, Alameda Point, Alameda, August 15.

Tetra Tech EM Inc. and Einarson, Fowler, and Watson, 1998, Data Transmittal Memorandum for Sites 4 and 5 Chlorinated Solvent Plume Definition and Site 14 Sump Investigation at Alameda Point, Alameda, California, Prepared for Department of the Navy Western Division, Naval Facilities Engineering Command, San Bruno, California, June 26.

Tetra Tech EM Inc., 1999, Draft CLEAN II-Operable Unit-2 Remedial Investigation Report, Alameda Point, Alameda, California, June.

Tetra Tech EM Inc., 2000, Determination of the Beneficial Uses of Groundwater at Alameda Point, Alameda, California, Final, July.





Tetra Tech EM Inc., 2001, Installation Restoration Sites 4 and 5 Dense Nonaqueous Phase Liquid and Dissolved Source Removal Action Engineering Evaluation and Cost Analysis (EE/CA), Alameda Point, Alameda, California, January 5 (Note: Revisions from February 5 were considered).


Vogel, T. M., C. S. Criddle and P. L. McCarty, 1987, *Transformations of Halogenated Aliphatic Compounds*, Environ. Sci. Technol. 21 (8), 722-736.


Figures


	IMAGE	X-REF ALA1BASE	OFFICE CONC	DRAW!	10-18-07	CHECKED I	BY -18-07	APPRO DC	VED BY 11-12-07	DRAWING NUMBER	124716-A2
SAN FRANCISCO BAY		INNER HARBOR								NOMBER	
COLDEN GATE BRIDGE SO ALAMEDA POINT (880)	<u> </u>	SAN FRANCIS BAY		SCAL 180		3600 FEET			DEPART SOU WAL FACILITI SAN I	Shaw Envi	ISION PRING COMMAND FORNIA I N MAP DINT

























Figure 11. Cumulative VOC Mass Recovery and Temperature Plots Versus Hours of Operation During In-Situ Groundwater Treatment at Plume 4-2, Bulding 360, Alameda Point, Alameda, California





Tables

Table 1 Summary of Additional System Design Investigation Soil Sample Results

·	ittoliai System Desig				1400	140.0	1405	140.0	140.0	M40 E	144.0	1444.0	I 1440.0 I	140.5	N44.0
Sample Location	<u> </u>	Alameda	K12-0	K12-3	L12-0	L12-3	L12-5 5	M10-0	M10-3	M10-5	M11-0	M11-3	M12-0	M12-5	N11-0
Sample Depth (feet bgs Date Collected		Background	8/28/2006	8/15/2006	8/28/2006	8/15/2006	8/15/2006	8/28/2006	8/15/2006	8/15/2006	8/28/2006	8/15/2006	8/28/2006	8/16/2006	8/28/2006
Parameter Parameter	Units	Concentration	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual					
Metals (EPA 6020/7471			j Resultiqual	Result[Qual	Result[Qual]	Result Qual	resuit[Quai [Result Qual	Result[Qual	Result[Qual	Result[Qual	Result[Qual	Resultiqual	Result[Qual	Resultiqual
	mg/kg	2.7	10.7 U	12 UJ	11 I U	10.8 UJ	11.1 UJ	11.1 U	11 UJ	11.8 UJ	10.8 U	10.8 U	10.4 U	11.5 U	10.4 J
Antimony	mg/kg	3.1	1.91	12 U	1.51 U	1.13 U	1.42	4.6	1.28	1.37	1.77 U	1.5	10.4 U	2.43	1.43 U
Arsenic Barium	mg/kg	47.4	33	30.7	39.1	34.1	84.9	49.2	1.20	45.6	50.2	40.9	139	88.6	53.1
Beryllium	mg/kg	0.6	0.22 J	0.602 U	0.316 J	0.539 U	0.554 U	0.314 J	0.549 U	0.588 U	0.308 J	0.217 J	0.214 J	0.246 J	0.405 J
Cadmium	mg/kg	0.42	0.536 U	0.602 U	0.549 U	0.539 U	0.554 U	2.65	0.549 U	0.588 U	0.542 U	0.538 U	0.521 U	34.6	0.558 U
Chromium	mg/kg	33.1	29.1	29.9	21.2	24.5	27.7	124	36.4	31.8	34.9	45.5	73.2	301	1180
Cobalt	mg/kg	7.9	4.61 J	3.34 J	4.21 J	4.6 J	3.91 J	17.7	3.02 J	3.91 J	6.09	4.99 J	5.04 J	14.7	7.13
Copper	mg/kg	10.5	7.64	6.93	7.19	5.89	6.13	24.8	4.97 J	6.7	8.73	7.13	39.4	177	13.5
Hexavalent Chromium	mg/kg	30 (PRG)	0.6	1.37	0.439 U	1.19	1.9	74	9	5.08	3.08	6.82	8.82	43.1	905
Lead	mg/kg	9.9	4.19	1.72	4.27	4.26	3.93	26.6	3.9	3.14	7.89	5.05	5.76	56.6	10.1
Mercury	mg/kg	0.12	0.215 U	0.241 U	0.22 U	0.216 U	0.221 U	0.138 J	0.22 U	0.235 U	0.217 U	0.215 U	0.208 U	0.231 U	0.223 U
Molybdenum	mg/kg		5.36 U	6.02 U	5.49 U	5.39 U	5.54 U	5.55 U	5.49 U	5.88 U	5.42 U	5.38 U	5.21 U	5.77 U	5.58 U
Nickel	mg/kg	30.1	23.8 J	21.9 J	22.9 J	20.8 J	19.6 J	87.1 J	19.5 J	18.5 J	28.6 J	22.7 J	413 J	431 J	33.9 J
Selenium	mg/kg		2.92	1.86	2.65	2.48	2.44	6.49	1.98	2.77	3.36	2.41	2.91	4.78	3.58
Silver	mg/kg	0.58	5.36 U	6.02 U	5.49 U	5.39 U	5.54 U	5.55 U	5.49 U	5.88 U	5.42 U	5.38 U	7.87	25.7	7.32
Thallium	mg/kg		1.07 U	1.2 U	1.1 U	1.08 U	1.11 U	1,11 U	1.1 U	1.18 U	1.08 U	1.08 U	1.04 U	1.15 U	1.12 U
Vanadium	mg/kg	25.1	19.6	14.5	17	16.4	17.3	24.1	14	17.7	22.5	18.8	18.3	23	25.3
Zinc	mg/kg	29.2	19	12.5	19.1	17.4	16.7	80	14.8	15.7	24.6	23.2	23.9	52.9	34
General Chemistry															
Carbon, Total Organic	mg/kg	<u>-</u>	NA	NA	NA	13400	2690	NA	1100 U	1180 U	NA	NA	NA NA	1150 U	NA
Cyanide, Total	mg/kg		NA	NA	NA	1.08 U	1.11 U	NA	1.1 U	1.18 U	NA	NA .	NA	NA NA	NA
	oounds (EPA 5035/8260B)		,												
1,1,1,2-Tetrachloroetha		-	4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
1,1,1-Trichloroethane	μg/kg		2.7 J	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	12	4.7 U	220 J	4.6 J
1,1,2,2-Tetrachloroetha		-	4.8 U	5.2 U	5.2 U	4.8 UJ	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 UJ	4.7 U	5.1 UJ	5.1 U
1,1,2-Trichloroethane	μg/kg		4.8 U 4.8 U	5.2 U 5.2 U	5.2 U 5.2 U	4.8 U 5 J	4.9 U 2.3 J	5.2 U 5.2 U	5 U 5 U	5 U 5 U	4.4 U 4.4 U	4.6 U 1.9 J	4.7 U 4.7 U	4.9 J 71 J	5.1 U 5.1 U
1,1-Dichloroethane 1,1-Dichloroethene	μg/kg μg/kg		4.6U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	51J	5.1U
1,1-Dichlorogropene	μg/kg		4.80	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	51U	5.1U
1,2,3-Trichlorobenzene	μg/kg	 	4.8U	5.2 U	5.2 U	4.8 UJ	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 UJ	4.7 U	5.1UJ	5.1 U
1,2,3-Trichloropropane	µg/kg		4.8 U	5.2 U	5.2 U	4.8 UJ	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 UJ	4.7 U	5.1 UJ	5.1 U
1,2,4-Trichlorobenzene	µg/kg		4.8 U	5.2 U	5.2 U	4.8 UJ	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 UJ	4.7 U	5.1 U.I	5.1 U
1,2,4-Trimethylbenzene		-	4.8 U	5.2 U	5.2 U	4.8 UJ	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 UJ	4.7 U	5.1 UJ	5.1 U
1,2-Dibromo-3-Chloropi			4.8 U	5.2 U	5.2 U	4.8 UJ	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 UJ	4.7 U	5.1 UJ	5.1 U
1,2-Dibromoethane	μg/kg		4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
1,2-Dichlorobenzene	μg/kg		4.8 U	5.2 U	5.2 U	4.8 UJ	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 UJ	4.7 U	5.1 UJ	5.1 U
1,2-Dichloroethane	µg/kg		4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 UJ	5 UJ	4.4 U	4.6 UJ	4.7 U	5.1 U	5.1 U
1,2-Dichloropropane	μg/kg		4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
1,3,5-Trimethylbenzene			4.8 U	5.2 U	5.2 U	4.8 UJ	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 UJ	4.7 U	5.1 UJ	5.1 U
1,3-Dichlorobenzene	μg/kg	<u>-</u>	4.8 U	5.2 U	5.2 U	4.8 UJ	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 UJ	4.7 U	5.1 UJ	5.1 U
1,3-Dichloropropane	μg/kg	-	4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
1,4-Dichlorobenzene	µg/kg		4.8 U	5.2 U	5.2 U	4.8 UJ	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 UJ	4.7 U	5.1 UJ	5.1 U
2,2-Dichloropropane	µg/kg		4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
2-Butanone	µg/kg		11	10 U	10 U	8.1 J	9.9 U	11	10 UJ	10 UJ	13	9.3 UJ	10	8.3 J	27
2-Chlorotoluene	µg/kg		4.8 U 48 U	5.2 U 52 U	5.2 U 52 U	4.8 UJ 48 U	4.9 U 49 U	5.2 U 30 J	5 U 50 UJ	5 U 50 UJ	4.4 U 44 U	4.6 UJ 46 UJ	4.7 U 47 U	5.1 UJ 51 U	5.1 U 16 J
2-Hexanone 4-Chlorotoluene	μg/kg μg/kg		4.8 U	5.2 U	5.2 U	4.8 UJ	49 U	5.2 U	50 U	5 U	4.4 U	4.6 UJ	47 U	5.1 UJ	5.1 U
			4.8 U	5.2 U	5.2 U	4.8 UJ	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 UJ	4.7 U	5.1UJ	5.1U 5.1U
4-Isopropyltoluene 4-Methyl-2-Pentanone	μg/kg μg/kg		9.5 U	5.2 U 10 U	10 U	9.6 U	9.9 U	5.2 U	10 UJ	10 UJ	8.8 U	9.3 UJ	9.5 U	10 U	10 U
Acetone	μg/kg		43	10 U	15	37 J	9.910	39	8.4 J	16	64	9.5 05	53	53 J	170
Benzene	µg/kg		4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5.4 J	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
Benzene, Propyl-	µg/kg		4.8 U	5.2 U	5.2 U	4.8 UJ	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 UJ	4.7 U	5.1 UJ	5.1 U
Bromobenzene	µg/kg		4.8 U	5.2 U	5.2 U	4.8 UJ	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 UJ	4.7 U	5.1 UJ	5.1 U
Bromochloromethane	µg/kg	-	4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
Bromodichloromethane		-	4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
Bromoform	µg/kg		9.5 U	10 U	10 U	9.6 UJ	9.9 U	10 U	10 U	10 U	8.8 U	9.3 UJ	9.5 U	10 UJ	10 U
Bromomethane	µg/kg		4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U

Table 1
Summary of Additional System Design Investigation Soil Sample Results

Sample Location		Alameda	K12-0	K12-3	L12-0	L12-3	L12-5	M10-0	M10-3	M10-5	M11-0	M11-3	M12-0	M12-5	N11-0
Sample Depth (feet bgs)		Background	0	3	0	3	5	0	3	5	0	3	0	5	
Date Collected		Concentration	8/28/2006	8/15/2006	8/28/2006	8/15/2006	8/15/2006	8/28/2006	8/15/2006	8/15/2006	8/28/2006	8/15/2006	8/28/2006	8/16/2006	8/28/2006
Parameter	Units		Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual							
Carbon Tetrachloride	µg/kg	"	4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
Chlorobenzene	µg/kg		4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
Chlorodibromomethane	µg/kg		4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
Chloroethane	µg/kg		9.5 U	10 U	10 U	9.6 U	9.9 U	10 U	10 U	10 U	8.8 U	9.3 U	9.5 U	10 U	10 U
Chloroform	µg/kg		4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
Chloromethane	µg/kg		9.5 U	10 U	10 U	9.6 U	9.9 U	10 U	10 U	10 U	8.8 U	9.3 U	9.5 U	10 U	10 U
Cis-1,2-Dichloroethene	µg/kg		4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
Dibromomethane	µg/kg		4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
Dichlorodifluoromethane	µg/kg		9.5 U	10 U	10 U	9.6 U	9.9 U	10 U	10 U	10 U	8.8 U	9.3 U	9.5 U	10 U	10 U
Ethylbenzene	μg/kg		4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
Hexachlorobutadiene	μg/kg	'	4.8 U	5.2 U	5.2 U	4.8 UJ	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 UJ	4.7 U	5.1 UJ	5.1 U
Isopropylbenzene	µg/kg_		4.8 U	5.2 U	5.2 U	4.8 UJ	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 UJ	4.7 U	5.1 UJ	5.1 U
M,P-Xylene	µg/kg		4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
Methyl Tert-Butyl Ether	µg/kg		4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
Methylene Chloride	µg/kg		4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
N-Butylbenzene	µg/kg		4.8 U	5.2 U	5.2 U	4.8 UJ	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 UJ	4.7 U	5.1 UJ	5.1 U
Naphthalene	µg/kg		4.8 U	5.2 U	5.2 U	4.8 UJ	4.9 U	5.2 U	5 U	.5 U	4.4 U	4.6 UJ	4.7 U	5.1 UJ	5.1 U
O-Xylene	µg/kg		4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
Sec-Butylbenzene	µg/kg		4.8 U	5.2 U	5.2 U	4.8 UJ	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 UJ	4.7 U	5.1 UJ	5.1 U
Styrene	µg/kg		4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
T-Butyl Alcohol (Tba)	µg/kg		19 U	21 U	21 U	19 U	20 U	21 U	20 UJ	20 UJ	18 U	19 UJ	19 U	20 U	20 U
Tert-Butylbenzene	µg/kg		4.8 U	5.2 U	5.2 U	4.8 UJ	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 UJ	4.7 U	5.1 UJ	5.1 U
Tetrachloroethene	µg/kg		4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
Toluene	µg/kg	-	4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
Trans-1,2-Dichloroethene	µg/kg		4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	5.1 U
Trichloroethene	µg/kg		25	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 U	5 U	4.4 U	4.6 U	4.7 U	5.1 U	7.3
Trichlorofluoromethane	µg/kg		4.8 U	5.2 U	5.2 U	4.8 U	4.9 U	5.2 U	5 UJ	5 UJ	4.4 U	4.6 UJ	4.7 U	5.1 U	5.1 U
Vinyl Chloride	µg/kg		9.5 U	10 U	10 U	9.6 U	9.9 U	10 U	10 U	10 U	8.8 U	9.3 U	9.5 U	10 U	10 U

Table 1 Summary of Additional System Design Investigation Soil Sample Results

Sam	nple Location		Alameda	N11-3	N11-5	N12-0	N12-3	N12-5	P12-0	P12-5
	pple Depth (feet bgs)		Background	3	5	0	3	5	0	5
`	e Collected		Concentration	8/15/2006	8/15/2006	8/28/2006	8/16/2006	8/16/2006	8/28/2006	8/15/2006
/ <u></u>	ameter	Units	Concontiduon	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual
	als (EPA 6020/7471A)					i ioo an i quar	, to the Qual	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·
	mony	mg/kg	2.7	11.5 U	12.2 UJ	10.6 U	10.8 U	11.7 U	10.7 U	11.4 UJ
Arse		mg/kg	3.1	1.15 U	1.22 U	1.79 U	1.73	1.61	1.57 U	1.14 U
Bari		mg/kg	47.4	25.2	41.9	295	48.9	33.8	121	48.3
	yllium	mg/kg	0.6	0.576 U	0.608 U	0.243 J	0.539 U	0.585 U	0.305 J	0.572 U
	lmium	mg/kg	0.42	0.576 U	0.608 U	0.531 U	10.5	2.33	0.535 U	0.732 U
	omium	mg/kg	33.1	341	33.4	27.2	284	109	56.9	116
Cob		mg/kg	7.9	3.7 J	3.13 J	5.06 J	15	9.53	7.57	6.48
Cop		mg/kg	10.5	6.36	5.57 J	10.4	34.3	16	13.4	29.8
	avalent Chromium	mg/kg	30 (PRG)	163	9.51	45.9	37.7	7.47	6.89	26.4
Lead		mg/kg	9.9	5.15	2.48	7.24	35.8	13.8	6.52	16
Merc		mg/kg	0.12	0.0762 J	0.243 U	0.212 U	0.216 U	0.234 U	0.214 U	0.229 U
	ybdenum	mg/kg		5.76 U	6.08 U	5.31 U	5.39 U	5.85 U	5.35 U	5.72 U
Nick		mg/kg	30.1	40.1 J	15.4 J	26.3 J	157 J	75.6 J	30.8 J	44.6 J
					2.2	3.06			2.93	
	enium	mg/kg	0.58	2.44			4.73	4.15		2.34
Silve		mg/kg		4 J	6.08 U	5.31 U	16.6	3.74 J	5.35 U	5.72 U
	llium	mg/kg	 25 4	1.15 U	1.22 U	1.06 U	1.08 U	1.17 U	1.07 U	1.14 U
	adium	mg/kg	25.1	17.7	16.5	23.3	19.1	19.4	20.9	18.5
Zinc		mg/kg	29.2	19.1	13.7	28	36.4	28	22.6	26.6
	neral Chemistry			4450111	LIAT I	MAI	2070	MAI	MAI	2000
	bon, Total Organic	mg/kg		1150 U	NA .	NA 100	3970	NA	NA	3090
	nide, Total	mg/kg		0.291 J	1.22 U	1.33	1.59	NA	NA	1.14 U
	atile Organic Compounds (EPA 5035		r -	l		_1				
	1,2-Tetrachloroethane	µg/kg	-	5.1 U	5 U	5 U	5 U	4.9 U	4.9 U	4.9 U
	1-Trichloroethane	µg/kg		20	200	37	700	9500	52000	26000
	2,2-Tetrachloroethane	µg/kg		5.1 U	5 U	5 U	5 R	4.9 UJ	4.9 UJ	4.9 UJ
	2-Trichloroethane	µg/kg		5.1 U	5 U	5 U	5 U	15 J	4.9 U	4.9 U
	Dichloroethane	µg/kg		17	120	5 U	11 J	170 J	73 J	280 J
	Dichloroethene	µg/kg		20	560	4.1 J	18 J	240 J	98 J	180 J
	Dichloropropene	µg/kg		5.1 U	5 U	5 U	5 U	4.9 U	4.9 U	4.9 U
	3-Trichlorobenzene	µg/kg		5.1 U	5 U	5 U	5 R	4.9 UJ	4.9 UJ	4.9 UJ
	3-Trichloropropane	µg/kg		5.1 U	5 U	5 U	5 R	4.9 UJ	4.9 UJ	4.9 UJ
	4-Trichlorobenzene	µg/kg		5.1 U	5 U	5 U	5 R	4.9 UJ	4.9 UJ	4.9 UJ
1,2,4	4-Trimethylbenzene	µg/kg		5.1 U	5 U	5 U	5 R	4.9 UJ	4.9 UJ	4.9 UJ
<u> 1,2-</u> l	Dibromo-3-Chloropropane	µg/kg		5.1 U	5 U	5 U	5 R	4.9 UJ	4.9 UJ	4.9 UJ
1,2-	Dibromoethane	µg/kg		5.1 U	5 U	5 U	5 U	4.9 U	4.9 U	4.9 U
1,2-	Dichlorobenzene	μg/kg		5.1 U	5 U	5 U	5 U	4.9 UJ	4.9 UJ	4.9 UJ
1,2-1	Dichloroethane	μg/kg	-	5.1 UJ	5 UJ	5 U	5 R	4.8 J	4.9 U	4.9 U
1,2-	Dichloropropane	μg/kg		5.1 U	5 U	5 U	5 U	4.9 U	4.9 U	4.9 U
	5-Trimethylbenzene	μg/kg		5.1 U	5 U	5 U	5 R	4.9 UJ	4.9 UJ	4.9 UJ
	Dichlorobenzene	µg/kg		5.1 U	5 U	5 U	5 R	4.9 UJ	4.9 UJ	4.9 UJ
1,3-	Dichloropropane	µg/kg		5.1 U	5 U	5 U	5 ป	4.9 U	4.9 U	4.9 U
	Dichlorobenzene	µg/kg		5.1 U	5 U	5 U	5 R	4.9 UJ	4.9 UJ	4.9 UJ
	Dichloropropane	μg/kg		5.1 U	5 U	5 U	5 U	4.9 U	4.9 U	4.9 U
	utanone	μg/kg		10 UJ	10 UJ	19	14 J	9.7 U	5 J	6.4 J
	hlorotoluene	µg/kg		5.1 U	5 U	5 U	5 R	4.9 UJ	4.9 UJ	4.9 UJ
	exanone	μg/kg	-	51 UJ	50 UJ	50 U	50 U	49 U	49 U	49 U
	hlorotoluene	μg/kg		5.1 U	5 U	5 U	5 R	4.9 UJ	4.9 UJ	4.9 UJ
	opropyltoluene	µg/kg		5.1 U	5 U	5 U	5 R	4.9 UJ	4.9 UJ	4.9 UJ
	lethyl-2-Pentanone	µg/kg		10 UJ	10 UJ	10 U	10 U	9.7 U	9.7 U	9.8 U
	tone	µg/kg		16	7.2 J	60	64 J	18 J	21 J	15 J
	izene	µg/kg		5.1 U	7.23 5 U	5 U	5 U	4.9 U	4.9 U	4.9 U
	zene, Propyl-	µg/kg		5.1 U	5 U	5 U	5 R	4.9 UJ	4.9 UJ	4.9 UJ
	mobenzene	µg/kg_		5.1 U	5 U	5 U	5 R	4.9 UJ	4.9 UJ	4.9 UJ
	mochloromethane	µg/kg		5.1 U	5 U	5 U	5 U	4.9 U	4.9 U	4.9 U
	modichloromethane	µg/kg µg/kg		5.1 U	5 U	5 U	5 U	4.9 U	4.9 U	4.9 U
				10 U	10 Ü	10 U		9.7 UJ	9.7 UJ	9.8 UJ
	moform	µg/kg			100	10 U	10 R			
Rior	momethane	µg/kg		5.1 U	5 U	อุเบ	5 U	4.9 U	4.9 U	4.9 U

Table 1 Summary of Additional System Design Investigation Soil Sample Results

Sample Location		Alameda	N11-3	N11-5	N12-0	N12-3	N12-5	P12-0	P12-5
			3	5	0	3	5	0	5
Sample Depth (feet bgs) Date Collected		Background	8/15/2006	8/15/2006	8/28/2006	8/16/2006	8/16/2006	8/28/2006	8/15/2006
Parameter	Units	Concentration	Result Qual						
				5 U	5 U	5 U	4.9 U	4.9 U	4.9 U
Carbon Tetrachloride	µg/kg		5.1 U	5 U	5 U	5 U	4.9U	4.9 U	4.9 U
Chlorobenzene	µg/kg	-	5.1 U	5 U	5 U	5 U			
Chlorodibromomethane	µg/kg		5.1 U				4.9 U	4.9 U	4.9 U
Chloroethane	μg/kg	-	10 U	10 U	10 U	10 U	9.7 U	9.7 U	9.8 U
Chloroform	μg/kg	-	5.1 U	5 U	5 U	5 U	4.9 U	4.9 U	4.9 U
Chloromethane	μg/kg		10 U	10 U	12	10 U	9.7 U	9.7 U	9.8 U
Cis-1,2-Dichloroethene	μg/kg		2.2 J	4.2 J	5 U	5 U	5.2 J	4.9 U	4.9 U
Dibromomethane	μg/kg		5.1 U	5 U	5 U	5 U	4.9 U	4.9 U	4.9 U
Dichlorodifluoromethane	µg/kg		10 U	10 U	10 U	10 U	9.7 U	9.7 U	9.8 U
Ethylbenzene	µg/kg		5.1 U	5 U	5 U	5 U	4.9 U	4.9 U	4.9 U
Hexachlorobutadiene	µg/kg		5.1 U	5 U	5 U	5 R	4.9 UJ	4.9 UJ	4.9 UJ
Isopropylbenzene	µg/kg	••	5.1 U	5 U	5 U	5 R	4.9 UJ	4.9 UJ	4.9 UJ
M,P-Xylene	µg/kg		5.1 U	5 U	5 U	5 U	4.9 U	4.9 U	4.9 U
Methyl Tert-Butyl Ether	µg/kg		5.1 U	5 U	5 U	5 U	4.9 U	4.9 U	4.9 U
Methylene Chloride	μg/kg		5.1 U	5 U	5 U	5 U	4.9 U	4.9 U	4.9 U
N-Butylbenzene	μg/kg		5.1 U	5 U	5 U	5 R	4.9 UJ	4.9 UJ	4.9 UJ
Naphthalene	µg/kg		5.1 U	5 U	5 U	5 R	4.9 UJ	4.9 UJ	4.9 UJ
O-Xylene	µg/kg		5.1 U	5 U	5 U	5 U	4.9 U	4.9 ป	4.9 U
Sec-Butylbenzene	μg/kg		5.1 U	5 U	5 U	5 R	4.9 UJ	4.9 UJ	4.9 UJ
Styrene	µg/kg		5.1 U	5 U	5 U	5 U	4.9 U	4.9 U	4.9 U
T-Butyl Alcohol (Tba)	μg/kg		21 UJ	20 UJ	20 U	20 U	19 U	19 U	20 U
Tert-Butylbenzene	μg/kg		5.1 U	5 U	5 U	5 R	4.9 UJ	4.9 UJ	4.9 UJ
Tetrachloroethene	μg/kg		5.1 U	5 U	5 U	5 U	4.9 U	4.9 U	4.9 U
Toluene	µg/kg		5.1 U	5 U	5 U	5 U	4.9 U	4.9 U	44 J
Trans-1,2-Dichloroethene	µg/kg		5.1 U	5 U	5 U	5 U	4.1 J	4.9 U	4.9 U
Trichloroethene	µg/kg		11	9.3	5 U	5 U	4.1 J	2.1 J	4.9 U
Trichlorofluoromethane	µg/kg		5.1 UJ	5 UJ	5 U	5 U	4.9 U	4.9 U	4.9 U
Vinyl Chloride	µg/kg		10 U	10 U	10 U	10 U	7.3 J	9.7 U	17 J

Table 1 Summary of Additional System Design Investigation Soil Sample Results

Table 1 Notes:

µg/kg denotes micrograms per kilogram.
bgs denotes below ground surface.
J denotes estimated value.
mg/kg denotes milligrams per kilogram.
NA denotes not analyzed.
U denotes not detected at or above the stated reporting limit.
UJ denotes estimated reporting limit.

Table 2 Summary of Additional System Design Investigation Groundwater Sample Results

Summary of Additional System	em Design														
Location Code		Alameda	D-6	E-5	J-5	K-12	K-13	L-11	L-12	L-13	L-14	M-10	M-11	M-13	M-14
Sample Number		Background Metals 1	4-2-D6	4-2-E5	SW OF BLDG 360 ANNEX	4-2-K12	4-2-K13	4-2-L11	4-2-L12	4-2-L13	4-2-L14	4-2-M10	4-2-M11	4-2-M13	4-2-M14
Sample Date		Concentration	8/25/2006	8/25/2006	8/24/2006	8/23/2006	8/24/2006	8/22/2006	8/22/2006	8/25/2006	8/24/2006	8/22/2006	8/22/2006	8/24/2006	8/23/2006
Parameter	Units	1	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual
Metals	•		•			•					•		•		
Antimony	µg/L	11.8	1 U	1 U	1 I U	1 U	1.32	1 U	1 1 U	2.3	3.99	1 U	1 1 U	1 I U	1 U
Arsenic	ug/L	8	12.8	16.3	9.95	2.75	3.67	5.35	3.73	11.1	4.56	5.29	3.71	1.12	3.57
Barium	µg/L	123.3	193	495	131	67.6	73.2	85.8	80.5	427	111	67.5	120	164	243
Beryllium	µg/L	1	0.768 J	1.83	1 U	1 U	1 U	10	1 U	0.952 J	1 U	1 U	1 U	1 U	1 U
Cadmium	µg/L	1.3	1 U	0.606 J	1 U	1 U	1 U	1 U	1 U	86.8	2.48	1 U	1 U	3.76	1 U
Calcium	µg/L	78223	9230	NA	NA	NA	30400	25000	NA	62700	NA	NA	NA	NA	NA
Chromium	µg/L	3.4	62.1	125	18.8	3.07	23.7	12.5	4.02	10500	34.6	15.8	5.98	291	0.884 J
Cobalt	μg/L	100.6	15.8	33.6	5.85	2.56	7.64	5.28	4.12	43.4	7.48	5.24	2.88	9.24	7.12
Copper	µg/L	4.6	20.7	55.6	6.24	2.46	7.97	4.74	2.17 J	123	7.17	5.92	1.14 J	1.78	1.03
Hexavalent Chromium	µg/L	7.5	13.9 J	27.2 J	10 U	10 UJ	10 UJ	10 UJ	10 U	778 J	10 . UJ	10 U	10 U	13.9 J	10 UJ
Iron	μg/L	1624	25800	NA	NA	NA	6570	2560	NA	41700	NA	NA	NA	NA	NA
Lead	μg/L	1.3	7.72	17.8	2.32	0.626 J	2.01	2.18	0.541 J	219	2.11	0.888 J	1 0	1 U	1 U
Magnesium	μg/L		9120	NA	NA	NA	14900	17400	NA	18200	NA	NA	NA	NA	NA
Manganese	µg/L	1171	509	NA	NA	NA	525	660	NA	835	NA	NA	NA	NA	NA
Mercury	µg/L	0.1	0.2 U	0.2 U	0.2 U	0.2 UJ	0.2 U	0.2 UJ	0.2 U	0.385	0.2 U	0.2 UJ	0.2 U	0.2 U	0.2 UJ
Molybdenum	μg/L	5.6	65.2	26.5	30	19.9 U	30.9	21.9 U	21.3	107	90.9	57.1	8.7	34.1	18.1 U
Nickel	μg/L	7.4	84.5	158	22	6.27	25.1	14.5	10.5	719	48.7	22.1	6.55	146	15.8
Potassium	µg/L	40552	1560	NA	NA	NA	7490	17200	NA	16700	NA	NA	NA	NA	NA
Selenium	µg/L	1.9	1 U	0.93 J	1 U	1 U	1 U	1 U	1 U	1.27	0.521 J	0.691 J	0.76 J	0.986 J	0.767 J
Silver	µg/L	1.6	1 U	1 U	0.755 J	1 U	0.744 J	1 U	1 U	61.6	0.939 J	1 U	1 U	1 U	1 U
Sodium	μg/L	937369	270000 J	NA	NA	NA	94900	222000	NA	118000 J	NA	NA	NA	NA	NA
Thallium	µg/L	2.3	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 0	1 U	1 U	1 0	1 U
Vanadium	µg/L	8.4	63.3	121	20.3	13.2	23.1	23.6	7.76	91.3	8.79	20.1	3.51	3.45	4.12
Zinc	µg/L	10.5	54.9	108	25.6	9.48 J	19.9	21	6.43 J	145	12.6	15.7	6.34 J	13	7.36 J
General Chemistry			44.4		NIAL I			44.0	I 1141	4-1	314		1 1/4		
Carbon, Total Organic	mg/L		11.4	NA NA	NA NA	NA NA	NA NA	11.3	NA NA	15	NA NA	NA NA	NA NA	NA NA	NA NA
Chloride Charida Total	mg/L		20.7 NA	NA NA	0.01 U	NA 0.01 U	NA 0.0432	101 0.104	NA NA	65.7 0.0573	NA NA	NA NA	NA 0.106	NA NA	0.01 U
Cyanide, Total Sulfate	mg/L		24.9	NA NA	NA NA	NA NA	0.0432 NA	30.5	NA NA	56.9	NA NA	NA NA	0.106 NA	NA NA	NA NA
Total Alkalinity	mg/L mg/L		600	NA NA	NA NA	NA NA	NA NA	485	NA NA	300	NA NA	NA NA	NA NA	NA NA	NA NA
Total Dissolved Solids	mg/L		1650	NA NA	NA NA	NA NA	NA NA	885	NA NA	560	NA NA	NA NA	NA NA	NA NA	NA NA
Volatile Organic Compounds	ing/L		1030	I IVAI	INA	INA	IVA	000]	INA	500	NA ₁	I INAI	i ivaj	NA	NA _I
1,1,1,2-Tetrachloroethane	µg/L	I	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
1,1,1-Trichloroethane	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	290	45	0.5 U	9.6	5800	110	31
1,1,2,2-Tetrachloroethane	ug/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
1,1,2-Trichloroethane	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	13	5.9	5.8	12	56	18	120
1.1-Dichloroethane	µg/L		14	5.1	2.5	33	0.96	16	580	210	280	130	3700	500	5700
1,1-Dichloroethene	ug/L		1.4	0.85	15	13	0.5	11	530	200	140	1200	5500	880	8500
1,1-Dichloropropene	ug/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
1,2,3-Trichlorobenzene	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
1,2,3-Trichloropropane	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
1,2,4-Trichlorobenzene	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
1,2,4-Trimethylbenzene	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
1,2-Dibromo-3-Chloropropane	µg/L		2 UJ	2 UJ	2 UJ	2 U	2 UJ	2 U	2 U	2 U	2 U	2 U	2 U	2 U	2 U
1,2-Dibromoethane	μg/L		1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
1,2-Dichlorobenzene	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
1,2-Dichloroethane	μg/L		0.5 U	0.5 U	0.25 J	0.64	0.5 U	0.5 U	14	8.3	19	14	62	29	220
1,2-Dichloropropane	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.32 J
1,3,5-Trimethylbenzene	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 UJ	0.5 U	0.5 U	0.5 U	0.5 UJ	0.5 U	0.5 U
1,3-Dichlorobenzene	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
1,3-Dichloropropane	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
1,4-Dichlorobenzene	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
2,2-Dichloropropane	µg/L		0.5 U	0.5 U	0.5 U	0.5 UJ	0.5 U	0.5 U	0.5 U	0.5 UJ	0.5 UJ	0.5 UJ	0.5 U	0.5 UJ	0.5 UJ
2-Butanone	µg/L		10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U
2-Chlorotoluene	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
2-Hexanone	µg/L		10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U

Table 2 Summary of Additional System Design Investigation Groundwater Sample Results

Location Code		Alameda	D-6	E-5	J-5	K-12	K-13	L-11	L-12	L-13	L-14	M-10	M-11	M-13	M-14
) Sample Number		Background Metals 1	4-2-D6	4-2-E5	SW OF BLDG 360 ANNEX	4-2-K12	4-2-K13	4-2-L11	4-2-L12	4-2-L13	4-2-L14	4-2-M10	4-2-M11	4-2-M13	4-2-M14
Sample Date		Concentration	8/25/2006	8/25/2006	8/24/2006	8/23/2006	8/24/2006	8/22/2006	8/22/2006	8/25/2006	8/24/2006	8/22/2006	8/22/2006	8/24/2006	8/23/2006
Parameter	Units	1	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual
4-Chlorotoluene	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
4-Isopropyltoluene	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
4-Methyl-2-Pentanone	μg/L.		10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U
Acetone	μg/L	-	10 U	10 U	10 U	10 U	10 U	5.3 J	10 U	10 U	10 U	10 U	5.3 J	10 U	10 U
Benzene	μg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.33 J	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.83
Benzene, Propyl-	μg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
Bromobenzene	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
Bromochloromethane	µg/L	-	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Bromodichloromethane	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
Bromoform	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
Bromomethane	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
Carbon Tetrachloride	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
Chlorobenzene	µg/L		0.5 U	0.5 U	0.28 J	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
Chlorodibromomethane	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
Chloroethane	µg/L	-	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.75	1.1	0.97	0.5 UJ	4.1	0.5 U	3.7 UJ
Chloroform	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.94	2.1	0.5 U	0.92	5	1.1	4.6
Chloromethane	µg/L	<u> </u>	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	1.7
Cis-1,2-Dichloroethene	µg/L		1.3	1.7	1.3	2.9	0.5 U	8.4	12	3.6	4.1	13	34	10	82
Dibromomethane	μg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
Dichlorodifluoromethane	μg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
Ethylbenzene	µg/L	ļ 	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
Hexachlorobutadiene	µg/L	-	1 U	1 U	1 0	1 U	1 0	1 U	1 U	1 U	1 U	1 0	1 U	1 U	1 U
Isopropylbenzene	µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
M,P-Xylene	µg/L	-	1 U	1 U	1 10	1 0	1 U	1 U	1 U	10	0.91 J	1 U	10	1 U	1 U
Methyl Tert-Butyl Ether	µg/L	-	1 U	1 U	1 10	1 U	1 U	1 U	1 U	1 U	1 U	10	10	1 U	1 U
Methylene Chloride	μg/L		1 U	1 U	1 1U	1 U	ijŪ	1 UJ	1 UJ	1 U	1 U	1 U	1.1 J 0.5 U	1 U	1.2 0.5 U
N-Butylbenzene	µg/L		0.5 U 0.5 U	0.5 U 0.5 U	0.5 U 0.5 U	0.5 U 0.5 U	0.5 U 0.5 U	0.5 U	0.5 U 0.5 U	0.5 U 0.5 U	0.5 U 0.5 U	0.5 U 0.5 U	0.5 U	0.5 U 0.5 U	0.5 U
Naphthalene	µg/L			0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U		0.5 U	0.5 U	0.5 U
O-Xylene Sec-Butylbenzene	μg/L		0.5 U 0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.28 J 0.5 U	0.5 U 0.5 U	0.5 U	0.5 U	0.5 U
	µg/L µg/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
Styrene T-Butyl Alcohol (Tba)	µg/L µg/L	-	20 U	20 U	20 U	20 U	20 U	20 UJ	20 U	20 U	20 U	20 UJ	20 U	20 U	20 UJ
	ug/L ug/L	-	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U
Tert-Butylbenzene Tetrachloroethene	ug/L ug/L	-	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.50	0.5 U	0.8
Toluene	ug/L		0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.5 U	0.39 J	0.42 J	0.5 U	0.5 U
Trans-1.2-Dichloroethene	ug/L		0.5 U	0.50 0.29 J	0.49 J	0.76	0.5 U	0.50	5.3	1.8	1.5	4.5	18	4.9	42
Trichloroethene	µg/L µg/L		0.5 U	0.29 J	0.49 J	1.4	0.5 U	1.2	6.4	0.59	0.5 U	7.5	12	1.1	8.2
Trichlorofluoromethane	µg/L µg/L		0.29 J	0.5 U	0.5 U	0.5IU	0.5 U	0.5 UJ	0.5 UJ	0.5 U	0.5 U	0.5 U	0.5 UJ	0.5 U	0.5 U
Vinyl Chloride	ug/L	 	0.5 U	0.50	0.50 0.42 J	0.65	0.5 U	0.5 U	13	1.6	1	2.7	34	5.50	48
vinyi Chloride	µg/L		บ.อุเบ	U.4JJ	U.4ZJJ	J.00.U	บ.อุเบ	บ.อุเบ	13	I.0	4	2.1	J 34	ગ	40

Table 2 Summary of Additional System Design Investigation Groundwater Sample Results

Location Code		Alameda	N-11	N-1:	2	N-13	3	P-12	2	P-13	}
Sample Number		Background Metals ¹	4-2-N11	4-2-N	12	4-2-N	13	4-2-P	12	4-2-P1	13
Sample Date		Concentration	8/22/2006	8/23/2	006	8/23/20	006	8/22/20	006	8/23/20	006
Parameter	Units		Result Qu	ual Result	Qual	Result	Qual	Result	Qual	Result	
Metals											
Antimony	µg/L	11.8	1 U	1	Ū	1	U	1	U	1	U
Arsenic	µg/L	8	1.92	14.9		7.8		6.7		4.28	
Barium	µg/L	123.3	155	432		481		438		718	
Beryllium	µg/L	1	1 U	0.86	J	1.08		1	U	1.05	
Cadmium	µg/L	1.3	1 U	0.683	J	2.12		1.98		55.9	
Calcium	μg/L	78223	78100 J	NA NA		154000		NA		NA	-
Chromium	μg/L	3.4	15.3	48.4		3.2		10.6		9.65	
Cobalt	μg/L	100.6	4.06	39.1		327		110		810	
Copper	µg/L	4.6	1 UJ			1.1		1.16		37.5	
Hexavalent Chromium	µg/L	7.5	10 UJ			10	UJ		UJ	10	IJ
Iron	µg/L	1624	266 J	NA NA		57200		NA		NA	
Lead	µg/L	1.3	1 U	****		,	U	_	U	0.573	J
Magnesium	µg/L		46600	NA		49300		NA		NA	
Manganese	µg/L	1171	2950	NA NA		15700		NA		NA	
Mercury	µg/L	0.1	0.2 U		UJ	0.2		0.2		0.2	
Molybdenum	µg/L	5.6	6.4	10.4		3.65	U	2	U	2.89	U
Nickel	µg/L	7.4	3.84	137		1120		442		5760	
Potassium	µg/L	40552	27400	NA		31400		NA		NA	
Selenium	μg/L	1.9	1.29	1.54		1.1		1.3		0.896	
Silver	µg/L	1.6	1 U		U		U		U	1	U
Sodium	µg/L	937369	101000 J	NA.		179000		NA.		NA	
Thallium	µg/L	2.3	1 U		U		U	1	U	1	U
Vanadium	µg/L	8.4	2.01	40		2.47		2		1.59	
Zinc	µg/L	10.5	10.9	53.1	İ	18.7		24.4		924	
General Chemistry		r	E 001	l NA	_	40.0		l NA		NA	
Carbon, Total Organic Chloride	mg/L		5.89 265	NA NA		10.8 713	-	NA NA		NA NA	
Cyanide, Total	mg/L		0.01 U			0.01	11	NA NA		0.01	11
Sulfate	mg/L mg/L		55.9	NA NA		30.2	U	NA NA		NA	U
Total Alkalinity	mg/L		240	NA NA		108		NA NA		NA NA	
Total Dissolved Solids	mg/L		875	NA NA		1720		NA NA		NA NA	
Volatile Organic Compounds	I IIIg/L		0/0	1 11/2		1720		l IVA		INA	
1,1,1,2-Tetrachloroethane	µg/L		0.5 U	2.5	lii	0.5	П	0.28		0.96	ī
1,1,1-Trichloroethane	µg/L		5000	15000		30000		NA		68000	
1,1,2,2-Tetrachloroethane	µg/L		0.5 U	2.5		0.5		0.5		0.5	
1,1,2-Trichloroethane	µg/L		38	160		340		100		250	
1,1-Dichloroethane	µg/L		2300	7600		23000		NA		11000	
1,1-Dichloroethene	µg/L		6800	18000		37000		NA		18000	
1,1-Dichloropropene	µg/L		0.5 U	2.5		0.5	U	0.5		0.5	Ū
1,2,3-Trichlorobenzene	µg/L		0.5 U	2.5		0.5		0.5		0.5	
1,2,3-Trichloropropane	µg/L		0.5 U			0.5		0.5		0.5	
1,2,4-Trichlorobenzene	µg/L		0.5 U			0.5		0.5		0.5	
1,2,4-Trimethylbenzene	µg/L		0.5 U			0.23		0.5		0.64	
1,2-Dibromo-3-Chloropropane	µg/L		2 U				U		U	2	
1,2-Dibromoethane	µg/L		1 U		U	1	U	1	U	1	
1,2-Dichlorobenzene	µg/L		0.5 U			0.5	U	0.5		0.5	U
1,2-Dichloroethane	μg/L		36	200		410		180		300	
1,2-Dichloropropane	μg/L		0.5 U			0.34	J	0.5		0.5	
1,3,5-Trimethylbenzene	µg/L		0.5 UJ			0.5		0.5		0.5	
1,3-Dichlorobenzene	μg/L		0.4 J	2.5		2.2		0.51		0.71	
1,3-Dichloropropane	µg/L		0.5 U			0.5		0.5		0.5	
1,4-Dichlorobenzene	µg/L		0.5 U			0.5		0.5		0.5	
2,2-Dichloropropane	µg/L		0.5 U		UJ	0.5		0.5		0.5	UJ
2-Butanone	μg/L		10 U			970		47		830	
2-Chlorotoluene	µg/L		0.5 U			0.5		0.5		0.5	
2-Hexanone	µg/L		10 U	50	Ū	8.8	J	10	U	19	J

Table 2 Summary of Additional System Design Investigation Groundwater Sample Results

Location Code		Alameda	N-11	N-12	N-13	P-12	P-13
Sample Number		Background Metals ¹	4-2-N11	4-2-N12	4-2-N13	4-2-P12	4-2-P13
Sample Date		Concentration	8/22/2006	8/23/2006	8/23/2006	8/22/2006	8/23/2006
Parameter	Units]	Result Qual				
4-Chlorotoluene	µg/L		0.5 U	2.5 U	0.5 U	0.5 U	0.5 U
4-Isopropyltoluene	µg/L		0.5 U	2.5 U	0.5 U	0.5 U	0.5 U
4-Methyl-2-Pentanone	µg/L		10 U	50 U	10 U	10 U	10 U
Acetone	µg/L		10 U	180	250	48 J	610
Benzene	μg/L		0.5 U	2.5 U	1.9 J	0.75 J	1.1 J
Benzene, Propyl-	μg/L		0.5 U	2.5 U	0.5 U	0.5 U	0.5 U
Bromobenzene	µg/L		0.5 U	2.5 U	0.5 U	0.5 U	0.5 U
Bromochloromethane	µg/L		1 U	5 U	1 U	1 U	1 U
Bromodichloromethane	µg/L		0.5 U	2.5 U	0.5 U	0.5 U	0.5 U
Bromoform	µg/L		0.5 U	2.5 U	0.5 U	0.5 U	0.5 U
Bromomethane	µg/L		0.5 U	2.5 U	0.5 U	0.5 U	0.5 U
Carbon Tetrachloride	µg/L		0.5 U	2.5 U	0.5 U	0.5 U	0.5 U
Chlorobenzene	µg/L		0.5 U	2.5 U	0.5 U	0.5 U	0.5 U
Chlorodibromomethane	µg/L		0.5 U	2.5 U	0.5 U	0.5 U	0.5 U
Chloroethane	µg/L		1.8	7.1	52 J	7.7 J	27 J
Chloroform	µg/L		5	9.5	29 J	12 J	19 J
Chloromethane	µg/L		0.5 U	8.7	12 J	0.75 J	22 J
Cis-1,2-Dichloroethene	µg/L		38	73	260	90	93
Dibromomethane	µg/L		0.5 U	2.5 U	0.5 U	0.5 U	0.5 U
Dichlorodifluoromethane	µg/L		0.5 U	2.5 U	0.5 U	0.5 U	0.5 U
Ethylbenzene	µg/L		0.5 U	2.5 U	0.35 J	0.23 J	0.55 J
Hexachlorobutadiene	µg/L		1 U	5 U	1 U	1 U	1 U
Isopropylbenzene	μg/L		0.5 U	2.5 U	0.5 U	0.5 U	0.5 U
M,P-Xylene	µg/L		1 U	5 U	1 U	1 U	0.66 J
Methyl Tert-Butyl Ether	μg/L		1 U	5 U	1 U	1 U	1 U
Methylene Chloride	μg/L		0.68 J	4 J	7.5 J	3.9 J	4.6 J
N-Butylbenzene	μg/L		0.5 U	2.5 U	0.5 U	0.5 U	0.5 U
Naphthalene	µg/L		0.5 U	2.5 U	0.5 U	0.67 J	0.55 J
O-Xylene	μg/L		0.5 U	2.5 U	0.5 U	0.5 ป	0.27 J
Sec-Butylbenzene	µg/L_		0.5 U	2.5 U	0.5 U	0.5 U	0.5 U
Styrene	μg/L		0.5 U	2.5 U	0.5 U	0.5 U	0.5 U
T-Butyl Alcohol (Tba)	μg/L		20 U	100 U	20 UJ	20 U	20 UJ
Tert-Butylbenzene	μg/L		0.5 U	2.5 U	0.5 U	0.5 ป	0.5 U
Tetrachloroethene	μg/L		2.4	3.7	8.7 J	6.4 J	7.4 J
Toluene	μg/L		0.55	340	650	480	1300
Trans-1,2-Dichloroethene	μg/L		25	47	170	72	54
Trichloroethene	μg/L		31	19	47 J	17 J	26 J
Trichlorofluoromethane	μg/L		0.5 UJ	2.5 U	0.5 U	0.5 UJ	0.5 U
Vinyl Chloride	µg/L		21	33	130	33 J	34



Table 2

Summary of Additional System Design Investigation Groundwater Sample Results

Table 2 Notes

¹ Alameda background metals concentrations from: Summary of Background Concentrations in Soil and Groundwater, Alameda Point, Alameda California, Tetra Tech EM Inc., Nobember 2001

µg/L denotes micrograms per liter.
EPA denotes U.S. Environmental Protection Agency.
J denotes estimated value.
mg/L denotes milligrams per liter.
NA denotes not analyzed.
U denotes not detected at or above the stated reporting limit.
UJ denotes estimated reporting limit.

Table 3
Summary of Groundwater SA Concentrations from Baseline through Post-Treatment

Parameter		1,1,1- Trichloroethane	1,1,2- Trichloroethane	1,1- Dichloroethane	1,1. Dichloroethene	1,2-Dichloroethane	Cis-1,2- Dichloroethene	Tetrachloro- ethene	Trans-1,2- Dichloroethene	Trichloroethene	Vinyl Chloride	Total SAs
Units		μ _g ν	µ₅⁄∟	μ _{g/L}	µыг	µу́г	μ _{g/L}	μ _g ν	μøι	μøι	µgr	μgr
Well ID	Collection Date	Result	Result	Result	Result	Result	Result	Result	Result	Result	Result	
MW4-2-1	08/30/06	390	59	510	12000	110	46	< 5.0	37	16	4.8	13,173
MW4-2-1	12/11/06	220	45	550	16000	71	46	0.33	39	23	31	17,025
MW4-2-1	01/22/07	< 12	24	410	11000	50	43	< 12	37	26	< 12	11,590
MW4-2-1	02/13/07	< 12	17	280	10000	39	51	< 12	46	28	12	10,473
MW4-2-1	03/19/07	< 12	< 12	18	5300	7.3	75	< 12	50	32	8.2	5,491
MW4-2-1	05/16/07	< 0.50	< 0.50	0.67	1600	< 0.50	61	< 0.50	26	19	2.6	1,709
MW4-2-1	07/11/07	< 0.50	< 0.50	< 0.50	50	< 0.50	20	< 0.50	1.7	1.3	< 0.50	73
MW4-2-1	09/24/07	< 0.50	< 0.50	< 0.50	22	< 0.50	1.4	< 0.50	< 0.50	0.31	< 0.50	24
MW4-2-2	08/30/06	2100	140	100	41000	80	81	< 5.0	110	15	< 5.0	43,626
MW4-2-2	12/11/06	11	44	78	15000	48	45	0.29	41	17	5.6	15,290
MW4-2-2	01/22/07	< 12	< 12	12	6000	7.8	23	< 12	21	5.9	< 12	6,070
MW4-2-2	02/13/07	< 12	< 12	< 12	3700	< 12	18	< 12	14	< 12	< 12	3,732
MW4-2-2	03/19/07	< 5.0	< 5.0	< 5.0	1700	< 5.0	12	< 5.0	8.8	< 5.0	< 5.0	1,721
MW4-2-2	05/16/07	0.66	< 0.50	< 0.50	580	< 0.50	5.9	< 0.50	2.4	0.37	0.43	590
MW4-2-2	09/24/07	< 0.50	< 0.50	< 0.50	290	< 0.50	4.8	< 0.50	1.7	< 0.50	1.2	298
MW4-2-3	08/29/06	9400	300	130	72000	130	170	5	230	24	6.8	82,396
MW4-2-3	12/11/06	1200	240	150	33000	150	160	< 12	170	21	5.6	35,097
MW4-2-3	01/22/07	14	88	98	50000	86	130	< 12	160	20	< 12	50,596
MW4-2-3	02/13/07	5.3	12	25	36000	32	130	< 12	< 12	21	< 12	36,225
MW4-2-3	03/19/07	< 12	< 12	< 12	15000	< 12	96	< 12	93	11	< 12	15,200
MW4-2-3	04/10/07	3.2	< 0.50	< 0.50	600	< 0.50	14	< 0.50	8.1	1	< 0.50	626
MW4-2-3	05/16/07	2.4	< 0.50	< 0.50	400	< 0.50	2.3	< 0.50	0.68	0.74	< 0.50	406
MW4-2-3	09/24/07	0.89	< 0.50	< 0.50	170	< 0.50	3.4	< 0.50	1.3	< 0.50	0.3	176

Table 3 Summary of Groundwater SA Concentrations from Baseline through Post-Treatment

Parameter		1,1,1- Trichloroethane	1,1,2- Trichloroethane	1,1- Dichloroethane	1,1- Dichloroethene	1,2-Dichloroethane	Cis-1,2- Dichloroethene	Tetrachloro- ethene	Trans-1,2- Dichloroethene	Trichloroethene	Vinyl Chloride	Total SAs
Units		μgr	μ _{gr}	hэл	μφι	þgr	þъг	μ _ο ν	µցւ	µցւ	µуъ	þзr
Well ID	Collection Date	Result	Result	Result	Result	Result	Result	Result	Result	Result	Result	
MW4-2-4	08/30/06	15	280	260	34000	400	210	< 5.0	200	22	3.1	35,390
MW4-2-4	12/13/06	< 12	99	180	14000	170	100	< 12	95	14	7.6	14,666
MW4-2-4	01/22/07	< 12	56	67	32000	110	230	< 12	250	30	< 12	32,743
MW4-2-4	02/13/07	< 12	< 12	< 12	9800	< 12	140	< 12	100	10	< 12	10,050
MW4-2-4	03/19/07	< 0.50	< 0.50	< 0.50	300	< 0.50	9.7	< 0.50	4.3	0.4	< 0.50	314
MW4-2-4	05/17/07	< 0.50	< 0.50	< 0.50	150	< 0.50	3.5	< 0.50	1.9	< 0.50	< 0.50	155
MW4-2-4	09/25/07	< 0.50	< 0.50	< 0.50	610	< 0.50	15	< 0.50	7.7	0.28	0.52	634
MW4-2-5	08/30/06	4.6	85	41	12000	82	73	< 5.0	79	2.9	< 5.0	12,368
MW4-2-5	12/11/06	< 0.50	79	140	26000	190	130	0.79	150	15	12	26,717
MW4-2-5	01/22/07	< 12	< 12	18	12000	38	94	< 12	100	6.5	< 12	12,257
MW4-2-5	02/13/07	< 12	< 12	< 12	9600	6.4	83	< 12	90	< 12	< 12	9,779
MW4-2-5	03/19/07	< 5.0	< 5.0	< 5.0	2600	< 5.0	42	< 5.0	31	< 5.0	< 5.0	2,673
MW4-2-5	05/16/07	< 5.0	< 5.0	< 5.0	4600	< 5.0	84	< 5.0	48	< 5.0	< 5.0	4,732
MW4-2-5	07/11/07	< 0.50	< 0.50	< 0.50	690	< 0.50	24	< 0.50	16	0.86	0.36	731
MW4-2-5	09/25/07	< 0.50	< 0.50	< 0.50	7400	< 0.50	120	< 0.50	75	1.7	2.2	7,599
MW4-2-6	08/29/06	360	300	1100	40000	460	270	3.6	220	40	43	42,797
MW4-2-6	12/12/06	69	230	790	31000	330	210	< 12	180	45	46	32,900
MW4-2-6	01/23/07	< 12	71	340	46000	130	160	< 12	220	45	24	46,990
MW4-2-6	02/14/07	< 12	56	130	27000	78	230	< 12	250	41	19	27,804
MW4-2-6	03/19/07	0.35	0.26	1.5	610	0.39	11	< 0.50	6	2.1	< 0.50	632
MW4-2-6	05/17/07	< 0.50	< 0.50	0.24	63	< 0.50	0.74	< 0.50	< 0.50	0.48	< 0.50	64
MW4-2-6	09/24/07	< 0.50	< 0.50	< 0.50	8.5	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50	< 0.50	9

Table 3 Summary of Groundwater SA Concentrations from Baseline through Post-Treatment

Parameter		1,1,1- Trichloroethane	1,1,2- Trichloroethane	1,1- Dichloroethane	1,1- Dichloroethene	1,2-Dichloroethane	Cis-1,2- Dichloroethene	Tetrachloro- ethene	Trans-1,2- Dichloroethene	Trichloroethene	Vinyl Chloride	Total SAs
Units	·	μ _ð r	μgr	μ _g ν	µgr	μ _σ ι	μ ₉ ν	μgr	µgъ	þgr	μ _θ ν	µgч
Well ID	Collection Date	Result	Result	Result	Result	Result	Result	Result	Result	Result	Result	
MW4-2-7	08/29/06	2000	280	320	52000	230	190	2.3	210	32	13	55,277
MW4-2-7	12/11/06	< 12	310	290	29000	270	260	< 12	260	36	13	30,439
MW4-2-7	01/22/07	3.2	< 5.0	2.4	2600	< 5.0	25	< 5.0	19	2.2	< 5.0	2,652
MW4-2-7	02/13/07	1.2	< 0.50	0.64	700	< 0.50	1.7	< 0.50	2.8	0.61	< 0.50	707
MW4-2-7	03/19/07	0.73	< 0.50	< 0.50	310	< 0.50	0.39	< 0.50	0.44	0.42	< 0.50	312
MW4-2-7	05/16/07	0.5	< 0.50	0.2	140	< 0.50	< 0.50	< 0.50	< 0.50	0.2	< 0.50	141
MW4-2-7	09/24/07	< 0.50	< 0.50	< 0.50	15	< 0.50	1.7	< 0.50	0.41	< 0.50	< 0.50	17
MW4-2-8	08/29/06	1300	140	90	28000	120	130	2.1	150	8.5	5.2	29,946
MW4-2-8	12/12/06	24	160	69	40000	100	130	< 12	190	12	< 12	40,685
MW4-2-8	01/22/07	< 12	< 12	< 12	7600	< 12	110	< 12	81	< 12	7.1	7,798
MW4-2-8	02/13/07	< 12	< 12	< 12	510	< 12	27	< 12	8	< 12	< 12	545
MW4-2-8	03/20/07	0.62	< 0.50	< 0.50	110	< 0.50	0.93	< 0.50	0.43	< 0.50	< 0.50	112
MW4-2-8	05/16/07	0.34	< 0.50	< 0.50	190	< 0.50	1.6	< 0.50	0.48	< 0.50	0.32	193
MW4-2-8	09/24/07	< 0.50	< 0.50	< 0.50	270	< 0.50	6.8	< 0.50	3	< 0.50	0.83	281
MW4-2-9	08/29/06	450	69	1200	21000	120	79	< 5.0	57	63	26	23,064
MW4-2-9	12/12/06	130	35	570	9200	63	42	< 12	33	46	6.8	10,126
MW4-2-9	01/23/07	6.8	37	820	20000	89	71	< 12	61	63	14	21,162
MW4-2-9	02/14/07	< 12	40	800	19000	86	82	< 12	75	74	23	20,180
MW4-2-9	03/20/07	< 12	< 12	21	670	6.8	42	< 12	8.1	9.6	< 12	758
MW4-2-9	05/15/07	0.35	< 0.50	1.4	81	< 0.50	0.41	< 0.50	0.56	1.1	< 0.50	85
MW4-2-9	09/24/07	< 0.50	< 0.50	< 0.50	26	< 0.50	0.63	< 0.50	0.33	< 0.50	< 0.50	27

Table 3
Summary of Groundwater SA Concentrations from Baseline through Post-Treatment

Parameter		1,1,1- Trichloroethane	1,1,2- Trichloroethane	1, 1- Dichloroethane	1,1- Dichloroethene	1,2-Dichloroethane	Cis-1,2- Dichloroethene	Tetrachloro- ethene	Trans-1,2- Dichloroethene	Trichloroethene	Vinyl Chloride	Total SAs
Units		μοι	µыг	μ _{9/L}	har	µgл	μg/L	µg∕r	μον	μgr	µуг	μg/L
Well ID	Collection Date	Result	Result	Result	Result	Result	Result	Result	Result	Result	Result	
MW4-2-10	08/30/06	6.1	110	120	17000	170	90	< 5.0	90	7	< 5.0	17,593
MW4-2-10	12/11/06	< 12	74	78	16000	110	94	< 12	99	9.7	< 12	16,465
MW4-2-10	01/22/07	< 12	< 12	< 12	4700	5.4	81	< 12	63	5.3	< 12	4,855
MW4-2-10	02/13/07	< 0.50	< 0.50	< 0.50	1400	< 0.50	43	< 0.50	27	2.1	0.73	1,473
MW4-2-10	03/19/07	< 5.0	< 5.0	< 5.0	3900	< 5.0	62	< 5.0	48	4.2	< 5.0	4,014
MW4-2-10	05/17/07	< 0.50	0.44	< 0.50	520	0.79	4.9	< 0.50	3.8	0.34	0.27	531
MW4-2-10	09/24/07	< 0.50	7	11	1400	9.7	18	< 0.50	16	2	1	1,465
MW4-2-11	08/29/06	44000	42	11000	14000	150	120	7.2	80	27	47	69,473
MW4-2-11	12/12/06	9300	190	7100	56000	140	370	5.5	280	45	280	73,711
MW4-2-11	01/23/07	16	4.2	63	3800	2.6	65	< 5.0	57	6.1	16	4,030
MW4-2-11	02/14/07	< 12	8.3	59	6000	< 12	180	< 12	86	8.3	16	6,358
MW4-2-11	03/20/07	1.7	11	34	2700	< 2.5	430	1.5	70	7.1	17	3,272
MW4-2-11	05/15/07	2.1	3.4	4.6	1500	< 2.5	200	< 2.5	40	3.1	3	1,756
MW4-2-11	09/24/07	0.47	< 0.50	1	18	< 0.50	1.3	< 0.50	0.22	< 0.50	0.5	21
MW4-2-12	08/29/06	20000	87	290	54000	51	54	9.6	86	18	7.1	74,603
MW4-2-12	12/12/06	28	81	83	66000	35	100	16	180	25	8.2	66,556
MW4-2-12	01/23/07	8.4	< 0.50	< 0.50	330	< 0.50	0.94	0.47	1.2	0.27	< 0.50	341
MW4-2-12	02/14/07	3.1	< 0.50	< 0.50	210	< 0.50	3.8	0.24	2.5	< 0.50	< 0.50	220
MW4-2-12	03/20/07	1.7	< 0.50	< 0.50	420	< 0.50	11	0.25	5	0.36	0.26	439
MW4-2-12	05/15/07	2	< 0.50	< 0.50	390	< 0.50	15	0.23	9.2	0.37	0.22	417
MW4-2-12	09/24/07	0.37	< 0.50	< 0.50	1300	< 0.50	15	< 0.50	11	0.33	1.3	1,328

Table 3
Summary of Groundwater SA Concentrations from Baseline through Post-Treatment

Parameter		1,1,1- Trichloroethane	1,1,2- Trichloroethane	1,1- Dichloroethane	1,1- Dichloroethene	1,2-Dichloroethane	Cis-1,2- Dichloroethene	Tetrachloro- ethene	Trans-1,2- Dichloroethene	Trichloroethene	Vinyl Chloride	Total SAs
Units		μ₀ռ	μ _g νι	μgr	μφι	μ ₉ ι	μ _g ι	μ ₉ λ	µø≀	har	μ _{g/L}	Hgr
Well ID	Collection Date	Result	Result	Result	Result	Result	Result	Result	Result	Result	Result	
MW4-2-13	08/29/06	150000	810	350	240000	230	460	26	860	63	3.7	392,803
MW4-2-13	12/12/06	2600	1900	1400	150000	170	1600	41	1800	100	220	159,831
MW4-2-13	01/23/07	1500	8.7	20	8800	< 12	68	< 12	64	< 12	< 12	10,461
MW4-2-13	02/14/07	810	< 12	8.9	5100	< 12	100	< 12	52	< 12	< 12	6,071
MW4-2-13	03/20/07	310	< 12	< 12	5300	< 12	280	< 12	120	5.8	< 12	6,016
MW4-2-13	05/15/07	350	< 12	< 12	7100	< 12	190	< 12	110	< 12	< 12	7,750
MW4-2-13	07/11/07	210	0.87	0.66	730	< 0.50	66	0.45	21	0.78	0.64	1,030
MW4-2-13	09/24/07	21	< 0.50	< 0.50	1400	< 0.50	70	< 0.50	34	0.86	1.9	1,528
MW4-2-14	08/28/06	26	160	5600	8000	260	140	< 5.0	80	11	130	14,407
MW4-2-14	12/13/06	5.9	170	8200	15000	340	160	< 12	99	11	140	24,126
MW4-2-14	01/24/07	< 12	220	8300	14000	350	200	< 12	130	20	77	23,297
MW4-2-14	02/15/07	< 12	270	8200	15000	490	240	< 12	150	19	88	24,457
MW4-2-14	03/20/07	< 12	210	8900	17000	280	200	< 12	120	23	110	26,843
MW4-2-14	05/15/07	< 12	190	2100	5200	150	220	5.4	100	18	52	8,035
MW4-2-14	07/11/07	< 0.50	2.6	46	78	1	7.2	0.49	2.9	1.7	3.9	144
MW4-2-14	09/25/07	< 0.50	< 0.50	4.6	16	< 0.50	< 0.50	< 0.50	0.36	< 0.50	1.6	23
MW4-2-15	08/29/06	10	29	44	7800	29	22	< 5.0	22	2.6	< 5.0	7,959
MW4-2-15	12/13/06	< 12	37	77	17000	45	33	< 12	43	< 12	< 12	17,235
MW4-2-15	01/24/07	< 12	13	57	9900	19	34	< 12	38	< 12	< 12	10,061
MW4-2-15	02/14/07	< 12	< 12	< 12	10000	< 12	28	< 12	32	< 12	< 12	10,060
MW4-2-15	03/19/07	< 12	< 12	< 12	3200	< 12	22	< 12	16	< 12	< 12	3,238
MW4-2-15	05/15/07	< 12	< 12	< 12	5000	< 12	26	< 12	19	< 12	< 12	5,045
MW4-2-15	07/11/07	0.35	< 0.50	0.49	830	< 0.50	1.2	0.47	1.7	0.79	< 0.50	835
MW4-2-15	09/24/07	< 0.50	< 0.50	< 0.50	490	< 0.50	4.7	< 0.50	2.4	0.36	0.29	498

Table 3
Summary of Groundwater SA Concentrations from Baseline through Post-Treatment

Parameter	-	1,1,1- Trichloroethane	1,1,2- Trichloroethane	1,1- Dichloroethane	1,1- Dichloroethene	1,2-Dichloroethane	Cis-1,2- Dichloroethene	Tetrachloro- ethene	Trans-1,2- Dichloroethene	Trichloroethene	Vinyl Chloride	Total SAs
Units		µу∟	μ ₉ /ι	Нал	μgr	μ _ο ν	μ ₉ /ι	μ ₉ ⁄ι	μgr	μ _{δν}	μgι	μ _g ι
Well ID	Collection Date	Result	Result	Result	Result	Result	Result	Result	Result	Result	Result	
MW4-2-16	08/28/06	5500	120	5300	22000	190	120	6	92	15	160	33,503
MW4-2-16	12/12/06	8000	130	5300	38000	200	120	10	120	22	220	52,122
MW4-2-16	01/24/07	1200	180	7200	53000	190	150	16	160	38	67	62,201
MW4-2-16	02/15/07	23	250	4900	39000	260	210	15	190	31	83	44,962
MW4-2-16	03/20/07	6.6	300	1100	16000	140	190	7.1	110	23	64	17,941
MW4-2-16	04/10/07	5.1	6.6	6.4	830	0.42	2.9	0.67	1.7	1.1	0.32	855
MW4-2-16	05/15/07	5.5	1.4	5.5	630	< 0.50	0.76	0.79	0.79	0.65	0.23	646
MW4-2-16	09/25/07	0.46	< 0.50	0.47	1200	< 0.50	0.54	< 0.50	1.4	< 0.50	0.69	1,204
MW4-2-17	08/28/06	970	4.4	15	1500	2.9	2.5	0.4	3.8	0.68	0.57	2,500
MW4-2-17	12/13/06	5.5	4.7	43	610	11	5.2	< 0.50	4.9	0.38	1.1	686
MW4-2-17	01/24/07	0.43	2.6	13	1200	3	4	1.5	7.8	1.2	1.1	1,235
MW4-2-17	02/15/07	0.22	1.3	2	1600	0.9	4.6	1.4	9.9	1	0.73	1,622
MW4-2-17	03/19/07	< 0.50	< 0.50	< 0.50	790	< 0.50	2.9	0.58	6.4	0.69	0.21	801
MW4-2-17	05/15/07	0.34	< 0.50	< 0.50	1100	< 0.50	1.4	0.36	2	0.34	< 0.50	1,104
MW4-2-17	09/24/07	< 0.50	< 0.50	< 0.50	12000	< 0.50	22	0.65	20	1.4	0.8	12,045
MW4-2-17	10/23/07	< 0.50	< 0.50	< 0.50	4700	< 0.50	13	0.26	7.8	0.55	0.3	4,722
MW4-2-18	05/15/07	< 0.50	2.8	220	270	9	5.4	< 0.50	3.8	0.69	91	603
MW4-2-18	09/25/07	< 0.50	0.94	120	310	4.5	11	< 0.50	5.2 .	0.66	24	476
MW4-2-19	05/15/07	< 12	9.3	470	33000	9	190	5.1	190	94	50	34,017
MW4-2-19	07/11/07	3.2	3	23	1200	2.9	110	< 2.5	33	16	4	1,395
MW4-2-19	09/24/07	4.6	0.24	14	660	0.34	27	< 0.50	9.9	8.5	15	740

Notes:

SAs denotes site-specific Screening Analytes.

Table 4
Groundwater VOC Concentration Comparison
Between Baseline and Last Progress Sampling

	August 2006 (Baseline)							
Well ID	voc	Concentration (μg/L)	Reduction					
MW4-2-1	13,173	73	99.5					
MW4-2-2	43,626	587	98.7					
MW4-2-3	82,396	400	99.5					
MW4-2-4	35,390	155	99.6					
MW4-2-5	12,368	731	94.0					
MW4-2-6	42,797	64	99.9					
MW4-2-7	55,277	140	99.8					
MW4-2-8	29,946	190	99.4					
MW4-2-9	23,064	81	99.6					
MW4-2-10	17,593	531	97.0					
MW4-2-11	69,473	1,756	97.5					
MW4-2-12	74,603	417	99.4					
MW4-2-13	392,803	1,030	99.7					
MW4-2-14	14,402	144	99.0					
MW4-2-15	7,959	835	89.5					
MW4-2-16	33,503	646	98.0					
MW4-2-17	2,500	1,104	55.8					

VOC (volatile organic compound) concentration is based on the total concentration of the 10 screening analytes (refer to Table 3 of the Removal Action Completion Report for a complete list of the VOCs).

MW4-2-18 and MW4-2-19 were not included because these two wells were not part of the original DNAPL treatment monitoring well network.

μg/L denotes microgram per liter.

Table 5
Groundwater Chloriniated VOC Concentration Comparison
Between May/July and September 2007

	May/July 2007	September 2007	Daharma
Well Identification	Chlorinated VOC	Concentration (µg/L)	Rebound
MW4-2-1	73	24	No
MW4-2-2	587	298	No
MW4-2-3	400	175	No
MW4-2-4	155	634	Yes
MW4-2-5	731	7,599	Yes
MW4-2-6	64	9	No
MW4-2-7	140	17	No
MW4-2-8	190	281	Yes
MW4-2-9	81	27	No
MW4-2-10	531	1,465	Yes
MW4-2-11	1,756	21	No
MW4-2-12	417	1,328	Yes
MW4-2-13	1,030	1,528	Yes
MW4-2-14	144	23	No
MW4-2-15	835	498	No
MW4-2-16	646	1,204	Yes
MW4-2-17	1,104	12,045/4,722ª	Yes
MW4-2-18	603	476	No
MW4-2-19	1,395	740	No

Chlorinated volatile organic compound (VOC) concentration is based on the total concentration of the 10 screening analytes (refer to Table 3 of the Removal Action Completion Report for a complete list of the VOCs).

 $[^]a$ MW4-2-17 was sampled again in October 2007. The sample results are reported at 4,722 μ g/L as shown. μ g/L denotes microgram per liter.

Table 6
DO and ORP Data Comparison Between Baseline and Post-Treatment
Plume 4-2, Building 360, Alameda Point, Alameda, California

Well		eline st 2006)		eatment ber 2007)	Post-Treatm 200	•
Identification	DO (ppm)	ORP (mV)	DO (ppm)	ORP (mV)	DO (ppm)	ORP (mV)
MW4-2-1	0.7	131.0	2.0	-195.5	NR	NR
MW4-2-2	2.3	48.1	0.2	-80.3	NR	NR
MW4-2-3	12.1ª	98.1	0.6	-125.7	NR	NR
MW4-2-4	3.1	128.1	0.2	-124.5	NR	NR
MW4-2-5	0.5	162.8	0.3	-200.2	NR	NR
MW4-2-6	1.9	56.8	0.8	-82.4	3.5	-36.6
MW4-2-7	1.7	35.4	0.4	27.0	NR	NR
MW4-2-8	2.3	79.2	0.2	-164.8	NR	NR
MW4-2-9	0.3	-54.0	1.9	51.5	2.1	91.8
MW4-2-10	3.3	75.1	0.3	35.9	NR	NR
MW4-2-11	5.2	-62.4	0.4	-285.9	2.3	-271.0
MW4-2-12	1.2	-54.4	0.4	37.0	NR	NR
MW4-2-13	1.0	74.5	0.8	68.1	1.3	-218.2
MW4-2-14	3.0	-10.1	1.8	-79.2	NR	NR
MW4-2-15	1.0	-59.9	0.2	-142.3	NR	NR
MW4-2-16	2.9	-17.2	0.3	-79.2	NR	NR
MW4-2-17	2.0	4.5	0.8	-112.1	NR	NR
MW4-2-18	9.5	-7.2	0.6	-109.4	1.0	-66.0
MW4-2-19	5.2	143.2	1.5	-184.2	1.7	-255.0

DO denotes dissolved oxygen.

Note

mV denotes millivolt.

NR denotes not recorded.

ORP denotes Oxidation-Reduction Potential.

ppm denotes parts per million (or milligram per liter).

^aThis value is suspicious, probably due to reading error.

Table 7
Summary of Additional System Design Investigation Groundwater Sample Results

Well ID	Alameda Metals		MW360-	<u>, T</u>	MW4-2-6	MW4-2-6	I MAI	4-2-6	MW4-2-6	MW4-2-6	MW4-2-9	MW4-2-9	MW4-2-9	MW4-2-9	MW4-2-9	MW4-2-11
Sample Collection Date	Background		08/30/0	-	08/29/06	12/12/06	01/2		02/14/07	10/23/07	08/29/06	12/12/06	01/23/07	02/14/07	10/23/07	08/29/06
· ·	1	 		_		i I		Γ					T	† 1		1
Parameter	Shallow Groundwater 1	Units	Result Qu	ıal	Result Qual	Result Qual	Result	Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual
Metals																
Aluminum	96.2	µg/L	NA		NA	1000 U	1000	U	NA	NA	NA	1000 U	1000 U	NA	NA	NA
Antimony	11.8	µg/L	1 U		0.666 J	 1 U	0.664	J	0.577 J	1 U	1 U	1 0	1 U	0.607 J	1 U	0.673 J
Arsenic	8	µg/L	3.19		8.42	4.48	7.75		10.8	23.2	3.32	9.63	16.5	25.1	5.27	3.76
Barium	123.3	µg/L	683		145	269	859		850	752	57	43.8	63.2	78.4	293	63.6
Beryllium	1	µg/L	1 U		1 U	1 U	1	U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Cadmium	1.3	µg/L	1 U		1 U	1 U	1	U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Calcium	78223	µg/L	138000		125000	101000	206000		NA	NA	26100	22100	25800	NA	NA	272000
Chromium	3.4	µg/L	1 U		1.3	1 U	1.18		1.03	1 U	1 U	0.749 J	0.63 J	0.765 J	1 U	162
Cobalt	4.6	µg/L	14.3		4.14	4.07	3.6		2.81	1.85	3.79	6.73	2.3	1.83	1.2	2.53
Copper	7.5	μg/L	1 U		1.09	2.28	0.924	J	0.591 J	1 U	1.53	3.09	2.81	3.03	1 U	40.2
Hexavalent Chromium	100.6	µg/L	10 UJ		10 U	10 U	10		10 U	10 U	10 U	10 U	10 U	10 U	10 U	92.6
Iron	1624	µg/L	375 J		1000 U	1000 U	1000	U	NA	NA	1000 U	1000 U	1000 U	NA	NA	1000 U
Lead	1.3	µg/L	1 U		1 U	1 U	1	U	1 U	1 U	1 U	1 U	<u>1</u> U	1 U	1 U	1 U
Magnesium	<u></u>	µg/L	163000		106000	104000	195000		NA	NA	33400	21900	23900	NA	NA	366 J
Manganese	1171	µg/L	3750		221	1340	3550		NA	NA	509	366	449	NA	NA	1 U
Mercury	0.1	µg/L	0.2 U		0.2 U	0.2 U	0.2		0.2 U	0.2 UJ	0.2 U	0.2 U	0.2 U	0.2 U	0.2 UJ	0.2 U
Molybdenum	5.6	µg/L	1.76 J		10.5	5.03	3.22		3.07	1.19 J	18.6	27.7	13.9	11.1	2 U	97
Nickel	7.4	µg/L	17.8		9.49	7.34	12.5		9.3	6.36	20.5	23.3	10.9	10.6	30.9	9.1
Potassium	40552	µg/L	990 J		7430	3950	5850		NA	NA	2980	3750	5250	NA	NA	34600
Selenium	1.9	µg/L	1 U		1.2	1.04	2		1.68	0.94 J	0.901 J	0.874 J	2.19	2.74	0.744 J	2.04
Silver	1.6	µg/L	1 U		1 U	1 U	1	U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Sodium	937369	µg/L	435000		353000	280000	532000		NA	NA	276000	239000	286000	NA	NA	148000
Thallium	2.3	µg/L	1 U		1 U	1 U	1	U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Vanadium	8.4	µg/L	1 U		6.72	8.17	8.3		6.85	3	1.08	1.51	4.55	4.59	3.77	12.1
Zinc	10.5	µg/L	7.58 J		5 J	14.1	9.56	J	6.5 J	8.48 J	50.7	16.1	13.3	18.3	10.6	10 U
General Chemistry		,							,		<u></u>					
Carbon, Total Organic	-	mg/L	8.35		11.7	NA NA	NA NA		NA	NA NA	13.7	NA	NA	NA	NA	28.1
Chloride	-	mg/L	776		772	NA	. NA	-	NA	NA	316	NA	NA	NA	NA	542
Cyanide, Total	-	mg/L	0.01 U	ļ	0.01 U	0.01 U	NA.		NA	NA	0.01 U	0.01 U	NA	NA	NA	0.01 U
Sulfate	-	mg/L	152		122	NA	NA ¹		NA	NA	71.1	NA	NA	NA	NA	69.2
Total Alkalinity	-	mg/L	444		289	NA	NA		NA	NA	313	NA	NA	NA	NA	254
Total Dissolved Solids		mg/L	1960		1710	NA	NA NA		NA	NA	920	NA	NA-	NA	NA	1230

Table 7
Summary of Additional System Design Investigation Groundwater Sample Results

Well ID	Alameda Metals	T	MW4-2-11	MW4-2-11	MW4-2-11	MW4-2-11	MW4-2-13	MW4-2-13	MW4-2-13	MW4-2-13	MW4-2-14	MW4-2-18	MW4-2-18	MW4-2-18
Sample Collection Date	Background		12/12/06	01/23/07	02/14/07	10/23/07	12/12/06	01/23/07	02/14/07	10/23/07	08/28/06	08/31/06	12/12/06	01/23/07
Parameter	Shallow Groundwater 1	Units	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual	Result Qual
	Silation Civalianate	V	rioun qua	Troom qua.	1100011 4001	1 toodil dadi	Troodit Quai	Troodit Quai	Troodin dadi	1 tooding duci	Trootin Quan	riodit dua	7100dit Quai	1 toodit Quai
Metals	T			1	,		}		 		 	<u> </u>		
Aluminum	96.2	µg/L	1000 U	642 J	NA	NA NA	2370	240 J	NA	NA	NA	NA	1000 U	1000 U
Antimony	11.8	µg/L	0.975 J	1.76	1.17	10	10	0.671 J	0.928 J	1 U	0.519 J	1 U	0.769 J	1 U
Arsenic	8	μg/L	29.5	113	117	160	34	62.7	39.2	10.4	15.2	2.27	6	7.83
Barium	123.3	µg/L	105	74	146	871	510	305	400	250	275	68.8	16.9	12.6
Beryllium	1	µg/L	1 U	1 U	1 U	1 U	3.51	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Cadmium	1.3	μg/L	1 U	1 U	1 U	1 U	17.9	2.3	3.14	16.1	1 U	1 U	1 U	1 U
Calcium	78223	μg/L	182000	102000	NA	NA	113000	42100	NA	NA	189000	NA	67900	75000
Chromium	3.4	μg/L	2.85	77.7	44.5	13.1	7700	428	201	17.7	3.67	7	1.27	2.05
Cobalt	4.6	μg/L	6.85	5.1	4.62	3.1	357	5.47	3.43	2.08	8.31	2.98	1.88	2.12
Copper	7.5	μg/L	1.03	2.26	1 U	1 U	1.9	3.37	1.64	96.5	1.36	1 U	1 U	1 U
Hexavalent Chromium	100.6	μg/L	10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U	10 U
Iron	1624	μg/L	263 J	576 J	NA	NA:	171000	3570	NA	NA	6920	NA	1000 U	205 J
Lead	1.3	μg/L	1 U	0.898 J	1 U	1 U	11.5	1.04	1.31	0.781 J	1 U	1 U	1 U	1 U
Magnesium		μg/L	67600	3310	NA	NA	76000	35000	NA	NA	116000	NA	29100	20600
Manganese	1171	μg/L	1190	102	NA		12900	2100	NA	NA	13700	NA	740	681
Mercury	0.1	μg/L	0.2 U	0.2 U	0.2 U	0.2 UJ	0.2 U	0.218	0.185 J	0.354 J	0.2 U	0.2 U	0.2 UJ	0.2 U
Molybdenum	5.6	μg/L	25.2	39.5	21.1	11.4	8.56	38.9	14.1	1.38 J	4.9	9.26	10.7	9.44
Nickel	7.4	µg/L	13.6	13	14.8	2.4	15800	98.9	31.7	31	12.2	7.56	5.73	5.13
Potassium	40552	μg/L	50600	45800	NA		24900	17000	NA	NA	29000	NA	9110	10500
Selenium	1.9	µg/L	2.65	10	7.33	2.75	1.24	1.04	1.04	1 U	0.776 J	1 U	1 U	1 U
Silver	1.6	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1.09	1 U	1 U	1 U	1 U
Sodium	937369	µg/L	227000	125000	NA		1680000	1570000	NA	NA	356000	NA	106000	95200
Thallium	2.3	µg/L	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
Vanadium	8.4	μg/L	3.06	17.9	10.2	2.89	34	5	5.07	2.51	5.58	3.32	1 U	0.532 J
Zinc	10.5	μg/L	8.36 J	7.74 J	5.5 J	9 J	148	14.4	7.22 J	6.22 J	10 U	5.31 J	13.7	9.09 J
General Chemistry			•		· ^ 	•	'	<u> </u>		-1	1	<u> </u>	•	
Carbon, Total Organic	-	mg/L	NA	NA NA	NA	NA NA	NA	NA	NA	NA	14.8	NA	NA	NA
Chloride	-	mg/L	NA	NA	NA.	NA	NA	NA	NA	NA NA	752	NA NA	NA NA	NA
Cyanide, Total	-	mg/L	0.028	0.01 U	0.01 U	0.01 U	NA	NA	NA	NA	0.01 U	NA	NA NA	NA
Sulfate	-	mg/L	NA ·	NA	NA	NA	NA	NA	NA	NA	46.4	NA NA	NA NA	NA NA
Total Alkalinity	-	mg/L	NA	NA	NA NA	NA NA	NA	NA	NA	NA	534	NA NA	NA NA	NA
Total Dissolved Solids		mg/L	NA	NA	NA NA	NA	NA	NA NA	NA NA	NA	1930	NA NA	NA	NA NA

Table 7
Summary of Additional System Design Investigation Groundwater Sample Results

Well ID	Alameda Metals		MW4	-2-18	MW4	-2-18	MW ²	1-2-19	MW4	-2-19	MW4	-2-19	MW4	l-2 - 19	MW4	-2-19
Sample Collection Date	Background		02/1	4/07	10/2	3/07	08/3	31/06	12/1	3/06	01/2	3/07	02/1	14/07	10/2	3/07
Parameter	Shallow Groundwater 1	Units	Result	Qual	Result	Qual	Result	Qual	Result	Qual	Result	Qual	Result	Qual	Result	Qual
Metals								•	•				•			
Aluminum	96.2	µg/L	NA		NA		NA		1000	U	1000	U	NA		NA	
Antimony	11.8	µg/L	1	U	1	U	1	U	0.757	J	1	U	0.618	J	1	U
Arsenic	8	µg/L	8.83		21.5		2.23		11.3		15.7		22.8		46.2	
Barium	123.3	µg/L	10.8		307		158		116		963		1170		1020	
Beryllium	1	µg/L	1	U	1	U	1	U	1	U	1	U	1	U	1	U
Cadmium	1.3	µg/L	1	U	1	U	1	U	1	U	1	U	1	U	1	U
Calcium	78223	µg/L	NA		NA		NA		61500		352000		NA		NA	
Chromium	3.4	µg/L	1.7		3.05		6.81		0.861	J	4.18		1.68		8.97	
Cobalt	4.6	μg/L	2.51		3.8		9.29		1.42		1.68		1.41		1.27	
Copper	7.5	μg/L	0.625	J	1	U	3.17		1.33		1.25		1	U	1	U
Hexavalent Chromium	100.6	μg/L	10	U	10	U	14.6		10	U	10	U	10	U	10	U
Iron	1624	µg/L	NA				NA		1000	U	448	J	NA		NA	
Lead	1.3	μg/L	1	U	1	U	1	U	1	U	0.816	J	1	U	1	U
Magnesium		μg/L	NA		NA		NA		24000		56600		NA		NA	
Manganese	1171	μg/L	NA		NA		NA		768		3470		NA		NA	
Mercury	0.1	μg/L	0.2	U	0.2	U	0.2	U	0.2	U	0.2	U	0.2	U	0.2	UJ
Molybdenum	5.6	µg/L	9.77		5.93		3.89		13.3		9.23		8.9		8.37	
Nickel	7.4	μg/L	6.66		8.4		16.6		4.27		4.59		4.15		2.99	
Potassium	40552	µg/L	NA				NA		28000		61000		NA		NA	
Selenium	1.9	μg/L	1	U	0.618	J	1.44		0.807	J	2.29		2.18		1.5	
Silver	1.6	µg/L	1	U	1	U	1	U	1	U	1	U	1	U	1	U
Sodium	937369	μg/L	NA		NA		NA		111000		466000		NA		NA	
Thallium	2.3	µg/L	1	U	1	U	1	U	1	U	1	U	1	υ	1	U
Vanadium	8.4	μg/L	0.604	J	1.1		2.69		3.2		9.76		1.17		1.81	
Zinc	10.5	μg/L	8.82	J	5.19	J	5.64	J	5.81	J	10.9		10	U	10	U
General Chemistry																
Carbon, Total Organic		mg/L	NA		NA		NA		NA		NA		NA		NA	
Chloride	-	mg/L	NA	-	NA		NA	Ī	NA.		NA		NA		NA	
Cyanide, Total	-	mg/L	NA		NA		NA	j	NA		NA.		NA		NA	
Sulfate		mg/L	NA		NA		NA		NA.		NA.		NA.		199	
Total Alkalinity	-	mg/L	NA		NA		NA		NA		NA		NA		NA	
Total Dissolved Solids	-	mg/L	NA		NA		NA		NA		NA		NA.		NA	



Summary of Additional System Design Investigation Groundwater Sample Results

Table 7 Notes

¹ Alameda background metals concentrations from:

Summary of Background Concentrations in Soil and Groundwater, Alameda Point, Alameda California, Tetra Tech EM Inc., Nobember 2001 J denotes estimated value.

mg/L denotes milligrams per liter.


NA denotes not analyzed.

U denotes not detected at or above the stated reporting limit.

UJ denotes estimated reporting limit.

µg/L denotes micrograms per liter.

Appendix A TRS Process Equipment Schematic, Construction Drawings and Summary Details for Electrodes, Temperature Monitoring Points, Vapor Piezometers



	Project:	ALA05							
REGION 1 (20 Electrodes)									
Date Completed	te Completed Electrode								
Not Installed	C5								
6/22/2006	C6	41							
6/22/2006	C7	41							
6/26/2006	D4	41							
6/21/2006	D5	41							
7/9/2006	D6	41							
7/9/2006	D7	41							
7/9/2006	D8	41							
7/8/2006	E4	41							
6/21/2006	E5	41							
6/15/2006	E6	41							
7/10/2006	E7	41							
6/2/2006	E8	41							
6/23/2006	E9	41							
6/20/2006	F4	41							
6/20/2006	F5	41							
6/16/2006	F6	41							
6/1/2006	F7	41							
7/8/2006	F8	41							
6/15/2006	G5	41							
REGION 1	AVERAGES:	41							

Electrode Construction Summary


REGION 2 (13 Electrodes)							
Date Completed	Electrode	Total Depth					
6/1/2006	F9	30.25					
6/23/2006	F10	30					
6/1/2006	G9	30.25					
5/23/2006	G10	30					
6/22/2006	G11	30					
6/2/2006	H10	30.5					
5/30/2006	H11	30					
6/3/2006	J11	30.5					
6/29/2006	J12	30					
9/8/2006	K12	30					
9/7/2006	K13	30.25					
9/18/2006	L13	30					
9/7/2006	L14	30					
REGION 2	AVERAGES:	30.1					


REGION 3 (8 Electrodes)							
Date Completed	Electrode	Total Depth					
9/13/2006	M14	19					
6/5/2006	N14	19					
6/3/2006	N15	19.5					
6/4/2006	P14	19					
6/3/2006	P15	19					
6/4/2006	Q15	19.5					
6/3/2006	Q16	19.5					
6/4/2006	R16	19.5					
REGION 3	AVERAGES:	19.3					


Date Completed	Electrode	Total Depth
5/30/2006	G6	45
7/7/2006	G7	45
7/8/2006	G8	45
7/7/2006	Н6	45
5/25/2006	H7	45
5/26/2006	H8	45.5
6/29/2006	H9	45
5/25/2006	J7	45.5
5/31/2006	J8	45.5
6/29/2006	J9	45
6/4/2006	J10	45.5
6/29/2006	K8	45
6/6/2006	K9	45.5
6/5/2006	K10	45
6/4/2006	K11	45.5
5/24/2006	L9	45
6/5/2006	L10	45
9/8/2006	L11	45
9/15/2006	L12	45
9/12/2006	M10	45
9/13/2006	M11	45
9/14/2006	M12	45
9/19/2006	M13	45
9/11/2006	N11	45
9/12/2006	N12	45
9/14/2006	N13	45
9/11/2006	P12	45
9/13/2006	P13	45
REGION 4	AVERAGES:	45.1

Date Completed	Electrode	Total Depth
6/27/2006	E3	36
6/16/2006	F3	41
6/19/2006	G3	36
6/19/2005	G4	36'
6/16/2006	H4	36
6/16/2006	H5	36
6/27/2006	J5	36
6/1/2006	J6	36
6/16/2006	K6	36
6/1/2006	K7	36
6/2/2006	L7	36
6/1/2006	L8	36
6/6/2006	M9	36
6/6/2006	N10	36
6/13/2006	P11	36
6/12/2006	Q12	36
6/13/2006	Q13	36
6/14/2006	Q14	36
6/6/2006	R13	36
6/13/2006	R14	36
6/14/2006	R15	36
6/15/2006	S15	36
6/15/2006	S16	36


Date Completed	MW	Screen Interval
6/6/2006	MW 4-2-14	6' - 11'
6/6/2006	MW 4-2-17	26' - 31'
6/7/2006	MW 4-2-15	26' - 31'
6/12/2006	MW 4-2-9	13' - 18'
6/12/2006	MW 4-2-8	15' - 20'
6/26/2006	MW 4-2-13	35' - 40'
6/27/2006	MW 4-2-11	5' - 10'
7/7/2006	MW 4-2-16	9' - 14'
7/7/2006	MW 4-2-10	25' - 30'
7/8/2006	MW 4-2-4	25' -30'
7/8/2006	MW 4-2-6	15' 20'
7/9/2006	MW 4-2-7	26' - 31'
7/10/2006	MW 4-2-3	30' - 35'
7/11/2006	MW 4-2-5	32' - 37'
7/12/2006	MW 4-2-1	20' - 25'
7/12/2006	MW 4-2-2	31' - 36'
7/12/2006	MW 4-2-12	26' - 31'
Date Completed	TMP	Total Depti
6/13/2006	G07	45.0
6/15/2006	P11	35.0
6/15/2006	P15	19.0
6/13/2006	H10	29.0
6/14/2006	K08	45.0
6/14/2006	J05	35.0
6/16/2006	C07	40.0
6/16/2006	D04	40.0
6/15/2006	Q13	35.0
6/16/2006	M12	45.0
6/23/2006	F03	40.0
6/23/2006	F04	35.0
6/30/2006	E07	40
9/7/2006	K11	







ELECTRODE AND VAPOR
RECOVERY WELL
REGION 3 INDOORS
TYPICAL OF 8






CONFIDENTIAL

INFORMATION CONTAINED IN THIS DOCUMENT IS CONFIDENTIAL AND THE PROPERTY OF THERMAL REMEDIATION SERVICES, INC. NO INFORMATION CONTAINED HEREIN MAY BE DUPLICATED, USED OR DISTRIBUTED WITHOUT THE EXPRESSED WRITTEN PERMISSION OF THERMAL REMEDIATION SERVICES, INC. LONGVIEW, WA.


												,		
DCR-ALAOS-08	AUGS-ED-03			VE	1/	DKS/	SEPERATED THE AND MY ADDED MY SHEET		DRAME DK SEILER GEORD	DATE (-16-86		ALA05		
				1/	1/			1	DETG APNO		r	REGION		
		\Box	1	1	17			T		4-15- 45	£	LECTRODE	DETAIL	
MEMSON REFERENCE NO	DRAWNG TITLE	RR M	r m /	PT/	1.7	07/	DESCRIPTION		ON-CA			ALAMEDA		
REFERE	NCE DRAWINGS	╁	/ Duft	DANE	/ OAT	[JEATE	REVISIONS	1~	APPROVED FOR INPLEMENTATION	×		NONE	3	6
DATE 6-20-05		1					CHOFLE ALAOS ED		BY	- ;	ala0	5-ED-03		F





TEMPERATURE MONITORING ELECTRODE AND VAPOR ELECTRODE AND VAPOR TEMPERATURE POINT (TMP) RECOVERY WELL RECOVERY WELL MONITORING POINT REGION 5 INSIDE REGION 5 DUTDOORS REGION 5 INDOORS (TMP) P11; Q13 TYPICAL DF 12 TYPICAL OF 11 REGION 5 DUTSIDE F03; J05 -POWER CABLE +5.5' 3.75' ABOVE GRADE POWER CABLE 6"x4" CPVC PIPE - 6"x8" CPVC PIPE NEAT CEMENT GROUT (5 GAL/90 LB) 3'x4' STEEL PIPE 8-10 SIEVE SAND 4' 8-10 SIEVE SAND 4' 3" FINE MASONRY SAND 3' FINE MASONRY SAND 3" FINE MASONRY SAND 3" FINE MASONRY SAND THREADED CONNECTION THREADED CONNECTION 5' 8-10 SIEVE SAND - K. TELLON TABING - K' TEFLON TUBING 8-10 SIEVE SAND 3'x10.5' STEEL PIPE VITH 0.04' AXIAL SLOTS FROM 0.5 TO 10 AXIAL FT (4% OPEN AREA) - 3°×10.5° STEEL PIPE WITH 0.04° AXIAL SLOTS FROM 0.5 TO 10 AXIAL FT (4% OPEN AREA) 10' 10' 13.5 13.5 THREADED CONNECTION THREADED CONNECTION 15' APPROX. TREATMENT INTERVAL - 3'x10.5' STEEL PIPE 50, 20' 3.x51, ZIEEF LILE 24 THREADED CONNECTION 25' 25' CONDUCTIVE BACKFILL CONDUCTIVE BACKFILL - 34 CPVC PIPE K. CPVC PIPE 3"x10.5" STEEL PIPE 30, 30, THREADED CONNECTION THREADED CONNECTION CPVC CAP (VATER TIGHT) CPVC CAP (VATER TIGHT) 4" D.D. 12° O.D. 12" D.D. ALA05 CONFIDENTIAL REGION 5 INFORMATION CONTAINED IN THIS DOCUMENT IS CONFIDENTIAL AND THE PROPERTY OF THERMAL REMEDIATION SERVICES, INC. NO INFORMATION CONTAINED HEREIN MAY BE DUPLICATED, USED OR DISTRIBUTED WITHOUT THE EXPRESSED WRITTEN PERMISSION OF THERMAL REMEDIATION SERVICES, INC. LONGVIEW, WA. ELECTRODE DETAIL REMEDIATION ALAMEDA, CA services inc. NONE REFERENCE DRAWINGS REVISIONS \$ ALA05−ED−05 DATE: 6-20-05 CHOPLE ALAOS ED

Appendix B
Building Floor Survey for Utility Clearance



Appendix C Monitoring Well Construction As-Builts




Monitoring Well

Continued Next Page

MW4-2-1

Silavy	Page: 2 of 5
Project Alameda Pt CTO 133 Owner US Navy	COMMENTS
Location Alameda, CA Proj. No. $\frac{108816}{108816}$ Surface Elev. (msl) $\frac{13.14 \text{ ft.}}{13.14 \text{ ft.}}$ Total Hole Depth $\frac{27.0 \text{ ft.}}{10.0 \text{ ft.}}$ North $\frac{470459}{10.0 \text{ ft.}}$ East $\frac{1481805}{1481805}$ Top of Casing $\frac{NA}{108816}$ Water Level Initial $\frac{1}{2}$ 10.0 ft. Static $\frac{NA}{108816}$ Diameter $\frac{8}{108816}$ Screen: Dia $\frac{2}{108816}$ Length $\frac{5}{108816}$ Type/Size $\frac{8}{108816}$ Sch $\frac{1}{108816}$ Screen: Diameter $\frac{8}{108816}$ Type/Size $\frac{8}{108816}$ Sch $\frac{1}{108816}$ Screen: $\frac{1}{108816}$ Type/Size $\frac{8}{108816}$ Sch $\frac{1}{108816}$ Screen: Diameter $\frac{8}{108816}$ Type/Size $\frac{8}{108816}$ Sch $\frac{1}{108816}$ Sch $\frac{1}{108816}$ Screen: Diameter $\frac{8}{108816}$ Type/Size $\frac{8}{108816}$ Sch $\frac{1}{108816}$	Annular seal - Cement, Type
Fill Material See Comments Rig/Core Limited Access CME-75 Drill Co. WDC Exploration & Wells Method Hollow Stem Auger	Protective Casing - 4 in dia Sch 40 CPVC
Driller R. McGahey/A. Vasquez _{Log} By Garrick Anderson, CPG Date 7/12/06 Permit # W2006-0441 Checked By Eugene Mullenmeister, PG C57 License No. 283326	Surface elevation reflects surveyed raised floor.
Description (ft.) Well Completion Sample ID SpiD (Color, Texture, Stru Craphic Log Color, Texture, Stru	





Monitoring Well

MW4-2-1

Page: 3 of 5

Alameda Pt CTO 133 Owner US Navy Alameda, CA 108816 Location Proj. No. Blow Count Recovery ASTM/USCS Well Completion Sample ID % Recovery Description Graphic Log Depth (ft.) PID (mdd) (Color, Texture, Structure) Geologic Descriptions are Based on ASTM/USCS. Continued POORLY GRADED SAND; dark grayish brown (2.5Y 4/2); fine grained with trace medium grains; trace silt; wet 16 SP 18 POORLY GRADED SAND WITH SILT; olive brown (2.5Y 4/4); loose; fine grained; 10-15% silt; wet SP-SM 20 22 POORLY GRADED SAND; olive brown (2.5Y 4/2); fine grained with trace medium grains; trace silt; wet 24 SP - 26 TD=27 ft 28 30 32 34

SINGLE COMPLETION WELL D	ETAILS Page: 4 of 5
PROJECT NUMBER: 108816	BORING/WELL NO.: MW4-2-1
PROJECT NAME: Alameda Pt CTO 133	_ TOP OF CASING ELEV.: <u>n/a</u> (MSL)
COUNTY: Alameda	_ GROUND SURFACE ELEV.: <u>13.14 ft.</u> (MSL)
WELL PERMIT NO.: <u>W2006-0441</u>	DATUM: CCS27, Zone 3, NAVD88
←— M ——→	
	EXPLORATION BORING
	A. Total Depth <u>27</u> ft.
	B. Boring Diameter8 in.
G	Drilling Method Hollow Stem Auger
	WELL CONSTRUCTION
	C. Casing Length (BGL)
	Material Sch 5, Type 304, Stainless Steel
	D. Casing Diameter in.
	E. Depth to Top of Screen ft.
E H	F. Screen Length5 ft.
	Slotted Interval from <u>20</u> to <u>25</u> ft.
	Slot Type continuous wrap SS
	Slot Size o.020 in.
	G. Surface Seal ft.
A C	Seal Material <u>n/a</u>
	H. Annular Seal17 ft.
	Seal Material Baselite I-II-V cement
	I. Transition Sand1 ft.
	Transition Material RMC Pacific #60 sand
	J. Filter Pack9 ft.
	Material RMC Pacific-Lapis Lustre # 2/16 sand
	K. Backfill ft.
	Material n/a
	L. Top of Casing Height <u>n/a</u> ft.
	M. Protective Cover Diameter 4 in.
	MSL = mean sea level
<u> </u>	BGL = below ground level
← —B —→	



Monitoring Well

MW4-2-2 Page: 2 of 5

	Alameda Pt		3		_ 0	wner <u>US Navy</u>	COMMENTS Annular seal - Cement, Type
	Alameda, C					Proj. No. <u>108816</u>	I-II-V Transition sand - RMC Pacific
			Total Hole De			North <u>470456</u> East <u>1481801</u>	#60 sand
Top of Cas	sing <u>NA</u>						Filter Pack - RMC Pacific, Lapis Lustre #2/16 sand
Screen: Di						Type/Size <u>Sch 40 PVC/0.020 in.</u>	Well Casing - Sch 5, Type 304 Stainless Steel (SS)
Casing: Di			Length 31 f			TypeSch 5, Type 304, Stainless Steel	Screen - 0.020 in continuous
	See Cor					g/Core Limited Access CME-25	wrap, Sch 5, Type 304 SS Protective Casing - 4 in dia Sch
	WDC Explo					Stem Auger	40 CPVC
	McGahey/A. _{By Eugene}		^z Log By <u>Garr</u> meister, PG			PG Date 7/12/06 Permit #_W2006-0449 No. 283326	Surface elevation reflects surveyed ground level
Depth (ft.)	Well	(mdd) Old	Sample ID % Recovery Blow Count Brown	Graphic Log	ASTM/USCS	Description (Color, Texture, Structur Geologic Descriptions are Based on A	· ·
						Depths are below ground level.	
- 0 - 2 -						Initial hole cleared for utilities to five feet with with air-knifed cuttings. Cuttings above 10 for no sample returns to surface.	n air-knife and backfilled eet not described due to
4 -							
- 6 - - 8 -						·	
- 10 \\		0.0			sм	SILTY SAND; dark grayish brown (2.5Y 4/2 grained sand, 5% medium grained; loose; w); 15-20% silt; fine erv wet
40					""	, , , , , , , , , , , , , , , , , , , ,	,
90		0.0				POORLY GRADED SAND WITH SILT; dec very wet	creased silt to 10-15%;
14 14					SP- SM	·	
16 –					SM		
GINT.GPJ CALTRANS.GDT						SILTY SAND; dark grayish brown (2/5Y 4/2); 25-30% silt: 70-75%
			;			fine grained sand; wet/soupy	,, == == :: = :: = :: = :: = :: = :: =
11/8					SM		
္ဂြီ – 22 –							
108816 DRILLING LOG Rev 22 24							
10881				الم المناطقة		Continued Next Page	



Monitoring Well

MW4-2-2

Page: 3 of 5

Project _Alameda Pt CTO 133 Owner US Navy Location Alameda, CA 108816 Proj. No. Blow Count Recovery ASTM/USCS Well Completion Description Graphic Log Depth (ft.) Old (mdd) (Color, Texture, Structure) Geologic Descriptions are Based on ASTM/USCS. Continued POORLY GRADED SAND WITH SILT; dark olive brown (2.5Y 3/3); fine grained with trace medium grains; 10-15% silt; very wet 26 SP-SM 28 1.8 30 SILTY SAND; dark grayish brown (2.5Y 4/2); 20-25% silt; very wet/soupy 32 SM 34 25-30% silt and soupy at 35 feet. 36 POORLY GRADED SAND WITH SILT; olive brown (2.5Y 4/3); fine sand; loose; saturated/soupy 38 TD=37 ft 40 42 46 48 50 52 54 56 58

SINGLE COMPLETION WELL D	ETAILS Page: 4 of 5
PROJECT NUMBER: 108816	BORING/WELL NO.: MW4-2-2
PROJECT NAME: Alameda Pt CTO 133	TOP OF CASING ELEV.: <u>n/a</u> (MSL)
COUNTY: Alameda	GROUND SURFACE ELEV.: 13.05 ft. (MSL)
WELL PERMIT NO.: W2006-0449	DATUM: CCS27, Zone 3, NAVD88
├ M →	·
	EXPLORATION BORING
	A. Total Depth <u>37</u> ft.
	B. Boring Diameter8 in.
	Drilling Method Hollow Stem Auger
	WELL CONSTRUCTION
	C. Casing Length (BGL) 36 ft.
	Material Sch 5, Type 304, Stainless Steel
	D. Casing Diameter2 in.
	E. Depth to Top of Screen 31 ft.
	F. Screen Length5ft.
	Slotted Interval from <u>31</u> to <u>36</u> ft.
	Slot Type <u>continuous wrap SS</u>
	Slot Size in.
A C	G. Surface Seal ft.
	Seal Materialn/a
	H. Annular Seal ft.
	Seal Material Baselite I-II-V cement
	I. Transition Sand1 ft.
	Transition Material RMC Pacific #60 sand
	J. Filter Pack ft.
	Material RMC Pacific-Lapis Lustre # 2/16 sand
	K. Backfill ft.
	Material <u>n/a</u>
	L. Top of Casing Heightn/a ft.
	M. Protective Cover Diameter4 in.
	MSL = mean sea level
K \$	BGL = below ground level
B → B	



Monitoring Well MW4-2-3
Page: 2 of 5

•	Alameda Pt Alameda, C		3		_ 0	wner US Navy	COMMENTS Annular seal - Cement, Type
			T-1-111-1- D	36	5 ff	Proj. No Proj. No	I-II-V Transition sand - RMC Pacific
		JU IL.	Total Hole De Water Level I			North 470429 East 1481821	#60 sand Filter Pack - RMC Pacific, Lapis
	sing <u>NA</u> a 2 in.						Lustre #2/16 sand
Screen: Di			Length 5 ft			••	Well Casing - Sch 5, Type 304 Stainless Steel (SS)
Casing: Dia	a <u>2111.</u>		Length 30	и		Type Sch 5, Type 304, Stainless Steel	Screen - 0.020 in continuous wrap, Sch 5, Type 304 SS
	See Col					g/Core <u>Limited Access</u>	Protective Casing - 4 in dia Sch 40 CPVC
_	WDC Explo					Stem Auger	
			Log By Gar				Surface elevation value reflects surveyed raised floor.
Checked B	Lugene	wullerii	neister, PG	C57 Lic	ense	No. <u>283326</u>	
Depth (ft.)	Well Completion	OIA (mdd)	Sample ID % Recovery Blow Count	Graphic Log	ASTM/USCS	Description (Color, Texture, Structur Geologic Descriptions are Based on A	•
- 0 -						Depths are below ground level.	
- 2 - - 4 - - 6 - - 8 - - 10 \(\frac{1}{2}\)					SM	Initial hole cleared for utilities to five feet with with air-knifed cuttings. Cuttings above 10 for no sample returns to surface. SILTY SAND; dark grayish brown (2.5Y 4/2 75-80% fine sand; wet	eet not described due to
14.1/13/06 - 14 - 14						POORLY GRADED SAND WITH SILT; dar (10YR 4/4); 10% silt; loose; fine grained; we	k yellowish brown
108816 DRILLING LOG Rev: 11/8/06 GINT.GPJ CALTRANS.GDT 11/13/06					SP- SM	(1011) Tity, 1070 Siit, 10036, lille grained, we	Ì
- 20 20 20						POORLY GRADED SAND; light olive brown grained; wet	n (2.5Y 5/4); loose; fine
22 – 22 –					SP		
816 E							
108				_		Continued Next Page	



Monitoring Well

MW4-2-3

Page: 3 of 5

 Project
 Alameda Pt CTO 133
 Owner
 US Navy

 Location
 Alameda, CA
 Proj. No.
 108816

Location .	_Alameda, C	;A					Proj. No
Depth (ft.)	Well	PID (ppm)	Sample ID % Recovery	Blow Count Recovery	Graphic Log	ASTM/USCS	Description (Color, Texture, Structure) Geologic Descriptions are Based on ASTM/USCS.
- 26 -						SP	Continued POORLY GRADED SAND; light olive brown (2.5Y 5/4); loose; fine grained; wet Wet at 25 feet.
- 28 -						SP- SM	POORLY GRADED SAND WITH SILT; olive brown (2.5Y 4/4); 10% silt; loose; wet
- 30 - 32 -							SILTY SAND; light olive brown (2.5Y 5/3); 20-30% silt; fine sand; loose; wet/saturated
- 34 -						sм	
- 36 -							
- 38 -							TD=36.5 ft
- 40 -							
- 42 - 		;					
- 44 -							
- 46 -							
- 20 84							
NT.GPJ CALI					İ	!	
90/8/L1 - 54 -							
56 – 56 –							
108816 DRILLING LOG Rev: 11/8/06 GINT.GPJ CALTRANS.GDT 11/13/06							

SINGLE COMPLETION WELL D	ETAILS Page: 4 of 5
PROJECT NUMBER: 108816	BORING/WELL NO.: MW4-2-3
PROJECT NAME: Alameda Pt CTO 133	TOP OF CASING ELEV.: <u>n/a</u> (MSL)
- · · ·	_ CEMENT FLOOR ELEV.: <u>16.50 ft.</u> (MSL)
WELL PERMIT NO.: W2006-0450	DATUM: CCS27, Zone 3, NAVD88
├ ── M ──→	
	EXPLORATION BORING
	A. Total Depth <u>36.5</u> ft.
	B. Boring Diameter8 in.
G	Drilling Method Hollow Stem Auger
	WELL CONSTRUCTION
	C. Casing Length (BGL)35 ft.
	Material Sch 5, Type 304, Stainless Steel
	D. Casing Diameter in.
	E. Depth to Top of Screen
	F. Screen Length5 ft.
	Slotted Interval from <u>30</u> to <u>35</u> ft.
	Slot Type <u>continuous wrap SS</u>
	Slot Size in.
	G. Surface Seal ft.
A C	Seal Material <u>n/a</u>
	H. Annular Seal25 ft.
	Seal Material Baselite I-II-V cement
	I. Transition Sand1 ft.
	Transition Material RMC Pacific #60 sand
	J. Filter Pack 10.5 ft.
	Material RMC Pacific-Lapis Lustre # 2/16 sand
	K. Backfill ft.
	Material n/a
	L. Top of Casing Heightn/a ft.
	M. Protective Cover Diameter4 in.
	MSL = mean sea level
	BGL = below ground level
├ ──В ──→	



Monitoring Well MW4-2-4
Page: 2 of 5

Location Alameda, C Surface Elev. (msl) 12. Top of Casing 13.92 Screen: Dia 2 in. Casing: Dia 2 in. Fill Material See Con Drill Co. WDC Exploi	75 ft. ft. nments ration &	Water Level Initial Length 5 ft. Length 25.5 ft. Wells Method Ho	5 ft. 5.2 ft. Rig	Proj. No. 108816 North 470373 East 1481785 Static NA Diameter 8 in. Type/Size Sch 40 PVC/0.020 in. Type Sch 5, Type 304, Stainless Steel g/Core Geoprobe 7730DT Stem Auger Date 7/8/06 Permit # W2006-0451	•
108916 DRILLING LOG Rev. 11/18/06 GINT GPJ. CALTRANS. GDT. 11/13/06 - 2 - 4 \$\frac{1}{2}\$ - 6 - 8 10 12 14 16 18 10 12 18 10 12 -	0.0		SP- SM	Depths are below ground level. 6" concrete surface. Initial hole cleared for u air-knife and backfilled with air-knifed cutting POORLY GRADED SAND WITH SILT; dai (10YR 4/2); 90% very fine sand; 10% silt; lower silt. Becomes moist at 6 feet; silt content increations and; 40% "fines," nonplastic; saturated At 15 feet, silt content decreases. Contains sand, with trace coarser sand. Continued Next Page	gs. rk yellowish brown rose; noncohesive; damp ses. OYR 5/4); 60% very fine



Monitoring Well

MW4-2-4

Page: 3 of 5

 Project
 Alameda Pt CTO 133
 Owner
 US Navy

 Location
 Alameda, CA
 Proj. No. 108816

Location	Alameda, C	<u> </u>					Proj. No
Depth (ft.)	Well	Old (mdd)	Sample ID % Recovery	Blow Count Recovery	Graphic Log	ASTM/USCS	Description (Color, Texture, Structure) Geologic Descriptions are Based on ASTM/USCS.
- 26 30 34	M COmit	d 0.0	Sam % Re	Blow Rec	Gra	S S ASTM	· ·
- 42 44 46 448 502 48 502 56 56 58							

Page: 4 of 5 SINGLE COMPLETION WELL DETAILS BORING/WELL NO .: MW4-2-4 PROJECT NUMBER: 108816 (MSL) PROJECT NAME: Alameda Pt CTO 133 TOP OF CASING ELEV .: _13.92 ft. GROUND SURFACE ELEV .: _ 12.75 ft. _ (MSL) COUNTY: Alameda DATUM: CCS27, Zone 3, NAVD88 WELL PERMIT NO.: <u>W2006-0451</u> Μ **EXPLORATION BORING** 30.5 ft. A. Total Depth 8 _ in. B. Boring Diameter Hollow Stem Auger G **Drilling Method** WELL CONSTRUCTION 31.67 ft. C. Casing Length Sch 5, Type 304, Stainless Steel Material D. Casing Diameter __ in. 25.5 ft. E. Depth to Top of Screen 5 F. Screen Length . ft. 25.5 to 30.5 ft. Slotted Interval from continuous wrap SS Slot Type Slot Size in. G. Surface Seal . ft. C n/a Seal Material 21 H. Annular Seal Baselite I-II-V cement Seal Material 2.5___ ft. I. Transition Sand RMC Pacific #60 sand Transition Material J. Filter Pack RMC Pacific-Lapis Lustre # 2/16 sand Material K. Backfill n/a Material 1.17 ft. L. Top of Casing Height M. Protective Cover Diameter MSL = mean sea level BGL = below ground level



Monitoring Well MW4-2-5 Page: 2 of 5 COMMENTS

Casing: Dia 2 in. Fill Material See Comm Drill Co. WDC Explorati Driller J. Zimmer/J. Trujillo Checked By Eugene Mo	ft. Total Hole Dep Water Level In Length 5 ft. Length 32 ft ents on & Wells Log By J. Str	th 39.0 itial $\sqrt{2}$ 6 hood Hollo ack/G. And C57 Lice	ft. 5.3 ft. Rig/Co ow Stem Jerson, C	Proj. No. 108816 North 470375 East 1481788 Static NA Diameter 8 in. Type/Size Sch 40 PVC/0.020 in. Type Sch 5, Type 304, Stainless Steel Type Geoprobe 7730DT Auger PGDate 7/11/06 Permit # W2006-0452	· I
- 2 - 4 - 5 - 6 - 10 - 10 - 10 - 10 - 10 - 10 - 10			SP-SM	epths are below ground level. 6" concrete surface. Initial hole cleared for air-knife and backfilled with air-knifed cutting POORLY GRADED SAND WITH SILT; da (10YR 4/2); 90% very fine to fine sand; 10° noncohesive; damp to moist Becomes moderate yellowish brown (10YI feet. SILTY SAND; moderate yellowish brown (to fine sand; 20% silt, nonplastic; loose; sate poor sand; sate poor sa	ark yellowish brown % silt; loose; R 5/4) and wet near 6 10YR 5/4); 80% very fine sturated



Monitoring Well

MW4-2-5

Page: 3 of 5

 Project
 Alameda Pt CTO 133
 Owner
 US Navy

 Location
 Alameda, CA
 Proj. No.
 108816

Location	Alameda, C	<u>A</u>					Proj. No
Depth (ft.)	Well	PID (mdd)	Sample ID % Recovery	Blow Count Recovery	Graphic Log	ASTM/USCS	Description (Color, Texture, Structure) Geologic Descriptions are Based on ASTM/USCS.
- 26 - - 28 - - 30 - - 32 -						SP- SM	Continued POORLY GRADED SAND WITH SILT; 10% silt, trace medium to coarse grained sand; saturated, soupy
- 34 - - 36 - - 38 -						SM	SILTY SAND; olive brown (2.5Y 4/3); 25-35% silt; fine grained with trace medium sand; saturated
40 -							TD=39 ft
" -							
- 42 -							Note: Above 30 feet, soil descriptions were generated from soil grab sample specimens collected from the veins of hollow stem auger flytes. As a result, the depths of all descriptions and soil horizon boundaries are approximate.
44 -							··
-							
– 46 –				•			
- 48 –							
100%							
50 –							
a 30 .							
ਰੂ – 52 –	∥ ∥						
			;				
% - 54 −							
Sev: 7							
56 –							
58 – 58 –							
108816 DRILLING TOOK THROW GINT GPJ CALTRANS, GDT 11/13/06 CINT		!					
			L				

Page: 4 of 5 SINGLE COMPLETION WELL DETAILS PROJECT NUMBER: 108816 BORING/WELL NO.: MW4-2-5 PROJECT NAME: Alameda Pt CTO 133 TOP OF CASING ELEV .: _n/a (MSL) COUNTY: Alameda GROUND SURFACE ELEV.: _ 12.85 ft. (MSL) WELL PERMIT NO.: <u>W2006-0452</u> DATUM: CCS27, Zone 3, NAVD88 Μ **EXPLORATION BORING** A. Total Depth B. Boring Diameter G Hollow Stem Auger **Drilling Method** WELL CONSTRUCTION 38.5 ft. C. Casing Length Sch 5, Type 304, Stainless Steel Material D. Casing Diameter __ in. 32 __ ft. E. Depth to Top of Screen 5 _ ft. F. Screen Length <u>32</u> to <u>37</u> ft. Slotted Interval from continuous wrap SS Slot Type 0.020 Slot Size G. Surface Seal Seal Material n/a 29 H. Annular Seal Baselite I-II-V cement Seal Material 1 I. Transition Sand ft. Transition Material RMC Pacific #60 sand J. Filter Pack RMC Pacific-Lapis Lustre # 2/16 sand Material K. Backfill n/a Material 1.5 ft. L. Top of Casing Height M. Protective Cover Diameter MSL = mean sea level BGL = below ground level



12

Drilling Log

A							Drining Log	
Sh	āw®						Monitoring W	/ell MVV4-2-6 Page: 2 of 5
Project _	lameda Pt	CTO 13	3			_ 0	ner _US Navy	COMMENTS
ocation _	Alameda, (CA			·		Proj. No	Annular seal - Cement, Type
Surface Ele	ev. (msl) <u>16</u>	.47 ft.	Total Ho	ole Dep	th <u>20</u>	.5 ft.	North <u>470388</u> East <u>1481834</u>	Transition sand - RMC Pacific #60 sand
op of Casi	ing <u>NA</u>		Water L	evel ini	itial <u>NA</u>	١		Filter Pack - RMC Pacific, Lapi
	2 in.		Length	5 ft.			Type/Size Sch 40 PVC/0.020 in.	Lustre #2/16 sand Well Casing - Sch 5, Type 304
asing: Dia	2 in.		Length				Type Sch 5, Type 304, Stainless Steel	Stainless Steel (SS) Screen - 0.020 in continuous
	See Co.	mments					/Core Geoprobe 7730DT	wrap, Sch 5, Type 304 SS Protective Casing - 4 in dia Sci
rill Co	WDC Explo	oration 8	Wells	_ Meth			fem Auger	40 CPVC
riller <i>J<u>. Zi</u></i>	mmer/J. Tr	ujillo	Log By	Joe S	track		Date <u>7/8/06</u> Permit # <u> W2006-0453</u>	Surface elevation value reflect
hecked By	, <u>Eugene</u>	Mullen	meister, l	PG	C57 Lie	cense	No283326	surveyed raised floor.
						11		<u></u>
ے	tion_		Sample ID % Recovery	ount ery	္ခ	ASTM/USCS	Description	
Depth (ft.)	Well	Old (mdd)		Blow Count Recovery	Graphic Log	M/U	(Color, Texture, Strue	rturo\
-	Š		sl _r	8 %	၅	AST	Geologic Descriptions are Based	•
	_							
	$+ \Box \Box \Box$						Depths are below ground level.	
. 0 -	** ** * * * * * * * *						Initial hole cleared for utilities to five feet v	
	%						with air-knifed cuttings. Cuttings above 5	feet not described.
1	X X							
	6 6							
2 —	\bowtie							
	% %							
-								
	X							
- 4 -	\otimes							
	%							
	ii ii ii ii ii ii ii ii ii ii ii ii ii				<u> </u>			
							SILTY SAND; moderate yellowish brown	(10YR 5/4); 60% very fine
	\otimes						grained sand; 40% silt, nonplastic; loose;	nonconesive; saturated

SM

Continued Next Page



Monitoring Well

MW4-2-6

Page: 3 of 5

 Project
 Alameda Pt CTO 133
 Owner
 US Navy

 Location
 Alameda, CA
 Proj. No. __108816

Location	Alameda, C	<i>A</i>			-		Proj. No
Depth (ft.)	Well Completion	PID (mpd)	Sample ID % Recovery	Blow Count Recovery	Graphic Log	ASTM/USCS	Description (Color, Texture, Structure) Geologic Descriptions are Based on ASTM/USCS.
- 16 - - 18 -						SM	Continued SILTY SAND; moderate yellowish brown (10YR 5/4); 60% very fine grained sand; 40% silt, nonplastic; loose; noncohesive; saturated
- 20 -							
							TD=20.5 ft
- 22 -							Note: Soil descriptions were generated from soil grab sample specimens collected from the veins of hollow stem auger flytes. As a result, the depths of all descriptions and soil horizon boundaries are
- 24 - 							approximate.
– 26 –							
- 28 – 28 –							
108816 DRILLING LOG Rev. 11/8/06 GINT.GPJ CALTRANS.GDT 11/13/06 C							
11/8/06 GINT.GP.							
.ing Log Rev: -							
108816 DRILLII							

SINGLE COMPLETION WELL D	ETAILS Page: 4 of 5
PROJECT NUMBER: 108816	BORING/WELL NO.: MW4-2-6
PROJECT NAME: Alameda Pt CTO 133	TOP OF CASING ELEV.: <u>n/a</u> (MSL)
	_ CEMENT FLOOR ELEV.: <u>16.47 ft.</u> (MSL)
WELL PERMIT NO.: W2006-0453	DATUM: CCS27, Zone 3, NAVD88
← Μ →	
	EXPLORATION BORING
	A. Total Depth 20.5 ft.
	B. Boring Diameter8 in.
G	Drilling Method Hollow Stem Auger
	WELL CONSTRUCTION
	C. Casing Length (BGL) ft.
	Material Sch 5, Type 304, Stainless Steel
	D. Casing Diameter2 in.
	E. Depth to Top of Screen15 ft.
E H	F. Screen Length5 ft.
	Slotted Interval from15to _20_ ft.
	Slot Type <u>continuous wrap SS</u>
	Slot Size 0.020 in.
	G. Surface Seal ft.
	Seal Material <u>n/a</u>
	H. Annular Seal 12 ft.
	Seal Material Baselite I-II-V cement
	I. Transition Sand1 ft.
	Transition Material RMC Pacific #60 sand
	J. Filter Pack7 ft.
	Material RMC Pacific-Lapis Lustre # 2/16 sand
	K. Backfill ft.
	Material <u>n/a</u>
	L. Top of Casing Heightn/a ft.
	M. Protective Cover Diameter4 in.
	MSL = mean sea level
	BGL = below ground level
<mark>├ В</mark>	



16


18

20

22

Drilling Log

Monitoring Well MW4-2-7



loose; fine grained; wet

Silt decreases to 10% at 21 feet.

POORLY GRADED SAND; trace silt; wet

POORLY GRADED SAND WITH SILT; 10-15% silt; wet

Continued Next Page

SM



Monitoring Well

MW4-2-7 Page: 3 of 5

Project .	Alameda Pt CTO 133	 Owner	US Navy		
Location	Alameda, CA	 		Proj. No.	108816

Location	Alameda, C	<u> </u>					Proj. No
Depth (ft.)	Well Completion	(mdd)	Sample ID % Recovery	Blow Count Recovery	Graphic Log	ASTM/USCS	Description (Color, Texture, Structure) Geologic Descriptions are Based on ASTM/USCS.
	Well Completion	(mdd) Cld	Sample ID % Recovery	Blow Count Recovery	Graphic Log	W W W W W W W W W W W W W W W W W W W	Description (Color, Texture, Structure)
907 – 54 – 54 – 56 – 56 – 56 – 56 – 56 – 56							
9816 DRILLING F	-						

Page: 4 of 5 SINGLE COMPLETION WELL DETAILS BORING/WELL NO .: MW4-2-7 PROJECT NUMBER: 108816 TOP OF CASING ELEV.: n/a (MSL) PROJECT NAME: Alameda Pt CTO 133 16.48 ft. (MSL) **CEMENT FLOOR ELEV.:** COUNTY: Alameda DATUM: CCS27, Zone 3, NAVD88 WELL PERMIT NO .: <u>W2006-0454</u> **EXPLORATION BORING** 31.5 ft. A. Total Depth 8 _ in. B. Boring Diameter Hollow Stem Auger G **Drilling Method** WELL CONSTRUCTION 31.2 ft. C. Casing Length (BGL) Sch 5, Type 304, Stainless Steel Material D. Casing Diameter __ in. 26.2 ft. E. Depth to Top of Screen 5 F. Screen Length ft. 26.2 to 31.2 ft. Slotted Interval from continuous wrap SS Slot Type 0.020 Slot Size in. G. Surface Seal C n/a Seal Material 22.8 ft. H. Annular Seal Baselite I-II-V cement Seal Material 1.2___ft. Transition Sand RMC Pacific #60 sand Transition Material 7.5 ft. J. Filter Pack RMC Pacific-Lapis Lustre # 2/16 sand Material K. Backfill n/a Material n/a L. Top of Casing Height M. Protective Cover Diameter MSL = mean sea level BGL = below ground level



Monitoring Well M

MW4-2-8

Page: 2 of 5 Project Alameda Pt CTO 133 Owner US Navy COMMENTS Annular seal - Cement, Type Location Alameda, CA Proj. No. <u>108816</u> Transition sand - RMC Pacific North <u>4703</u>99 Surface Elev. (msl) 16.48 ft. Total Hole Depth 40.0 ft. #60 sand Filter Pack - RMC Pacific, Lapis Lustre #2/16 sand Well Casing - Sch 5, Type 304 Stainless Steel (SS) Screen - 0.020 in continuous Top of Casing NA __ Water Level Initial __NA_ Static NA __ Diameter <u>8 in.</u> Type/Size Sch 40 PVC/0.020 in. Screen: Dia 2 in. Length 5 ft. Casing: Dia 2 in. Length 35 ft. Type Sch 5, Type 304, Stainless Steel wrap, Sch 5, Type 304 SS Protective Casing - 4 in dia Sch 40 CPVC Fill Material See Comments Rig/Core Geoprobe 7730DT Drill Co. WDC Exploration & Wells Method Hollow Stem Auger Driller J. Zimmer/J. Trujillo Log By Eugene Mullenmeister Date 6/12/06 Permit # W2006-0455 Surface elevation value reflects

Depths are below ground level. Depths are below ground level. Initial hole cleared for utilities to five feet with air-knifed cuttings. Cuttings above 5 feet not described by sand; 20% silt; trace clay; wet SILTY SAND; olive brown (2.5Y 4/4); 80% fine to m sand; 20% silt; trace clay; wet SILTY SAND; olive brown (2.5Y 5/4) at ~15 feet.	veyed raised floor.	surve		C57 Lic		neister, F		Eugene	
Initial hole cleared for utilities to five feet with air-knif with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings above 5 feet not defined by the feet with air-knifed cuttings. Cuttings are feet all cuttings are feet air-knifed cuttings. Cuttings are feet air-knifed cuttings. Cuttings are feet air-knifed cuttings. Cuttings are feet a	A/USCS.	(Color, Texture, Structure)	ASTM/USCS	Graphic Log	Blow Count Recovery	Sample ID % Recovery	OIA (mdd)	Well Completion	Depth (ft.)
Becomes light olive brown (2.5Y 5/4) at ~15 feet.	ot described.	Initial hole cleared for utilities to five feet with air-k with air-knifed cuttings. Cuttings above 5 feet not SILTY SAND; olive brown (2.5Y 4/4); 80% fine to							2 - 4 - 6 - 8 -
POORLY GRADED SAND WITH SILT; light olive be 90% fine to medium grained sand; 10% silt; wet		Becomes light olive brown (2.5Y 5/4) at ~15 feet. POORLY GRADED SAND WITH SILT; light olive 90% fine to medium grained sand; 10% silt; wet							14 - 16 - 18 - 20 -



Monitoring Well

MW4-2-8

Page: 3 of 5

 Project
 Alameda Pt CTO 133
 Owner
 US Navy

 Location
 Alameda, CA
 Proj. No. 108816

Loc	ation .	Alameda, CA					Proj. No		
	Depth (ft.)	Well Completion	PID (mdd)	Sample ID % Recovery	Blow Count Recovery	Graphic Log	ASTM/USCS	Description (Color, Texture, Structure) Geologic Descriptions are Based on ASTM/USCS.	
	- 26 28 30 32 34 36 36						SP- SM	Continued POORLY GRADED SAND WITH SILT; light olive brown (2.5Y 5/6); 90% fine to medium grained sand; 10% silt; wet	
-	38 -						SM	SILTY SAND; light olive brown (2.5Y 5/6); 65% fine to medium grained sand; 25% silt; 5% clay; wet	
r	40 –							TD=40 ft	
-	42 -							Note: Soil descriptions were generated from soil grab sample specimens collected from the veins of hollow stem auger flytes. As a result, the depths of all descriptions and soil horizon boundaries are approximate.	
90/	46 -								
8916 DRILLING LOG Rev: 11/8/06 GINT.GPJ CALTRANS.GDT 11/13/06	48 -								
CALTRAN	50 -	-							
VOG GINT.GF	52 -);						
3 Rev: 11/8	54 -	-							
SILLING LOC	56 -	-							
8816 DF	58 -	-							

SINGLE COMPLETION WELL DETAILS Page: 4 of 5							
PROJECT NUMBER: 108816	BORING/WELL NO.: MW4-2-8						
PROJECT NAME: Alameda Pt CTO 133	TOP OF CASING ELEV.: <u>n/a</u> (MSL)						
COUNTY: Alameda	CEMENT FLOOR ELEV.: 16.48 ft. (MSL)						
WELL PERMIT NO.: W2006-0455	DATUM: CCS27, Zone 3, NAVD88						
← M — →							
	EXPLORATION BORING						
	A. Total Depth						
	B. Boring Diameter8 in.						
	Drilling Method Hollow Stem Auger						
	WELL CONSTRUCTION						
	C. Casing Length (BGL)						
	Material Sch 5, Type 304, Stainless Steel						
	D. Casing Diameter in.						
	E. Depth to Top of Screen 35 ft.						
E H	F. Screen Length5 ft.						
	Slotted Interval from <u>35</u> to <u>40</u> ft.						
	Slot Type <u>continuous wrap SS</u>						
	Slot Size 0.020 in.						
	G. Surface Seal ft.						
A C +	Seal Material <u>n/a</u>						
	H. Annular Seal31.5_ ft.						
	Seal Material Baselite I-II-V cement						
	I. Transition Sand1.5 ft.						
	Transition Material RMC Pacific #60 sand						
	J. Filter Pack7 ft.						
	Material RMC Pacific-Lapis Lustre # 2/16 sand						
	K. Backfill ft.						
	Materialn/a						
	L. Top of Casing Heightn/a ft.						
	M. Protective Cover Diameter 4 in.						
	MSL = mean sea level						
<u> </u>	BGL = below ground level						
├ Β 							



Monitoring Well MW4-2-9

5n	aw®						world we	Page: 2 of 5
•	Alameda Pt		3			_ 0	wner US Navy	COMMENTS Annular seal - Cement, Type
	Alameda,					0.0	Proj. No. <u>108816</u>	I-II-V Transition sand - RMC Pacific
	ev. (msl <u>) 16</u>							#60 sand Filter Pack - RMC Pacific, Lap
	ing <u><i>NA</i></u> a <u>2 in.</u>						0 1 40 70 40 40 40	Lustre #2/16 sand Well Casing - Sch 5, Type 304
	2 in.		_				Type/Size Sch 40 PVC/0.020 in. Type Sch 5, Type 304, Stainless Steel	Stainless Steel (SS)
	See Co						g/Core Geoprobe 7730DT	Screen - 0.020 in continuous wrap, Sch 5, Type 304 SS
	WDC Explo			Meth			item Auger	Protective Casing - 4 in dia So 40 CPVC
	immer/J. Tr		Log By					Surface elevation value reflec
hecked B	y <u>Eugene</u>	Mullen	meister, I	PG	C57 Lic	cense		surveyed raised floor.
_	ion		⊕ Gy	t a	U	SCS	Description	
Depth (ft.)	Well Completion	Old (mdd)	Sample ID % Recovery	Blow Count Recovery	Graphic Log	M/US	•	·n)
ا	Sol	=	Sar R R	g g	Ū	ASTM/USCS	(Color, Texture, Structur Geologic Descriptions are Based on	•
	-					<u> </u>	<u></u>	
							Depths are below ground level.	
م ا								
							Initial hole cleared for utilities to five feet with with air-knifed cuttings. Cuttings above 5 feet.	
_							with an-kinned cuttings. Outlings above 5 let	st not described.
	\bowtie							
2 _	M			ĺ				
	\bowtie							
	M							
4								
-								
					<u> </u>			
							SILTY SAND; olive brown (2.5Y 4/4); 80% f sand; 20% silt; trace clay; wet	ine to medium grained
6 -							Sand, 20 /0 Sit, trace clay, Wet	
·]	\bowtie							
]								
ا_ ۾								
8 –								
		0.0						
1		0.0						
10 —								
'U _						SM		
_								
7								
		i i	II .		1 . 1. •1			
12 -								

Color change to light olive brown (2.5Y 5/6).

Continued Next Page



Monitoring Well

Page: 3 of 5

Project Alameda Pt CTO 133 Owner US Navy 108816 Alameda CA

Location	Alameda, C	CA			<u>.</u>		Proj. No. <u>108816</u>
Depth (ft.)	Well	OID (mdd)	Sample ID % Recovery	Blow Count Recovery	Graphic Log	ASTM/USCS	Description (Color, Texture, Structure) Geologic Descriptions are Based on ASTM/USCS.
- 16 						SM	Continued SILTY SAND; light olive brown (2.5Y 5/6); 80% fine to medium grained sand; 20% silt; wet
- 18 -							TD=18.3 ft
- 20 -							Note: Soil descriptions were generated from soil grab sample specimens collected from the veins of hollow stem auger flytes. As a
- 22 -							specimens collected from the veins of hollow stem auger flytes. As a result, the depths of all descriptions and soil horizon boundaries are approximate.
- 24 -							
- 26 -							
- 28 -							
ALTRANS.GDT							
GINT.GPJ C	-						
- 32 –							
288 30 11/13/06 GINT.GPJ CALTRANS.GDT 11/13/06 1							

SINGLE COMPLETION WELL DE	ETAILS Page: 4 of 5
PROJECT NUMBER: 108816	BORING/WELL NO.: MW4-2-9
PROJECT NAME: Alameda Pt CTO 133	TOP OF CASING ELEV.: <u>n/a</u> (MSL)
	CEMENT FLOOR ELEV.: 16.46 ft. (MSL)
WELL PERMIT NO.: W2006-0456	DATUM: CCS27, Zone 3, NAVD88
├ ── M ──→	
	EXPLORATION BORING
	A. Total Depth18.3ft.
	B. Boring Diameter8 in.
G	Drilling Method Hollow Stem Auger
	WELL CONSTRUCTION
	C. Casing Length (BGL) 18.3 ft.
	Material Sch 5, Type 304, Stainless Steel
	D. Casing Diameter in.
E H	E. Depth to Top of Screen 13.3 ft.
E H	F. Screen Length5 ft.
	Slotted Interval from 13.3 to 18.3 ft.
	Slot Type <u>continuous wrap SS</u>
	Slot Size 0.020 in.
	G. Surface Seal ft.
A C	Seal Material <u>n/a</u>
	H. Annular Seal 9.9 ft.
	Seal Material Baselite I-II-V cement
	I. Transition Sand 1.4 ft.
	Transition Material RMC Pacific #60 sand
	J. Filter Pack ft.
	Material RMC Pacific-Lapis Lustre # 2/16 sand
	K. Backfill ft.
	Material n/a
	L. Top of Casing Heightft.
	M. Protective Cover Diameter 4 in.
	W. Flotective Cover Diameter III.
	MSI = moon and lovel
K T	MSL = mean sea level BGL = below ground level
ן פין	



Monitoring Well MW4-2-10
Page: 2 of 5

Project	Alameda Pt	CTO 13	3		_ 0	wner <u>US Navy</u>	COMMENTS			
	Alameda, (Proj. No. <u>108816</u>	Annular seal - Cement, Type I-II-V			
Surface Elev. (msl) 12.57 ft. Total Hole Depth Top of Casing NA Water Level Initial $\sqrt{2}$						30.0 ft. North 470333 East 1481820 Transition sand - RMC Pacific				
			Length 24.5			Type Sch 5, Type 304, Stainless Steel	Stainless Steel (SS)			
	See Co						Screen - 0.020 in continuous wrap, Sch 5, Type 304 SS			
	WDC Explo					g/Core Stem Auger	Protective Casing - 4 in dia Sch 40 CPVC			
							PID from "headspace."			
			Log By Garrio							
Checked B	y <u>Lugene</u>	iviulieili	meister, PG	C57 Lic	ense	No283326	Surface elevation reflects surveyed ground level.			
Depth (ft.)	Well	PID (ppm)	Sample ID % Recovery Blow Count Recovery	Graphic Log	ASTM/USCS	Description (Color, Texture, Structur Geologic Descriptions are Based on	·			
										
- 0 -						Depths are below ground level.				
						Initial hole cleared for utilities to five feet with with air-knifed cuttings. Cuttings above 2 feet				
2 <u>-</u>						POORLY GRADED SAND; dark grayish br	own (2.5Y 4/2); loose;			
<u> </u>						fine grained sand, rare medium grained san	d; trace silt; wet			
- 4 -		0.2								
- 6 -	\bowtie				SP					
"					5-					
8 -	\bowtie									
- -										
├ 10 ├				-511		POORLY GRADED SAND WITH SILT; OIN	re brown (2.5V 4/3) fine			
						grained; loose; wet	e blowii (2.51 4/5) iiile			
L 12 _		00								
'2		0.0			SP- SM					
8		0.0				Contains 10-15% silt at 13 feet.				
14 -		0.3								
		0.4			$\lfloor - \rfloor$					
Rev. 11/8/06 GINT.GPJ CALTRANS.GDT						SILTY SAND; light olive brown (2.5Y 5/3); fi loose; wet	ne grained; ~20% silt;			
ਨੇ ਫ਼ੂ– 18 –					\$М					
		_								
		0.1				Silt decreases to 15% at 19 feet.				
% 20 −						Saturated at 20 feet. No cuttings returns to	surface from 20-27 feet.			
<u> </u>						and the second s				
9 22										
SN -										
- 24										
24	∵⊟∷									
108						Continued Next Page				



Monitoring Well

MW4-2-10 Page: 3 of 5

Project _	Alameda Pt CTO 133	Owner	US Navy		
•	Alameda, CA			Proj. No.	108816


L	ocation .	Alameda, CA					_	Proj. No		
	Depth (ft.)	Well	OIA (mdd)	Sample ID % Recovery	Blow Count Recovery	Graphic Log	ASTM/USCS	Description (Color, Texture, Structure) Geologic Descriptions are Based on ASTM/USCS.		
	- 26 - - 28 -		0.0					Continued Saturated at 20 feet. No cuttings returns to surface from 20-27 feet.		
	- 30 -						SM	SILTY SAND; light olive brown (2.5Y 5/4); fine grained sand; 25-45% silt; very loose; saturated/fluid TD=30 ft		
	- 32 -							1D-30 R		
	- 34 - 									
	- 38 -									
[- 40 -									
ŀ	- 42 - - 44 -			•						
13/06	- 46 - - 46 -									
TRANS.GDT 11/	- 48 - - 50 -									
GINT.GPJ CAL	- 52 -									
3 Rev: 11/8/06	- 54 -									
08816 DRILLING LOG Rev. 11/8/06 GINT.GPJ CALTRANS.GDT 11/13/06	- 56 - - 58 -									
99		H	II	II		11	II	II		

SINGLE COMPLETION WELL DETAILS Page: 4 of 5 PROJECT NUMBER: 108816 BORING/WELL NO.: MW4-2-10 PROJECT NAME: Alameda Pt CTO 133 TOP OF CASING ELEV.: n/a (MSL) COUNTY: Alameda GROUND SURFACE ELEV.: 12.57 ft. (MSL) WELL PERMIT NO.: <u>W2006-0442</u> DATUM: CCS27, Zone 3, NAVD88 **EXPLORATION BORING** 30 _ ft. A. Total Depth 8 __ in. B. Boring Diameter Hollow Stem Auger G **Drilling Method** WELL CONSTRUCTION 31.83 ft. C. Casing Length Sch 5, Type 304, Stainless Steel Material D. Casing Diameter __ in. 24.5 ft. E. Depth to Top of Screen Н 5 F. Screen Length __ ft. Slotted Interval from 24.5 to 29.5 ft. continuous wrap SS Slot Type Slot Size 0.020 in. G. Surface Seal _ ft. n/a Seal Material 22 ft. H. Annular Seal Baselite I-II-V cement Seal Material 1 1. Transition Sand RMC Pacific #60 sand Transition Material J. Filter Pack RMC Pacific-Lapis Lustre # 2/16 sand Material K. Backfill n/a Material 2.33 ft. L. Top of Casing Height M. Protective Cover Diameter MSL = mean sea level BGL = below ground level



Monitoring Well MW4-2-11

Page: 2 of 4



SINGLE COMPLETION WELL D	ETAILS Page: 3 of 4			
PROJECT NUMBER: 108816	BORING/WELL NO.: MW4-2-11			
PROJECT NAME: Alameda Pt CTO 133	_ TOP OF CASING ELEV.: <u>n/a</u> (MSL)			
COUNTY: Alameda	CEMENT FLOOR ELEV.: 16.47 ft. (MSL)			
WELL PERMIT NO.: W2006-0443	DATUM: CCS27, Zone 3, NAVD88			
├ ── M ──→				
	EXPLORATION BORING			
	A. Total Depth10 ft.			
	B. Boring Diameter8 in.			
	Drilling Method <u>Hollow Stem Auger</u>			
	WELL CONSTRUCTION			
	C. Casing Length (BGL)10 ft.			
	Material Sch 5, Type 304, Stainless Steel			
	D. Casing Diameter in.			
E H	E. Depth to Top of Screen5 ft.			
	F. Screen Length5 ft.			
	Slotted Interval from <u>5</u> to <u>10</u> ft.			
	Slot Type <u>continuous wrap SS</u>			
	Slot Size in.			
	G. Surface Seal ft.			
	Seal Material <u>n/a</u>			
	H. Annular Seal ft.			
	Seal Material Baselite I-II-V cement			
	I. Transition Sand0.75 ft.			
	Transition Material RMC Pacific #60 sand			
	J. Filter Pack 7.25 ft.			
	Material RMC Pacific-Lapis Lustre # 2/16 sand			
	K. Backfill ft.			
	Material <u>n/a</u>			
	L. Top of Casing Heightn/a ft.			
	M. Protective Cover Diameter4 in.			
	MSL = mean sea level			
	BGL = below ground level			
├ B -				



Monitoring Well

MW4-2-12 Page: 2 of 5

Project Alameda Pt CTO 13 Location Alameda, CA Surface Elev. (msl) 16.45 ft. Top of Casing NA Screen: Dia 2 in. Casing: Dia 2 in. Fill Material See Comments Drill Co. WDC Exploration 8	Total Hole Depth Water Level Initial Length 5 ft. Length 26 ft.	31.2 ft. NA	Proj. No. 108816 North 470384 East 1481930 Static NA Diameter 8 in. Type/Size Sch 40 PVC/0.020 in. Type Sch 5, Type 304, Stainless Steel Limited Access CME-25	COMMENTS Annular seal - Cement, Type III-V Transition sand - RMC Pacific #60 sand Fitter Pack - RMC Pacific, Lapis Lustre #2/16 sand Well Casing - Sch 5, Type 304 Stainless Steel (SS) Screen - 0.020 in continuous wrap, Sch 5, Type 304 SS Protective Casing - 4 in dia Sch 40 CPVC
Driller R. McGahey/A. Vasque Checked By <u>Eugene Mullen</u>	z _{Log By} <u>Garrick And</u> meister, PG C57	erson, CPG License No	Date 7/12/06 Permit #_W2006-0444 	Surface elevation value reflects surveyed raised floor. PID by "headspace"
Depth (ft.) Well Completion PID (ppm)	Sample ID % Recovery Blow Count Recovery Graphic	ASTM/USCS	Color, Texture, Structu Geologic Descriptions are Based on	-
- 0 - 1 - 2 - 1 - 4 - 1 - 6 - 1 - 10.6 - 10.6 - 10.6 - 10.6 - 10.6 - 10.6 - 15.7 - 18 - 15		SM	Depths are below ground level. Initial hole cleared for utilities to five feet wit with air-knifed cuttings. Cuttings above 15 of the second	fine grained sand; Trace medium sand. 25% silt; very wet; poor



Monitoring Well

MW4-2-12

Page: 3 of 5

 Project
 Alameda Pt CTO 133
 Owner
 US Navy

 Location
 Alameda, CA
 Proj. No. 108816

Location	Alameda, C	CA					Proj. No
Depth (ft.)	Well Completion	(mdd) Old	Sample ID % Recovery	Blow Count Recovery	Graphic Log	ASTM/USCS	Description (Color, Texture, Structure) Geologic Descriptions are Based on ASTM/USCS.
- 26 28 30 32 34		27				SM	Continued SILTY SAND; loose fine-grained sand; 20-25% silt; very wet; poor cuttings returns Turns soupy at 30 feet. TD=31.2 ft
- 36 - - 38 - - 40 - - 42 - - 44 -							
- 46							
50 – 50 – 50 – 52 – 52 – 52 – 52 – 52 –							
90816 DALLING TORN THRONG GIVE GET THRONG GIVE GIVE GIVE GIVE GIVE GIVE GIVE GIV							
1 00							

SINGLE COMPLETION WELL D	ETAILS Page: 4 of 5
PROJECT NUMBER: 108816	BORING/WELL NO.: MW4-2-12
PROJECT NAME: Alameda Pt CTO 133	TOP OF CASING ELEV.: <u>n/a</u> (MSL)
· · · · · · · · · · · · · · · · · · ·	_ CEMENT FLOOR ELEV.: <u>16.45 ft.</u> (MSL)
WELL PERMIT NO.: W2006-0444	DATUM: CCS27, Zone 3, NAVD88
k M→	
	EXPLORATION BORING
	A. Total Depth 31.2 ft.
	B. Boring Diameter8 in.
Ġ Ġ	Drilling Method Hollow Stem Auger
	WELL CONSTRUCTION
	C. Casing Length (BGL) 31 ft.
	Material Sch 5, Type 304, Stainless Steel
	D. Casing Diameter in.
	E. Depth to Top of Screen ft.
E H	F. Screen Length5ft.
	Slotted Interval from <u>26</u> to <u>31</u> ft.
	Slot Type <u>continuous wrap SS</u>
	Slot Size 0.020 in.
	G. Surface Seal ft.
A C	Seal Material <u>n/a</u>
	H. Annular Seal23 ft.
	Seal Material Baselite I-II-V cement
	I. Transition Sand1 ft.
	Transition Material _RMC Pacific #60 sand
	J. Filter Pack ft.
	Material RMC Pacific-Lapis Lustre # 2/16 sand
	K. Backfill ft.
	<u>,</u>
	2. 10p or odoling riolgin
	M. Protective Cover Diameter4 in.
	MSL = mean sea level BGL = below ground level
- Consequences	3
l	



Monitoring Well

MW4-2-13 Page: 2 of 5

Project _	Alameda Pt	CTO 13	3		0	wner <u>US Navy</u>	COMMENTS
Location	Alameda, C	CA				Proj. No. <u>108816</u>	Annular seal - Cement, Type I-II-V
Surface El	Transition sand - RMC Pacific #60 sand						
Top of Casing NA Water Level Initial NA Static NA Diameter 8							Filter Pack - RMC Pacific, Lapis Lustre #2/16 sand
Screen: Di	ia <u>2 in.</u>		Length _5	ft.		Type/Size <u>Sch 40 PVC/0.020 in.</u>	Well Casing - Sch 5, Type 304
Casing: Di	ia <u>2 in.</u>		Length _3	5 ft.		Type Sch 5, Type 304, Stainless Steel	Stainless Steel (SS) Screen - 0.020 in continuous
Fill Materia	al See Cor	mments			R	g/Core Geoprobe 7730DT	wrap, Sch 5, Type 304 SS Protective Casing - 4 in dia Sch
Drill Co	WDC Explo	ration 8	Wells	Method _	tollow S	Stem Auger	40 CPVC
Driller J. Z	Zimmer/J. Tru	ujillo	Log By Ji	m Teo		Date <u>6/26/06</u> Permit #_W2006-0445	Surface elevation value reflects
Checked E	By Eugene	Mullen	meister, PG	C57	License	No. <u>283326</u>	surveyed raised floor.
	11 11		<u> </u>	- 11	1		
ء ا	tion		ery (ery	i. 🚰	ပ္သင္တ	Description	
Depth (ft.)	Well Completion	PID (mdd)	Sample ID % Recovery	Recovery Graphic	ASTM/USCS	(Color, Texture, Structu	uro)
-	ပို		Sal %		AST	Geologic Descriptions are Based on	•
	╫──-			 -	₩`		
	1						
		,			ļ		
						Depths are below ground level.	
├ 0 -					╢	Initial hole cleared for utilities to five feet wit	h air-knife and backfilled
						with air-knifed cuttings. Cuttings above 4 fe	et not described.
١ ,							
2 -							
-							
L 4 -						011 TX 04 ND 1 1 (7.5) (7.4)	
						SILTY SAND; dark gray (7.5YR 4/2); loose	/no cohesion; wet
						Becomes dark reddish gray (5YR 4/2). Moi	st to wet.
├ 6 −							
-							
L 8 -							
l °			:			Dark gray (7.5YR 4/2). Loose/no cohesion	and wet.
F -					sм		
- 10 -							
L .							
1							
12 −							
اي							
) - 14 -							
된 '국							
					1	SILTY SAND (60%); (10YR 4/2); loose, noi	n-cohesive; mixed with
ଞ୍ଚ⊢ 16 −						SANDY SILT WITH CLAY (40%); 10YR 4/4	4); slightly stiff; wet
<u>ا</u>					SM/ML		
립 - 18 -						·	
§ – 20 –							
11/8						SILTY SAND; (10YR 4/2); loose; fine-grain wet	ed sand; non-choesive;
						Wot	
္ခ် <mark> – 22 –</mark>					:∥_		
					SM		
					:		
24 −							
- 4	PIN VIA			F. 1.31.3	.	Continued Next Page	
_,	11			11	11	1 20	



Monitoring Well

MW4-2-13

Page: 3 of 5

US Navy Alameda Pt CTO 133 Project Owner Alameda, CA 108816 Proj. No. Location ASTM/USCS Blow Count Recovery Well Completion Description Graphic Log PID (bpm) Depth (ft.) (Color, Texture, Structure) Geologic Descriptions are Based on ASTM/USCS. Continued SILTY SAND; (10YR 4/2); loose; fine-grained sand; non-choesive; 26 28 30 32 SM 34 Becomes slightly cohesive at 35 feet. 36 38 Becomes (10YR 4/4) Sandy Silt at 40 feet. Some clay, cohesive, 40 and wet. TD=40 ft 42 Note: Soil descriptions were generated from soil grab sample specimens collected from the veins of hollow stem auger flytes. As a result, the depths of all descriptions and soil horizon boundaries are approximate. 46 48 50 52 54 56 58

SINGLE COMPLETION WELL DETAILS Page: 4 of 5 PROJECT NUMBER: 108816 BORING/WELL NO.: MW4-2-13 PROJECT NAME: Alameda Pt CTO 133 TOP OF CASING ELEV.: n/a (MSL) COUNTY: Alameda **CEMENT FLOOR ELEV.:** 16.48 ft. (MSL) WELL PERMIT NO .: _ W2006-0445 DATUM: CCS27, Zone 3, NAVD88 **EXPLORATION BORING** 40 _ ft. A. Total Depth B. Boring Diameter G Hollow Stem Auger **Drilling Method** WELL CONSTRUCTION 40 C. Casing Length (BGL) ft. Sch 5, Type 304, Stainless Steel Material D. Casing Diameter in. 34.75 ft. E. Depth to Top of Screen 5 __ ft. F. Screen Length Slotted Interval from 34.75 to 39.75 ft. Slot Type continuous wrap SS Slot Size 0.020 in. G. Surface Seal ft. C Seal Material n/a 33.<u>5</u> ft. H. Annular Seal Baselite I-II-V cement Seal Material 1 I. Transition Sand ft. RMC Pacific #60 sand Transition Material 5.5 J. Filter Pack RMC Pacific-Lapis Lustre # 2/16 sand Material K. Backfill n/a Material n/a L. Top of Casing Height ft. M. Protective Cover Diameter MSL = mean sea level BGL = below ground level



Monitoring Well

MW4-2-14 Page: 2 of 4

Page: 2 of 4


	Alameda Pt		3			_ 0	wner US Navy	COMMENTS
Location	Alameda,	Annular seal - Cement, Type I-II-V						
Surface El	lev. (msl) <u>16</u>	Transition sand - RMC Pacific #60 sand						
Top of Cas	sing <u>NA</u>	Filter Pack - RMC Pacific, Lapis Lustre #2/16 sand						
Screen: Di			Length				Type/Size <u>Sch 40 PVC/0.020 in.</u>	Well Casing - Sch 5, Type 304 Stainless Steel (SS)
Casing: Di			Length	6 ft.			Type Sch 5, Type 304, Stainless Steel	Screen - 0.020 in continuous
Fill Materia	See Co	mments				_ Ri	g/Core <u>Geoprobe 7730DT</u>	wrap, Sch 5, Type 304 SS Protective Casing - 4 in dia Sch
Drill Co.	WDC Explo		_	Meth			Stem Auger	40 CPVC
	immer/J. Tr		Log By		ne Muller	meist	er Date <u>6/6/06</u> Permit # <u>W2006-0446</u>	Surface elevation value reflects surveyed raised floor.
Checked E	By <u>Eugene</u>	e Mulleni	meister, P	<u>'G</u>	C57 Lic	ense	No. <u>283326</u>	
	د		اد ا	¥ .		ιχ	Description	
Depth (ft.)	Well Completion	PID (ppm)	Sample ID % Recovery	Blow Count Recovery	Graphic Log	ASTM/USCS	Description	
8°	A mo	P (9)	Re	Ş o Ş	Gra	TX	(Color, Texture, Structu	•
L	٥		01%	<u> </u>		¥	Geologic Descriptions are Based on	ASTM/USCS.
:	 							
	∥│ ┌─ ┤│						Depths are below ground level.	
- o -							Initial hole cleared for utilities to five feet with	h air knife and haakfilled
							with air-knifed cuttings. Cuttings above 5 fe	
-								
- 2 -	\bowtie							
L 4 -								
L _		0.0			L]	$\lfloor _{-} floor$		
		0.0					SILTY SAND; olive gray (5Y 4/2); 85% fine	to medium grained
							sand; 15% silt; wet	
- 6 -								
_								
8 -						SM		
1								
<u>-</u>								
ġ C								
10								
<u>-</u>	-1.0 F. 0					\vdash		
							TD=11 ft	
12 –							10-11 lt	
						:		
-							Nata Call day 1 ff	
<u> </u>							Note: Soil descriptions were generated from specimens collected from the veins of hollow	n soil grab sample wistem auger flytes. As a
_ 14 <i>_</i>							result, the depths of all descriptions and soi	I horizon boundaries are
							approximate.	
				İ				
<u> </u>								

SINGLE COMPLETION WELL D	ETAILS Page: 3 of 4
PROJECT NUMBER: 108816	BORING/WELL NO.: MW4-2-14
PROJECT NAME: Alameda Pt CTO 133	TOP OF CASING ELEV.: <u>n/a</u> (MSL)
· · · · · · · · · · · · · · · · ·	_ CEMENT FLOOR ELEV.: <u>16.48 ft.</u> (MSL)
WELL PERMIT NO.: W2006-0446	DATUM: CCS27, Zone 3, NAVD88
├ ── M ──→	
	EXPLORATION BORING
	A. Total Depth11 ft.
	B. Boring Diameter8 in.
	Drilling Method Hollow Stem Auger
	WELL CONSTRUCTION
	C. Casing Length (BGL)11 ft.
	Material Sch 5, Type 304, Stainless Steel
	D. Casing Diameter in.
	E. Depth to Top of Screen6 ft.
E H	F. Screen Length5 ft.
	Slotted Interval from 6 to 11 ft.
	Slot Type <u>continuous wrap SS</u>
	Slot Size in.
	G. Surface Seal ft.
	Seal Material <u>n/a</u>
	H. Annular Seal3 ft.
	Seal Material Baselite I-II-V cement
	I. Transition Sand1 ft.
	Transition Material RMC Pacific #60 sand
	J. Filter Pack ft.
	Material RMC Pacific-Lapis Lustre # 2/16 sand
	K. Backfill ft.
	Material <u>n/a</u>
	L. Top of Casing Heightn/a ft.
	M. Protective Cover Diameter4 in.
	MSL = mean sea level BGL = below ground level
K T	DOL - Delow gloutiu level
├ ── Β ──→	



Monitoring Well MW4-2-15

Page: 2 of 5





Monitoring Well

MW4-2-15 Page: 3 of 5

Project .	Alameda Pt CTO 133	Owner	US Navy		
Location	Alameda, CA			Proj. No.	108816

Location .	Alameda, C	CA					Proj. No. <u>108816</u>
Depth (ft.)	Well Completion	Old (mdd)	Sample ID % Recovery	Blow Count Recovery	Graphic Log	ASTM/USCS	Description (Color, Texture, Structure) Geologic Descriptions are Based on ASTM/USCS.
- 26 - - 28 - - 30 -						SP- SM	Continued POORLY GRADED SAND WITH SILT; light olive brown (2.5Y 5/4); 92% fine to medium grained sand; 8% silt; wet
- 32 -					1261		TD=31 ft
					:		Note: Soil descriptions were generated from soil grab sample
- 34 -							Note: Soil descriptions were generated from soil grab sample specimens collected from the veins of hollow stem auger flytes. As a result, the depths of all descriptions and soil horizon boundaries are
- 36 -							approximate.
- 38 -							
- 40 -							
- 42 -	:						
_ 44 _							
-							
46 							
= - 48 -							
ANS.GD							
50 -							
전 년 - 52 -							
8/06 GI							
- 54 –							
- 56 -						;	
108816 DRILLING LOG Rev: 118/06 GINT.GPJ CALTRANS.GDT 11/13/06 8 9 9 6 7 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8							

SINGLE COMPLETION WELL DI	ETAILS Page: 4 of 5
PROJECT NUMBER: 108816	BORING/WELL NO.: MW4-2-15
PROJECT NAME: Alameda Pt CTO 133	TOP OF CASING ELEV.: <u>n/a</u> (MSL)
COUNTY: Alameda	CEMENT FLOOR ELEV.: 16.49 ft. (MSL)
WELL PERMIT NO.: <u>W2006-0447</u>	DATUM: CCS27, Zone 3, NAVD88
k M>	
	EXPLORATION BORING
	A. Total Depth 31 ft.
	B. Boring Diameter8 in.
G	Drilling Method Hollow Stem Auger
	y
	WELL CONSTRUCTION
	C. Casing Length (BGL) 31 ft.
	Material Sch 5, Type 304, Stainless Steel
	D. Casing Diameter in.
	E. Depth to Top of Screen
E H	F. Screen Length5 ft.
	Slotted Interval from <u>26</u> to <u>31</u> ft.
	Slot Type continuous wrap SS
	Slot Size 0.020 in.
	G. Surface Seal ft.
A C	Seal Materialn/a
	H. Annular Seal 22.25 ft.
	Seal Material Baselite I-II-V cement
	0.05
	i. Transition datid
	7.0
	J. Filter Pack 7.3 ft.
	Material RMC Pacific-Lapis Lustre # 2/16 sand
	K. Backfill ft.
	Material <u>n/a</u>
	L. Top of Casing Heightn/aft.
	M. Protective Cover Diameter4 in.
	MSL = mean sea level
	BGL = below ground level
H → B → H	



MW4-2-16 Page: 2 of 4 Monitoring Well

Project _	Alameda Pt	CTO 13	3			_ 0	wner <u>US Navy</u>	COMMENTS
	Alameda, (Proj. No. <u>108816</u>	Annular seal - Cement, Type I-II-V
	lev. (msl) <u>16</u>						North <u>470359</u> East <u>1481974</u>	Transition sand - RMC Pacific #60 sand
	sing <u>NA</u>					4.3 ft		Filter Pack - RMC Pacific, Lapis Lustre #2/16 sand
Screen: Di	ia <u>2 in.</u>		Length	5 ft.			Type/Size Sch 40 PVC/0.020 in.	Well Casing - Sch 5, Type 304
	ia <i>2 in</i> .						Type Sch 5, Type 304, Stainless Steel	Stainless Steel (SS) Screen - 0.020 in continuous
	al See Cor					_ Ri	g/Core	wrap, Sch 5, Type 304 SS Protective Casing - 4 in dia Sch
	WDC Explo			Meth	nod Ho		Stem Auger	40 CPVC
	Zimmer/J. Tr			_				Surface elevation value reflects
	By Eugene						No283326	surveyed raised floor.
C	1				 	il i		
_	io	_		iz int	ی	ျွ ဗ္ဂ	Description	
Depth (ft.)	Well	OIA (bpm)	Sample ID % Recovery	Blow Count Recovery	Graphic Log	ASTM/USCS	·	
	S	ן שַ שַ	San R.R	Blow	ַ פֿ	ST	(Color, Texture, Structur	•
<u> </u>	1					^	Geologic Descriptions are Based on A	451M/U5C5.
			i]		1 1		
			i]		1		
	$\ \cdot\ _{T_{T}}$		i	1			Depths are below ground level.	
- o -					<u> </u>	 		- Ir-rad assess Couttings
Ĺ <u> </u>				ļ			Initial hole cleared for utilities to five feet with above 5 feet not described.	nand auger. Cuttings
			i	ľ			45010 0 10011101 4002112021	
2 -			d d					
-								
L 4 ₩			i					
L . +			i					
-			i			1 1	POORLY GRADED SAND; brown (10YR 5)	/3): fine grained sand;
- 6 -			i				trace silt; wet	9/1
Į,			i					
			i			1 1		
8 -			i			1 1		
	₩ :\ _ :\		i			SP		
<u> </u>			i			3-		
J 10	:: <u> ::</u>		i					
-			i					
<u> </u>			i					
<u> </u>			i					
_			i			L_	 	
- 14 -	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		i			ML	~5 inches of Silt near bottom.	
<u>-</u>	∐ ∥		i				TD=14 ft	
2 46			i					
<u> </u>	1		i				Note: Soil descriptions were generated from	ı soil grab sample
 	1 1		i				specimens collected from the veins of hollow result, the depths of all descriptions and soil	v stem auger flytes. As a
_ 18 <i>_</i>	<u> </u>						approximate.	nonzon boundaries are
- T	1		i					
20 –	1 1		il					
]		il.					
			4					
22 –	1		i					
}} -	╢ ∥							
_ 24 _	<u> </u>							
<u>-</u>								
-	1							


SINGLE COMPLETION WELL D	ETAILS Page: 3 of 4
PROJECT NUMBER: 108816	BORING/WELL NO.: MW4-2-16
PROJECT NAME: Alameda Pt CTO 133	TOP OF CASING ELEV.: <u>n/a</u> (MSL)
COUNTY: Alameda	CEMENT FLOOR ELEV.: 16.46 ft. (MSL)
WELL PERMIT NO.: W2006-0448	DATUM: CCS27, Zone 3, NAVD88
← M —→	
- * *	EXPLORATION BORING
	A. Total Depth14 ft.
	B. Boring Diameter8 in.
	Drilling Method Hollow Stem Auger
	WELL CONSTRUCTION
	C. Casing Length (BGL)14 ft.
	Material Sch 5, Type 304, Stainless Steel
	D. Casing Diameter in.
	E. Depth to Top of Screen9 ft.
	F. Screen Length5 ft.
	Slotted Interval from 9 to 14 ft.
	Slot Type <u>continuous wrap SS</u>
	Slot Size 0.020 in.
	G. Surface Seal ft.
A C	Seal Material <u>n/a</u>
	H. Annular Seal6 ft.
	Seal Material Baselite I-II-V cement
	I. Transition Sand1 ft.
	Transition Material RMC Pacific #60 sand
	J. Filter Pack ft.
	Material RMC Pacific-Lapis Lustre # 2/16 sand
	K. Backfill ft.
	Material <u>n/a</u>
	L. Top of Casing Height <u>n/a</u> ft.
	M. Protective Cover Diameter4 in.
	MSL = mean sea level
	BGL = below ground level



Monitoring Well

MW4-2-17

Page: 2 of 5





Monitoring Well

MW4-2-17

Page: 3 of 5

 Project
 Alameda Pt CTO 133
 Owner
 US Navy

 Location
 Alameda, CA
 Proj. No. 108816

Description Color, Texture, Structure) Structure Color, Texture, Structure C	Location	Alameda, C	<u>A</u>					Proj. No. <u>108816</u>
WELL GRADED SAND WITH SILT; light yellowish brown (10YR 6/4); 90% fine to medium grained sand; 10% silt; wet TD=30 ft Note: Soil descriptions were generated from soil grab sample specimens collected from the veins of hollow stem auger flytes. As a result, the depths of all descriptions and soil horizon boundaries are approximate. 38 - 40 - 42 - 44 - 44 - 46 - 46 - 46 - 46 - 46	Depth (ft.)	Well	PID (ppm)	Sample ID % Recovery	Blow Count Recovery	Graphic Log	ASTM/USCS	(Color, Texture, Structure)
TD=30 ft Note: Soil descriptions were generated from soil grab sample specimens collected from the veins of hollow stem auger flytes. As a result, the depths of all descriptions and soil horizon boundaries are approximate. - 36	28 - - 28 -					100 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	sw	
result, the depths of all descriptions and soil horizon boundaries are approximate.	- 32 -							TD=30 ft
- 36	- 34 - - 34 -							result, the depths of all descriptions and soil horizon boundaries are
	- 36 -							
-	- 38 —							
	- 40 -							
46 -	- 42 -							
	_ 44 _							
- 48								
- 50	- 48 -							
- 52 - - 54 - - 56 - - 58 -	- - 50 -							
	- 52 -							
- 54 -	<u> </u>							
- 56 - 	- 54 - 							
[- ₅₈ -]	- 56 -							
/I	- 58 -							

SINGLE COMPLETION WELL DE	TAILS Page: 4 of 5
PROJECT NUMBER: 108816	BORING/WELL NO.: MW4-2-17
PROJECT NAME: Alameda Pt CTO 133	TOP OF CASING ELEV.: <u>n/a</u> (MSL)
	CEMENT FLOOR ELEV.: 16.48 ft. (MSL)
WELL PERMIT NO.: W2006-0557	DATUM: CCS27, Zone 3, NAVD88
COUNTY: Alameda WELL PERMIT NO.: W2006-0557 A C F F	
	MSL = mean sea level
κ <u>‡</u>	BGL = below ground level
l	



Monitoring Well

MW4-2-18 Page: 2 of 4

	Alameda Pt		3			_ 0	wner <u>US Navy</u>	COMMENTS
Location .	Alameda, (CA					Proj. No. <u>108816</u>	Annular seal - Cement, Type I-II-V
Surface Ele	ev. (msl <u>) 16</u>	.48 ft.	Total Hol	le Dept		0 ft.		Transition sand - RMC Pacific #60 sand
Top of Cas	sing <i>NA</i>		Water Le	evel Ini	tial 👱	4.5 ft		Filter Pack - RMC Pacific, Lapis Lustre #2/16 sand
Screen: Dia	a <u>2 in.</u>		Length	_5 ft.			Type/Size <u>Sch 40 PVC/0.020 in.</u>	Well Casing - Sch 5, Type 304
Casing: Dia			Length	6.5 ft	<u>!</u>		Type Sch 5, Type 304, Stainless Steel	Stainless Steel (SS) Screen - 0.020 in continuous
Fill Materia	See Co.	mments	. <u> </u>			_ Ri	g/Core Geoprobe 6620DT	wrap, Sch 5, Type 304 SS Protective Casing - 4 in dia Sch
Drill Co.	ResonantS	onic Inte	mational	Meth	nod Ho	llow S	Stem Auger	40 CPVC
Driller J. A	mbriz		Log By	Joe S	track		Date <u>8/28/06</u> Permit #_W2006-0721	Surface elevation value reflects
Checked B	y <u>Eugene</u>	Mulleni	neister, P	G	C57 Lic	ense	No. <u>283326</u>	surveyed raised floor.
			>	+		Ø		
\$ _	Well	ر آو	Sample ID % Recovery	Blow Count Recovery	ا ا ا	ASTM/USCS	Description	
Depth (ft.)	Well	PID (ppm)	Seginar Segina) wc	Graphic Log	TM/I	(Color, Texture, Structu	re)
	ŭ		₀₀ %	ăĽ		AS	Geologic Descriptions are Based on	ASTM/USCS.
i	l l							
							Depths are below ground level.	
n								
	M M						Asphalt and concrete debris.	·
	\bowtie							
- 2 -	\bowtie							
							POORLY GRADED SAND WITH SILT; dai	k yellowish brown; 90%
	\bowtie						very fine to fine sand; 10% silt; medium den	se; noncohesive; moist
1								
						SP		
 				İ				
- -							Concrete debris near 5 feet.	
				ļ				
├ 6 ┤							SILTY SAND; moderately yellowish brown;	very fine sand: 20% silt:
							wet	very line sand, 2070 sit,
 - -								
g _ 8 −								
1/13/								
						SM		
<u> </u>								
- 10 -								
룅 '								
<u> </u>								
9 46								
9/8/- 12 -							TD=11.5 ft	
9c: -								
<u>*</u>								
ğ 							Note: Soil descriptions were generated from	n soil grab sample
14							specimens collected from the veins of hollow	v stem auger flytes. As a
							result, the depths of all descriptions and soil approximate.	norizon boundaries are
- 182							арролинас.	
₽ _								

SINGLE COMPLETION WELL DETAILS Page: 3 of 4 PROJECT NUMBER: 108816 BORING/WELL NO.: MW4-2-18 PROJECT NAME: Alameda Pt CTO 133 TOP OF CASING ELEV .: n/a (MSL) COUNTY: Alameda CEMENT FLOOR ELEV.: 16.48 ft. (MSL) WELL PERMIT NO.: <u>W2006-0721</u> DATUM: CCS27, Zone 3, NAVD88 **EXPLORATION BORING** 12___ft. A. Total Depth B. Boring Diameter 8 in. G Hollow Stem Auger **Drilling Method** WELL CONSTRUCTION 11.5__ ft. C. Casing Length (BGL) Sch 5, Type 304, Stainless Steel Material D. Casing Diameter _ in. E. Depth to Top of Screen 6.3 _ ft. Н 5 ft. F. Screen Length Slotted Interval from 6.3 to 11.3 ft. continuous wrap SS Slot Type Slot Size 0.020 in. G. Surface Seal ft. C n/a Seal Material 3.5 H. Annular Seal Baselite I-II-V cement Seal Material 2 I. Transition Sand ft. Transition Material RMC Pacific #60 sand J. Filter Pack RMC Pacific-Lapis Lustre # 2/16 sand Material K. Backfill n/a Material n/a ft. L. Top of Casing Height M. Protective Cover Diameter in. MSL = mean sea level BGL = below ground level



MW4-2-19 Page: 2 of 4 Monitoring Well

Project .	Alameda Pt (CTO 133	3			_ Ov	vner <u>US Navy</u>	COMMENTS
Location	Alameda, C	:A					Proj. No. <u>108816</u>	Annular seal - Cement, Type I-II-V
	lev. (msl) <u>16.</u>		Total Hole	Deptl			North 470335 East 1481920	Transition sand - RMC Pacific #60 sand
Top of Ca	sing NA		Water Lev	el Init	ial 🛂	5.0 ft.		Filter Pack - RMC Pacific, Lapis Lustre #2/16 sand
Screen: [)ia <i>2 in</i> .		Length _	5 ft.			Type/Size <u>Sch 40 PVC/0.020 in.</u>	Well Casing - Sch 5, Type 304 Stainless Steel (SS)
)ia <u>2 in.</u>				·		Type Sch 5, Type 304, Stainless Steel	Screen - 0.020 in continuous
Fill Mater	ial See Con	nme <u>nts</u>					g/Core Geoprobe 6620DT	wrap, Sch 5, Type 304 SS Protective Casing - 4 in dia Sch
Drill Co.	ResonantSc	onic Inte				llow S	tem Auger	40 CPVC
Driller _				Joe St	rack		Date <u>8/24/06</u> Permit # <u>W2006-0722</u>	Surface elevation value reflects surveyed raised floor.
Checked	By <i>Eugene</i>	Mullenr	neister, PC	3	C57 Lic	ense	No. <u>283326</u>	
Depth (ft.)	Well	PID (mdd)	Sample ID % Recovery	Blow Count Recovery	Graphic Log	ASTM/USCS	Description (Color, Texture, Structur Geologic Descriptions are Based on	· ·
							Depths are below ground level.	
Γ"							POORLY GRADED SAND WITH SILT AN 90% very fine to fine sand; 10% fines; loose	D CLAY; olive brown;
1		,					moist	e, poor conesion, siightiy
ſ				1				
_ 2 -								
			 			SP-		
						SM		
ľ		ļ	1	ŀ				
١.								
4 -		.						
7								
-							SILTY SAND; wet to saturated	
F 6 -								
]					
†	1:: 1::]					
8 -	1 目:1					SM		
-			1					
<u> </u>	1: = 1							
3								
[- 10 ·	1:]					
7				ļ				
5	1:13							
5								
- 12 ·	1						TD=11.5 ft	
-								
ž	1							
- 14 ·							Note: Soil descriptions were generated fror specimens collected from the veins of hollo result, the depths of all descriptions and so approximate.	w stem auger flytes. As a
ğ		!				1		

SINGLE COMPLETION WELL DETAILS Page: 3 of 4 PROJECT NUMBER: 108816 BORING/WELL NO.: MW4-2-19 PROJECT NAME: Alameda Pt CTO 133 (MSL) TOP OF CASING ELEV .: n/a COUNTY: Alameda CEMENT FLOOR ELEV .: __16.51 ft.__(MSL) WELL PERMIT NO.: <u>W2006-0722</u> DATUM: CCS27, Zone 3, NAVD88 **EXPLORATION BORING** 12.5_ ft. A. Total Depth 8 __ in. B. Boring Diameter G **Drilling Method** Hollow Stem Auger WELL CONSTRUCTION 11.5 ft. C. Casing Length (BGL) Sch 5, Type 304, Stainless Steel Material 2___ in. D. Casing Diameter 6.3 ft. E. Depth to Top of Screen Н 5 F. Screen Length __ ft. Slotted Interval from 6.3 to 11.3 ft. continuous wrap SS Slot Type Slot Size 0.020 in. G. Surface Seal ft. C n/a Seal Material 3.5 H. Annular Seal Baselite I-II-V cement Seal Material 1.25 ft. I. Transition Sand Transition Material RMC Pacific #60 sand 5.2___ft. J. Filter Pack RMC Pacific-Lapis Lustre # 2/16 sand Material K. Backfill n/a Material n/a ft. L. Top of Casing Height M. Protective Cover Diameter in. MSL = mean sea level BGL = below ground level

Appendix D
System Installation Test Report

Installation and Testing Report for SPH Operations & Maintenance for Plume 4-2, Former Alameda NAS, Alameda, CA



Submitted October 23, 2006

Prepared by Thermal Remediation Services, Inc for Shaw Environmental & Infrastructure, Inc.

Purpose

The purpose of this report is to present a brief description of Thermal Remediation Services, Inc. (TRS) system installation and start up testing methods and results for the remedial work at Plume 4-2, Former Alameda NAS, Alameda, CA.

System Construction

Subsurface installation of the electrodes commenced on May 23, 2006 and continued until July 18, 2006 when drilling activities were stopped, at Shaw's direction, to further investigate contaminated liquids found in the vats of the Plate Shop, inside Building 360. Subsurface installation resumed on September 7, 2006 and concluded on September 19, 2006. Ninety-one electrodes, seventeen groundwater monitoring wells, and fourteen temperature monitoring points were installed by the TRS drilling subcontractor. The as-built information for the above mentioned system components are attached with this document.

The surface equipment was delivered in three different phases, with electrode cables and the vapor recovery (VR) blower received on June 27, 2006, the Power Control Unit (PCU) received on June 29, 2006, and the condenser unit/cooling tower received on September 19, 2006. The condenser unit and the cooling tower were placed inside a 20' x 40' x 4" secondary containment berm. Interlock wiring was completed on all of TRS' equipment on October 3, 2006.

The VR blower unit is a skid mounted 40 horsepower rotary displacement blower, equipped with inlet and discharge silencers, housed inside an insulated sound enclosure. The control components are permanently mounted on the exterior of the enclosure for simplification of installation and operation. This unit was tested at the manufacturer's facility prior to delivery and has been field tested for proper operation at one other site prior to installation at Alameda NAS and maintenance has been completed in accordance with the manufacturer's specifications.

The TRS PCU is a 2,000 kilowatt (kW), self contained, variable output transformer. The unit is housed in an 8' x 8' x 40' modified shipping container. A control room is situated at one end where the unit can be operated, manually or remotely, by the integrated computer and programmable logic controller (PLC) system.

The TRS steam condenser consists of two skid-mounted units. One unit contains a water-cooled plate heat exchanger, two condensate storage tanks (knock-out pots), condensate pump, condensate filter, recycle pump, blowdown pump, and the control components and valves to operate the system, all housed in an insulated, galvanized steel enclosure. The second unit consists of a cooling tower and cooling fan. These units were factory tested for leaks and functionality prior to shipment to the site.

Vapor recovery piping and treatment system construction commenced on July 17, 2006 and was completed with the addition of the vapor granular activated carbon (GAC) vessels on October 7, 2006. The VR system is constructed with schedule 40 CPVC (chlorinated

polyvinyl chloride) pipe and schedule 80 CPVC pipe fittings influent of the condenser unit. Post condenser materials include schedule 80 PVC pipe and fittings, polypropylene cam and lock fittings, and PVC suction hose.

Electrical power was brought to the site and connected to the PCU during the week ending September 1, 2006.

The liquid hold up vessel (6,500 gallon high density polyethylene tank) was delivered to the site on September 26, 2006 and placed inside a 24' diameter by 28" high secondary containment berm. A float switch was installed in the tank and interlocked to shut down the SPH system in the event of a high tank liquid level condition.

The condensate treatment system construction was initiated on October 3, 2006 with the arrival of the liquid GAC vessels. Construction of the condensate treatment system was completed on October 17, 2006. The system is constructed with schedule 80 CPVC pipe, fittings, and PEX® tubing and fittings.

As-built drawings for the installation locations of each of the components are attached with this document.

System Quality Inspections and Testing

Quality control inspections of the heating and treatment system were performed in accordance with TRS' standard operating procedures, and are divided into five steps:

- 1. Integrity and completion of the vapor recovery piping
- 2. Function testing of the treatment system components
- 3. Step-and-touch voltage safety checks
- 4. Subsurface energy application evaluation (start up)
- 5. Subsurface vacuum influence evaluation

Vapor Recovery Piping Inspections

Inspection of the vapor recovery system requires first a visual inspection of each of the joined components (glue joints) as well as inspecting the integrity of the vapor recovery piping itself. Upon achieving a satisfactory result of the visual inspection, the inspection is conducted again with the vacuum blower operating, simulating normal site conditions. This test involves visually and audibly inspecting the entire VR piping system for leaks.

The vacuum blower was activated for testing on October 7, 2006, at an operating vacuum of approximately 3" Hg. Due to higher than expected groundwater levels in the treatment area, the applied field vacuum was limited during testing to prevent the collection of excessive water from the subsurface. This was accomplished by opening the dilution air valve at the vapor recovery blower inlet. Visual and audible inspections were conducted over a span of 90 minutes. No leaks were found in the VR piping system.

On October 18, 2006, vacuum gauge connections were installed at the end of each vapor recovery header (thirty total) to verify vacuum influence over the entire VR piping system. All thirty test locations indicated negative pressures, confirming vacuum application throughout the entire VR piping system.

Treatment System Function Tests

Testing of the treatment system commenced on September 25, 2006. The condenser cooling tower sump was filled with water and the condenser operation was initiated. Items inspected include checks for leaks and functionality (hand/off/auto switches, float switches, valves), and the ability to maintain normal operation. Once functionality was determined satisfactory, equipment interlock testing commenced. Testing of interlocks took place between September 27, 2006 and October 6, 2006 and performed as designed.

The condensate treatment system was tested for readiness by initiating the system under normal operating conditions and visually inspecting all connections for leaks. The system was also verified for the proper operational parameters (flow, differential pressures, and applied field vacuum) on all gauges and valves. The discharge line to the POTW discharge point was tested with potable water and inspected for leaks at each connection over the entire length of the line. Final testing was completed on October 17, 2006. No leaks were found in the conveyance piping, liquid granular activated carbon vessels, and the treated condensate discharge line to the POTW discharge point. Each of these tests was deemed satisfactory. An as-built process-flow diagram is included with this document.

Step-and-Touch Voltage Safety Tests

This test is a critical safety test for application of the heating technology. Refer to the submitted Standard Operating Procedures (SOPs) "ALA05 Voltage Safety Survey SOP 1.0 100406 acf.pdf" and "ALA05 Exclusion Zone Entry SOP 2.0 100506 acf.pdf". The electrode field was initially energized on October 3, 2006 for step and touch, and step and step voltage safety testing. No voltage potential in any area around the site was greater than the 15 volt limit in dry conditions. After a rain event on October 5, 2006, the grout seals on eight of the electrodes on the south side of the exterior of the Building 360 annex had elevated voltage potentials. TRS has electrically isolated the grout seals with a suitable elastomer to provide the required electrical isolation and covered this material with plywood to protect the elastomer from the outdoor elements. An additional voltage survey was conducted on October 18, 2006, after the final electrode cabling configuration was completed. No voltage potential in any area around the site was greater than the 15 volt limit. The voltage survey results are attached with this document.

Subsurface Energy Application Evaluation

System testing and energy application evaluation commenced on October 3, 2006. TRS initiated applying electrical energy to the electrode field to evaluate the electrical conditions of the load (treatment volume). The evaluation includes observations of cable/electrode amperage as well as an overall evaluation of the electrical balance of the load. This

evaluation was conducted over night on October 7, 2006. This pre-operation test indicates we will be operating at approximately 150 to 300 volts and well within the amperage limits of the delivery cables.

Subsurface Vacuum Influence Evaluation

Vacuum influence on the site is measured at vacuum piezometers installed at each temperature monitoring point location (14). The results of the piezometer vacuum measurements are included with this document. Due to higher than expected groundwater levels in the treatment area, the applied field vacuum is being limited to prevent collecting excessive water from the subsurface. This is accomplished by opening the dilution air valve at the vapor recovery blower inlet.

As of October 20, 2006, TRS has completed installation and testing of the SPH system at Plume 4-2, Former Alameda NAS, Alameda, CA. The system is ready for full operation, and will commence upon written approval from Shaw Environmental & Infrastructure.

e III.			ĮI.	12					
	Project:	ALA05		Electrod	le, TMP,	& Monit	oring W	ell As-Bu	tilt Construction Data
Date Completed	Electrode	Total (Refusal) Depth	Bottom of Casing	Bottom of Conductive Zone	Top of Conductive Zone	Bottom of Vent	Top of Vent	TRS Personnel	Other Notes
REGION 1 (20 Ele Not installed	C5		Transcription of the latest and the	- Tableson		Total Control	1 CONTROL STATE	Annalisation	Not installed, due to obstruction/refusal in area
6/22/2006 6/22/2006	C6 C7	41	39.5 39.5	41	6.75 7	13.5 13.5	3	Cossins	
6/25/2006	D4	41	39.5	41	7	13.5	3	Cossins	
- 6	D5 D6	41	39.5 39.5	41	7	13.5 13.5	3	Cossins Cossins	
719/2006	D7	41 41	39.5 39.5	41 41	7	13.5 13.5	3	Cossins Cossins	
7/8/2006	E4	41	39.5	41	7	13.5	3	Cossins	
6/21/2006 6/15/2006	E5	41	39.5 40.5	41	7	13.5 14.5	3 1*	Cossins Pierce	Electrode had to be re-drilled due to bridging problems during consruction.
7/10/2006 6/2/2006	E7 E8	41	39.5 39.5	41	7	13.5 13.5	3	Cossins Knight	
6/23/2006	E9 F4	41	39.5 39.5	41	7	13.5	3	Cossins	
6/20/2006 6/20/2006	F5	41	39.5	41	7	13.5	3	Cossins Cossins	
6/16/2006 6/1/2006	F6 F7	41	41 39.5	41	7	14 13.5	3' 1"	Pierce Cossins	
7/8/2006 6/15/2006	F8 G5	40.5 41	39.5 39.5	40.5 41	7	13.5 13.5	3	Cossins Pierce	
REGION 1	AVERAGES:	41.0	39.6	41.0	7.0	13.6	3	(C)	
6/1/2006	F9	30.25	27.5	30.25	7	13.5	3	Cossins	
6/23/2006 6/1/2006	F10 G9	30 30.2	27.5 27.5	30 30.2	7	13.5 13.5	3	Cossins Cossins	
5/23/2006 6/22/2006	G10 G11	30 30	27 27.5	30 30	7	13.5 13.5	3	Cossins	
6/2/2006	H10	30.5	27.5	30.5	7	13.5	3	Knight	
5/30/2006 6/3/2006	H11 J11	30 30.5	27 27	30 30.5	7	13.5 13.5	3	Cossins Knight	
6/29/2006 9/8/2006	J12 K12	30 30	27.5 27	30 30	7	13.5 13.5	3	Cossins Pierce	
9/7/2006 9/18/2006	K13 L13	30.25 30	28.5 27.5	30.25 30	7.2	13.7 13.5	3	Pierce Rianda	
9/7/2006	L14	30	27.5	30.3	7	13.5	3	Pierce	
REGION 3 (8 Elec	AVERAGES: trodes)	30.1	27.4	30.2	7.0	13.5	3		
9/13/2006 6/5/2006	M14 N14	19 19	17	19 19	7	13.5	3	Rianda Bianco	
6/3/2006 6/4/2006	N15 P14	19.5 19	17	19.5 19	7	13.5 13.5	3	Knight Knight	
6/3/2006	P15	19	17	19	7	13.5	3	Knight	
6/4/2006 6/3/2006	Q15 Q16	19.5 19.5	17	19.5 19.5	7	13.5 13.5	3	Knight Knight	
6/4/2006 REGION 3	R16 AVERAGES:	19.5 19.3	17	19.5 19.3	7	13.5	3	Knight	
5/30/2006	G6	45	45	45	7	13.5	3	Knight	
7/7/2006 7/8/2006	G7 G8	45 45	45 45	45 45	7	13.5 13.5	3	Cossins	Additional grout in interior of oversieeve to adjust for off-center fit at grade surface
7/7/2006	H6 H7	45 45	45 45	45 45	7	13.5	3	Cossins	
5/25/2006 5/26/2006	Н8	45.5	45	45	7	13.5	3	Cossins Knight	
6/29/2006 5/25/2006	H9 J7	45 45.5	45 45	45 45	7	13.5 13.5	3	Cossins Cossins	
5/31/2006 6/29/2006	18 28	45.5 45	45 45	45 36	7	13.5 13.5	3	Cossins	Re-drilled due to excessive heave up to water table surface (5' bgs), experienced more heave after re-drill, a lot of sand likely intermixed with the conductive backfill
6/4/2006 6/29/2006	J10 K8	45.5 45	45 45	45.5 45	7 6.5	13.5 13.5	3	Knight Cossins	
6/6/2006 6/5/2006	K9 K10	45.5 45	45 45	40 45	7	13.5 13.5	3	Knight Bianco	Augers left in borehole overnight, bottome five feet filled with sand
6/4/2006	K11	45.5	45	45.5	7	13.5	3	Knight	
5/24/2006 6/5/2006	L9 L10	45 45	44 45	45 45	7	13.5 13.5	3	Cossins Knight	
3	L11 L12	45 45	45 45	45 45	7	13.5	3	Pierce Rianda	
006	M10 M11	45 45	45 45	45 45	7	13.5 13.5	3	Pierce Pierce	
9/14/2006 9/19/2006	M12 M13	45 45	45 45	45 45	7	13.5 13.5	3	Rianda Pierce	
9/11/2006 9/12/2006	N11 N12	45 45	45 45	45 45	7	13.5 13.5	3 3	Pierce Pierce	
9/14/2006 9/11/2006	N13 P12	45 45	45 45	45 45	8 7	13.5	3 3	Rianda	
9/13/2006	P13	45	45	45	7	13.5	3	Knight Pierce	
REGION 5 (23 EI		45.1	45.0	44.5	7,0	13.5	3	and the second	
6/27/2006 6/16/2006	E3 F3	36 41	34.5 34.5	36 36	7	13.5 13.5	3	Cossins Pierce	
6/19/2006 6/19/2005	G3 G4	36 36'	34.6 34.5	36 36	7.1	13.6 13.5	3.1	Pierce Cossins	
6/16/2006	H4	36	35.5	36	7	14.5	3.1	Pierce	
6/16/2006 6/27/2006	H5 J5	36 36	34.5 34.5	36 36	7	13.5 13.5	3	Pierce Cossins	
6/1/2006 6/16/2006	J6 K6	36 36	34.25 34.5	36 36	7	13.25 13.5	2.8	Knight Pierce	
6/1/2006 6/2/2006	K7	36 36	34.3 34.5	36 36	7	13.25 13.5	2.8	Knight Knight	
6/1/2006 6/6/2006	L8 M9	36 36	34.5 34.5	36 36	7	13.5	3	Knight Bianco	
6/6/2006 6/13/2006	N10 P11	36 36	34.5 34.5	36 36	7	13.5	3	Bianco	
6/12/2006	Q12	36	36	36	7	15	3.2	Bianco	
6/13/2006 6/14/2006	Q13 Q14	36 36	34.5 34.5	36 36	7	13.5 13.5	3	Pierce Pierce	
6/6/2006 6/13/2006	R13 R14	36 36	34.5 34.5	36 36	7	13.5 13.5	3	Knight Pierce	
6/14/2006 6/15/2006	R15	36 36	36 35.5	36 36	7 7	15.5 14.5	3.1 3.1	Pierce Pierce	
6/15/2006	S16	36	34.5	36	7	13.5	3	Pierce	
	Averages:	36.2 37.6	34.7 36.3	36 37.4	7.0	13.7	3.0		
Date Completed	ТМР	REGION	Grade Completion	Total Depth	Bottom of Casing	Vacuum F	lezometer alled	TRS Personnel	
6/13/2006 6/15/2006	G07 P11	4 5	Above Above	45.0 35.0	45 35	Y	9S 9S	Pierce	Due to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6"


	G5	41	39.5	41	7	13.5	3	Pierce	
	AVERAGES:	41.0	39.6	41.0	7.0	13.6	3	STATE OF THE PARTY.	
6/1/2006	F9	30.25	27.5	30.25	7	13.5	3	Cossins	
6/23/2006	F10	30	27.5	30	7	13.5	3	Cossins	
6/1/2006 5/23/2006	G9 G10	30.2 30	27.5 27	30.2 30	7	13.5 13.5	3	Cossins Cossins	
6/22/2006	G11	30	27.5	30	7	13.5	3	Cossins	
6/2/2006	H10	30.5	27.5	30.5	7	13.5	3	Knight	
5/30/2006 6/3/2006	H11 J11	30 30.5	27	30 30.5	7	13.5 13.5	3	Cossins Knight	
6/29/2006	J12	30	27.5	30	7	13.5	3	Cossins	
9/8/2006	K12	30 30.25	27 28.5	30 30.25	7.2	13.5 13.7	3	Pierce Pierce	
9/7/2006 9/18/2006	K13 L13	30.25	28.5	30.25	7.2	13.7	3	Pierce Rianda	
9/7/2006	L14	30	27.5	30.3	7	13.5	3	Pierce	
REGION 2	AVERAGES:	30.1	27.4	30.2	7.0	13.5	3	100000	
9/13/2006 8 Elect	trodes) M14	19	17	19	7	13.5	3	Rianda	
6/5/2006	N14	19	17	19	7	13.5	3	Bianco	
6/3/2006	N15	19.5	17	19.5	7	13.5	3	Knight	
6/4/2006 6/3/2006	P14 P15	19 19	17	19 19	7	13.5	3	Knight Knight	
6/4/2006	Q15	19.5	17	19.5	7	13.5	3	Knight	
6/3/2006	Q16 R16	19.5	17	19.5 19.5	7	13.5 13.5	3	Knight	
6/4/2006 REGION 3		19.5	17	19.5	7	13.5	3	Knight	
REGION 4 (28 Elec	ctrodes)	AND PROPERTY.	diam'r.	NO ASSESSED	STREET, ST	200 V/200	132 (2021)		
5/30/2006	G6 G7	45 45	45	45 45	7	13.5 13.5	3	Knight Cossins	Additional grout in interior of oversleeve to adjust for off-center fit at grade surface
7/7/2006 7/8/2006	G7 G8	45	45 45	45	7	13.5	3	Cossins	учили на учил и имети и именателе на вирал на интелета ил вл. учил винаме
7/7/2006	H6	45	45	45	7	13.5	3	Cossins	
5/25/2006 5/26/2006	H7 H8	45 45.5	45 45	45 45	7	13.5	3	Cossins Knight	
6/29/2006	Н9	45	45	45	7	13.5	3	Cossins	
5/25/2006	J7	45.5	45	45	7	13.5	3	Cossins	
5/31/2006 6/29/2006	J8 J9	45.5 45	45 45	45 36	7 7	13.5 13.5	3	Cossins	Re-drilled due to excessive heave up to water table surface (5' bgs), experienced more heave after re-drill, a lot of sand likely intermixed with the conductive backfill
6/4/2006	J10	45.5	45	45.5	7	13.5	3	Knight	and a process and a company of the c
6/29/2006	K8	45	45	45	6.5	13.5	3	Cossins	August 18 to backed a manifold between the feet filed with energ
6/6/2006 6/5/2006	K9 K10	45.5 45	45 45	40 45	7	13.5 13.5	3	Knight Bianco	Augers left in borehole overnight, bottome five feet filled with sand
6/4/2006	K10 K11	45.5	45	45.5	7	13.5	3	Knight	
5/24/2006	L9	45	44	45	7	13.5	3	Cossins	
6/5/2006	L10 L11	45 45	45 45	45 45	7	13.5	3	Knight Pierce	
3	L12	45	45	45	7	13.5	3	Rianda	
06	M10 M11	45 45	45 45	45 45	7	13.5 13.5	3	Pierce Pierce	
9/14/2006	M12	45	45 45	45	7	13.5	3	Rianda	
9/19/2006	M13	45	45	45	7	13.5	3	Pierce	
9/11/2006 9/12/2006	N11 N12	45 45	45 45	45 45	7	13.5 13.5	3 3	Pierce Pierce	
9/14/2006	N13 P12	45	45	45	8	13.5	3	Rianda	
9/11/2006		45	45	45	7	13.5	3	Knight	
9/13/2006 REGION 4	P13 AVERAGES:	45.1	45 45.0	45 44.5	7.0	13.5	3	Pierce	
REGION 5 (23 Ele	ctrodes)				. 45 . SA		225500	200 Miles	
6/27/2006	E3	36	34.5	36	7	13.5	3	Cossins	
6/16/2006 6/19/2006	F3 G3	41 36	34.5 34.6	36 36	7.1	13.5 13.6	3.1	Pierce Pierce	
6/19/2005	G4	36'	34.5'	36	7	13.5	3	Cossins	
6/16/2006 6/16/2006	H4 H5	36 36	35.5 34.5	36 36	7	14.5 13.5	3.1	Pierce Pierce	
6/27/2006	J5	36	34.5	36	7	13.5	3	Cossins	
6/1/2006	J6	36	34.25	36	7	13.25	2.8	Knight	
6/16/2006 6/1/2006	K6 K7	36 36	34.5 34.3	36 36	7	13.5 13.25	2.8	Pierce Knight	
6/2/2006	L7	36	34.5	36	7	13.5	3	Knight	
6/1/2006 6/6/2006	L8 M9	36 36	34.5 34.5	36 36	7	13.5 13.5	3	Knight Bianco	
6/6/2006	N10	36	34.5	36	7	13.5	3	Bianco	
014070000			34.5	36	7	13.5	3	Pierce	-
6/13/2006	P11	36	200	36	7	15 13.5	3.2	Bianco Pierce	
6/12/2006	Q12	36	36	36	7	13.5	3	Pierce	
6/12/2006 6/13/2006 6/14/2006	Q12 Q13 Q14	36 36 36	36 34.5 34.5	36 36		70.0			
6/12/2006 6/13/2006 6/14/2006 6/6/2006	Q12 Q13 Q14 R13	36 36 36 36	36 34.5 34.5 34.5	36 36	7	13.5	3	Knight	
6/12/2006 6/13/2006 6/14/2006	Q12 Q13 Q14 R13 R14 R15	36 36 36 36 36 36	36 34.5 34.5 34.5 34.5 34.5	36 36 36 36	7 7 7	13.5 13.5 15.5	3.1	Pierce Pierce	
6/12/2006 6/13/2006 6/14/2006 6/6/2006 6/13/2006 6/14/2006 6/15/2006	Q12 Q13 Q14 R13 R14 R15 S15	36 36 36 36 36 36 36 36	36 34.5 34.5 34.5 34.5 36 35.5	36 36 36 36 36	7 7 7 7	13.5 13.5 15.5 14.5	3 3.1 3.1	Pierce Pierce Pierce	
6/12/2006 6/13/2006 6/14/2006 6/16/2006 6/13/2006 6/14/2006 6/15/2006 6/15/2006	Q12 Q13 Q14 R13 R14 R15 S15	36 36 36 36 36 36 36 36 36	36 34.5 34.5 34.5 34.5 36 35.5 34.5	36 36 36 36 36 36 36	7 7 7 7 7	13.5 13.5 15.5 14.5 13.5	3 3.1 3.1 3	Pierce Pierce	
6/12/2006 6/13/2006 6/14/2006 6/6/2006 6/13/2006 6/14/2006 6/15/2006 6/15/2006 REGION 5	Q12 Q13 Q14 R13 R14 R15 S15 S16 AVERAGES:	36 36 36 36 36 36 36 36 36 36	36 34.5 34.5 34.5 34.5 36 35.5 34.5 34.7	36 36 36 36 36 36 36	7 7 7 7 7 7	13.5 13.5 15.5 14.5 13.5	3 3.1 3.1 3 3.0	Pierce Pierce Pierce	
6/12/2006 6/13/2006 6/14/2006 6/6/2006 6/15/2006 6/15/2006 6/15/2006 REGION 5 Total Site	Q12 Q13 Q14 R13 R14 R15 S15 S16 AVERAGES; Averages:	36 36 36 36 36 36 36 36 36 37 36 37	36 34.5 34.5 34.5 34.5 36 35.5 34.5	36 36 36 36 36 36 36 37.4	7 7 7 7 7	13.5 13.5 15.5 14.5 13.5 13.7 13.6 Vacuum F	3 3.1 3.1 3 3 3.0 3.0 2 2 3.0 2 3.0	Pierce Pierce Pierce	
6/12/2006 6/13/2006 6/14/2006 6/6/2006 6/13/2006 6/13/2006 6/15/2006 6/15/2006 REGION 5 Total Site	Q12 Q13 Q14 R13 R14 R15 S15 S16 AVERAGES: TMP	36 36 36 36 36 36 36 36 37 36 37.6 REGION	36 34.5 34.5 34.5 36 35.5 34.7 36.3 Grade Completion	36 36 36 36 36 36 37.4 Total Depth	7 7 7 7 7 7 7.0 7.0 8ottom of Casing	13.5 13.5 15.5 14.5 13.5 13.7 13.6 Vacuum P	3 3.1 3.1 3 3.0 3.0 3.0 Plezometer	Pierce Pierce Pierce Pierce TRS Personnel	Due to consists a conditional constitute of the 3 fina a conditions the 50 fina a conditions in 6".
6/12/2006 6/13/2006 6/14/2006 6/6/2006 6/6/2006 6/14/2006 6/14/2006 6/15/2006 REGION 5 Total Site Date Completed 6/13/2006	Q12 Q13 Q14 R13 R14 R15 S15 S16 AVERAGES: AVERAGES: TMP	36 36 36 36 36 36 36 36 36 37.6 REGION	36 34.5 34.5 34.5 34.5 36 35.5 34.5 34.7 36.3 Grade Completion Above	36 36 36 36 36 36 36 37.4	7 7 7 7 7 7.0 7.0 Bottom of	13.5 13.5 15.5 14.5 13.7 13.6 Vacuum F	3 3.1 3.1 3 3 3.0 3.0 2 2 3.0 2 3.0	Pierce Pierce Pierce Pierce TRS Personnel	Oue to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6"
6/12/2006 6/13/2006 6/14/2006 6/6/2006 6/13/2006 6/14/2006 6/15/2006 REGION 5 Total Site Date Completed 6/13/2006 6/15/2006	Q12 Q13 Q14 R13 R14 R15 S15 S16 AVERAGES: AVERAGES: TMP G07 P11 P15	36 36 36 36 36 36 36 36 37 36 37.6 REGION	36 34.5 34.5 34.5 34.5 36 35.5 34.7 36.3 Grade Completion Above Above	36 36 36 36 36 36 37.4 Total Depth 45.0 19.0	7 7 7 7 7 7 7 7 7 7 7 7 7 0 8 6 6 6 6 6 6 6 7 6 7 7 7 7 7 7 7 7 7 7	13.5 13.5 15.5 14.5 13.7 13.6 Vacuum P Inst	3 3.1 3.1 3.0 3.0 3.0 Plezometer alled es	Pierce Pierce Pierce Pierce Pierce Pierce TRS Personnel Pierce Pierce Pierce	Oue to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6" Oue to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout intrusion past the 3" fine sand layer is 6" Due to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6"
6/12/2006 6/13/2006 6/14/2006 6/14/2006 6/13/2006 6/15/2006 6/15/2006 6/15/2006 7 Total Site Date Completed 6/13/2006 6/15/2006 6/15/2006 6/15/2006	Q12 Q13 Q14 R13 R14 R15 S15 S16 AVERAGES: AVERAGES: TMP G07 P11 P15 H10	36 36 36 36 36 36 36 36 36 36 2 37.6 REGION 4 5 3	36 34.5 34.5 34.5 36 35.5 34.7 36.3 Grade Completion Above Above Above	36 36 36 36 36 36 37.4 Total Depth 45.0 35.0 19.0 29.0	7 7 7 7 7 7 7 7 7 7 7 0 8ottom of Casing 45 35 45 29	13.5 13.5 15.5 14.5 13.5 13.7 13.6 Vacuum F Inst	3 3.1 3.1 3 3.0 3.0 3.0 Plezometer alled es	Pierce Pierce Pierce Pierce Pierce TRS Personnel Pierce Pierce Pierce Pierce	Due to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6"
6/12/2006 6/13/2006 6/14/2006 6/13/2006 6/13/2006 6/13/2006 6/13/2006 6/13/2006 6/13/2006 6/13/2006 6/13/2006 6/13/2006 6/13/2006 6/13/2006 6/13/2006 6/13/2006	Q12 Q13 Q14 R13 R14 R15 S15 S16 AVERAGES: AVERAGES: TMP G07 P11 P15 H10 K08	36 36 36 36 36 36 36 36 36 38 2 37.6 REGION 4 5 3	36 34.5 34.5 34.5 34.5 36 35.5 34.7 36.3 Grade Completion Above Above Above Above Above Above Above Above	36 36 36 36 36 36 37.4 Total Depth 45.0 35.0 19.0 29.0 45.0 35.0	7 7 7 7 7 7 7 7 7 7 7 0 8ottom of Casing 45 45 45 29 45 35	13.5 13.5 15.5 14.5 13.7 13.6 Vacuum F Inst Y Y Y Y	3 3.1 3.1 3.0 3.0 3.0 3.0 2lezometer alled es	Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce	Due to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6"
6/12/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/15/2006 6/15/2006 7 Total Site Date Completed 6/15/2006 6/15/2006 6/15/2006 6/15/2006 6/15/2006 6/15/2006 6/15/2006 6/14/2006 6/14/2006	Q12 Q13 Q14 R13 R14 R15 S16 S16 AVERAGES: AVERAGES: TMP G07 P11 P15 H10 K08 J05	36 36 36 36 36 36 36 36 36 36 37 36 37 37 4 5 3	36 34.5 34.5 34.5 34.5 36 35.5 34.7 36.3 Grade Completion Above Above Above Above Above Above Above	36 36 36 36 36 36 37.4 Total Depth 45.0 35.0 19.0 29.0 45.0 35.0 40.0	7 7 7 7 7 7 7 7 7 7 7 7 7 8 8 8 8 8 8 8	13.5 13.5 15.5 14.5 13.5 13.7 13.6 Vacuum P Instr Y Y Y Y Y	3 3.1 3.1 3.0 3.0 3.0 2Plezometer alled es es es	Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce	Due to possible grout influsion past the 3" fines sand layer, the fine sand layer is 6" Due to possible grout influsion past the 3" fines sand layer, the fine sand layer is 6" Due to possible grout influsion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout influsion past the 3" fine sand layer, the fine sand layer is 6"
6/12/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/15/2008 REGION 3 Total Site Date Completed 6/15/2006 6/15/2006 6/15/2006 6/15/2006 6/15/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006	Q12 Q13 Q14 R13 R14 R15 S15 S15 S16 AVERAGES: TMP G07 P11 P15 H10 K08 J05 C07 D04	36 36 36 36 36 36 36 36 36 38 2 37.6 REGION 4 5 3	36 34.5 34.5 34.5 34.5 36 35.5 34.7 36.3 36.3 37.5 34.7 36.3 4.7 36.3 4.7 36.3 4.7 4.7 4.7 4.7 4.7 4.7 4.7 4.7 4.7 4.7	36 36 36 36 36 36 37.4 Total Depth 45.0 35.0 19.0 29.0 45.0 35.0	7 7 7 7 7 7 7 7 7 7 7 0 8ottom of Casing 45 45 45 29 45 35	13.5 13.5 15.5 14.5 13.5 13.7 13.6 Vacuum F Inst Y Y Y Y Y Y Y	3 3.1 3.1 3.0 3.0 3.0 3.0 2lezometer alled es	Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce Pierce	Due to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6"
6/12/2006 6/14/2006	Q12 Q13 Q14 R13 R14 R15 S16 S16 Averages: TMP G07 P11 H10 K08 J05 C07 D04 Q13 M12	36 36 36 36 36 36 36 36 36 36 38 2 37.6 REGION 4 5 3 2 4 4 5	36. 34.5 34.5 34.5 34.5 36.3 35.5 34.5 36.3 Grade Completion Above	36 36 36 36 36 36 37.4 Total Depth 45.0 35.0 19.0 29.0 45.0 35.0 40.0 40.0 45.0	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 8 8 8 8	13.5 13.5 15.5 14.5 13.7 13.6 Vacuum F Y Y Y Y Y Y Y Y	3 3.1 3.1 3.0 3.0 3.0 3.0 2.0 2 2 2 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	Pierce Pierce	Due to possible grout influsion past the 3" fines sand layer, the fine sand layer is 6" Due to possible grout influsion past the 3" fines sand layer, the fine sand layer is 6" Due to possible grout influsion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout influsion past the 3" fine sand layer, the fine sand layer is 6"
6/12/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/15/2006	Q12 Q13 Q14 R13 R14 R15 S15 S15 S15 S15 S16 Verages: TMP G07 P11 P15 H10 K08 J05 C07 D04 G13 M12 F63	36 36 36 36 36 36 36 36 36 36 36 36 36 2 37.6 REGION 4 5 5 1 1 1 5	36. 34.5 34.5 34.5 34.5 36.3 35.5 34.5 36.3 Grade Completion Above	36 36 36 36 36 36 37.4 Total Depth 45.0 35.0 19.0 29.0 45.0 35.0 40.0 40.0 40.0	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 8	13.5 13.5 13.5 15.5 14.5 13.7 13.6 Vacuur Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	3 3.1 3.1 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0	Pierce Cossins	Due to possible grout influsion past the 3" fines sand layer, the fine sand layer is 6" Due to possible grout influsion past the 3" fines sand layer, the fine sand layer is 6" Due to possible grout influsion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout influsion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout influsion past the 3" fines sand layer, the fine sand layer is 6" Due to possible grout influsion past the 3" fines sand layer, the fine sand layer is 6" Due to possible grout influsion past the 3" fines sand layer, the fine sand layer is 6"
6/12/2006 6/14/2006	Q12 Q13 Q14 R13 R14 R15 S16 S16 Averages: TMP G07 P11 H10 K08 J05 C07 D04 Q13 M12	36 36 36 36 36 36 36 36 36 36 38 2 37.6 REGION 4 5 3 2 4 4 5	36. 34.5 34.5 34.5 34.5 36.3 35.5 34.5 36.3 Grade Completion Above	36 36 36 36 36 36 37,4 Total Depth 45,0 19,0 45,0 19,0 45,0 45,0 45,0 45,0 45,0 45,0 45,0 45	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	13.5 13.5 15.5 14.5 13.5 13.7 13.7 13.7 13.7 Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	3 3.1 3.1 3.1 3.1 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0	Pierce Right	Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Re-located closer to F07
6/12/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/15/2006 7 Total Site Date Completed 6/15/2006	Q12 Q13 Q14 R13 R14 R15 S15 S16 AVERAGES: AVERAGES: AVERAGES: OC7 P11 H10 K88 J05 C07 D04 Q13 M12 F03 F04	36 36 36 36 36 36 36 36 36 36 36 36 36 3	36 34.5 34.5 34.5 34.5 34.5 34.5 36 35.5 36.3 36.3 36.3 36.3 36.3 36.3	36 36 36 36 36 37.4 Total Depth 45.0 35.0 19.0 45.0 35.0 40.0 40.0 35.0 40.0 35.0	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	13.5 13.5 15.5 14.5 13.5 13.7 13.7 13.7 13.7 Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	3 3.1 3.1 3.1 3.1 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0	Pierce Pierce	Due to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6" Oue to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6" Oue to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6" Oue to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6" Oue to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6" Oue to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6" Oue to possible grout intrusion past the 3" fine sand layer, the fine sand layer is 6"
6/12/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/15/2006	Q12 Q13 Q14 R13 R14 R15 S15 S15 S15 S46 AVERAGES: AVERAGES: TMP GG7 P11 P15 H10 K08 J05 CG7 GG7 Q13 M12 FG3 FG3 FG3 FG3 FG3 FG3 FG3 FG3 FG3 FG3	36 36 36 36 36 37 36 37 36 38 38 38 38 38 38 38 38 38 38 38 38 38	36 34.5 34.5 34.5 34.5 34.5 36.3 35.5 34.7 36.3 36.7 36.7 36.7 36.7 36.7 36.7 36	36 36 36 36 36 36 37,4 Total Depth 45,0 19,0 45,0 19,0 45,0 45,0 45,0 45,0 45,0 45,0 45,0 45	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	13.5 13.5 15.5 14.5 13.5 13.7 13.7 13.7 13.7 Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	3 3.1 3.1 3.1 3.1 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0	Pierce Pi	Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Re-located closer to F07
6/12/2006 6/13/2006 6/14/2006 6/14/2006 6/13/2006 6/13/2006 6/13/2006 6/15/2006 7/15/2006 7/15/2006 6/15/2006	Q12 Q13 Q14 R13 R14 R15 S15 S15 S15 S16 AVERAGES: AVERAGES: TMP G07 P11 H10 K08 J05 C07 D04 Q13 M12 F04 E04 E04 E04 E04 E04 E04 E04 E04 E04 E	36 36 36 36 36 36 36 36 36 36 36 37.6 8 5 37.6 1 1 1 1 5 4	36 34.5 34.5 34.5 34.5 34.5 34.5 36.3 36 35.5 34.7 36.3 36.3 36.3 36.3 36.2 36.2 36.2 36.2	36 36 36 36 36 36 37.4 Total Depth 45.0 35.0 45.0 45.0 45.0 45.0 45.0 45.0 45.0 4	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	13.5 13.5 15.5 14.5 13.5 13.7 13.7 13.7 13.7 Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	3 3.1 3.1 3.1 3.1 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0	Pierce Pierce	Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Re-located closer to F07
6/12/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/15/2006 7 Total Site Date Completed 6/15/2006	Q12 Q13 Q14 R13 R14 R15 S15 S15 S16 AVERAGES: AVERAGES: TMP G07 P11 P15 H10 K08 J05 C07 D04 Q13 M12 F03 F04 E07 KM1 MW 42-17	36 36 36 36 36 36 36 36 36 36 37 37 4 4 5 5 1 1 1 5 4 4 1 1 5 4 4 1 1 5 4 4 1 1 5 4 4 5 4 5	36. 34.5 34.5 34.5 34.5 34.5 34.5 34.5 34.	36 36 36 36 36 36 37 37 4 Total Depth 45 9 45 9 45 9 40 9 40 9 40 9 40 9 40 9	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	13.5 13.5 15.5 14.5 13.5 13.7 13.7 13.7 13.7 Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	3 3.1 3.1 3.1 3.1 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0	Pierce Responsibility Pierce Shaw Pierce Band Materiestete Materiestete	Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Re-located closer to F07
6/12/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/15/2006	Q12 Q13 Q14 R13 R14 R15 S15 S15 S16 AVERAGES: AVERAGES: TMP G07 P11 H10 K08 J05 C07 D04 Q13 M12 F63 F63 F64 MW 42-14 42-17	36 36 36 36 36 36 36 36 36 36 36 37 37 4 5 1 1 1 5 4 5 1 1 1 5 4 1 5 4 5 4 5 7 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	36 34.5 34.5 34.5 34.5 34.5 36.3 36.3 36.3 36.3 36.3 36.3 36.3 36	36 36 36 36 36 36 37.4 Total Depth 45.0 35.0 19.0 45.0 45.0 35.0 45.0 45.0 45.0 35.0 45.0 45.0 35.0 45.0 45.0 35.0 35.0 45.0 45.0 35.0 35.0 45.0 35.0 35.0 45.0 35.0 35.0 35.0 35.0 35.0 35.0 35.0 3	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	13.5 13.5 15.5 14.5 13.5 13.7 13.7 13.7 13.7 Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	3 3.1 3.1 3.1 3.1 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0	Pierce Missensiste Multermistet Multermistete Multe	Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Re-located closer to F07
6/12/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/15/2006 7 Total Site Date Completed 6/15/2006	Q12 Q13 Q14 R13 R14 R15 S15 S15 S16 AVERAGES: AVERAGES: TMP G07 P11 H10 K08 J05 C07 D04 Q13 M12 F03 F03 F04 42-14 42-17 42-15 42-29	36 36 36 36 36 36 36 36 36 36 37 37 37 4 5 1 1 5 4 1 5 4 1 5 4 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	36. 34.5 34.5 34.5 34.5 34.5 34.5 34.5 34.	36 36 36 36 36 36 36 36 36 37.4 Total Depth 45 0 35 0 45 0 45 0 45 0 45 0 45 0 45 0	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	13.5 13.5 15.5 14.5 13.5 13.7 13.7 13.7 13.7 Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	3 3.1 3.1 3.1 3.1 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0	Pierce Responsibility Pierce Shaw Pierce Band Materiestete Materiestete	Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Re-located closer to F07
6/12/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/15/2008 REGION 3 Total Site Date Completed 6/15/2006	Q112 Q13 Q14 R13 Q14 R13 R14 R15 S15 S15 S16 AVERAGES: AVERAGES: TMP G07 P11 P15 H10 K08 J05 C07 G07 G07 G07 G07 G07 G07 G07 G07 M12 F03 M12 F03 H10 MW 42-11 MW 42-17 42-15 42-13	36 36 36 36 36 36 36 36 36 37 36 37 37 37 4 4 5 5 1 1 5 4 4 1 5 4 REGION 3 3 4 REGION 3 4 4 4 5 5 4 4 4 4 4 4 4 4 4 4 4 4 4 4	36. 34.5 34.5 34.5 34.5 34.5 34.5 34.5 36.3 35.5 36.7 36.7 36.7 36.7 36.7 36.7 36.7 36.7	36 36 36 36 36 36 37.4 Total Depth 45.0 35.0 40.0 35.0 40.0 40.0 40.0 40.0 40.0 45.0 110.0 31.0 31.0 31.0 31.0	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	13.5 13.5 15.5 14.5 13.5 13.7 13.7 13.7 13.7 Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	3 3.1 3.1 3.1 3.1 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0	Pincos Pi	Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Re-located closer to F07
6/12/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/15/2006	Q12 Q13 Q14 R13 Q14 R13 R14 R15 S15 S15 S16 AVERAGES: TMP G07 P11 P15 H10 K08 J05 C07 D04 Q13 F04 Q13 F04 Q13 F04 42-11 42-17 42-15 42-29 42-28 42-13	36 36 36 36 36 36 36 36 36 37 37 37 4 5 1 1 5 4 1 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	36 34.5 34.5 34.5 34.5 34.5 36.3 35.5 34.7 36.3 36.3 36.3 36.3 36.3 36.3 36.3 36	36 36 36 36 38 36 38 36 37.4 Total Depth 45.0 35.0 19.0 45.0 45.0 45.0 45.0 45.0 45.0 45.0 45	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	13.5 13.5 15.5 14.5 13.5 13.7 13.7 13.7 13.7 Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	3 3.1 3.1 3.1 3.1 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0	Pierce Pi	Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Re-located closer to F07
6/12/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/15/2006 7 Total Site Date Completed 6/15/2006	Q112 Q13 Q14 R13 Q14 R13 R14 R15 S15 S15 S16 AVERAGES: AVERAGES: TMP G07 P11 P15 H10 K08 J05 C07 G07 G07 G07 G07 G07 G07 G07 G07 G07 G	36 36 36 36 36 36 36 36 36 37 36 37 37 37 4 4 5 5 1 1 5 4 4 1 5 4 REGION 3 3 4 REGION 3 4 4 4 5 5 4 4 4 4 4 4 4 4 4 4 4 4 4 4	36. 34.5 34.5 34.5 34.5 34.5 34.5 34.5 36.3 35.5 36.7 36.7 36.7 36.7 36.7 36.7 36.7 36.7	36 36 36 36 36 36 37.4 Total Depth 45.0 35.0 40.0 35.0 40.0 40.0 40.0 40.0 40.0 45.0 110.0 31.0 31.0 31.0 31.0	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	13.5 13.5 15.5 14.5 13.5 13.7 13.7 13.7 13.7 Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	3 3.1 3.1 3.1 3.1 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0	Pincos Pi	Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Re-located closer to F07
6/12/2006 6/14/2006	Q112 Q13 Q14 R13 Q14 R13 R14 R15 S15 S15 S16 AVERAGES: AVERAGES: TMP G07 P11 P15 H10 K08 J05 C07 G07 G07 G07 G07 G07 G07 G07 G07 G07 G	36 36 36 36 36 36 36 36 36 37 37 37 37 4 4 5 5 1 1 5 4 REGION REGION REGION 4 5 5 4 4 5 5 5 5 7 1 1 4 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	36 34 5 34 5 34 5 34 5 34 5 34 5 34 5 34	36 36 36 36 36 36 37.4 Total Depth 45.0 35.0 40.0 35.0 40.0 35.0 40.0 35.0 40.0 35.0 40.0 35.0 40.0 40.0 40.0 40.0 40.0 40.0 40.0 4	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	13.5 13.5 15.5 14.5 13.5 13.7 13.7 13.7 13.7 Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	3 3.1 3.1 3.1 3.1 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0	Pierce Pi	Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Re-located closer to F07
6/12/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/15/2006 7/15/2006 7/15/2006 6/15/2006	Q12 Q13 Q14 R13 Q14 R13 R14 R15 S15 S15 S15 S16 AVERAGES: TMP G07 P11 P15 H10 C08 M12 F03 M12 F04 M12 F04 M12 H2 H2 H2 H2 H2 H2 H2 H2 H2 H2 H2 H2 H2	36 36 36 36 36 36 36 36 36 36 36 37 37 4 5 3 1 1 1 4 4 4 4 4 4 4 5 5	36 34.5 34.5 34.5 34.5 34.5 36.3 35.5 34.7 36.3 36.3 36.3 36.3 36.3 36.3 36.3 36	36 36 36 36 36 36 37.4 Total Depth 45.0 35.0 19.0 45.0 35.0 40.0 45.0 35.0 40.0 45.0 35.0 40.0 40.0 45.0 35.0 40.0 40.0 40.0 40.0 40.0 40.0 40.0 4	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	13.5 13.5 15.5 14.5 13.5 13.7 13.7 13.7 13.7 Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	3 3.1 3.1 3.1 3.1 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0	Pierce Pi	Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Re-located closer to F07
6/12/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/15/2006 7/15/2006 7/15/2006 7/15/2006 7/15/2006 6/15/2	Q12 Q13 Q14 R13 Q14 R13 R14 R15 S15 S15 S15 S16 Averages: TMP G07 P11 P15 H10 K08 J05 C07 D04 Q13 M12 F03 M12 F03 M12 F03 M22 F03 M22 F03 M24 42-14 42-16 42-16 42-16 42-16 42-16 42-16 42-17	36 36 36 36 36 36 36 36 36 36 36 37 37 4 5 3 2 4 5 1 1 4 4 4 5 5 5 1 1 4 4 4 5 5 1 1 4 4 4 5 5 5 1 1 4 4 4 4	36 34.5 34.5 34.5 34.5 34.5 34.5 36.3 36.3 35.5 34.7 36.3 36.3 36.3 36.3 36.3 36.3 36.3 36	36 36 36 36 36 36 37.4 Total Depth 45.0 35.0 19.0 45.0 35.0 40.0 45.0 35.0 40.0 45.0 35.0 40.0 40.0 45.0 35.0 40.0 40.0 40.0 40.0 40.0 40.0 40.0 4	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	13.5 13.5 15.5 14.5 13.5 13.7 13.7 13.7 13.7 Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	3 3.1 3.1 3.1 3.1 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0	Pierce Anderseite Adderseite	Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Re-located closer to F07
6/12/2006 6/14/2006	Q112 Q13 Q14 R13 Q14 R13 R14 R15 S15 S15 S16 AVERAGES: AVERAGES: TMP G07 P11 P15 H10 K08 J05 C07 G07 G07 G07 G07 G07 G07 G07 G07 G07 G	36 36 36 36 36 36 36 36 37 37 37 37 4 4 5 5 1 1 5 4 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	36. 36.34.5 34.5 34.5 34.5 34.5 34.5 34.5 36.35 35.5 36.7 36.7 36.7 36.7 36.7 36.7 36.7 36.7	36 36 36 36 36 36 37.4 Total Depth 45 0 35 0 19 0 45 0 35 0 44 0 35 0 44 0 35 0 45 0 35 0 40 0 35 0 35 0 40 0 35 0 35 0 40 0 35 0 35 0 35 0 35 0 35 0 35 0 35 0 3	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	13.5 13.5 15.5 14.5 13.5 13.7 13.7 13.7 13.7 Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	3 3.1 3.1 3.1 3.1 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0	Pierce Pi	Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Re-located closer to F07
6/12/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/14/2006 6/15/2008 REGION 3 Total Site Date Completed 6/15/2006 6/15/2006 6/15/2006 6/15/2006 6/15/2006 6/14/2006 6/14/2006 6/15/2006 6/14/2006 6/14/2006 6/15/2006	Q12 Q13 Q14 R13 Q14 R13 R14 R15 S15 S15 S15 S16 Averages: TMP G07 P11 P15 H10 K08 J05 C07 D04 Q13 M12 H21 H21 H21 H21 H21 H21 H21 H21 H21 H	36 36 36 36 36 36 36 36 36 36 36 37 37 4 5 3 2 4 5 1 1 4 4 4 5 5 5 1 1 4 4 4 5 5 1 1 4 4 4 5 5 5 1 1 4 4 4 4	36 34.5 34.5 34.5 34.5 34.5 34.5 36.3 36.3 36.3 36.3 36.3 36.3 36.3 36	36 36 36 36 36 36 37.4 Total Depth 45.0 35.0 19.0 45.0 35.0 40.0 45.0 35.0 40.0 45.0 35.0 40.0 40.0 40.0 40.0 40.0 40.0 40.0 4	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	13.5 13.5 15.5 14.5 13.5 13.7 13.7 13.7 13.7 Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	3 3.1 3.1 3.1 3.1 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0	Pierce Anderseite Adderseite	Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Re-located closer to F07
6/12/2006 6/14/2006	Q112 Q13 Q14 R13 Q14 R13 R14 R15 S15 S15 S16 AVERAGES: AVERAGES: TMP G07 P11 P15 H10 K08 J05 C07 G07 G07 G07 G07 G07 G07 G07 G07 G07 G	36 36 36 36 36 36 36 36 36 36 36 37 36 37 37 4 5 3 2 4 5 1 1 5 4 4 4 4 4 4 1 1 1 1	36. 36.34.5 34.5 34.5 34.5 34.5 34.5 34.5 36.35 35.5 36.7 36.7 36.7 36.7 36.7 36.7 36.7 36.7	36 36 36 36 36 36 37.4 Total Depth 45 0 35 0 19 0 45 0 35 0 44 0 35 0 44 0 35 0 45 0 35 0 40 0 35 0 35 0 40 0 35 0 35 0 40 0 35 0 35 0 35 0 35 0 35 0 35 0 35 0 3	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	13.5 13.5 15.5 14.5 13.5 13.7 13.7 13.7 13.7 Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	3 3.1 3.1 3.1 3.1 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0	Pierce Anderseite Multipresider Multipresider Multipresider Multipresider Multipresider Multipresider Multipresider Multipresider Multipresider Multipresider Multipresider Andersein Joe Joe Andersein	Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Re-located closer to F07
6/12/2006 6/14/2006	Q112 Q13 Q14 R13 Q14 R13 R14 R15 R15 S15 S15 S16 AVERAGES: AVERAGES: TMP G07 P11 P15 H10 K08 J08 J09 G07 G07 G07 G07 G07 G07 G07 G07 G07 G07	36 36 36 36 36 36 36 36 36 37 36 38 38 38 38 38 38 39 37 37 37 4 4 5 5 1 1 1 5 4 4 4 5 5 5 1 1 4 4 4 5 5 5 1 1 4 4 4 5 5 5 1 1 4 4 4 5 5 5 1 1 1 1	36 34 5 34 5 34 5 34 5 34 5 34 5 34 5 34	36 36 36 36 36 36 36 36 36 36 36 36 36 3	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	13.5 13.5 15.5 14.5 13.5 13.7 13.7 13.7 13.7 Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	3 3.1 3.1 3.1 3.1 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0	Pierce Pi	Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Re-located closer to F07
6/12/2006 6/14/2006	Q112 Q13 Q14 R13 Q14 R13 R14 R15 R15 S15 S15 S16 AVERAGES: AVERAGES: TMP G07 P11 P15 H10 K08 J08 J09 G07 G07 G07 G07 G07 G07 G07 G07 G07 G07	36 36 36 36 36 36 36 36 36 37 36 38 38 38 38 38 38 39 37 37 37 4 4 5 5 1 1 1 5 4 4 4 5 5 5 1 1 4 4 4 5 5 5 1 1 4 4 4 5 5 5 1 1 4 4 4 5 5 5 1 1 1 1	36 34 5 34 5 34 5 34 5 34 5 34 5 34 5 34	36 36 36 36 36 36 36 36 36 36 36 36 36 3	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	13.5 13.5 15.5 14.5 13.5 13.7 13.7 13.7 13.7 Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	3 3.1 3.1 3.1 3.1 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0	Pierce Pi	Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Re-located closer to F07
6/12/2006 6/14/2006	Q112 Q13 Q14 R13 Q14 R13 R14 R15 R15 S15 S15 S16 AVERAGES: AVERAGES: TMP G07 P11 P15 H10 K08 J08 J09 G07 G07 G07 G07 G07 G07 G07 G07 G07 G07	36 36 36 36 36 36 36 36 36 37 36 38 38 38 38 38 38 39 37 37 37 4 4 5 5 1 1 1 5 4 4 4 5 5 5 1 1 4 4 4 5 5 5 1 1 4 4 4 5 5 5 1 1 4 4 4 5 5 5 1 1 1 1	36 34 5 34 5 34 5 34 5 34 5 34 5 34 5 34	36 36 36 36 36 36 36 36 36 36 36 36 36 3	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	13.5 13.5 15.5 14.5 13.5 13.7 13.7 13.7 13.7 Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	3 3.1 3.1 3.1 3.1 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0	Pierce Pi	Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Re-located closer to F07
6/12/2006 6/14/2006	Q112 Q13 Q14 R13 Q14 R13 R14 R15 R15 S15 S15 S16 AVERAGES: AVERAGES: TMP G07 P11 P15 H10 K08 J08 J09 G07 G07 G07 G07 G07 G07 G07 G07 G07 G07	36 36 36 36 36 36 36 36 36 37 36 38 38 38 38 38 38 39 37 37 37 4 4 5 5 1 1 1 5 4 4 4 5 5 5 1 1 4 4 4 5 5 5 1 1 4 4 4 5 5 5 1 1 4 4 4 5 5 5 1 1 1 1	36 34 5 34 5 34 5 34 5 34 5 34 5 34 5 34	36 36 36 36 36 36 36 36 36 36 36 36 36 3	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	13.5 13.5 15.5 14.5 13.5 13.7 13.7 13.7 13.7 Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	3 3.1 3.1 3.1 3.1 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0	Pierce Pi	Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Due to possible grout infrusion past the 3" fine sand layer, the fine sand layer is 6" Re-located closer to F07


Vacuum Influence Test

10/18/2006

Pizeometer Location	Measured Vac (in WC)
C07	-0.80
D04	-2.30
F04	-0.05
F03	-0.16
J05	-0.35
K08	-0.25
G07	-0.10
E07	-0.01
H10	-0.08
K11	-0.34
M12	-0.09
P11	-0.07
Q13	-2.00
P15	-0.85

Blower Vac (in Hg)	Condenser Inlet Vac (in Hg)	Flowrate (SCFM)
4.5	2.5	440





VOLTAGE SAFETY SURVEY RESULTS AND LOCATION MAP

Voltage Survey

Maximum allowable observed voltage is 15-volts.

) Date/time: <u>10/7/2006</u> 7:15__

Inspector's Name: G Knight

585 VAC

Location	Voltag	ge Detection Points	Voltage	Fixed or
Number	Black Probe	Red Probe	Readings (Volts)	Random Location (F/R)
1	Gate Post	Gate Handle	0	F
2	Concrete	Fence Post	0	F
3	Concrete	Fence Post	0	F
4	Concrete	Bldg. 163 fence Post	0	F
5	Concrete	Bldg. 163 Steel Door Frame	0	F
6	Fence Post	Gate Handle	0	F
7	Concrete	Fence Post (by switch gear box)	0	F
8	Concrete	Fence Post (by switch gear box)	0	F
9	Concrete	Fence Post/Gate	0	F
10	Concrete	SDXR-2	0	F
11	Concrete	SDXR-1	0	F
12	Concrete	Pad Lock/Access Grate	1.09	F
13	Concrete	Water Valve Bollard	0 -	F
14	Concrete	Water Valve	0	F
15	Concrete	H4 Concrete Seal	4.6	F
16	Concrete	K7 Concrete Seal	4.4	F
17	Concrete	L7 Concrete Seal	2.8	F
18	Concrete	Water Valve Bollard	0	F
19	Concrete	Annex Door Frame	0	F
20	Concrete	Building 360 Door Frame	0	F
21	Concrete	Annex Center Column	0	F
22	Concrete	Annex Door Frame	0	F
/ 23	Concrete	Plate Shop Door Frame	0	F
24	Concrete	Plate Shop Door Frame	0	F
25	Concrete	SDXR-4	0.9	R
26	Concrete	Annex Access Grate	1.8	R
27	Concrete	Locker (south annex wall)	4.8	R
28				
29				
30				
31				
32				


Voltage Survey

Maximum allowable observed voltage is 15-volts.

Date/time: 10/18/2006 16:00 Inspector's Name: B.Pierce

PCU output Voltage: 585 VAC

Location	Voltag	ge Detection Points	Voltage	Fixed or
Number	Black Probe	Red Probe	Readings (Volts)	Random Location (F/R)
1	Gate Post	Gate Handle	0	F
2	Concrete	Fence Post	0	F
3	Concrete	Fence Post	0	F
4	Concrete	Bldg. 163 fence Post	0	F
5	Concrete	Bldg. 163 Steel Door Frame	0	F
6	Fence Post	Gate Handle	0	F
7	Concrete	Fence Post (by switch gear box)	0	F
8	Concrete	Fence Post (by switch gear box)	0	F
9	Concrete	Fence Post/Gate	0	F
10	Concrete	SDXR-2	0.76 V	F
11	Concrete	SDXR-1	0.67 V	F
12	Concrete	Pad Lock/Access Grate	0	F
13	Concrete	Water Valve Bollard	0.92 V	F
14	Concrete	Water Valve	0	F
15	Concrete	H4 Concrete Seal	0.62 V	F
16	Concrete	K7 Concrete Seal	0	F
17	Concrete	L7 Concrete Seal	0	F
18	Concrete	Water Valve Bollard	0	F
19	Concrete	Annex Door Frame	0	F
20	Concrete	Building 360 Door Frame	0	F
21	Concrete	Annex Center Column	0	F
22	Concrete	Annex Door Frame	0	F
23	Concrete	Plate Shop Door Frame	0	F
24	Concrete	Plate Shop Door Frame	0	F
25	Concrete	SDXR-4	0	R
26	Concrete	Annex Access Grate	1 V	R
27	Concrete	Locker (south annex wall)	0	R
28	Gate Post	Gate Post	0	R
29	Concrete	Fence Post near D 4	0	R
30	Concrete	Metal Door near G 11	0.84V	R
31	Concrete	South Access Gate	0	R
32	Concrete	SDXR-3	0	R
33	Concrete	Hallway Access Door Frame	1.7 V	R
34	Concrete	Water Supply Manifold	0	R
35	Concrete	Stairs	0	R



Appendix E Waste Manifests

	15858					
	NON-HAZARDOUS 1. Generator's US EPA ID No. WASTE MANIFEST (A. Z. 1. 7. 0. 0. 2. 3. 2. 3. 6 .2. 2. 1. 1	1	6 1 			
*	3. Generator's Name and Mailing Address Navy Ruse C. Alamada Point 2050 Suratoga Street, Suic 200 Alamada CA 74501	4				
	4. Generator's Phone (510) 749 = 5942		·			
	5. Transporter 1 Company Name 6. US EPA ID Number	A. Trai	nsporter's Pl		. 7/17 7	
	F. 1. p 1/15 1 1/15 1 1 2 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	B. Trai	nsporter's P		74+2	•
ŀ						• • • •
	9. Designated Facility Name and Site Address 10. US EPA ID Number At hamound 1 and 11. Road Road Road Road Road Road Road Road	C. Fac	ility's Phone	:	•••	
	LIVERWORD CA 74510	92	5-4	155	-7300	
	11. Waste Shipping Name and Description		12. Conta		13. Total Quantity	14. Unit Wt/Vol
	a Nan Hozordous Woster soll		n a D		a in 70	ý
GENE						
RATOR						
						300 A
	Additional Descriptions for Materials Listed Above 18.6 4 55 38 7 300 3.13.4 3 360 8.13	E. Haik	imig Codes	or was	tes Listed Above	***************************************
	15. Special Handling Instructions and Additional Information USE Appropriate 代任 つらっち いだ	4				
	24 hour Energy of the 507-7455					
	16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulation.	ions for re	porting prope	r disposa		
Ł	Gregory J. Grace Signature Augus 1	Di	·ce.	F # 3	Month Day 11.2 7.2	Year O.L.
TRANSP	17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Signature M.K.C.J.D.W.S.E.D.W.S.E.D.W.M.D.W.M.S.E.D.W.M.	5_			Month Day	Year
SPORTE	18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name Signature			•	Month Day	Year
R	19. Discrepancy Indication Space	* * .			<u> </u>] "
FAC	13. Discrepancy mulication opaco			•		
L	Pacility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item	m 19.				
4	Printed/Typed Name Signature		•		.Month Day	Year
	GENERATOR'S COPY			10.E		2/98

		:	1,20							
	NON-HAZARDOUS WASTE MANIFEST	1. Generator's U		Manifest Documen No.	2. Page of	1				
,	3. Generator's Name and Mailing Address	EVY 801	ue Alema area luga 3	•						
ì	MERMITON, CA GUELL	•	5, +6							
	4. Generator's Phone (576) 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	LACK .	·	ID Number	A. Transp	porter's P	hone			
	Philip West Industrial Services		C. A A G C. C	7. 0. 8. 4. 1 . 4 . 5		-800-8		172		
	7. Transporter 2 Company Name		1	ID Number	B. Transp	orter's Pl	ione	•		
	9. Designated Facility Name and Site Address			ID Number	C. Facilit	y's Phone				
	MIRAMONT LAND PILL MELLE ALLAMENT PASSED. LIVERMONE (A. 94556									•
	[181 X-010 k E . (A. 473 50		<u> </u>	<u> </u>				7360		·
	11. Waste Shipping Name and Description				. 1	12. Conto	Type	13. Total Quantii		14. Unit Wt/Vol
	a NON HATARDOUS WASTE, S.	OLIA					CM	Quanti		Y
						انم م	10		1.5	-
G	b.		<u> </u>	· · · · · · · · · · · · · · · · · · ·		/ / 				
N			•						.	
RA	c	·								
T O R					· .					·
Ì	d.	1								
		• •		·		. [1			
							. 1	• • •	- 1	
	Additional Descriptions for Materials Listed Abo	ove .	40.0.		E. Handli	ng Codes	for Wo	stes Listed /	bove	
	Profile # 55787300	ove B.	· + R1803	1 ML	E. Handli	ng Codes	for Wo	istes Listed /	Above	
	Profile # 55787300 £ TO 133 5104 360 6.45	8	· + R1803	1 ML	E. Handli	ng Codes	for Wo	stes Listed /	Above	
	Profile # 557873 CO £ 10 / 33 £ (24 360 £ 5 15. Special Handling Instructions and Additional In	8	~ # R1803	1 ML	E. Handli	ng Codes	for Wo	stes Listed /	Above	
	Profile # 557873 CO E TO 133 560 8.46 15. Special Handling Instructions and Additional In Use Appropriate PPE	Bre	· # R1803	1 ML	E. Handli	ng Codes	for Wo	istes Listed A	Above	
	Profile # 557873 CO E TO 133 560 8.46 15. Special Handling Instructions and Additional In Use Appropriate PPE	8	~ ≠ R1803	1 ML	E. Handli	ng Codes	for Wo	istes Listed A	Above	
	Profile # 597873 CU (TO 133 5133 360 5 c 15. Special Handling Instructions and Additional In Use Appropriate PPE Botal	formation ACM	~ ≠ R1803	1 ML	Job #	ng Codes	for Wo	istes Listed A	Above	
	Profile # 597873 CU CTO 133 SIDE 360 15. Special Handling Instructions and Additional In Use Appropriate PPE BIN 24 HR EMERGENCY # 1-800-56	16 reaction 7-7455			Job #	76-	urv.	11.67		
	Profile # 597873 CU CTO 133 360 15. Special Handling Instructions and Additional Ir Use Appropriate PPE STATE 24 HIP EMERGENCY # 1-800-56	16 reaction 7-7455	ove on this manifest are		Job #	76-	urv.	1. 1 To Taposal of Haz	ardous V	
	Profile # 597873 CU CTO 133 SIDE 360 15. Special Handling Instructions and Additional In Use Appropriate PPE BIN 24 HR EMERGENCY # 1-800-56	16 reaction 7-7455			Job #	76-	urv.	11.67	ardous V	Waste.
	Profile # 557873 CO LTO 133 360 15. Special Handling Instructions and Additional In Use Appropriate PPE ATTA 24 HFI EMERGENCY # 1-800-56 16. GENERATOR'S CERTIFICATION: I certify the m Printed/Typed Name Poly ICTC 1 Communication of Receipt of Additional Inc. 17. Transporter 1 Acknowledgement of Receipt of Additional Inc. 18. Special Handling Instructions and Additional Inc. 19. Special Handling Instructions and Additional Inc. 19. Special Handling Instructions and Additional Inc. 24 HFI EMERGENCY # 1-800-56 16. GENERATOR'S CERTIFICATION: I certify the m Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Additional Inc. 18. Special Handling Instructions and Additional Inc. 19. Specia	Bit of the state o	ove on this manifest are	not subject to federal reg	Job #	76-	urv.	sposal of Haz Month	ardous V	Year
- FE4Z01	Profile # 557873 CO £ TO 133 £ 15. Special Handling Instructions and Additional In Use Appropriate PPE £ 1500-56 16. GENERATOR'S CERTIFICATION: 1 certify the m Printed/Typed Name Pox 1270-1200-1	Bit of the state o	ove on this manifest are	not subject to federal reg	Job #	76-	urv.	1. 1 To Taposal of Haz	ardous V	
S	24 HF EMERGENCY # 1-800-56. 16. GENERATOR'S CERTIFICATION: 1 certify the management of Receipt of American Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of American Printed/Typed Name 18. Transporter 2 Acknowledgement of Receipt of American Printed/Typed Name 18. Transporter 2 Acknowledgement of Receipt of American Printed/Typed Name	formation 7-7455 noterials described about	ove on this manifest are Signature. Signature	not subject to federal reg	Job #	76-	urv.	Sposal of Haz Month (Day	Year Year
- HEAZOPORHE	Profile # 597873 CO (TO 133 360 15. Special Handling Instructions and Additional In Use Appropriate PPE BAN 24 HIP EMERGENCY # 1-800-56 16. GENERATOR'S CERTIFICATION: I certify the m Printed/Typed Name Pox March 1200-1 17. Transporter 1 Acknowledgement of Receipt of A Printed/Typed Name Receipt Mare Receipt Mare Receipt Mare Receipt Mare Receipt Mare Receipt Mare Receipt Mare Receipt Mare Receipt Mare Receipt Mare Receipt Mare Receipt Mare Receipt Mare Receipt Mare Receipt Mare Receipt Mare	formation 7-7455 noterials described about	ove on this manifest are	not subject to federal reg	Job #	76-	urv.	sposal of Haz Month	ardous V	Year
S	24 HF EMERGENCY # 1-800-56. 16. GENERATOR'S CERTIFICATION: 1 certify the management of Receipt of American Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of American Printed/Typed Name 18. Transporter 2 Acknowledgement of Receipt of American Printed/Typed Name 18. Transporter 2 Acknowledgement of Receipt of American Printed/Typed Name	formation 7-7455 noterials described about	ove on this manifest are Signature. Signature	not subject to federal reg	Job #	76-	urv.	Sposal of Haz Month (Day	Year Year
の 日本 一 日本 一 日本 日本 日本 日本 日本 日本 日本 日本 日本 日本 日本 日本 日本	Profile # 597873 CU (TO 133 360 15. Special Handling Instructions and Additional In Use Appropriate PPE 24 HIP EMERGENCY # 1-500-56 16. GENERATOR'S CERTIFICATION: I certify the m Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of In Printed/Typed Name 18. Transporter 2 Acknowledgement of Receipt of In Printed/Typed Name	formation 7-7455 noterials described about	ove on this manifest are Signature. Signature	not subject to federal reg	Job #	76-	urv.	Sposal of Haz Month (Day	Year Year
SPORTER	24 HF EMERGENCY # 1-500-56. 15. Special Handling Instructions and Additional In Use Appropriate PPE 24 HF EMERGENCY # 1-500-56. 16. GENERATOR'S CERTIFICATION: I certify the management of Receipt of Appropriate Post Control of Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Appropriate Post Control of Printed/Typed Name 18. Transporter 2 Acknowledgement of Receipt of Appropriate Printed/Typed Name 19. Discrepancy Indication Space	formation 7-7455 Naterials described above	Signature Signature Signature Signature	not subject to federal reg	Job #	Z6-reporting p	urv.	Sposal of Haz Month (Day	Year Year
SPORTER FAC-L-F	Profile # 597873 CU (TO 133 360 15. Special Handling Instructions and Additional In Use Appropriate PPE 24 HIP EMERGENCY # 1-500-56 16. GENERATOR'S CERTIFICATION: I certify the m Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of In Printed/Typed Name 18. Transporter 2 Acknowledgement of Receipt of In Printed/Typed Name	formation 7-7455 Naterials described above	Signature Signature Signature Signature	not subject to federal reg	Job #	Z6-reporting p	urv.	Sposal of Haz Month (Day	Year Year
SPORTHE FAC-L-	24 HF EMERGENCY # 1-500-56. 15. Special Handling Instructions and Additional In Use Appropriate PPE 24 HF EMERGENCY # 1-500-56. 16. GENERATOR'S CERTIFICATION: I certify the management of Receipt of Appropriate Post Control of Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Appropriate Post Control of Printed/Typed Name 18. Transporter 2 Acknowledgement of Receipt of Appropriate Printed/Typed Name 19. Discrepancy Indication Space	formation 7-7455 Naterials described above	Signature Signature Signature Signature	not subject to federal reg	Job #	Z6-reporting p	urv.	Sposal of Haz Month (Day	Year Year

GENERATOR'S COPY

	andagingsagesonsuesessess	158	35						
	NON-HAZARDOUS WASTE MANIFEST	1. Generator's US EPA I		Manifest Document No.	2. Pag of	. 1			•
- (Generator's Name and Mailing Address AIA WILDAM, CA. PUSU 4. Generator's Phone (SIC)	7 3450 5016	Alemena . Ligar S Soller	reit					
	5. Transporter 1 Company Name Philip West Industrial Services	6.	US EPA ID NO	ļ	A. Trai	rsporter's F		470	
	7. Transporter 2 Company Name	8.	US EPA ID No	mber	B. Tran	sporter's P		T J 2	
	9. Designated Facility Name and Site Address ALTA IVIONT LANDFILL ICELIU ALTAIVIONT PASS	10. P∆	US EPA ID No	ımber		lity's Phone			
	LIVEEMOPE, CA. 941550	<u> </u>			(4)	2(5) 4/		7200	14,
	11. Waste Shipping Name and Description					No.	Туре	Total Quantity	Unit Wt/Vol
	ONON HATARIXUS WAS	>1t /SQL113				2.0.1	C.M	<u>00.01</u>	5 Y
GEZE	b.		•			• •			
K A T O R	.					• • •			
	d.	1			. :	, , , , , , , , , , , , , , , , , , ,			
	Additional Descriptions for Materials Listed Ab Profile # 65387.00 CTO 133 Fig. 360 8.45	ove SIN #			E. Hand	dling Code	s for We	astes Listed Abo	ve
			•						
	15. Special Handling Instructions and Additional I Use Approprizte PPE	Information			dob.	*	• .		
	15. Special Handling Instructions and Additional I Use Appropriate PPE 24 149 EMERGENCY # 1-800-58	37-7455			PO #	t 76-		01.07	
	15. Special Handling Instructions and Additional I Use Appropriate PPE 24 117 EMERGENCY # 1-800-56 16. GENERATOR'S CERTIFICATION: I certify the I Printed/Typed Name	37-7455 materials described above on t	his manifest are not s Signature	ubject to federal regu	PO #	t 76-			y Year
- Frazs	15. Special Handling Instructions and Additional I Use Appropriate PPE 24 117 EMERGENCY # 1-800-56 16. GENERATOR'S CERTIFICATION: I certify the I Printed/Typed Name	37–7455 materials described above on th Materials		ubject to federal regu	PO #	t 76-		isposal of Hazardo Month Da	y Year 2 ().6
	15. Special Handling Instructions and Additional I Use Appropriate PPE 24 117 EMERGENCY in 1-800-58 16. GENERATOR'S CERTIFICATION: I certify the I Printed/Typed Name 27. Transporter 1 Acknowledgement of Receipt of Printed/Typed Name	materials described above on the Materials Materials Materials	Signature C	ubject to federal regu	PO #	t 76-		Month Do	y Year 2 ().6
- Francortur	15. Special Handling Instructions and Additional I Use Appropriate PPE 24 117 EMERGENCY - 1-800-56 16. GENERATOR'S CERTIFICATION: I certify the operation of the certify the certification of the certi	materials described above on the Materials Materials Materials	Signature	ubject to federal regu	PO #	t 76-		Month Do	Y Year 2 0.6 Y Year 2 5.6
	15. Special Handling Instructions and Additional I Use Appropriate PPE 24 119 EMERGENCY = 1-800-56 16. GENERATOR'S CERTIFICATION: I certify the of Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Printed/Typed Name 18. Transporter 2 Acknowledgement of Receipt of Printed/Typed Name	materials described above on t Matérials Materials	Signature / Signature / Signature		PO #	F 76 -		Month Do	Y Year 2 0.6 Y Year 2 5.6
	15. Special Handling Instructions and Additional Use Appropriate PPE 24 117 EMERGENCY & 1-800-56 16. GENERATOR'S CERTIFICATION: I certify the operation of the printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Printed/Typed Name 18. Transporter 2 Acknowledgement of Receipt of Printed/Typed Name 19. Discrepancy Indication Space	materials described above on the Materials Materials Materials	Signature / Signature / Signature		PO #	F 76 -		Month Da	Y Year Y Year Y Year

Additional Descriptions for Materials Listed Above Partitle # F22 73 CC CT0133 E. Ja 340 E.v. 5 15. Special Handling Instructions and Additional Information Use Appropriate PPE 16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reparting proper disposed of Hexandow Want T. Transport I Administration: I certify the materials described above on this manifest are not subject to federal regulations for reparting proper disposed of Hexandow Want Printed/Typed Name Signature Month Day Ye 19. Discrepancy Indication Space Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.		iceptinti just mitespinori ostavi tile oranisti justini	1583	ر ا							
Control Note and Mailing Address 1			1. Generator's US EPA'I	D No.	Manifest Dodument No.	1 .	e l			77-1010EW/	
Control Florid Control Contr	-	3. Generator's Name and Mailing Address August 1997	ady Kure	Fr governo		 		<u></u> -			
S. Transporter Company Name Printing				ga 541. 200	À						
Promporter's Phone B. USEPA ID Number B. Transporter's Phone				US EPA ID N	lumber	A. Trai	nsporter's F	hone	····		
9. Designeted Facility Name and Site Address 10. US EPA ID Number 1. PANCHT LANNELL 1. ANNELL 1.		Philip West industrial Services	C. A	11 0 C C C	1. 8. 4.1.4.5	1	1-800-6	300-7-	72		
A THE MANT LINE STATE LIVE ENGINEER LIVE		7. Transporter 2 Company Name	8.	US EPA ID N	umber	B. Tran	isporter's P	hone			
1. Waste Shipping Name and Description 12. Container 13. 15. 1				US EPA ID N	umber	C. Faci	lity's Phone	,	· · · · · · · · · · · · · · · · · · ·		
11. Waste Skipping Nome and Description 12. Containers 13. India (Quantity) Will (Quantity) W		LIVERMORE, CALGUES	5 PA.			197	5)4	5ζ -	1000)	
No. Style Quantity Wr.	П	11. Waste Shipping Name and Description			,				13,		14. Unit
Additional Descriptions for Materials Listed Above Provide # ASS 73CC CT0133 E. 1 2 3W Fin 5 15. Special Handling Instructions and Additional Information Uso Appropriate PPE JGD # 16. GENERATOR'S CERTIFICATION: 1 certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazaedow West Printed/Typed Name J. 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name J. 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name J. 19. Discrepancy Indication Space Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.	П				····		No.	Туре			Wt/Vol
Additional Descriptions for Materials Listed Above Profile # 232 7300 LTO 133 E. Handling Codes for Wastes Listed Above Profile # 232 7300 LTO 133 15. Special Handling Instructions and Additional Information Uso Appropriate PPE Jab # 16. GENERATOR'S CERTIFICATION: 1 carify the materials described above on this manifest are not solved to federal regulations for reporting proper disposal of Hazardous Want Printed/Typed Name Signature Month Day Ye 17. Transporter I Acknowledgement of Receipt of Materials Printed/Typed Name Signature Menth Day We 19. Discrepancy Indication Space	ľ	O. NUN HAZARDOUS WI	NOTE, SOLID			<u>.</u>	• <u>0</u> • E	·		· * * * *	y
Additional Descriptions for Materials Listed Above Profile # 5327360 CT0133 15. Special Handling Instructions and Additional Information Uso Appropriate PPE 24 His EMERGENCY # 1-800-567-7455 16. GENERATOR'S CERTIFICATION: 1 certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposed of Recorded West Month Day Yes 17. Transporter I Acknowledgement of Receipt of Materials Printed/Typed Name 19. Discrepancy Indication Space Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.	E	b.					·		•		
Additional Descriptions for Materials Listed Above Profile # 639 7300 CT0133 EV 8 360 EV 7 15. Special Handling Instructions and Additional Information USO Appropriete PPE Job # 24 HR EMERGENCY # 1-800-567-7455 16. GENERATOR'S CERTIFICATION: I certify the materials described above on this monifiest are not subject to federal regulations for reporting proper disposal of Hazardous West Printed/Typed Name Signature Month Day Ye 17. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name Signature Month Day Ye 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name Signature Month Day Ye 19. Discrepancy Indication Space	B						<u> </u>				<u> </u>
Additional Descriptions for Materials Listed Above Profile # 18080.M. E. Handling Codes for Wastes Listed Above Profile # 18080.M. E. Handling Codes for Wastes Listed Above Profile # 18080.M. E. Handling Codes for Wastes Listed Above Profile # 18080.M. E. Handling Codes for Wastes Listed Above Profile # 18080.M. E. Handling Codes for Wastes Listed Above Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Listed Above For Listed Above E. Handling Codes for Listed Above For Listed Above E. Handling Codes for Listed Above For Listed Above E. Handling Codes for Listed Above For Listed Above For Listed Above E. Handling Codes for Listed Above For Listed Above E. Handling Codes for Listed Above For Listed Above For Listed Above For Listed Above For Listed Above For Listed Above For		c.		•	•						
Additional Descriptions for Materials Listed Above Profile # 18080.M. E. Handling Codes for Wastes Listed Above Profile # 18080.M. E. Handling Codes for Wastes Listed Above Profile # 18080.M. E. Handling Codes for Wastes Listed Above Profile # 18080.M. E. Handling Codes for Wastes Listed Above Profile # 18080.M. E. Handling Codes for Wastes Listed Above Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Wastes Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Wastes Listed Above For Listed Above E. Handling Codes for Listed Above For Listed Above E. Handling Codes for Listed Above For Listed Above E. Handling Codes for Listed Above For Listed Above E. Handling Codes for Listed Above For Listed Above For Listed Above E. Handling Codes for Listed Above For Listed Above E. Handling Codes for Listed Above For Listed Above For Listed Above For Listed Above For Listed Above For Listed Above For	î								 -		-
Profile # 15.24.73.00 LTO 133 Elia 36.0 Ein 5 15. Special Handling Instructions and Additional Information Use Appropriate PPE Job # 24 HR EMERGENCY # 1-800-567-7455 PO # 76-111.01.07 16. GENERATOR'S CERTIFICATION: I carlify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Want Printed/Typed Name Signature Manth Day Ye Printed/Typed Name Signature Month Day Ye 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name 19. Discrepancy Indication Space		d									
15. Special Handling Instructions and Additional Information USO Appropriete PPE 16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hozardous West Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Signature Month Day Ye 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name Signature Month Day Ye 19. Discrepancy Indication Space	1	Additional Descriptions for Materials Listed A	pove karna	4 E 1905	7.7. WI	E. Hand	dling Code	s for Wo	stes Listed	Above	
15. Special Handling Instructions and Additional Information USO Appropriate PPE Job # 24 HIR EMERGENCY # 1-800-567-7455 PO # 76-111. C/1.07 16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous West Printed/Typed Name Signature Month Day Ye 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Signature Month Day Ye 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name Signature Month Day Ye 19. Discrepancy Indication Space									."		
24 HR EMERGENCY # 1-800-567-7455 PO # 7 6-111 C1.07 16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waster Signature Printed/Typed Name Signature Month Day Ye 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Signature Month Day Ye 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name Signature Month Day Ye 19. Discrepancy Indication Space			Information	•			·				
16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Wast Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Signature Month Day Ye 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name Signature Month Day Ye 19. Discrepancy Indication Space		Use Appropriate PPE				Job :	#				
16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Wast Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name Signature Month Day Ye 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name Signature Month Day Ye 19. Discrepancy Indication Space				•					•		
16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Wastername Signature Printed/Typed Name Signature Month Day Ye 1.7.7.7.7.7.7.7.7.7.7.7.7.7.7.7.7.7.7.7		24 HR EMERGENCY # 1-800-5	67-7455			PO #	76	- 111,	61.0	Z_	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name Signature Month Day Ye 19. Discrepancy Indication Space Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.		16. GENERATOR'S CERTIFICATION: I certify the	materials described above on th	nis manifest are not	subject to federal reg						Waste.
Printed/Typed Name 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name Signature Month Day Ye 19. Discrepancy Indication Space Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.	Y			Signature	1	<u></u>			Month • j	Day	Year
Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.	T			· .					<u> </u>		·
Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.	A	Printed/Typed Name		Signature					Month	Day	Year
Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.	SP		i Matoriale		A section	• •					1::
Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.	Ŗ			Signature				•	Month	Dav	Year
Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.	Ė	ay iyea ramo							-		.
Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.	·	19. Discrepancy Indication Space	·		 						
Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.		, ·		•							. 100
$\frac{1}{1}$, \mathcal{I}	FAC			·	•						
も /	Ļ	Facility Owner or Operator: Certification of re	eceipt of waste materials cov	ered by this mani	est except as noted	in Item	19.				6
Y Printed/Typed Name Signature Month Day Yes	Ť` Y	Printed/Typed Name		Signature .		•			Month	Day	Year
	2605				·						

			5837						
(Booles)	NON-HAZARDOUS WASTE MANIFEST	1. Generator's U		Manife Pocumen	est 2. P	age 1			
一	Generator's Name and Mailing Address A A A A A A A A A A A A A A A A A A	TET 2450	Sora lago Site 720						
5. Ti	Fransporter 1 Company Name Philip West Industrial Serve Fransporter 2 Company Name	loes	6 A B 6 G 6	D Number 	4.5	ransporter	3 -200 -74	\$72	
162	Designated Facility Name and Site Add	ress C C. F. D.		D Number		acility's Ph		120	
	NE PRIVEE, (A. Waste Shipping Name and Description	1	<u></u>				ontainers	13. Total Quantity	
a. A	VIN MATTARDONS N	ASTE, SULIA				1		Quantity /	Т,
b.				· .					1
c.		·	- 						
		• • •				B 40"			-1
d.									
\r	Additional Descriptions for Materials List	?	BIN# R	18370 1	17 / E. H	andling Co	des for W	astes Listed Above	B
15. S	Profile # 65-38 7300	?	BIN# K	183700		andling Co	des for W	astes Listed Abov	8
15. S	Profile # 65387300 670133 560 bus Special Handling Instructions and Addi	o tional Information	BIN# K	183700	Jo	o ##		ostes Listed Abov	8
15. S	Special Handling Instructions and Adding Instructions Instruction	tional Information 00-567-7455 Ify the materials described abo			Joh	o # 21	1.1	UI.UZ Ispasal of Hazardou	s Wo
15. S	Special Handling Instructions and Additional Appropriate PPE 24 HIP EMERGENCY 1-86 SENERATOR'S CERTIFICATION: 1 cent Printed/Typed Name Transporter 1 Acknowledgement of Receivers	tional Information 00-567-7455 Ify the materials described abo	ove on this manifest are Signature	not subject to fed	PC	o # 21	g proper di	Sposal of Hazardou Month Day	s Wo
15. S 16. G Pr. 17. Yr	Special Handling Instructions and Adding Jae Appropriate PPE PA HA EMERGENCY 1-86 SENERATOR'S CERTIFICATION: I certificated/Typed Name Fransporter 1 Acknowledgement of Receivering Management of Receivering Management (Propriated/Typed Name) Fransporter 2 Acknowledgement of Receivering Management (Propriated/Typed Name)	tional Information 00-567-7455 Ify the materials described above the materials of the mat	ove on this manifest are Signature Signature	not subject to fed	PC	The 2 L	g proper di	isposal of Hazardou Month Day	s Wo
15. S 16. G Pr.	Special Handling Instructions and Addit Las Appropriate PPE BENERATOR'S CERTIFICATION: I certificated/Typed Name Fransporter 1 Acknowledgement of Receiving Management Management of Receiving Management Management Management of Receiving Management	tional Information 00-567-7455 Ify the materials described above the materials of the mat	ove on this manifest are Signature Signature	not subject to fed	PC	The 2 L	g proper di	ispasal of Hazardou Month Day	s Wo
15. S 16. G Pr 17. Ir Pr 18. Ir Pr	Special Handling Instructions and Adding Jae Appropriate PPE PA HA EMERGENCY 1-86 SENERATOR'S CERTIFICATION: I certificated/Typed Name Fransporter 1 Acknowledgement of Receivering Management of Receivering Management (Propriated/Typed Name) Fransporter 2 Acknowledgement of Receivering Management (Propriated/Typed Name)	tional Information 00-567-7455 If the materials described above the materials described above the materials 2	ove on this manifest are Signature Signature Signature	not subject to fede	PC eral regulations	# 2.6	g proper di	ispasal of Hazardou Month Day	s Wo

Additional Descriptions for Materials Listed Above Profile # 603℃ 73℃

NON-HAZARDOUS

WASTE MANIFEST

5. Transporter 1 Company Name

7. Transporter 2 Company Name

CTO 133 619a 360 Bins

15. Special Handling Instructions and Additional Information

Use Appropriate PPE

24 HR EMERGENCY # 1-800-567-7455

PO# 26-111, ULDZ

16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste. Month. Day Printed/Typed Name Pob Perricore 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name ----Signature ... Ten Tent 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name Signature

19. Discrepancy Indication Space

Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Signature

Month

		15839	•		
	NON-HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest 2	2. Page 1 of	
	. 3. Generator's Name and Mailing Address	avy KOICE MAME	Va Point		
		in a series of	atuga Street		•
Ì	ALAMETA CA. 945 4. Generator's Phone (SIC) 749-	ol Suite 7	00		
	5. Transporter I Company Name	6. US EPA ID	Number A	A. Transporter's Phone	·····
	Philip West Industrial Services	CAROGO		1-800-800-	• •
	7. Transporter 2 Company Name	8. US EPA ID	Number B	B. Transporter's Phone	
		10 15 504 5		C. E. Illedo Dhana	<u> </u>
	9. Designated Facility Name and Site Address ALTH-MCNTLANDF1 ICCHO ALTHMONT	10. US EPA ID	Nomber	C. Facility's Phone	
	LIVERMORE, CA. 9	4550		725-45	5.7300
	11. Waste Shipping Name and Description			12. Container	Total Unit
	a NCN HAZARDOUS	NASTE, SULID			
				0014	M00.0.15 Y
GENE	b.			April 1985 F	
RA	ć.				
o R					
1	d.				
	Additional Descriptions for Materials Listed Above	BIN# 20-1	31-73 E	. Handling Codes for	Wastes Listed Above
	Profile # 55387300				
	360 Bis				
	15. Special Handling Instructions and Additional Info	rmation		4. 2	
ľ	Use Appropriate PPE			Job #	
1					
	24 HR EMERGENCY # 1-800-567-	7455		PO# 26 - 11	1.01.02
	16. GENERATOR'S CERTIFICATION: 1 certify the mate		ot subject to federal regula	ations for reporting prope	
Ť	Printed/Typed Name Petricense	Signature,	<u>(() </u>		Month Day Year 1.0 0.3 0.4
T	17. Transporter 1 Acknowledgement of Receipt of Ma				
A N S P	Printed/Typed Name NAVM10 N. J. BEL	17 100 27 77	200 A.B.	w	Month Day Year
R	18. Transporter 2 Acknowledgement of Receipt of Ma				Month Day Year
E R	Printed/Typed Name	Signature			
	19. Discrepancy Indication Space			7	
A		•	· · · · · · · · · · · · · · · · · · ·	•.•.	
Ĭ	Facility Owner or Operator: Certification of receip	at of waste materials covered by this mo	inifest except as noted in	n Item 19.	
j)				•
! Y :	Printed/Typed Name	Signature		•	Month Day Year
! Y	Printed/Typed Name	Signature	,		Month Day Year

	158	040						
	NON-HAZARDOUS 1. Generator's WASTE MANIFEST	US EPA ID No.	Manifest Document Na	2. Pag	ge 1			966 (196-16)
7	Generator's Name and Mailing Address Novy Ru	TILE Ala	mida Point		1 1			
	4. Generator's Phone (511) 7115 (1) 5. Transporter 1 Company Name	6. US EP	'A ID Number	A Tra	nsporter's P	hone		
	Philip West Industrial Services	CAROO	6.0.8.4.1.4.	5	1-800-6	00-7	1 72	<u>.</u>
	7. Transporter 2 Company Name	1	A ID Number	B. Tra	nsporter's Pl	hone		
	9. Designated Facility Name and Site Address ALTAMONT LANDFILL 10840 ALTAMONT INSCRIPTION LIVERNUSE, CA. 94550		A ID Number	C. Fac	ility's Phone	:	-	<u>i -</u>
	11. Waste Shipping Name and Description				12. Cont	ainers	13. Total	14. Unit
	a NUN HAZARNOUS WASTE, S	7.1.4N	·	·····	No.	Туре	Quantity	Wt/Vol
	WON PIAZFIANCIAS WITTI, 3	CLIN	•	٠	ħ. O. 1	ر. در ان ان ان	j. 0.0.1.5	
 G	ь.				10.30.1	.,,0	(j.,,. O. (+3	7
mZm(•		
ATO	c.					:		
R			i			•		<u> </u>
	d.							. ,
1	Additional Descriptions for Materials Listed Above	BIN#R	18216ML	E. Han	dling Code	s for W	astes Listed Above	, v.·.
	Profile # 55387200							
ŀ	15. Special Handling Instructions and Additional Information	·	· · · · · · · · · · · · · · · · · · ·					
	Use Appropriate PPE	•		Job	静			
		•			•			
		•						
	24 HR EMERGENCY # 1-800-587-7455			PO ;	# 26-	-174	.01.62	
	16. GENERATOR'S CERTIFICATION: I certify the materials described a		re not subject to federal r	egulations f	or reporting	oroper d	·	
Y	Printed/Typed Name Fold Fernicance	Signature	& la -	مند			Month Day 1.0 0.4	106
T	17. Transporter 1 Acknowledgement of Receipt of Materials							
TRANSPORTER	Printed/Typed Name AANNOKIA T. B-22	Signature	10.	A. J.			Month Day	Year
P O R	18. Transporter 2 Acknowledgement of Receipt of Materials	100						
TER	Printed/Typed Name	Signature		:			Month Day	Year
	19. Discrepancy Indication Space							
F A C		16 ⁴						
Ĭ.'	Facility Owner or Operator: Certification of receipt of waste mate	terials covered by thi	s manifest except as not	ted in Item	19.			
Ÿ	Printed/Typed Name	Signature		•	· ,		Month Day	Year

GENERATOR'S COPY

l	5	B	4	~	
		~ ~ /			٠

	NON-HAZARDOUS WASTE MANIFEST	. Generator's US EPA ID No.	Manifest Postulation	2. Pag	e l			
Ť	3. Generator's Name and Mailing Address No. FINTEDIALS CO 1114 ALAMFDA, CA 94501 4. Generator's Phone (511) -7452-69	2450 Saraloga Suite 200	•					
	5. Transporter 1 Company Name Phillip West Industrial Services	6. US EPA I C. A. R. O. O. C	D Number 5. 0. 8. 4. 1. 4. 5 D Number		nsporter's F 1-800-8 nsporter's P	300-7	472	·
	7. Transporter 2 Company Name		D Number		lity's Phone			
	9. Designated Facility Name and Site Address ALTANIONT LANDFILL AUR 10840 ALTANIONT LIVETENIORE (A. 94)	PASCRA	, compa			•	- 1300	
	11. Waste Shipping Name and Description			L	12. Cont		13.	14.
					No.	Туре	Total Quantity	Unit Wt/Vol
	· NUN HAZARDOUS WA	STE, SULID			0.0.1	C.M	0.0.0.15	٧
GENE	b.					•		
RATOR	5			· .				
	d.				• . •			
	Additional Descriptions for Materials Listed Above	er and in the re-	121 27	E. Han	dling Code	s for W	astes Listed Above	
	Profile # 55387300 CT0/33 Blog 360 Blog	BIN# 20	7131-31					
	15. Special Handling Instructions and Additional Info	rmation						
	Use Appropriate PPE			dob	#			
						٠.		
	24 HR EMERGENCY # 1-900-567-	7455		PO ≠	+ 26	- 111.	01.02	
	16. GENERATOR'S CERTIFICATION: I certify the mate	,	not subject to federal regu	ulations fo	r reporting	otobet q	···	
1	Printed/Typed Name	Signature	<u>, (</u>			·	Month Day	Year
Ŗ	17. Transporter 1 Acknowledgement of Receipt of Ma	térials Signature		·/	, · · · · · · · · · · · · · · · · · · ·			·
NS	Printed/Typed Name KAYMOND J. BELL	Signature Author	earl L	11	A CONTRACTOR OF THE PARTY OF TH		Month Day	Year
g	18. Transporter 2 Acknowledgement of Receipt of Ma	terials						
RANSPORTER	Printed/Typed Name	Signature					Month Day	Year
	19. Discrepancy Indication Space							
FAC				 ·				
	Facility Owner or Operator: Certification of receip	t of waste materials covered by this m	anifest except as noted	l in Item	19.			
Ÿ	Printed/Typed Name	Signature					Month Day	Year
4			······································		TO WELL AND SH	50 x 200 x 0	STATE OF THE PARTY	

	The state of the s	1509		 •					
	NON-HAZARDOUS WASTE MANIFEST	1. Generator's US EPA	•	Manifest Dogument No.	2. Pag	3			
		2450 Sara	Alame						•
	5. Transporter 1 Company Name Pitilip West Industrial Services	6. C- /		D Number - 0 - 8 - 4 - 1 - 4 - 5	l .	nsporter's F 1-800-8		72	•
	7. Transporter 2 Company Name	8.] .	US EPĄ	D Number	B. Tran	sporter's P		•	
	9. Designated Facility Name and Site Address 107 HMCNT 11ND1 L 1091/10 ALINWCVT F1S LIVERMURE, CH. 9455	10. SPA ; t .	US EPA	D Number		Cr 1/4		7300	
	11. Waste Shipping Name and Description					12. Cont No.	ainers Type	13. Total Quantity	14. Unit Wt/Vol
	·NUN HINCARDOMS IN	MSTE, SOLI	ID			001	•	00015	
GHZHR	b.					•			
ATOR	c				•	•			
	d.							• • • •	
	Additional Descriptions for Materials Listed About 1300 1300 1300 1300 1300 1300 1300 130		# R1)	3218ML	E. Han	dling Code	s for We	astes Listed Above	
	Use Appropriate PPE							1.01.02	
	24 HR EMERGENCY # 1-800-56		this manifest are	not subject to federal reg				sposal of Hazardous	Waste.
٧	Printed/Typed Name		Signature R	19-					Year 0.6
TRANSP	17. Transporter 1 Acknowledgement of Receipt of A Printed/Typed Name FRINDIND J. BELL	۷	Signature S.M.	rond L	4		,,,,	Month Day	Year
ORTER	18. Transporter 2 Acknowledgement of Receipt of A Printed/Typed Name	Aaterials	Signature				· · · · · · · · · · · · · · · · · · ·	Month Day	Year
FAC	19. Discrepancy Indication Space		-75		•		.•		
1	Sacility Owner or Operator: Certification of rece	eipt of waste materials ca	vered by this m	anifest except as note	d in Item	19		<u>-</u>	
Y	Printed/Typed Name		Signature					Month Day	Year

GENERATOR'S COPY

		15 9	Art						
	NON-HAZARDOUS WASTE MANIFEST	1. Generator's US EPA	ID No.	Manifest Document No.	2. Page of	e 1			
/	3. Generator's Name and Mailing Address W	Dy Roice	Alameda						
ት	PHILDING TO HILLST		intoga :	street					
	4. Generator's Phone (Oli) 71/17. M		ic 700	•					
	5. Transporter 1 Company Name	6.	US EPA ID Num	ber	A. Tran	sporter's P	hone	· · · · · · · · · · · · · · · · · · ·	<u>.</u>
	Philip West Industrial Services	G: /	4 R G G G G G	3.4.1.4.5		1-800-8	00-74	172	
	7. Transporter 2 Company Name	8.	US EPA ID Num	ber.	B. Tran	sporter's P	one		•
	9. Designated Facility Name and Site Address	10.	US EPA ID Num	hae	C Small	lity's Phone			
			OS EFA ID ROIS	ibei	C. ruci	my's rhone		٠	
	ALTHMENT LANDFILL	SCPA.						•	
	LIVERMORE CA GU			• • • •	172			7200	· .
	11. Waste Shipping Name and Description					12. Cont		13. Total	14. Unit
		HATE C "				No.	Туре	Quantity	Wt/Vol
11	" NON HAZARDOUS WI	fisher such	/13	•	l		مندم		1.1/
	And the second of the second o					0.0.1	The state of	00.0.18	5 /
ģ	b.	•							
n Z n									
RA	c.								
7	## W.			÷	.				
Ř		•			·		•		
	d.						:		-
								·	
ļ)·	Additional Descriptions for Materials Listed Abo	Ye 17:	- C - 20 1 2 2 1	Tio 1	E. Hanc	lling Code	for W	astes Listed Abov	
1		₩ 11.3	1120 111 11 11 11 11						
	Δr	pin	井 20-131-	170		·			
	Profile # 155387260	βίN	# 20-131-	45					
	Profile #15387760 (TO133	p to	# 20-131-	45			·.	.,.	· · · · · · · · · · · · · · · · · · ·
	Profile #17367260 (TO133 15. Special Handling Instructions and Additional In	p to	# 20-131-	40			· .		
	Profile #15387760 (TO133	p to	# 20-131-	40	Joh 4	i.l.			
	Profile #17367260 (TO133 15. Special Handling Instructions and Additional In	p to	# 20-131-	40		;			
	Profile #17367260 (TO133 15. Special Handling Instructions and Additional In	p to	# 20-131-	40		, i			
	Profile #15367160 (T0133 15. Special Handling Instructions and Additional In Use Appropriate PPE	formation	# 20-131-	40	Joh 4				
	Profile # 15367160 (TO 133 15. Special Handling Instructions and Additional In Use Appropriate PPE 24 HR EMERGENCY # 1-800-567	formation			Jeb q PO #	ŧ 26-		01.02	
	Profile # 1387160 (TO 133 15. Special Handling Instructions and Additional In Uso Appropriate PPE 24 HR EMERGENCY # 1-800-567	formation	this manifest are not sub		Jeb q PO #	ŧ 26-		ひし. ひ Z isposal of Hazardo	us Waste.
	Profile # 1367160 (TO 133 15. Special Handling Instructions and Additional In Use Appropriate PPE 24 HR EMERGENCY # 1-800-567 16. GENERATOR'S CERTIFICATION: I certify the many printed/Typed Name	formation	this manifest are not sub Signature		Jeb q PO #	ŧ 26-		ひし、ひ Z isposal of Hazardo Month Da	us Waste, v Year
T Y	Profile # 1387160 (TO 133 15. Special Handling Instructions and Additional In Uso Appropriate PPE 24 HR EMERGENCY # 1-800-567	formation 7-7455 aterials described above on	this manifest are not sub		Jeb q PO #	ŧ 26-		ひし. ひ Z isposal of Hazardo	us Waste. v Year
TRAN	Profile #17367160 (TO133 15. Special Handling Instructions and Additional In Use Appropriate PPE 24 HR EMERGENCY # 1-800-567 16. GENERATOR'S CERTIFICATION: I certify the many printed/Typed Name Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Many Printed/Typed Name	formation 7-7455 aterials described above on	this manifest are not sub Signature		Jeb q PO #	ŧ 26-		ひし、ひ Z isposal of Hazardo Month Da	us Waste. Year
TRANSP	Profile # 1367160 (TO 133 15. Special Handling Instructions and Additional In Use Appropriate PPE 24 HR EMERGENCY # 1-800-567 16. GENERATOR'S CERTIFICATION: I certify the many printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Many Printed/Typed Name Printed/Typed Name	formation 7-7455 aterials described above on	this manifest are not sub		Jeb q PO #	ŧ 26-		isposal of Hazardo Month Da	us Waste. Year
- TRAZSPORT	Profile # 1367160 To 133 15. Special Handling Instructions and Additional In Use Appropriate PPE 24 HR EMERGENCY # 1-800-567 16. GENERATOR'S CERTIFICATION: I certify the many printed/Typed Name Printed/Typed Name 17. Transporter 1. Acknowledgement of Receipt of Many Printed/Typed Name 18. Transporter 2. Acknowledgement of Receipt of Many Printed/Typed Name	formation 7-7455 aterials described above on	this manifest are not sub Signature BL Signature		Jeb q PO #	ŧ 26-		Sposal of Hazardo Month Day 1 . 0 0 Month Day	us Waste. Year () Year
S P	Profile # 1367160 (TO 133 15. Special Handling Instructions and Additional In Use Appropriate PPE 24 HR EMERGENCY # 1-800-567 16. GENERATOR'S CERTIFICATION: I certify the many printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Many Printed/Typed Name Printed/Typed Name	formation 7-7455 aterials described above on	this manifest are not sub		Jeb q PO #	ŧ 26-		isposal of Hazardo Month Da	us Waste. Year () Year
S P	Profile # 1367160 To 133 15. Special Handling Instructions and Additional In Use Appropriate PPE 24 HR EMERGENCY # 1-800-567 16. GENERATOR'S CERTIFICATION: I certify the many printed/Typed Name Printed/Typed Name 17. Transporter 1. Acknowledgement of Receipt of Many Printed/Typed Name 18. Transporter 2. Acknowledgement of Receipt of Many Printed/Typed Name	formation 7-7455 aterials described above on	this manifest are not sub Signature BL Signature		Jeb q PO #	ŧ 26-		Sposal of Hazardo Month Day 1 . 0 0 Month Day	us Waste. Year () Year
S P	Profile # 1367160 (TO 133 15. Special Handling Instructions and Additional In Use Appropriate PPE 24 HR EMERGENCY # 1-800-567 16. GENERATOR'S CERTIFICATION: I certify the me Printed/Typed Name 17. Transporter 1. Acknowledgement of Receipt of Merinted/Typed Name 18. Transporter 2. Acknowledgement of Receipt of Merinted/Typed Name	formation 7-7455 aterials described above on	this manifest are not sub Signature BL Signature		Jeb q PO #	ŧ 26-		Sposal of Hazardo Month Day 1 . 0 0 Month Day	us Waste. Year () Year
SPORTER	Profile # 1367160 (TO 133 15. Special Handling Instructions and Additional In Use Appropriate PPE 24 HR EMERGENCY # 1-800-567 16. GENERATOR'S CERTIFICATION: I certify the me Printed/Typed Name 17. Transporter 1. Acknowledgement of Receipt of Merinted/Typed Name 18. Transporter 2. Acknowledgement of Receipt of Merinted/Typed Name	formation 7-7455 aterials described above on	this manifest are not sub Signature BL Signature		Jeb q PO #	ŧ 26-		Sposal of Hazardo Month Day 1 . 0 0 Month Day	us Waste. Year () Year
S	Profile # 1367160 (TO 133 15. Special Handling Instructions and Additional In Use Appropriate PPE 24 HR EMERGENCY # 1-800-567 16. GENERATOR'S CERTIFICATION: I certify the me Printed/Typed Name 17. Transporter 1. Acknowledgement of Receipt of Merinted/Typed Name 18. Transporter 2. Acknowledgement of Receipt of Merinted/Typed Name	F-7455 aterials described above on Acterials	this manifest are not sub Signature Signature	ject to federal regu	Joh ;	7.6- r reporting p		Sposal of Hazardo Month Day 1 . 0 0 Month Day	us Waste. Year () Year
SPORTER	Profile # 7367160 To 133 15. Special Handling Instructions and Additional In Use Appropriate PPE 24 HR EMERGENCY # 1-800-567 16. GENERATOR'S CERTIFICATION: I certify the many printed/Typed Name 17. Transporter 1. Acknowledgement of Receipt of Many Printed/Typed Name 18. Transporter 2. Acknowledgement of Receipt of Many Printed/Typed Name 19. Discrepancy Indication Space	F-7455 aterials described above on Acterials	this manifest are not sub Signature Signature	ject to federal regu	Joh ;	7.6- r reporting p		Sposal of Hazardo Month Day 1 . 0 0 Month Day	us Waste. Year () Year
SPORTER	Profile # 7367160 To 133 15. Special Handling Instructions and Additional In Use Appropriate PPE 24 HR EMERGENCY # 1-800-567 16. GENERATOR'S CERTIFICATION: I certify the many printed/Typed Name 17. Transporter 1. Acknowledgement of Receipt of Many Printed/Typed Name 18. Transporter 2. Acknowledgement of Receipt of Many Printed/Typed Name 19. Discrepancy Indication Space	F-7455 aterials described above on Acterials	this manifest are not sub Signature Signature	ject to federal regu	Joh ;	7.6- r reporting p		Sposal of Hazardo Month Day 1 . 0 0 Month Day	vs Waste. Year Year Year Year

NON-HAZARDOUS WASTE MANIFEST 2. Generator's USEPA ID No. WASTE MANIFEST 2. Generator's Name and Manifing Address FIELD STATE MANIFEST 2. HO STATE MANIFEST 2. HO STATE MANIFEST 3. Generator's Phone STATE MANIFEST 4. I A IT MILE MANIFEST 4. I A IT MILE MANIFEST 5. Transporter 1 Company Name 6. USEPA ID Number 7. Transporter 2 Company Name 8. USEPA ID Number 9. Designated Facility Name and Site Address 4. I TAMOUT I NOT II. 10. USEPA ID Number 9. Designated Facility Name and Site Address 4. I TAMOUT I NOT II. 11. Waste Shipping Name and Description 12. Containers 13. Total 14. I A IT MILE MANIFEST 15. Special Manifest 16. A STATE MANIFEST 17. Containers 17. Transporter's Phone 18. Transporter's Phone 19. Designated Facility Name and Site Address 10. USEPA ID Number 11. Waste Shipping Name and Description 12. Containers 13. Total 14. I MILE MANIFEST 15. Special Manifest M				•	Ψ.		200			
A Transporter's Phone A Transporter's Phone A Transporter's Phone Philip West industrial Services CARO O O O O O O O O O O O O O O O O O O			1.		4Document No.	1	e 1			
A LAWL DI CH GILL A Conservor's Phone (II) 747-940 5. Transporter I Company Name A. Transporter's Phone Philip West industried Services C. A. R. G. G. G. B. 8. 4. 1. 4. 5 1-809-900-7472 7. Transporter 2 Company Name B. Transporter's Phone D. Designated Facility Name and Site Address A L TH MILLY I I MOF II L USEPA ID Number C. Facility's Phone A L TH MILLY I I MOF II L USEPA ID Number C. Facility's Phone D. USEPA ID Number A L TH MILLY I I MOF II L USEPA ID Number C. Facility's Phone C. Facility Phone C.	_13.	Generator's Name and Mailing Address								
5. Transporter 1 Company Name Pfillip West Industrial Services C. A. B. G. G. G. B. A. 1. 4. 5 1.800-900-7472 7. Transporter 2 Company Name 8. US EPA ID Number 8. Transporter's Phone Posignated Facility Name and Site Address A 1 7 H WLVT I INDEFIL ILLUS IN TOTAL PASSED IN FIRM CEF (A. 7405C) 11. Waste Shipping Name and Description a. NUM INTERCUS WACTE SULIA Additional Descriptions for Materials Listed Above Profile # 138.73C Additional Descriptions for Materials Listed Above Profile # 138.73C Additional Descriptions for Materials Listed Above Profile # 138.73C Total Profile # 182.92 ML E. Handling Codes for Waster Listed Above Profile # 138.73C Total Profile # 182.92 ML Total Profile # 182.92 ML Additional Descriptions for Materials Listed Above Profile # 138.73C Total Profile # 182.92 ML Total Profile # 182.	ر آنا	ALAWEDA CH GYEI	γ ₂ 5 5		34,661,					
Philip West industrial Services 7. Transporter 2 Company Name 8. US EPA ID Number 9. Designated Facility Name and Site Address A 1 1 A W 1 Y 1 Y N D F 1 L 1	1			US FPA ID Nu	ımher	A. Tro	sporter's F	hone	· · · · · · · · · · · · · · · · · · ·	
7. Transporter 2 Company Name 8. US EPA ID Number 8. Transporter's Phone 9. Designated Facility Name and Site Address A 1 7 A W L V T 1 W D F I L I L L L L L L L L L L L L L L L L L		· · · · · · · · · · · · · · · · · · ·					•		172	
Additional Descriptions for Materials Listed Above Profile # 130 150 150 150 150 150 150 150 150 150 15	7.					B. Tran				
Additional Descriptions for Materials Listed Above Profile # 130 150 150 150 150 150 150 150 150 150 15	_			<u> </u>		<u> </u>			· · · · · · · · · · · · · · · · · · ·	
11. Waste Shipping Name and Description 12. Contoiners Total No. Type Total Quantity a. NUN FINTALXUS WACTE, SULIA 0.0:1 CM 00:0:1 5 b. O. O. I. CM 00:0:1 5 d. O. O. I. CM 00:0:1 5 BIN # 182 92 ML E. Handling Codes for Wastes Listed Above Profile # 138.73 CC CTO 133 Big 360 6:5 15. Special Handling Instructions and Additional Information Use Appropriate PPE Job #		ALTHINICINT LANDEIL	L	. US EPA ID Nu	mber	C. Faci	lity's Phone			
11. Waste Shipping Name and Description a. NUN HITAEXUS WACTE, SOLIA b. Additional Descriptions for Materials Listed Above Profile = 138.73\omega_ 55 15. Special Handling Instructions and Additional Information Use Appropriate PPE Job #		LEYCALTAMONT PA	195 KA. 1950 — 1.			92	5-49	ζ.	1300	
a. NUN FINTAFIXUS WACTE SULIA a. NUN FINTAFIXUS WACTE SULIA b. d. Additional Descriptions for Materials Listed Above Profile # 18292 ML CTO 133 Bly = 360 6.75 15. Special Handling Instructions and Additional Information Use Appropriate PPE Job ##	4 1					<u> </u>			13.	14.
Additional Descriptions for Materials Listed Above Additional Descriptions for Materials Listed Above Profile 2 360 6.75 15. Special Handling Instructions and Additional Information Use Appropriate PPE Job ##	11.		·				No.	Туре		Unit Wt/Vo
Additional Descriptions for Materials Listed Above Additional Descriptions for Materials Listed Above Profile = 138.73 CTO 133 Blog 360 f. ~ 5 15. Special Handling Instructions and Additional Information Use Appropriate PPE Job #	a.	NUN HAZAFIXUS W.	ACTE, SUL	14						
Additional Descriptions for Materials Listed Above Additional Descriptions for Materials Listed Above Profile = 133 Blog 360 6.05 15. Special Handling Instructions and Additional Information Use Appropriate PPE Job #						.	0.0.1	CM	00.01.5	Y
Additional Descriptions for Materials Listed Above Profile # 18292 ML C70 133 Blog 360 6.05 15. Special Handling Instructions and Additional Information Use Appropriate PPE Job #	g b.				•					
Additional Descriptions for Materials Listed Above Profile # 18292 ML C70 133 Blog 360 6.05 15. Special Handling Instructions and Additional Information Use Appropriate PPE Job #	N				•.					
Additional Descriptions for Materials Listed Above Profile # 18292 ML C70 133 Blog 360 6.05 15. Special Handling Instructions and Additional Information Use Appropriate PPE Job #	Ā				•	· ·			• • •	
Additional Descriptions for Materials Listed Above Profile # 18292 ML C70 133 Blog 360 6.05 15. Special Handling Instructions and Additional Information Use Appropriate PPE Job #	<u>ר</u>		•							
Additional Descriptions for Materials Listed Above Profile = 38.13	i L			·	· · · · · · · · · · · · · · · · · · ·		• ', •	. •		<u>.</u>
Profile # 673673W CTO 133 Blog 360 6.45 15. Special Handling Instructions and Additional Information Use Appropriate PPE Job #	d.									١.
Profile # 673673W CTO 133 Blog 360 6.45 15. Special Handling Instructions and Additional Information Use Appropriate PPE Job #	11									
CTO 133 Blog 360 6.45 15. Special Handling Instructions and Additional Information Use Appropriate PPE Job #	1.5.5	Additional Descriptions for Materials Listed Abo	ove / O i	114 1010	12 .4.	E. Hand	dling Code	s for W	astes Listed Abov	 'e
15. Special Handling Instructions and Additional Information Use Appropriate PPE Job ##	14	Profile # 6/38/13W	י כו	N# 1074	16 MIL			•		
15. Special Handling Instructions and Additional Information Use Appropriate PPE Job ##	Η,	CTO 133					• • •			
Use Appropriate PPE Job #		· · · · · · · · · · · · · · · · · · ·					· .	· ·		
			nformation							•
24 HR EMERGENCY # 1-800-587-7455 PO # ZG - 111 : 01. 0	Ш	Use Appropriate PPE			• • • • •	Job :	性	:		
24 HR EMERGENCY # 1-800-567-7455 PO # Z.G - 111 : 01. 6				erit grant for			, ,	٠.		
24 HR EMERGENCY # 1-800-587-7455 PO # ZG - 111:01.0										
" 26 11.01,0	$\ \cdot \ $	24 HR EMERGENCY # 1-800-56	7-7455			PO ±	5 71	7		~
16. GENERATOR'S CERTIFICATION: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous	16			this manifest are not su	bled to federal reg					
Printed/Typed Name Signature Month Day					· · · · · · · · · · · · · · · · · · ·					
1 13.0 /200 11.010.5	_	 	· .·	1 BCV					11.010.5	10.6
T 17. Transporter 1 Acknowledgement of Receipt of Materials	1 /		Materials							· ·
A Printed/Typed Name Signature Signature Month Day COS	L		٠ .	Signature)	Market Strategy of the Strategy	وتكنيس	A STATE OF THE STA		1 2 4 1 4 7	Year
18. Transporter 2 Acknowledgement of Receipt of Materials	18.	Transporter 2 Acknowledgement of Receipt of	Materials	· · · · · · · · · · · · · · · · · · ·	2					
Printed/Typed Name Signature Month Day		Printed/Typed Name		Signature					Month Day	Year
19. Discrepancy Indication Space	19.	Discrepancy Indication Space								
			•							*
				.* *	•				•	
F A C		Facility Owner or Operator: Certification of rec	eint of waste materials o	overed by this manife	est except as noted	in Item	19.			
Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted in Item 19.	 				·.					
A C -)		* . * *	······································				Month Day	Year

UNI	FORM HAZARDOUS	1. Generator ID Number	1 .		ergency Response		4. Manifest	Tracking N			
1	ASTE MANIFEST	CA2170023238	<u> </u>	1	890-4 2 4-9360				<u> 1029</u>	<u> 60t</u>	GBF
	nerator's Name and Mailin DICC - Alamada Po				tor's Site Address Eldg 360	(ii ditterent t	nan mailing addre	ss)		-	
	30 Saratoga St. Si Jueda, CA 94501	P## 500	•		2450 Saratog		ite 260				
	rator's Phone: 510-74	19-5940	• 1	•	Alameda, CA	84501	•				
6. Tra	insporter 1 Company Nam	e					U.S. EPA ID	Number	CAL	79825	1363
	nbeste Transport		<u></u>					بالمرا وري	52-		
7. Ira	nsporter 2 Company Name	e			•		U.S. EPÀ ID 1	Number	•		
8. De:	signated Facility Name and Temical Vivaste IVI	1 Site Address	 	•			U.S. EPA ID.I	Number			
	iemicai vvaste ivia 251 Old Skyline R								•		
	ttleman City, CA !	93239					. 0 4 700	~~.~.		•	
Facilit	y's Phone: 559-38		· · · · · · · · · · · · · · · · · · ·		· 		CATOO:	J64611	/		
9a. HM	9b. U.S. DOT Description and Packing Group (if a	n (including Proper Shipping Name, Hazard Class, ID Number, ny))		. ,	10. Contain No.	ers Type	11. Total Quantity	12. Unit Wt./Vol.	13.	Waste Code	es ·
200	1Hazardous Waste	e liquid. n.o.s. (cadmium, chromium), 9, NA307	77, PGIII				-		D006	D007	F008
RQ	(D006, D007)		•		001	īT	2500	G	722	723	
	2.		٠,								
	-			·						<u> </u>	
	3.									<u> </u>	
	3.										
											·
	4.										
											
14. Sp	ecial Handling Instructions	and Additional Information	•		1				·		
C	on: Wear Appropri	ate protective equipment when handling. All V ERG # 171. CTO-133, Site 4-2	olumes are	e Estin	nated.	•			•	•	
٠. ٠	, me # LO-9700, L	110 # 171. 010-133, Site 7-2		-		•		•	•	•	
			 					<u> </u>	· · · · · · · · · · · · · · · · · · ·		
m	narked and labeled/placard	S'S CERTIFICATION: I hereby declare that the contents of this led, and are in all respects in proper condition for transport according	ording to applica	able inte	mational and natio	cribed above nal governm	e by the proper shi ental regulations.	pping name If export shi	, and are clas ipment and I a	sified, packa am the Prima	aged,
E	xporter, I certify that the co certify that the waste minin	intents of this consignment conform to the terms of the attached nization statement identified in 40 CFR 262.27(a) (if I am a large	d EPA Acknowle e quantity gene	edgment rator) or	of Consent. (b) (if I am a small	quantity ger	nerator) is true.				
	tor's/Offeror's Printed/Type			aftire				• .	Mon	th Day	Year
61	regory J.	Grace			Liegon	<u>().</u>	siano	٧	10) //	106
	rnational Shipments	Import to U.S.	Export from U.		Port of entr	y/exit:			· , _		
	orter signature (for exports nsporter Acknowledgment o				Date leaving	J U.S.:	······				
	orter 1 Printed/Typed Name		Sign	attire/	1	$\mathcal{O}_{\overline{a}}$	1/1.	/	Mon	th Day	Year
6	ARY BILL	NUGSLEY		A	suy /	Sille	liny &	1 .	1/9	0/11	06
Transpo	orter 2 Printed/Typed Name	9	Sign	ature	//		11/		Mon	th Day	Year
40 Die		<u> </u>					_//_				
	crepancy screpancy Indication Space				/				·		
100. 01.	ociopancy indicatori opaci	e		L	Residue		Partial Reje	ction	L	Full Reje	ction
			·	Ma	nifest Reference N	lumber:			•		
18b. Alt	ernate Facility (or Generat	or)					U.S. EPA ID N	umber			
							4.		•		
	s Phone: malure of Alternate Facility	(or Generator)							Mor	nth Day	Year
	,	, to some any						•	1	. 1	1
19. Haz	ardous Waste Report Man	agement Method Codes (i.e., codes for hazardous waste treatr	nent, disposal,	and recy	cling systems)			· .			
1.)	2.	3.				4.				
-		<u> </u>					<u> </u>		·		
	ignated Facility Owner or (Typed Name	Operator: Certification of receipt of hazardous materials covered	d by the manife Signa		t as noted in Item	18a			Mon	th Day	Year
	- > >						•		lwon	32,	

. Pi	ase D	not or bose (normale signed for use on elite (12-pitch) typewriter.)		·			. For	n Approved	OMB No.	2050-0039
Ī	S Park	Infortion to the control of the cont	2. Page 1 of 3.	Emergency Response 800-424-9300		4. Manifest	racking N	nuper		GBF
		gerupg Varies and Walling Address Perupg Varies and Walling Address About Office Of	Ge	nerator's Site Address	(If different ti	nan mailing addres	ss)			
		Signature of Contract of Contr	•	Bldg 360	. ~ ~	* 000				, i
	770	aneda: CA 94501		2450 Saratog Alameda, CA		ite 200				
		Prone: 510-749-5940		Mailleda, CA	04001					
	10.00	ansporter # Company Name				U.S. EPAID	kumber R	et.	_ <u> </u>	
		inbeste Transportation				CAD98	35136	32 CAP	18251	3632
	I Tr	insporter 2 Company Name				U.S. EPA ID N				
Ħ	١	strated Facility Name and Site Address Pernical Waste Management	- ; - ; - ; - ; - ; - ; - ; - ; - ; - ;	5 455		1 (10 COURT	lund an			
H		signated Facility Name and Site Address remical Waste Management	, , , , , , , , , , , , , , , , , , ,	1. 34. 14. 14. 15. 1	$C_{i}^{i}(\mathbb{R}^{N})$	USTEPAIUT	Numper			
H		201 Old Skyline Road .								
П	4	iftieman City, CA 93239 itys Phone: 559-386-9711				I CATOO	064611	7		
П	9a.	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number,		10. Contain	NOTE:	11. Total		<u> </u>		
11	HM	and Packing Group (if any))		· No.	Type	Quantity	12, Unit WŁ/Vol,	13.	Waste Cod	85
1.1		Hazardous Waste liquid, n.o.s. (cadmium, chromium), 9, NA307	7, PGIII					D006	D007	F008
	RQ	(D006, D007)		001	TT	5000	G	722	723	
品	<u> </u>		··-=			3000	`	122	723	
GENERATOR	<i>;</i> .	2.				[[
Ĭ						}		<u> </u>		
H		3.								
11							,			
П										
П		4.								
11	/				:					
	//									
n	Caul	pedal Handling Instructions and Additional Information tion: Wear Appropriate projective equipment when handling. All V	olumes are F	stimated				•	•	
14	1: F	Frofile #EC-9768 ERG # 171. CTO-133, Site 4-2							٠	1
N.										[
	15.	GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this	cansignment are t	illy and accurately des	mhed show	by the proper shi	inning name	and are No	hen haliba	cared
M		marked and labeled/placarded, and late in all respects in proper condition for transport acco	ording to applicable	e international and natio	mai governm	ental regulations.	If export sh	ipment and I	am the Prin	nary
X		Exporter, I certify that the contents of this consignment conform to the terms of the attached I certify that the waste minimization statement identified in 40 CFR 252.27(a) (if I am a large	a EPA ACKnowledg e quantity generate	ment of Consent. or) or (b) (iff am a smal	I quantity ge	neratori is true.				1
П	Gàne	rator's/Offeror's Printed/Typed Name	Signatu	re (1				Мо	nth Day	/ Year
1	(oregory J. Grace Tomational Stipments		Bregory	_9.	Brace	<u>۔</u>	1/	0 10	106
LIN	ŀ	L importo v.s.	Export from U.S.	Port of ent						
€		porter signature (for exports only):		Date leavin	g U.S.:					
世		ansporter Acknowledgment of Receipt of Materials porter 1 Printed(Typed Name		11	2,1	/		·		
ြည်	<i>\</i>	(Signatur	Caller K	-///	in the	•	Mot		1
SS	Trans	ANY SILLINGSLEY porter 2 Printed/Typed Name	Signatu	* // (//	1. Till	<i>m///</i> _	·	Mar.		Year
TR ANSPORT			i i	~\	/	1]/.	٠	- 1	[1:004
두	18. Di	screpancy		\	//	/				
		Vannan I. Janka Carra F-7			<u>v</u> /	Desire :			7,	
	3	Control Contro		Residue	J~	Partial Reje		311] Full Rej	jection
	Xe		ndy 1	Manifest Reference	Number:	tadne	٣, ١	7111	<i>30</i>]
Ė	18b. A	Uternale Facility (or Generalta)	U			U.S. EPAID N	umber			
ទ្វ										- 1
DF		y's Phone:								
4TE	104.0	ignature of Alternate Facility (or Generator)					•	M	nth Da	y Year
DESIGNATED FACILITY	19 H	azardous Wasie Report Management Method Codes (i.e., codes for hazardous waste treat	mont disposal a-	d mouding contract					L	
ES	1.	2.	ment, disposat, an	u rocycumy systems)		14.				
_		HI39	[•		- "			•	. 1
$\prod_{i=1}^{n}$	20. De	asignated Facility Owner or Operator: Certification of receipt of hazardous materials covere	d by the manifest of	except as noted in Ham	18a 🦳	 -	 -			
1		Typed Name	Signatu		\`	1.0		Mo	nth Day	/ Year "
1	1	James Ward		Xamue.	<u> </u>	105D-	_]]	DILO	DO
EP/	Form	8700-22 (Rev. 3-05) Previous editions are obsolete.			où i		4900			· · · · · · · · · · · · · · · · · · ·
			DE	SIGNATED FA	CILITY	DESTIN	AHON	STATE	IF REC	MIKED)
				•					5 TO 3.	

Plea	serprint or type. (Form designed for use on elite (12-pitch) typewriter.)				14.00 16.00		Approved, C	MD NO. 2	200-0039
↑	WASTE MANIFEST CA 217 002 3236	1 92	S-250 -		4. Manifest		154 3	3 11	IK
	5. Generator's Name and Mailing Address ROICC - Alaweda Pour	Gener	ator's Site Address	if different tha	ı mailing addres	s)			
	2450 Sora loga St., suite 2 AlomeDo, CA 94501	00							1
	Generator's Phone: 510 - 749 - 5940								
	6. Transporter 1. Company Name	3			U.S. EPAID		~ ~ l		ا سر
	Phip west Industrial Secure 7. Transporter 2 Company Name	<u> </u>			U.S. EPAID	OO C	084	14:	2
	•				1			•	
	8. Designated Facility Name and Ste Address Chemical Waste Management				U.S. EPA ID I	kumber			
11	25751 Old Skyline Rood								
	Keltleman (:ty, (** 93239) Facility's Phone: 559-386-9711				CAT	(00	0641	6 1 1	7.
	Sa. Sb. U.S. DOT Description (Including Proper Shipping Name, Hazzard Class, ID Number,		10. Contain	1978	11. Total	12. Unit		aste Code	
	HM and Packing Group (if any))	(2	No.	Туре	Quantity	W.L.Vol.			
g	1-RQ 12010000 Works Solid, 10.5. X FOOZ, FOOB), 9, NA3077 76111 (((F001,			0 -		611		
Z	7	, ,	1 .	CM	20	Y	FOO!	WZ.	F008
GENERATOR	2.							•	
lĭ	 							,	
	3.		 					·	1.
11			, B	1	•			-	
П	4.	·	 				 		
Ш	·		}						
Ш		· 	<u></u>				Parish		Ĺ,
11	14. Special Handling Instructions and Additional Information Wear Appropriate (E CWN Prof.	ic #: K	147397	7		<i>!</i>	•	•	
11	,,,,		•		•				
П	AS ASSESSMENT CONTRACTOR ASSESSMENT ASSESSME			and about	but the appear of	shoing nom	, sind are class	ified nach	anad .
Ш	 GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this or marked and labeled/placarded, and are in all respects in proper condition for transport account. 	ding to applicable i	nternational and nat						
	Exporter, I certify that the contents of this consignment conform to the terms of the attached in certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large			all quantity gen	erator) is true.		· · ·		
Ш	Generators/Offeror's Printed/Typed Name	Signature	e.	. 0	,		Mont		
土	Gregory J. Grace		Rugor	J. 12	noce		1/4	- 4	106
탈	Import to U.SE Transporter signature (for exports only):	Export from U.S.	Port of en Date leav	Ary/extt: ing U.S.:	.,	. .	·		
臣	17. Transporter Acknowledgment of Receipt of Materials	••	_ <u> </u>		1,5				Vere
TRANSPORTER	Transporter 1 Printed/Typed Name	Signature	o I la	1	56		Mont	h Day コーク	1 06
18	Transporter 2 Printed/Typed Name	Signature	1 - We	7000			Mon	ti Day	
E			<u></u>				!_	L	
1	18. Discrepancy							- - : -	
Ш	18a. Discrepancy Indication Space . Quantity Type		Residue		Partial Re	ejection	Ł	Full Re	jection
			Manifest Reference	e Númber:					
FACILITY	18b. Alternate Facility (or Generator)				U.S. EPA ID	Number			
謡	Facility's Phone:				1				
	18c. Signature of Alternate Facility (or Generator)		1.		<u> </u>		Mo	nth Da	y Yeer
S	IO II	ant disposal and							
DESIGNATED	Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatm 2.	nent, disposal, and	recycling systems)		4.				
1_{i}	H132								, ,,,,,, ,,,
	 Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered Printed/Typed Name 			m 18a		<u>.</u>	Mo	nth Da	y Year
11	STEVEN HOWHOUSER	Signature	Sz . E	2	eh	<u>.</u> .	ıZ	212	-

rie	150 P	initi or type: (Form designed for use on eithe (12-ptich) typewriter.)		IA Mandana		Approved.	OMD NO.	1000-0039
1	UNI	NFORM TUZARGOUS 1. Generator ID Number 2. Page 1 of 3. Emergency Res	=	4. Marifeet T				W
) v	MASTE MANIFEST 1 CA 214 00 23 236 1 1 1925, 25	0-4687	1 00	155	154	4 J.	ĮΓ.
11	5. G	Generator's Name and Malting Address Could A locate On Pount Generator's Site Ad						
1		2450 Sera toga Str. Svile 700 Alameda, CAJ 94501					٠	
	C=-	nerator's Phone: 510 - 749 - 5940						
11		Fransporter 1 Company Name		U.S. EPA ID N	lumber			
П	١.	Philip West Industrial Services		ICAR	MA	20 84	143	5
П	7. Tr	Transporter 2 Company Name		U.S. EPA ID N	lumber			
H	l		. 4	4	. :		نة س	
Н	8. D	Destons and Facility Name and Site Address		U.S. EPAID N			·	
П		Designated Facility Name and Ste Address Chemical worste Management 35251 Old Skyline Road	٠.	<u> </u>		٠		
П	1	Kethleman City, CA 93239		The bit				
П	١			IC AT	٠	~4	1 11	7
14		W NO BOTO I C C I F D W I I N I I I I I I I I I I I I I I I I				6	6 11	7
П	9a.	and Doubles Cours (dami)	containers	11. Total Quantity	12. Unit WŁ/Vol.	13.	Waste Code	s .
	-	10.	Туре	Cicarioty	MDVac			
K	١.	1RQ Hozardors weste Solid, no. 5. (Foot,	1 1			6.11		
IĘ	IX	(FUOZ, FODS), 9, NA3077 PGIII/EFOUL)	CM	20	. 🗸		_	
ENERATOR	<u> </u>		L'M	20	/	FOOL	Finz.	ho8
	1					1	ν.	
19	1			•				
П	<u> </u>	1	اـــــــــــــــــــــــــــــــــــــ					
Ш		3.	اسا	•		:		
Ш						·	*	
11							,	
Ш								
Ш	1					ļ		
П								
		Special Handling Instructions and Additional Information			do no no			
Н	1	Wear Apropriate PPE COM Prof. Te # 1 KT	4737	77				
Ш	1	b L				,	•	
П	1							
11	15	GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this christoment are fully and accural	سيحلو المطانعواء بكوا	h) the namer sh	loolog ram	i and are de	esified naci	ened.
П	"	marked and labeled/placested, and are in all respects in proper condition for transport according to applicable international ar	nd national governm					
П	1	Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Actnoyledgment of Consen						
Ш	-	I certify that the westernininintzation statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am nerator) (if I am a large quantity generator) or (b) (if I am nerator) (if I am a large quantity generator) or (b) (if I am a large quantity generator)	s smelt disturb Ser	seranor) as true.			nda Day	Van
П	1		- The same of the same of	2			_	ilo/.
1		THE PARTY OF THE P	25 1 8	2 minus	•		212	LOB
ΙĘ	1	International Shipments Import to U.S. Export from U.S. Por	t of Gnitry (Exit:	<u> </u>				·
			e leaving U.S.:					
TRANSPORTER	17.1	Transporter Actinowledgment of Receipt of Makeriels	<u>: </u>	 	<u>: </u>			14000
15	11000	neporter 1 Printed/Pyted Name Signature				Mo	nth Dey	Year
18	بيإ	Jon Cusherberg					2 - 2	LOG
13	(Last)	nsporter 2 Printed Typed Name Signature				PRIC	hth "Dey	' Year
E	1						!_	
1	18.0	Discrepancy	•				<u> </u>	
Ш	18a.	L Discrepancy Indication Space Quantity Type Residue	•	Partial Rej	laction		Full Re	lection
H								,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
Ľ	L	Manifest Ref	erence Number:			<u>s</u>		
	18b.	a. Alternata Facility (or Generator)		U.S. ÉPA ID	Number	1	· · · ·	
님	1							
Z	Faci	#in/s Phone;		1				
	18c.	s. Signature of Alternate Facility (or Generator)			•	M	onth Da	y Year
IΞ	1				•	- 1	1	ı
DESIGNATED FACILITY	19:3	Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling syst	lams		····	!-		
S	1.	2		4.				·
	l"	4172		1"				
$\ \ $	20 -	Professional Conflict Courses Confliction of market of the state of th	11- Nove 40-	سنطب				
		Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted and Typed Name Sconsture	int nert 188		•		onth Da	y Year
Н			1 11			. m		,
L	<u></u>	STE Ut A HANHOUSEA STORM	- Man			<u>!/</u>	614	<i>\$6</i>
		III O LUEZZ UKRY (SUD). PTRYOUS ROMODS SIG OBSOIGE		DESIGNAT	ED EAR	MITTYT	OCH	ED ATO

Printed/Typed Name	Signature /	Month	Day Year
Gregory J. Grace	Kriggy , Brace	1017	0000
17. Transporter 1 Acknowledgement of Receipt of Materials		-	· · · · · · · · · · · · · · · · · · ·
Printed/Typed Name	Signature Carly	D 7	12006
18. Transporter 2 Acknowledgement of Receipt of Materials			
Printed/Typed Name	Signature	Month	Day Year
19. Discrepancy Indication Space			
20. Facility Owner or Operator Certification of receipt of hazardous materi	als covered by this manifest except as noted in Item 19.		17 174
Octobed / Torond Marin	Signature	Month	Day Year

DO NOT WRITE BELOW THIS LINE.

1 C. C. C. Herni	10.11	ifest Documen		1001		cramento, California
UNIFORM, HAZARDOUS, CIAI2111710	1012131213160	13 18	i No.	2. Page 1		in the shaded areas ed by Federal law.
frage and the control of the control	da Point	1 1 1	A. State	Nähifest Döcüme	nt Number	
2450 Saratoga St.			2018		44	88000
Alameda, CA 94501 4. Generalor's Phone 191251-363-3789- 618(5)	0) 749-594	G	B. Slale (enerator's ID		
	US EPA ID Number		C; State I	ransporter's ID [Reserved	
M = = = = = = = = = = = = = = = = = = =		2.00	THE THE PER			
	50986607 US EPA ID Number	12 1810		ransporter s ID (00 - 4 <u>2</u> 3	120 <u>0</u> 5
	30 -17,10		1			
Designated Facility Name and Site Address 10.	US EPA ID Number		就是其他个世 生	oriar s Phone s Acility's ID		
US Ecology Nevada				inicie).		
11 Miles 3. of Beatty on HWY 95 Beatty, NV880063			H. Facilit		4053424	
	V T 3 3 0 0 1 0		lainers	13, Total		
11. US DOT Description (including Proper Shipping Name, Hazard Class, a	ind ID Number)	No.	-Турв.	Quantity	Wt/Vol 🗓	Wasie Number v
Hazardous Waste Solid, N.O.S., 9,	NA3077. PGIII					late 352
(Activated Carbon)		01/13	8 A	1,7,3,0	UY I	18629, Boat
		13.57%		1775 - 7-18		role 25 Marie 2000
왕 그 그 그 이 작는 사람들 사람들이 있었다. 그 중에 가장 그 나는 것이다. 강조를 보고 하는 사람들은 이 기술을 하면 하는 것으로 되었다.					***************************************	PA/Other State 7 &
स्थित कर्ता । । विकासी प्रति प्रति प्राप्ति । पुर्व केरियानस्थानी व विकास विकास के प्रति के प्रति । स्थापी क रण विकास प्रति । स्थापीय विकास केरियान स्थापी । स्थापीय विकास विकास विकास विकास ।	<u>naszák Miller Miller (h. 1868)</u> 11. áznak – Gardina A					loie Vertical Control
						PA/Ohen Fall (1997)
		1,50 2,50 3,60 3,60 4,60				ilate
				i Lieta		PA/Other216_1211
J. Additional Descriptions for Materials Listed Above			K. Handli	ig Codes for Wa	stes Listed Above	
114.07-013-8972.DGQ3			o-U		6.76	
15. Special Handling Instructions and Additional Information		-9789				
24 Hour Emergency Contact: Norm H. Alternate Contact: Alex Peru @ 366	s consignment are fully and accu	raiely describ	ed above by	proper shipping	nome and are cla	assified, packed.
Alternate Contact: Alex Peru & 360	s consignment are fully and accu	rately describ applicable in	ed above by iternational	proper shipping and national go	nome and are cla vernment regulation	assified, packed, ons.
Alternate Contact: Alex Peru @ 360	s consignment are fully and occursport by highway according to ace to reduce the volume and to storage, or disposal currently	applicable in exicity of war	iternational ste generate me which m	and national go d to the degree inimizes the pre	vernment regulation I have determined	ons. d to be economically reat to human health
Alternate Contact: Alex Peru & 360 16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this marked, and labeled, and are in all respects in proper condition for trail. If I am a large quantity generator, I certify that I have a program in plantacticable and that I have selected the practicable method of treatment and the environment; OR, if I am a small quantity generator, I have may available to me and that I can afford.	s consignment are fully and occursport by highway according to ace to reduce the volume and to storage, or disposal currently	applicable in exicity of war	iternational ste generate me which m	and national go d to the degree inimizes the pre	vernment regulation I have determined	ons. I to be economically reat to human bealth
Alternate Contact: Alex Peru & 360 16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this marked, and labeled, and are in all respects in proper condition for training the contents of the marked, and labeled, and are in all respects in proper condition for training the content of the c	s consignment are fully and accurate to the second of the	applicable in exicity of war	iternational ste generate me which m	and national go d to the degree inimizes the pre	I have determine sent and future the sest waste manage Month	ons. d to be economically reat to human health ement method that is
Alternate Contact: Alex Peru & 360 16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this marked, and labeled, and are in all respects in proper condition for training the series of the practicable and that I have selected the practicable method of treatment and the environment; OR, if I am a small quantity generator, I have me available to me and that I con afford. Printed/Typed Name 17. Transporter I Acknowledgement of Receipt of Materials Printed/Typed Name	s consignment are fully and accurate to reduce the volume and to storage, or disposal currently ade a good faith effort to minimal Signature	applicable in exicity of war	iternational ste generate me which m	and national go d to the degree inimizes the pre	vernment regulation I have determined sent and future the sest waste manage	ons. d to be economically reat to human health ement method that is
Alternate Contact: Alex Peru @ 366 16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this marked, and lobeled, and are in all respects in proper condition for training the environment; OR, if I am a small quantity generator, I have may available to me and that I con afford. Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name 18. Transporter 2 Acknowledgement of Receipt of Materials	s consignment are fully and accurate to the second of the	applicable in exicity of war	iternational ste generate me which m	and national go d to the degree inimizes the pre	I have determine sent and future the sest waste manage Month	Day Year
Alternate Contact: Alex Peru & 360 16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this marked, and labeled, and are in all respects in proper condition for training the contents of the marked, and labeled, and are in all respects in proper condition for training the environment; OR, if I am a small quantity generator, I have many labele to me and that I can afford. Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name	s consignment are fully and accurate to highway according to ace to reduce the volume and to storage, or disposal currently ide a good faith effort to minimal Signature	applicable in exicity of war	iternational ste generate me which m	and national go d to the degree inimizes the pre	I have determine sent and future the sest waste manage Month	Day Year
Alternate Contact: Alex Peru @ 366 16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this marked, and lobeled, and are in all respects in proper condition for training the environment; OR, if I am a small quantity generator, I have may available to me and that I con afford. Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name 18. Transporter 2 Acknowledgement of Receipt of Materials	s consignment are fully and accurate to highway according to ace to reduce the volume and to storage, or disposal currently ide a good faith effort to minimal Signature	applicable in exicity of war	iternational ste generate me which m	and national go d to the degree inimizes the pre	I have determine sent and future the set waste manage Month	Day Year
Alternate Contact: Alex Peru & 360 16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this marked, and labeled, and are in all respects in proper condition for training the contents of the marked, and labeled, and are in all respects in proper condition for training the environment; OR, if I am a small quantity generator, I have many labele to me and that I can afford. Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name	s consignment are fully and accurate to highway according to ace to reduce the volume and to storage, or disposal currently ide a good faith effort to minimal Signature	applicable in exicity of war	iternational ste generate me which m	and national go d to the degree inimizes the pre	I have determine sent and future the set waste manage Month	Day Year
Alternate Contact: Alex Peru & 360 16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this marked, and labeled, and are in all respects in proper condition for training the contents of the marked, and labeled, and are in all respects in proper condition for training the environment; OR, if I am a small quantity generator, I have many labele to me and that I can afford. Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name	s consignment are fully and accurate to highway according to ace to reduce the volume and to storage, or disposal currently ide a good faith effort to minimal Signature	applicable in exicity of war	iternational ste generate me which m	and national go d to the degree inimizes the pre	I have determine sent and future the set waste manage Month	Day Year
Alternate Contact: Alex Peru & 366 16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this marked, and labeled, and are in all respects in proper condition for training the environment; OR, if I am a small quantity generator, I have made and the environment; OR, if I am a small quantity generator, I have made and the I con afford. Printed/Typed Name 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name 19. Discrepancy Indication Space	s consignment are fully and accuminate to the second occurrency of the second occurrency of the second occurrency of the second occurrency of the second occurrency o	applicable in oxicity of waxicity of waxicity of waxicity of waxicity ize my waste	ste generate me which m generation	and national go d to the degree inimizes the pre	I have determine sent and future the set waste manage Month	Day Year Day Year Day Year

DO NOT WRITE BELOW THIS LINE

T-685 NON-HAZARDOUS WASTE MANIFEST 1586

Ple	ase print or type (Form designed for use on elite (1	(2 pitch) typowriter)	<u> </u>	· · · · · · · · · · · · · · · · · · ·	<u> </u>	· · ·			T = =
	NON-HAZARDOUS WASTE MANIFEST	1. Generator's US EP. G A 2	17 0 0	23236	; 		Manifest Document No		2. Page 1 of
`\	3. Generator's Name and Mailing Address ROICC - Alameda Point						Non-Haz	z Man#	:
	2450 Saratoga St. Suite 200 A 4. Generator's Phone (510) 749-5939	lameda CA 94: Attn:		Ng -					
	5. Transporter 1 Company Name		6.	US EPA ID Numb	er		A. State Trans	porters ID	
	I Landster Global Lo	ouistics	1				B. Transponer	1 Phone	
<i>:</i> ·	7. Transporter 2 Company Name	1	8.	US EPA ID Numb	er`		C. State Trans		
		<u> </u>	<u></u>		<u> </u>		D. Transporter		
	9. Designated Facility Name and Site Address		10.	US EPA ID Numb	er _.		E. State Facili	ı ya in	
	CALGON Carbon Corp. 3200 E Eight Mile R	₹a -					F. Facility's Ph	Lone	
	Stockton, CA 95212	-9414	<u> </u>		 -1	12. Co	1-8	65-225-4	
	11. WASTE DESCRIPTION		•			No.	Туре	Total Quantity	14. Unit WL/Vol.
	a. Non-hazardous waste solid (va	por phase carbo)n)			6	CM	12,000 18	P
				· · · · · · · · · · · · · · · · · · ·		0	O		
G	b.						·		
N				•					
GENER	C.		<u>. i</u>						
A								•	
T O		. <u> </u>					`	·	
R	d.			•					
			:		İ				
	G. Additional Descriptions for Materials Listed Above						H, Handling Co	des for Wasles Listed Abov	9
	11axVessel, Profile # _5	078 N							•
			,				·	•	
į							• • • •		
	Vapor phase site 4-2		ta a t			<u> </u>			
	15. Special Handling Instructions and Additional Infor		ladhimae a		oloni n		مطبي صمالا	n bondling	•
Ы	Caution: Wear appropriate All volumes are approximate	biorecrive c	torining a	ing teshii	atory p	NO(G(MOIT WITE	at Hallullig.	
Ų	Site pick up address: Alameda F	 Doint Alamada	CA		•				
	- Alameda P	- On a Alameda							
	16. GENERATOR'S CERTIFICATION: I hereby certifing proper condition for transport. The materials de-	ly that the contents of this scribed on this manifest	are not subject t	ally and accurately o federal hazardou	r described ar us waste regu	nd are 10 8 Nations.	III respects		,
									Date
	Printed/Typed Name		Signa	sture _	`			Mont	
	Bob Parricone			为义(ر <u>-ينحمد</u>	<u> </u>	<u>َ ح</u>	<u> </u>	122 07
[]	17. Transporter 1 Acknowledgement of Receipt of Mar	terials			:				Date
	PrintedCtyped Name	• *	Signa	rure 7	Ti a so	×: -/2-		Monti	Day Year
;	18. Transporter 2 Acknowledgement of Receipt of Mai	terials		41	in	- 7			Date
1	Printed/Typed Name	······································	Signa	iture		.	· .	Montt	
			·	· · · · · · · · · · · · · · · · · · ·				, .	1
=	19. Discrepancy Indication Space			•				•	
1				•		:			
íŀ	20. Facility Owner or Operator: Cartification of receipt	of the waste materials co	overed by this m	anilest, except as	noted in item	19.			
÷ [Date
d	Printed/Typed Name	•	Signa	ature.			•	Month	Day Year
1	· · · · · · · · · · · · · · · · · · ·					· · · · · · · · · · · · · · · · · · ·			

WORLD ENVIRONMENTAL & ENERGY, INC.

P.O. Box 256

West Sacramento, CA 95691

Tel: (916) 371-3617

Fax: (916) 371-3684

No. 1.8459

NON-HAZARDOUS WASTE DATA FORM

	NAME ROLCC - A	lameda P	oint			15823	
	ADDRESS 2450 Sar	ationa St	rest			EPA I.D. NO.	
	CITY, STATE, ZIP Alams	<u>∋da, CA</u>	94501		. /	PHONE NO. (0748 5939
GENERATOR	CONTAINERS: 1	No. 45	Base	VOLUME/C	<u> 3 </u>	WEIGHT/TONS_	
NER	TYPE: TANK	DUMF TRUC	K DRUMS	CARTONS	OTHER	Folloff/Flash Ou	tas Vaci
<u> </u>	WASTE DESCRIPTION No.	r Frishle) singtos	- Washa	GENERATING PROCES	ss	
à	COMPONENTS OF W	VASTE	PPM	1%	COMPON	NENTS OF WASTE	PPM %
8		•					
百	1		<u> </u>		3		
<u> </u>		•					
BE COMPLETED BY	VOC-OVA READINGS						
TO BI	SITE VERIFICATION Ala	međa Pt.	, Rlag. 3	60, Alamed	aço Cā		JOS #5370
) .	PROPERTIES: pH	_ 🗆 sốup]sludge []si	LURRY DOTHER		
	HANDLING INSTRUCTIONS: _	USE F	ROFER RESI	TRATORY D	ALIFYENT	MENHING	
	THE GENERATOR CERT	IFIES THAT T	HE BAL	P	50 6	1	diolor
	HAZARDOUS.			PRINTED FULL NAM	ME & SIGNATURE	***************************************	07/9/06 DATE
E	HAZARDOUS.		TYPED OR	PRINTED FULL NAM	ME & SIGNATURE	EPA	DATE
ATER	NAME STEEL IN	G EMVIRO	TYPED OR		ME & SIGNATURE		
PORTER I	NAME STEFLING ADDRESS 10203 E	STREET	TYPED OR	PRINTED FULL NAM DEPORYSTICKY	AE & SIGNATURE	SERVICE ORDER NO.	DATE
NSPORTER I	NAME STEEL INC. ADDRESS 10203 F. CITY, STATE, ZIP CANCEL	G EMVIRO STREET	TYPED OR WENTAL CL CA 9	PRINTED FULL NAM	AE & SIGNATURE		DATE
RANSPORTER I	NAME STEEL INC. ADDRESS 10203 E. CITY, STATE, ZIP CANCER	G EMVIRO STREET	TYPED OR WENTAL CL CA 94	PRINTED FULL NAM DEPORTATION 1603, ,		SERVICE ORDER NO.	P % O C O 1 1 9
TRANS	NAME STEEL INC. ADDRESS 10203 F. CITY, STATE, ZIP CANCEL	G EMVIRO STREET	TYPED OR WENTAL CL CA 94	PRINTED FULL NAM DEPORATION 1603, , 4007		SERVICE ORDER NO.	F 1 0 0 0 1 1 9 5 1 1 9 1 6 6
ER TRANSPORTER	NAME STEEL INC ADDRESS 10203 E CITY, STATE, ZIP CANCLE PHONE NO. (SMO) 63% TRUCK UNIT, I.D. NO.	G EMVIRO STREET AND 3-2800	TYPED OR FIENTAL DI CA 96 TYPED OR	PRINTED FULL NAM DEPORATION 1603, 1607 FRINTED FULL NAM		SERVICE ORDER NO. PICK UP DATE	DATE F 1 0 0 0 119 \$\frac{5}{19/66} DATE
ITER	NAME STEEL IN ADDRESS 10203 E. CITY, STATE, ZIP COAKLE PHONE NO. (1510) 638 TRUCK, UNIT, LD. NO.	GEWIRO STREET WID 3-2800	TYPED OR WENTAL DI CA 94 TYPED OR	PRINTED FULL NAM DEPORATION 1603, 1607 FRINTED FULL NAM		SERVICE ORDER NO. PICK UP DATE EPA I.D. NO. C A R D D	DATE F \$ 0 0 0 1 1 9 \$ //9/66 / DATE
ITER	HAZARDOUS. NAME STERL INV. ADDRESS 10203 E. CITY, STATE, ZIP COAKLE PHONE NO. ((5)(0)63X TRUCK, UNIT, LD. NO. NAME WEST 10 E. ADDRESS 3208 WEST	G EMMIRO STREET AND 3-2800 WIRONNE ST CAPITE SACRANES	TYPED OR WENTAL DI CA 90 TYPED OR TYPED OR TYPED OR TAL & EMPLOYER J. AVENUE	PRINTED FULL NAM OFF OFF TION A603, A07 SPRINTED FULL NAM FROY		SERVICE ORDER NO. PICK UP DATE EPA I.D. NO. I.C. A R D D SERVICE ORDER NO.	DATE F \$ 0 0 0 119 \$ //9/66
ITER	NAME STEEL IN ADDRESS 10203 E. CITY, STATE, ZIP COAKLE PHONE NO. (1510) 638 TRUCK, UNIT, LD. NO.	G EMMIRO STREET AND 3-2800 WIRONNE ST CAPITE SACRANES	TYPED OR TYPED	PRINTED FULL NAM DEPORATION 4693, WY PRINTED FULL NAM FOY DE491	IE & SIGNATURE	SERVICE ORDER NO. PICK UP DATE EPA I.D. NO. C A R D D	DATE F \$ 0 0 0 119 \$ //9/66
ITER	NAME STEEL INV ADDRESS 10203 E CITY, STATE, ZIP COAKLA PHONE NO. (1510) 638 TRUCK, UNIT, LD. NO. NAME WERL 1) 63 ADDRESS 3208 WES CITY, STATE, ZIP WEST PHONE NO. (1716) 373	G EMMIRO STREET AND 3-2800 WIRONNE ST CAPITE SACRANES	TYPED OR TYPED	PRINTED FULL NAM OFF OFF TION A603, A07 SPRINTED FULL NAM FROY	IE & SIGNATURE	SERVICE ORDER NO. PICK UP DATE EPA I.D. NO. I.C. A R D D SERVICE ORDER NO.	DATE F \$ 0 0 0 119 \$ //9/66
ORTER	HAZARDOUS. NAME STERL INV. ADDRESS 10203 E. CITY, STATE, ZIP COAKLE PHONE NO. ((5)(0)63X TRUCK, UNIT, LD. NO. NAME WEST 10 E. ADDRESS 3208 WEST	G EMMIRO STREET AND 3-2800 WIRONNE ST CAPITE SACRANES	TYPED OR TYPED	PRINTED FULL NAM DEPORATION 4693, WY PRINTED FULL NAM FOY DE491	IE & SIGNATURE	SERVICE ORDER NO. PICK UP DATE EPA I.D. NO. LC A R D D SERVICE ORDER NO. PICK UP DATE	DATE F \$ 0 0 0 119 \$ //9/66
ITER	NAME STEEL INV ADDRESS 10203 E CITY, STATE, ZIP COAKLA PHONE NO. (1510) 638 TRUCK, UNIT, LD. NO. NAME WERL 1) 63 ADDRESS 3208 WES CITY, STATE, ZIP WEST PHONE NO. (1716) 373	G EMMIRO STREET AND 3-2800 WIRONNE ST CAPITE SACRANES	TYPED OR TYPED	PRINTED FULL NAM DEPORATION 4693, WY PRINTED FULL NAM FOY DE491	IE & SIGNATURE	SERVICE ORDER NO. PICK UP DATE EPA	DATE F 1 0 0 0 119 \$ //9/66 DATE DATE
ITER	HAZARDOUS. NAME STEEL INV. ADDRESS 10203 E. CITY, STATE, ZIP CAKL. PHONE NO. (500) 638 TRUCK, UNIT, I.D. NO. NAME WORLD ES ADDRESS 3208 WES CITY, STATE, ZIP WEST PHONE NO. (90.6) 321 TRUCK, UNIT, I.D. NO.	3 EMMIRO STREET SNO 3-2800 WIRONNE ST CAPIT SACRAME I-3617	TYPED OR TYPED OR TYPED OR TYPED OR TYPED OR	PRINTED FULL NAM DEPORATION 4693, WY PRINTED FULL NAM FOY DE491	IE & SIGNATURE	SERVICE ORDER NO. PICK UP DATE EPA LD NO. LC A R D D SERVICE ORDER NO. PICK UP DATE EPA LD NO. C A D 9 8	DATE F \$ 0 0 0 1 1 9 \$ //9/66 DATE DATE
TRANSPORTER	HAZARDOUS. NAME STERL INT. ADDRESS 10203 E. CITY, STATE, ZIP CARKLE PHONE NO. (5M.0) 638 TRUCK, UNIT, LD. NO. NAME WERLL) E. ADDRESS 3208 WES CITY, STATE, ZIP WEST PHONE NO. (99.6) 321 TRUCK, UNIT, LD. NO.	G EMMIRO STREET SNO 3-2800 WIRONTE SACRAME I GALT CARDETE TAKONT I	TYPED OR WENTAL CO CA 9. TYPED OF TYPED OF TYPED OF	PRINTED FULL NAME OF PORCE TO THE PRINTED FULL NAME OF THE PRINTED FULL	IE & SIGNATURE	SERVICE ORDER NO. PICK UP DATE EPA LD NO. LC A R D D SERVICE ORDER NO. PICK UP DATE EPA LD NO. C A D 9 8	DATE F \$ 0 0 0 1 1 9 \$ //9/66 DATE DATE DATE
TRANSPORTER	NAME STEEL IN ADDRESS 10203 E. CITY, STATE, ZIP UNIT, LD. NO. NAME WERL!) EST ADDRESS 3208 WES CITY, STATE, ZIP WEST PHONE NO. (97.6)371 TRUCK, UNIT, LD. NO. NAME ADDRESS 10840 (4.1) NAME ADDRESS 10840 (4.1) ADDRESS 10840 (4.1)	G EMMIRO STREET AND G-2800 AMIRONNE F CAPTIE SACRAME G-3617	TYPED OR WENTAL CO CA 9. TYPED OF TYPED OF TYPED OF	PRINTED FULL NAME OF PORCE TO THE PRINTED FULL NAME OF THE PRINTED FULL	IE & SIGNATURE	SERVICE ORDER NO. PICK UP DATE EPA NO. 1 C A P P B DISPOSAL	DATE F \$ 0 0 0 1 1 9 \$ //9/66 DATE DATE DATE
TRANSPORTER	HAZARDOUS. NAME STERL INT. ADDRESS 10203 E. CITY, STATE, ZIP CARKLE PHONE NO. (5M.0) 638 TRUCK, UNIT, LD. NO. NAME WERLL) E. ADDRESS 3208 WES CITY, STATE, ZIP WEST PHONE NO. (99.6) 321 TRUCK, UNIT, LD. NO.	G EMMIRO STREET AND G-2800 AMIRONNE F CAPTIE SACRAME G-3617	TYPED OR WENTAL CO CA 9. TYPED OF TYPED OF TYPED OF	PRINTED FULL NAME OF PORCE TO THE PRINTED FULL NAME OF THE PRINTED FULL	IE & SIGNATURE	SERVICE ORDER NO. PICK UP DATE EPA NO. 1 C A P P B DISPOSAL	DATE F \$ 0 0 0 1 1 9 \$ //9/66 DATE DATE DATE
TRANSPORTER	NAME STEEL IN ADDRESS 10203 E. CITY, STATE, ZIP UNIT, LD. NO. NAME WERL!) EST ADDRESS 3208 WES CITY, STATE, ZIP WEST PHONE NO. (97.6)371 TRUCK, UNIT, LD. NO. NAME ADDRESS 10840 (4.1) NAME ADDRESS 10840 (4.1) ADDRESS 10840 (4.1)	G EMMIRO STREET AND G-2800 AMIRONNE F CAPTIE SACRAME G-3617	TYPED OR WHENTAL CO CA 94 TYPED OF TYPED OF TYPED OF	PRINTED FULL NAME OF PORCE TO THE PRINTED FULL NAME OF THE PRINTED FULL	IE & SIGNATURE	SERVICE ORDER NO. PICK UP DATE EPA NO. 1 C A P P B DISPOSAL	DATE F \$ 0 0 0 1 1 9 \$ //9/66 DATE DATE DATE
ITER	NAME STEEL IN ADDRESS 10203 E. CITY, STATE, ZIP UNIT, LD. NO. NAME WERL!) EST ADDRESS 3208 WES CITY, STATE, ZIP WEST PHONE NO. (97.6)371 TRUCK, UNIT, LD. NO. NAME ADDRESS 10840 (4.1) NAME ADDRESS 10840 (4.1) ADDRESS 10840 (4.1)	G EMMIRO STREET AND G-2800 AMIRONNE F CAPTIE SACRAME G-3617	TYPED OR WHENTAL CO CA 94 TYPED OF TYPED OF TYPED OF	PRINTED FULL NAME OF PRINTED FULL NAME OF STATE	IE & SIGNATURE	SERVICE ORDER NO. PICK UP DATE EPA NO. 1 C A P P B DISPOSAL	DATE F \$ 0 0 0 1 1 9 \$ //9/66 DATE DATE DATE
TRANSPORTER	HAZARDOUS. NAME STERL INT. ADDRESS 10203 F. CITY, STATE, ZIP CANCLE PHONE NO. (500) 638 TRUCK, UNIT, I.D. NO. NAME WERL!) 63 ADDRESS 3208 WES CITY, STATE, ZIP WEST PHONE NO. (706) 321 TRUCK, UNIT, I.D. NO. NAME ADDRESS 10840 (ALL ADDRES	3 EMMIRO STREET AND 3-2800 AMIRONTE SACRAMES 1-3617 TAMORT II TAMORE 1	TYPED OR WENTAL CO CA 94 TYPED OF TYPED OF TYPED OF TYPED OF TYPED OF TYPED OF TYPED OF	PRINTED FULL NAME FOR PRINTED FULL NAME FOR	IE & SIGNATURE	SERVICE ORDER NO. PICK UP DATE EPA NO. 1 C A P P B DISPOSAL	DATE F \$ 0 0 0 1 1 9 \$ //9/66 DATE DATE DATE
TRANSPORTER	HAZARDOUS. NAME STEEL IN ADDRESS 10203 E. CITY, STATE, ZIP DAKLE PHONE NO. (1510) 638 TRUCK, UNIT, LD. NO. NAME WERL!) 63 ADDRESS 3208 WES CITY, STATE, ZIP WEST PHONE NO. (1710) 632 TRUCK, UNIT, LD. NO. NAME ALTONION ADDRESS 10840 (ALTONION ADDRESS 10840 (ALTONION ADDRESS CITY, STATE, ZIP LTV PHONE NO. (1710) (ALTONION ADDRESS CITY, STATE, ZIP LTV PHONE NO. (3 EMMIRO STREET AND 3-2800 AMIRONTE SACRAMES 1-3617 TAMORT II TAMORE 1	TYPED OR TYPED OR TYPED OF TYPED OF TYPED OF TYPED OF TYPED OF TYPED OF TYPED OF	PRINTED FULL NAME OF PRINTED F	IE & SIGNATURE	SERVICE ORDER NO. PICK UP DATE EPA NO. 1 C A P P B DISPOSAL	DATE F \$ 0 0 0 1 1 9 \$ //9/66 DATE DATE DATE

Τ-	1. Generator's US EP	A 1D No. Man	ifest Documen	t No.	2. Page 1		Sacramento, California
	UNIFORM HAZARDOUS		3 8	1 6	of		ired by Federal law.
3.	Generator's Name and Mailing Address	808	diament distance	A. State	Manifest Document N	lumber	
'	RCICC-Alamada Point						448020
-	2450 Saratoga Street, Mageda, C			116	Generalor's ID		
	Generator's Phone (510) 749, 5939 775-5940 Transporter 1 Company Name 6.	US EPA ID Number	<u> </u>		P T R F	4 D D	ERBPI
1.	Transporter I Company Name	O3 EFA ID Number				rved.j	
<u> </u>	STEPLING ENVIRONMENTAL.	US EPA ID Number	10119	D. Trans	oorter's Phone	5in	ESUSSENIO
7.	Transporter 2 Company Name 8.	US EPA ID Number	-	E: State	ransporter's ID (Rese	rved.]	
1	WORLD ENVIRON & ENERGY	AROGOST	ក្ខាខាន	F. Transi	orter's Phone	.916	371-3637
9,	Designated Facility Name and Site Address 10.	US EPA ID Number	1.7.1	G + State	Facility's ID		
	NWS HAY ROAD LANDFILL				/s Phone		
.	6426 HAY ROAD VACAVILLE, CA 95687	भाषा श्राह्म था था था थ	141715	n eddill	/ 3 Phone	1707	, 1451-3276
1	US DOT Description (including Proper Shipping Name, Hozard Class,		12. Con	tainers	13. Total	14. Unit	100000000000000000000000000000000000000
	a.	und in Moningi	No.	Туре	Quantity	Wt/Vol	L. Waste Number State
	B B ACECTOC B NA 9919 DE LE	•					30- 151 77-33
	R.O. ASBESTOS, 9, NA 2212, PG II		0412	BA	00004	1/	EPA/Other
	b.		ż			/	State was a State
					4		EPA/Other
							(4) (6)
			_	٠. في			State
3				1	1111		EPA/Other 3/4
	d 200 3 100 100 100 100 100 100 100 100 100					100	State
						9 1 4	EPA/Other as
739230			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 :		na Oras ansansan	AND WASTERNAME.
	Additional Descriptions for Materials Listed Above (2015)			K Handli	ng Codes for Wastes	Listed Abov	
	TRIGELE MEHENTINE CONTAIN INC. WAST				3623651		
						d / / / /	
15	Special Handling Instructions and Additional Information			WATER TO		<u> </u>	
1	in the community of the	24 HRS. EMERGENC	Y 1-800	7 -535 -	3033-112	とう	232
	SITE: Alameda Point, Bldg. 360,	Alameda, CA					JOB #5370
	EPA REGION IX ASBESTOS REMOVAL REGUIREMENT AND	PET (ROBOEN SEAL	FN & I		ERG#171) `	4.	
16.	GENERATOR'S CERTIFICATION: I hereby declare that the contents of it marked, and labeled, and are in all respects in proper condition for it	nis consignment are fully and accu	rately describ	ed above b	y proper shipping na	me and are	classified, packed,
.:	marked, and labeled, and are in all respects in proper condition for tr	ansport by highway according to	abblicable in	iternational	and national govern	ment regulo	ilions.
	If I am a large quantity generator, I certify that I have a program in practicable and that I have selected the practicable method of treatme	place to reduce the volume and I	oxicity of wa	ste general	ed to the degree I ho	rve determin	ned to be economically.
ļ ·	practicable and that I have selected the practicable method of treatme and the environment, OR, if I am a small quantity generator, I have a available to me and that I can afford.	nade a good faith effort to minim	iize my waste	generation	and select the best	waste man	gement method that is
	ted/Typed Name	Signature A		'		Mont	
	regory J. Grace	Buron 1	1. Bro	بصف		Ois	
17.	Transporter 1 Acknowledgement of Receipt of Materials	111					
	ted/Typed Name	Signature	1	71		Mont	h Day Year Slocis Idil
	OSC OM BIGK() Transporter 2 Acknowledgement of Receipt of Materials	1 A JA ()	Co .	2202	<u></u>	علايا	71()13161
_	ed/Typed Name	Signature				Mont	Day Year
10	Silver 6	L		•		للل	
19:	Discrepancy Indication Space			•			
١.			• .	. ,			
		• .	•				
						•	

DO NOT WRITE BELOW THIS LINE.

A 1		h) typewriter.						Sacramento, California
	UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EP C A Z 117 C	adno. 019213121316	Manifest Documen	1 No.	2. Page 1		n in the shaded areas ired by federal law.
	3. Generator's Name and Mailing Address ROICC SF BAY - ALI 2450 SARATOGA ST.,					Vanifest Document)	lumber	2517522
	4. Generator's Phone (510) 749 -	59.40	INTICOM CIT	77301	15327	enerator's ID		
	5. Transporter 1 Company Name		US EPA ID Number			ransporter's ID [Res		
ŧ 🛌	vorld environmental & en	ergy c	ARPPPBB	7288	D. Transp	orter's Phone (916)	371-3617
	7. Transporter 2 Company Name	. 8.	US EPA ID Number	125	1.00	ronspactor's ID (Rese	ryed.]	
-	2. Designated Facility Name and Site Address	10.	US EPAID Number	1177		orter's Phône		
	ROSBY & OVERTON INC.	•				16464.11		
	ONG BEACH CA 90813	β i	A P P 2 B 4 P	ppla	ti. Facility		432-5	445
	11. US DOT Description (including Proper Shippin	g Name, Hazard Class,	and ID Number)	12. Con	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste Number
N	o, Ion RCRA HAZARDOUS WASTE	SOUTH (MASS	TTC SLOVENT)					State: 352
		pane (ann.		01011	TAM	901.125	Y	ERA/Other
· [ь.				.·	-191		State,
1.					. 1			EPA/Other
	C.			1 1 1				State
								EPA/Other
-	d. /	• •				-1-1-1-1-1	*	Side
. .		• .						EPA/Other
N	CENTRE RECEIVATE MONTH OF THE	TERT CAL PRO	TLE #39108		K. Handlin	g Codes for Wastes	Usted Abov	
	DOITIONAL STATE CODES	121						
							d.	
	5. Special Handling Instructions and Additional In		<u> </u>	<u> </u>	<u> </u>		<u> </u>	
W	ORLD ENVIRONMENTAL & EN	SKGY Z4 HOUR	S EMERGENCY	(800) 428	3-5232	EPA REG	CON IX	
							•	
-	 `-, 		is constanment are fully an					Plassified packed
1	 GENERATOR'S CERTIFICATION: I hereby decli- marked, and labeled, and are in all respects in 	are that the contents of the proper condition for tr	ansport by highway accord	d accurately describe	ed above by ternational	proper shipping national govern	ne and are o ment regula	tions.
	marked, and labeled, and are in all respects in	proper condition for in	ansport by highway accord	ing to applicable in	ternational	and national govern	ment regula	tions.
	if I am a large quantity generator, I certify the practicable and that I have selected the practic and the environment; OR, if I am a small guan	i proper condition for in it i have a program in p able method of treatme	ansport by highway accord place to reduce the volume nt. storage, or disposal cup	and toxicity of was	ternational te generate	and national govern to the degree I ha	ment regula ve determin	ed to be economically
	marked, and labeled, and are in all respects if	i proper condition for in it i have a program in p able method of treatme	ansport by highway accord place to reduce the volume nt, storage, or disposal cun nade a good faith affort to	and toxicity of was	ternational te generate	and national govern to the degree I ha	ment regula ve determin and future : waste mana	tions. ed to be economically threat to human health gement instinct that is
Pr	if I am a large quantity generator, I certify the practicable and that I have selected the practic and the environment; OR, if I am a small quan available to me and that I can afford. infed/Typed Name	i proper condition for in it I have a program in p able method of treatmen lify generator, I have m	ansport by highway accord place to reduce the volume nt. storage, or disposal cup	and toxicity of was	ternational te generate	and national govern to the degree I ha	ment regula ve determin	tions. ed to be economically threat to human health gement inglined that is
Pr 2	if I am a large quantity generator, I certify that practicable and that I have selected the practic and the environment; OR, if I am a small quanticalle to me and that I can afford.	i proper condition for in it I have a program in p able method of treatmen lify generator, I have m	ansport by highway accord place to reduce the volume nt, storage, or disposal cun nade a good faith affort to	and toxicity of was	ternational te generate	and national govern to the degree I ha	went regular ve determin and future waste mana	ed to be economically threat to human health gement method that is Day Year
Pr 17 Pr	if I am a large quantity generator, I certify the practicable and that I have selected the practic and the environment; OR, if I am a small quan available to me and that I can afford. Inted/Typed Name Transporter 1 Acknowledgement of Receipt of Minted/Typed Name	i proper condition for in it I have a program in pable method of treatmentify generator, I have method of the condition of th	place to reduce the volume nt, storage, or disposal cun nade a good faith affort to	and toxicity of was	ternational te generate	and national govern to the degree I ha	went regula ve determin and future waste mana	tions. sed to be economically threat to human health gement method that is Day Year Day Year
Pr 17 Pr	if I am a large quantity generator, I certify the practicable and that I have selected the practic and the environment; OR, if I am a small quan available to me and that I can afford. Inted/Typed Name Transporter 1 Acknowledgement of Receipt of N	i proper condition for in it I have a program in pable method of treatmentify generator, I have method of the condition of th	place to reduce the volume nt, storage, or disposal cun nade a good faith affort to	and toxicity of was	ternational te generate	and national govern to the degree I ha	went regula ve determin and future waste mana	tions. Hed to be economically threat to human health gement in without that is Day Year Day Year
Pr 12 Pr 16 Pr	if I am a large quantity generator, I certify the practicable and that I have selected the practic and the environment; OR, if I am a small quan available to me and that I can afford. Inted/Typed Name Transporter 1 Acknowledgement of Receipt of Ninted/Typed Name	i proper condition for in it I have a program in pable method of treatmentify generator, I have method of the condition of th	ansport by highway accord place to reduce the volume nt, storage, or disposal cun tade a good faith affort to Signature Signature	and toxicity of was	ternational te generate	and national govern to the degree I ha	we determine and future waste mana	tions. Hed to be economically threat to human health gement in the that is Day Year Day Year
Pr 12 Pr 16 Pr	if I am a large quantity generator, I certify the practicable and that I have selected the practic and the environment; OR, if I am a small quan available to me and that I can afford. Inted/Typed Name Transporter 1 Acknowledgement of Receipt of N inted/Typed Name Tree-porter 2 Acknowledgement of Receipt of N inted/Typed Name	i proper condition for in it I have a program in pable method of treatmentify generator, I have method of the condition of th	ansport by highway accord place to reduce the volume nt, storage, or disposal cun tade a good faith affort to Signature Signature	and toxicity of was	ternational te generate	and national govern to the degree I ha	we determine and future waste mana	tions. Hed to be economically threat to human health gement method that is Day Year Day Year
Pr 17 Pr 16 Pr	if I am a large quantity generator, I certify the practicable and that I have selected the practic and the environment; OR, if I am a small quan available to me and that I can afford. Inted/Typed Name Transporter 1 Acknowledgement of Receipt of N inted/Typed Name Tree-porter 2 Acknowledgement of Receipt of N inted/Typed Name	i proper condition for in it I have a program in pable method of treatmentify generator, I have method of the condition of th	ansport by highway accord place to reduce the volume nt, storage, or disposal cun tade a good faith affort to Signature Signature	and toxicity of was	ternational te generate	and national govern to the degree I ha	we determine and future waste mana	tions. Hed to be economically threat to human health gement method that is Day Year Day Year
Pr 17 17 16 16 17 17 17 17	if I am a large quantity generator, I certify the practicable and that I have selected the practic and the environment; OR, if I am a small quan available to me and that I can afford. Inted/Typed Name Transporter 1 Acknowledgement of Receipt of N inted/Typed Name Tree-porter 2 Acknowledgement of Receipt of N inted/Typed Name	i proper condition for in it I have a program in p able method of treatmentify generator, I have m Laterials Laterials	ansport by highway accord place to reduce the volume int, storage, or disposal cun lade a good faith affort to Signature Signature Signature	ing to applicable in and toxicity of was rently ovailable to a minimize my waste	ternational te generate ne which m generation	and national govern to the degree I ha	we determine and future waste mana	tions. The data be economically threat to human health gement in without that is Day Year Day Year Day Year

NON-HAZARDOUS MANIFEST PKM10001

SHIPPER (FROM):
ROICC- Alamed Point
2450 Saratoge 57.5vite 200
Humeda, CA 9450
Building 360-TES

Job#: 3 2692575

No.	TYPE •	DESCRIPTION	WEIGHT
Shipping Units			
4	5	Spent Carbon – Non-Hazardous Waste	6
5		, in the second	MARIN
			4.7750
•		Circle one: AQUA VAPOR	
25	PM	Profile # 1 W 70057NH 5 2-6-09	8,7250
27			1750200
7	DM	Profile# W710100NH Exp. 2-21-09	1750

CUSTOMER INFORMATION:

DATE: PRINT NAME:

SIGNATURE:

10

TRANSPORTER:

NAME OF CARRIER #1:

DATE: SIGNATURE:

WESTATES CARBON

NAME OF CARRIER #2:

DATE:

SIGNATURE:

15

RECEIVED BY (FULL NAME):

16

DATE:

17

SIGNATURE:

18

- 1.) Name of Generator
- 2.) Generator site address
- 3.) Given job number
- 4.) Number of units being picked up
- 5.) Type of unit being picked up
- 6.) Total weight
- 7.) Profile number, MANDATORY
- 8.) Date service and/or pick up performed
- 9.) Name of person signing for Generator

- 10.) Signature of person in box 9
- 11.) Same as box 8
- 12.) Signature of driver for Transporter #1
- 13.) Name of carrier transporting to Plant
- 14.) Date the load was picked up to go to the Plant
- 15.) Driver's signature for Transporter #2
- 16.) Full name of Receiving person
- 17.) Date received into Plant
- 18.) Signature of Receiving person

MON HAZARDOUS MANITEST



NON-HAZARDOUS MANIFEST

PKM10001

			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		•
CONSIGNEE (TO):		SHIPPER (FROM):			•
☑ Westates Carbon-Arizona		ROICC-Alam			1
2523 Mutahar Street Parker, AZ 85344		2450 Saratog	•	200	
☐ Westates Carbon-California 11711 Reading Road	1		7450 l		
Red Bluff, CA 96080		Bldg 360-TR	.5		

Job#: 3 262675/

No. Shipping Units	TYPE •	DESCRIPTION WEIGHT
43	5 DM	Spent Carbon - Non-Hazardous Waste 1000
•		
		Circle one: AQUA VAPOR
		Profile # 1 W 700 5 7 N H
\		
/		

CUSTOMER INFORMATION:	·	
BATE: PRINT NAME: Gregory	J. Grace	SIGNATURE: Sugary 7: Same
TRANSPORTER:		
NAME OF CARRIER #1: AMILIA TENSON WESTATES CARBON	DATE:	SIGNATURE:
NAME OF CARRIER #2: 13	DATE:	SIGNATURE:
RECEIVED BY (FULL NAME):	DATE:	SIGNATURE:

- 1.) Name of Generator
- 2.) Generator site address
- 3.) Given job number
- 4.) Number of units being picked up
- 5.) Type of unit being picked up
- 6.) Total weight
- 7.) Profile number, MANDATORY
- 8.) Date service and/or pick up performed
- 9.) Name of person signing for Generator

- 10.) Signature of person in box 9
- 11.) Same as box 8
- 12.) Signature of driver for Transporter #1
- 13.) Name of carrier transporting to Plant
- 14.) Date the load was picked up to go to the Plant
- 15.) Driver's signature for Transporter #2
- 16.) Full name of Receiving person
- 17.) Date received into Plant
- 18.) Signature of Receiving person

NON-HAZARDOUS MANIJEST

NON-HA	ZARDOUS MA	NIFEST	and the second s		861	ne de la companya de	PKM1000
e e e e e e e e e e e e e e e e e e e		engile selection of the					
CONSIG	NEE (TO):			SHIPPER (FRO			and the second
	tates Carbo	en la la companya de la companya de la companya de la companya de la companya de la companya de la companya de			10 shau		
	Mutahar St	and the state of the same of t		1' thein	TAL Rem	ediatio	a Solvices
	er, AZ 8534	e and the page of the second o		399 11	st Sapla	12	
		n-California		Alexander	da Ca	12/10	-
	1 Reading R Bluff, CA 9			1129711	au ch		
	, 2392	. Edward on Walla.					
No. Shipping Units	TYPE •			DESCRIPTION			WEIGHT
·al.	* Ofuns	Spent Carl	bon – Non-	Hazardous '	Waste		· 8400
潮波落	第二个				CONTROL SA		
							A. 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 - 100 -
水水液		Circle one:	AQUA	(VAPOR	The same	为多数	245/45/27
					加度等於其次		CONTRACTOR AS
		Profile # 1	W70	100 N			
				4年40年18年16			WARRING TO
				of the sound	IXP à-	21-09	STEEN STEEN
						表 2000年	84004
CUSTOME	R INFORMATIO	N:					
DATE:		TNAME:	r let non	SIC 10	ONATURE:	والمالية	
TRANSPOR							
NAME OF C	ARRIER #1:		DATE:	33-77 SIC	INATURE:	4	
	ES CARBON		N/C		在 是1995年1995		
NAME OF C	ARRIER #2:		DATE:	SIG	INATURE:		
RECEIVED I	BY (FULL NAME)	DATE:	SIG	NATURE:		
e trigger e eft a Grand and a grand and a							
1.)	Name of Gene	rator		10.) Sig	nature of person	in box 9	
2.)	Generator site	address		11.) Sar	ne as box 8		
	Given job nun Number of un	iber its being picked i	1 p		nature of driver me of carrier tra		
5.) '	Type of unit b	eing picked up		14.) Dat	te the load was p	icked up to g	o to the Plant
-	Total weight Profile numbe	r. MANDATOR	Y		yer's signature f		er #2

8.) Date service and/or pick up performed9.) Name of person signing for Generator

17.) Date received into Plant
18.) Signature of Receiving person

NON-HA	ZARDOUS MA	ANIFEST	•	[#] 15859	PKM1000
	<u> </u>				
CONSIG	NEE (TO):		SHI	PPER (FROM):	
⊠ Wes	tates Carbo		, K	DICC ALAMEDA POINT	Box. 360
	Mutahar St		123	99 W. (SEADLANE LAC	cox l
Park	er, AZ 8534	4	ΙΛ	Λ .	.0.7.4
_		n-California		AMERA (A. 9450)	
	1 Reading F				
Red	Bluff, CA 9	6080			
Job#:	3 (D) NIME	<u> </u>	-		
No. Shipping Units	TYPE *		DESC	RIPTION	WEIGHT
14	5 DM	Spent Carbo	n – Non-Haz	ardous Waste	1.200
				:	
		Circle one:	AQUA Y	/APOR	
					
		Profile # 1	170057 NI	+ EXP. ozloclog	
	·				
CUSTOME	ER INFORMATIO	DN:	******		
DATE:		IT NAME:		SIGNATURE:	
~~	1-07	Bab Perri	conc	my) cike ("	تـــــــــــــــــــــــــــــــــــــ
TRANSPO	RTER:				·
NAME OF C	CARRIER #1:		DATE:	SIGNATURE:	
WESTAT	ES CARBON	•	12/09/0	7 / / / / AA	
	CARRIER #2:		DATE: /	SIGNATURE:	
RECEIVED	BY (FULL NAME	E):	DATE:	SIGNATURE:	
16			17	. 18	•
2.) 3.) 4.) 5.) 6.)	Type of unit Total weight	e address mber nits being picked up being picked up		10.) Signature of person in be 11.) Same as box 8 12.) Signature of driver for Telephone 13.) Name of carrier transposits.) Date the load was picked 15.) Driver's signature for Telephone 15.	ransporter #1 rting to Plant l up to go to the Plant ransporter #2
		er, MANDATORY and/or pick up perfo	rmed	16.) Full name of Receiving p 17.) Date received into Plant	C1300
·		F P	· 		· ·

18.) Signature of Receiving person

9.) Name of person signing for Generator

1>0~1

NON-HAZARDOUS WASTE DATA FORM

	NAME ROICE ST- BAY ALAMEDA POINT
	ADDRESS 2450 SARATOGA ST., STE 206 NO.
	CITY, STATE, ZIP. A LAMEDA, CA 94501 PHONE NO. ()
	CONTAINERS: No. VOLUME/CY 3 Y Yes, WEIGHT/TONS Y
	TYPE: TANK DUMP DRUMS CARTONS OTHER MGW H(2
	WASTE DESCRIPTION TOO TO GENERATING PROCESS
	COMPONENTS OF WASTE PPM % COMPONENTS OF WASTE PPM %
	2
	VOC-DVA READINGS
	VOD-OW TENDINGS
	SITE VERIFICATION
	PROPERTIES: pH
1.5	HANDUNG INSTRUCTIONS:
	HANDLING INSTRUCTIONS: THE WAS PARTICULAR TO THE PROPERTY OF
	NAME WORLD ENVIRONMENTAL & ENERGY BED TAYTH 2 SIGNATURE TYPED OR PRINTED FULL NAME & SIGNATURE FINAL PROPERTY NO. 1C A R 10 10 D 13 17 12 12 13 14 14 15 15 16 16 16 16 16 16
	NAME WORLD ENVIRONMENTAL & ENERGY ADDRESS PO BOX 192 THE WARRIES TO BOX 192 TO BOX 192 TO BOX 192 TO BOX 192 TO BOX 192 TO BOX 192 TO BOX 192 TO BOX 192 TO BOX 192 TO BOX 192
	NAME WORLD ENVIRONMENTAL & ENERGY BED TAYTH 2 SIGNATURE TYPED OR PRINTED FULL NAME & SIGNATURE FINAL PROPERTY NO. 1C A R 10 10 D 13 17 12 12 13 14 14 15 15 16 16 16 16 16 16
	NAME WORLD ENVIRONMENTAL & ENERGY ADDRESS PO BOX 192 CITY, STATE, ZIP SACRAMENTO CA 95691 PO TO TO TO TO TO TO TO TO TO TO TO TO TO
	PARTY SERVICE OF SERVI
	NAME WORLD ENVIRONMENTAL & ENERGY ADDRESS PO BOX 192 CITY, STATE, ZIP SACRAMENTO CA 95691 PHONE NO. 916 371-3617 THUCK, UNIT, LD, NO.
	PARTY SERVICE OF SERVI
	THE BARBAGE DESCRIBED SOME TYPED OR PRINTED FULL NAME & SIGNATURE NAME WORLD ENVIRONMENTAL & ENERGY ADDRESS PO BOX 192 CITY, STATE, ZIP SAGRAMENTO CA 95691 PHONE NO. 916 371-3617 THUCK, UNIT, LD. NO. NAME NWS HAY ROAD LANDFILL NO. C A D 9 8 2 0 4 2 4 7 DISPOSAL METHOD
	NAME WORLD ENVIRONMENTAL & ENERGY ADDRESS PO BOX 192 CITY, STATE, ZIP SACRAMENTO CA 95691 PHONE NO. 916 371-3617 TYPED OR PRINTED FULL NAME & SIGNATURE PHONE NO. 916 371-3617 TYPED OR PRINTED FULL NAME & SIGNATURE PHONE NO. 916 371-3617 THUCK, UNIT, LD, NO. NAME NWS HAY ROAD LANDFILL 6426 HAY ROAD ADDRESS VACAVILLE CA 95687 DISPOSAL METHOD LANDFILL DOTHER
	NAME: WORLD ENVIRONMENTAL & ENERGY MORLD ENVIRONMENTAL & ENERGY
	THE WASTE AS JESSE BEAUS 192 TYPED OR PRINTED FULL NAME & SIGNATURE PHONE NO. C A R 10 10 10 10 13 17 12 ADDRESS PO BOX 192 CITY, STATE, ZIP SACRAMENTO CA 95691 PHONE NO. 916 371-3617 THUCK, UNIT, LD. NO. NAME NWS HAY ROAD LANDFILL 6426 HAY ROAD ADDRESS VACAVILLE CA 95687 707 678-1492 CITY, STATE, ZIP CITY, STATE, ZIP CITY, STATE, ZIP CITY, STATE, ZIP
	NAME: WORLD ENVIRONMENTAL & ENERGY MORLD ENVIRONMENTAL & ENERGY
	TYPED OR PRINTED FULL NAME & SIGNATURE DATE NAME WORLD ENVIRONMENTAL & ENERGY NO. IC A R 10 10 10 D 13.17 12
	TYPED OR PRINTED FULL NAME & SIGNATURE DATE NAME WORLD ENVIRONMENTAL & ENERGY No. IC A R 10 10 10 13 17 12
	TYPED OR PRINTED FULL NAME & SIGNATURE NAME WORLD ENVIRONMENTAL & ENERGY No. IC & R 10 10 10 D 1317 12

Appendix F
Laboratory Analytical Data Packages for Treatment Impact
Assessment Soil and Groundwater Samples

APPENDIX F – LABORATORY ANALYTICAL DATA PACKAGES FOR TREATMENT IMPACT ASSESSMENT SOIL AND GROUNDWATER SAMPLES

THIS RECORD CONTAINS LARGE VOLUMES OF DATA AND IS NOT REQUIRED TO BE PHYSICALLY LOCATED WITH THE ADMINISTRATIVE RECORD DOCUMENT.

DUE TO EXTENSIVE VOLUME, THIS DATA WILL NOT BE IMAGED.

TO VIEW THE DATA, CONTACT:

DIANE C. SILVA
RECORDS MANAGEMENT SPECIALIST
NAVAL FACILITIES ENGINEERING COMMAND
SOUTHWEST
1220 PACIFIC HIGHWAY
SAN DIEGO, CA 92132

TELEPHONE: (619) 532-3676

Appendix G
Laboratory analytical data packages for Groundwater
Baseline, Progress, and Rebound Samples

APPENDIX G – LABORATORY ANALYTICAL DATA PACKAGES FOR GROUNDWATER BASELINE, PROGRESS, AND REBOUND SAMPLES

THIS RECORD CONTAINS LARGE VOLUMES OF DATA AND IS NOT REQUIRED TO BE PHYSICALLY LOCATED WITH THE ADMINISTRATIVE RECORD DOCUMENT.

DUE TO EXTENSIVE VOLUME, THIS DATA WILL NOT BE IMAGED.

TO VIEW THE DATA, CONTACT:

DIANE C. SILVA
RECORDS MANAGEMENT SPECIALIST
NAVAL FACILITIES ENGINEERING COMMAND
SOUTHWEST
1220 PACIFIC HIGHWAY
SAN DIEGO, CA 92132

TELEPHONE: (619) 532-3676

Appendix H
Laboratory Analytical Data Packages for System Compliance
Monitoring Samples

APPENDIX H – LABORATORY ANALYTICAL DATA PACKAGES FOR SYSTEM COMPLIANCE MONITORING SAMPLES

THIS RECORD CONTAINS LARGE VOLUMES OF DATA AND IS NOT REQUIRED TO BE PHYSICALLY LOCATED WITH THE ADMINISTRATIVE RECORD DOCUMENT.

DUE TO EXTENSIVE VOLUME, THIS DATA WILL NOT BE IMAGED.

TO VIEW THE DATA, CONTACT:

DIANE C. SILVA
RECORDS MANAGEMENT SPECIALIST
NAVAL FACILITIES ENGINEERING COMMAND
SOUTHWEST
1220 PACIFIC HIGHWAY
SAN DIEGO, CA 92132

TELEPHONE: (619) 532-3676

Appendix I
Statistical Analyses of September Rebound Groundwater
Sampling Data

Statistical Analysis of Alameda Plume 4-2

The objective of this statistical analysis is to estimate the mean concentration of total SAs in the Alameda Plume 4-2 during the September 2007 sampling event when all 19 wells were monitored, and to test whether the mean total SAs is less than 10,000 µg/L. The plume is monitored in 5 strata, or operational units, representing different proportions of the total water volume of the plume. Since each stratum represents a different volume of water in the plume a stratified statistical analysis design is appropriate. The use of stratification is a standard method of analysis to estimate the mean, variance of a characteristic and is discussed in sampling texts such as Cochran¹. Because the mass of all physical samples is insignificant compared to the total mass of the population, the finite population correction factor is ignored. Also, as Region 3 had only one sampling well it was impossible to get a reliable mean or variance estimate for this stratum and Region 3 was thus collapsed with Region 2 to form a single collapsed stratum. Table 1 below shows the 4 strata used in the statistical analysis design along with the results for Total SAs for each well within the stratum during the September 2007 sampling period. Table 2 gives the stratum weights representing the proportion of water volume each stratum represents.

Table 1. Strata and Results

Strata	Well ID	Sample Collection Date	Units	Total SAs
Region 1	MW4-2-1	9/24/2007	μg/L	23.71
i itegion i	MW4-2-2	9/24/2007	μg/L	297.70
	MW4-2-3	9/24/2007	μg/L	175.00
	MW4-2-4	9/24/2007	μg/L	633.50
	MW4-2-5	9/25/2007	μg/L	7598.90
Region 2&3	MW4-2-9	9/24/2007	μg/L	26.96
	MW4-2-18	9/25/2007	μg/L	476.30
	MW4-2-14	9/25/2007	μg/L	22.56
Region 4	MW4-2-6	9/24/2007	μg/L	8.50
region 4	MW4-2-7	9/24/2007	μg/L	17.11
	MW4-2-8	9/24/2007	μg/L	280.63
	MW4-2-11	9/24/2007	μg/L	21.49
	MW4-2-12	9/24/2007	μg/L	1328.00
	MW4-2-13	9/24/2007	μg/L	1527.76
Region 5	MW4-2-10	9/24/2007	μg/L	1464.70
3.0	MW4-2-15	9/25/2007	μg/L	497.75
	MW4-2-16	9/25/2007	μg/L	1203.56
1	MW4-2-17	9/24/2007	μg/L	12044.85
	MW4-2-19	9/24/2007	μg/L	739.58

¹ W. Cochramn (1977) Sampling. John Wiley, NY, NY

Table 2. Water Volume and Weights by Strata

Strata	Total GW Vol. by Region (L)	Stratum Weight	Number of Wells
Region 1	2,021,299.20	0.26	5
Region 2 & 3	637,259.40	0.08	3
Region 4	2,760,523.50	0.36	6
Region 5	2,251,548.00	0.29	5
Total	7,670,630.10	1.00	19

To determine if the plume mean for Total SAs is less than the $10,000~\mu g/L$ an upper 95% upper confidence limit (UCL), based on the t-statistic, was used. As the data within each strata and across all strata appears highly skewed Chen's test was also applied. Chen's test is suggested for use by EPA 2 when data appears highly skewed and is more appropriate in these situations than the 95% UCL based on the t-distribution. Table 3 below gives the stratum weights, weighted summary statistics, and the 95% UCL and results of Chen's test for testing whether the mean for Total SAs is greater than $10,000~\mu g/L$. Note the result for Chen's test is a p-value. The p-value is a probability and is thus a value between 0 and 1. If the p-value is less than 0.05, in our case, there is evidence to support the fact that the mean is greater than $10,000~\mu g/L$. However, as the p-value is 1.0, this strongly suggests that the mean for the plume is less than $10,000~\mu g/L$. The 95% UCL(t) based on the t-distribution gives a UCL of $3085.7\mu g/L$ which is also less than $10,000~\mu g/L$.

Table 3: Plume and Strata Estimates, UCL and Chen's Test

Strata	Stratum Weight	Weighted Mean (µg/L)	Weighted Variance	Weighted Variance of Mean	Weighted Third Moment about Mean	Weighted Standard Error of Mean	Weighted Skew- ness	95% UCL(T) (μg/L)	Chen's Test Mean > 10,000 (p- value)
Region 1	0.26	460.0	7.47E+05	1.49E+05	1.43E+09				
Region 2&3	0.08	14.6	4.69E+02	1.56E+02	1.76E+04				
Region 4	0.36	190.9	6.44E+04	1.07E+04	1.50E+07				
Region 5	0.29	936.4	2.12E+06	4.25E+05	6.82E+09				
Plume Total	1.00	1601.9	2.94E+06	5.85E+05	8.26E+09	7.65E+02	1.64E+00	3085.7	1.00

For comparative purposes, the analysis was also carried out on the unweighted and unstratified raw data. This analysis is inappropriate as it would down weight information representing a larger proportion of the water volume. However, it is being included here as it is commonly used whether it is appropriate or not. ProUCL 4.0, (which can not handle stratified data) gave a 95% UCL based on the gamma distribution of $3431 \mu g/L$ for the mean of Total SAs and Chen's test also gave a p-value of 1.0. Again, two procedures indicate that the mean concentration of Total SAs in the plume is less than $10,000 \mu g/L$.

² USEPA (2006), EPA QA/G-9:Data Quality Assessment A Reviewer's Guide, EPA/240/B-06/002 Chen, L (1995), Testing the mean of a skewed distribution, Journ. of The American Stata. Assoc., 90:767-772

ANALYTICAL DATA

THIS RECORD CONTAINS LARGE VOLUMES OF DATA AND IS NOT REQUIRED TO BE PHYSICALLY LOCATED WITH THE ADMINISTRATIVE RECORD DOCUMENT.

DUE TO EXTENSIVE VOLUME, THIS DATA WILL NOT BE IMAGED.

TO VIEW THE DATA, CONTACT:

DIANE C. SILVA
RECORDS MANAGEMENT SPECIALIST
NAVAL FACILITIES ENGINEERING COMMAND
SOUTHWEST
1220 PACIFIC HIGHWAY
SAN DIEGO, CA 92132

TELEPHONE: (619) 532-3676